

(if cash: receipt number\_

×

# **APPLICATION FOR APPEAL**

RECEIVED DEC 13 2011 CITY CLEAN

The City Clerk needs the following to process your appeal:

\$25 filing fee payable to the City of Saint Paul

Copy of the City-issued orders or letter which

AEC EN

# Saint Paul City Clerk

DEC 1 3 2011 310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102

CITY Telephone: (651) 266-8560

YOUR HEARING Date and Time:

are being appealed  Attachments you may wish to includ  This appeal form completed  □ Walk-In OR ★ Mail-In	Tuesday,   2   20   20   1  Time   30   P. M.  Location of Hearing:  Room 330 City Hall/Courthouse		
Address Being Appeal	ed:		
Number & Street: 461 Holly Aver	nue City: Saint Paul State: MN Zip: 55102		
Appellant/Applicant: Louis Frillman	Email [Ifrillman@marquetteadvisors.com		
Phone Numbers: Business 612-334-1274			
Signature: All H Meal C	CON BEHALF OF LOW FAILURD Dete: Dec 09, 2011		
/			
Address (if not Appellant's):			
Phone Numbers: Business	Residence Cell		
0 11	ed and Why? Attachments Are Acceptable		
Vacate Order/Condemnation/  Revocation of Fire C of O			
□ Summary/Vehicle Abatement			
□ Fire C of O Deficiency List			
₹ Fire C of O: Only Egress Windows	Fire Inspection Deficiency List Ref.# 14750, Item 12 (Unit 4-2nd		
□ Code Enforcement Correction Notice	Bedroom - MSFC 1026.1)		
□ Vacant Building Registration			
□ Other			

Application for Appeal St. Paul City Clerk 310 City Hall 15 W Kellogg Blvd St. Paul., MN 55102

461 Holly Ave
Fire Inspection C of O Deficiency List Item 12
Unit 4 – 2<sup>nd</sup> Bedroom – MSFC 1026.1 Escape Window
Ref. #: 14750

The Owner appeals referenced item above for the following reason:

461 Holly is a home designated as an historic building by the Historic Preservation Commission. The home was designed by prominent local architect, Clarence Johnston, and designed in the Georgian Revival style.

A series of circular gable windows are prominent features on the building. One of those gable windows is a required egress window and does not meet the opening requirements as noted by the fire inspector's report ref. #14750, Deficiency List Item 12.

The Owner's architect met with the Building Official and a member of the HPC on November 30, 2011 to discuss the deficiency. The architect mentioned changing the existing double-hung to a casement window may possibly meet escape window requirements, though that would change the historic character of the window. HPC noted the prominent gable feature and mentioned the Owner can apply for an appeal.

The Owner appeals Item 12 to retain the existing historic window in keeping with the historic character of the existing gable windows.



CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806 

 Telephone:
 651-266-8989

 Facsimile:
 651-266-8951

 Web:
 www.stpaul.gov/dsi

November 18, 2011

LOUIS FRILLMAN 50 6TH ST STE 1370 MINNEAPOLIS MN 55402

RE:

461 HOLLY AVE

Ref. # 14750

Dear Property Representative:

Your building was re-inspected on November 15, 2011. A re-inspection will be made on or after December 15, 2011. At this time, all work must be completed to approved plans and be inspected and approved under permit. Any work plans for further extension must be approved in advance of this date.

Saint Paul Legislative Code provides that no building shall be occupied without a Certificate of Occupancy. In order to re-occupy the building, the following deficiencies (if applicable) must be corrected and a complete Certificate of Occupancy inspection will be required. Failure to immediately complete the following deficiency list or the building vacated may result in a criminal citation.

# **DEFICIENCY LIST**

- 1. Unit 1 SPLC 34.10 (7), 34.33 (6) Repair and maintain the walls and ceilings in an approved manner.-Repair water damaged areas.

  Arrange for final inspection and approval of this work under permit. Contact DSI at (651) 266-8989.
- 2. Unit 4 2nd Bedroom MSFC1026.1 Provide and maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI at (651)- 266-9090. Refer to the Escape Windows for Residential Occupanices handout for more information.-Existing double-hung window does not meet openable height requirement. Window had a clear opening area of 15 inches high by 28.5 inches wide and a glazed area of 37 inches high by 31 inches wide, 8 square feet. NOTE: This room was in use as an office at time of inspection and did not have a bed in room.

3. Unit 4 - MSFC 1005.2 - Provide an approved additional means of egress due to an inadequate number of approved exits.
This 2rd floor unit requires two exits. Second exit is a stairway which goes to the 1s

This 3rd floor unit requires two exits. Second exit is a stairway which goes to the 1st floor roof and then ends with no landing, no guardrail and no means to further travel to grade level.

This work will require a building permit and plans. Contact DSI at (651) 266-8989.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8688) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: mitchell.imbertson@ci.stpaul.mn.us or call me at 651-266-8986 between 7:30 - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Mitchell Imbertson Fire Inspection

Ref. # 14750



# ALLLICATION FOR ALLEAL

RECEIVED

DEC 1 3 2011

REC

# Saint Paul City Clerk

DEC 1 3 2011 310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 CITY ULLIN

Telephone: (651) 266-8560

Managara	CITY CLE		1010p1101101 (001) 200 0000			
The City Clerk nee	ds the following to process y	your appeal:				
(if cash: receip	payable to the City of Saint F t number) ty-issued orders or letter wh		YOUR HEARING Date and Time:			
are being appe			Tuesday, 12/20/2011			
Attachments y  This appeal fo	ou may wish to include rm completed		Time_ 1:30 f. M.			
□ Walk-In OR			<u>Location of Hearing:</u> Room 330 City Hall/Courthouse			
Address Being Appealed:						
Number & Stre	et: 461 Holly Avenue	City: Sa	int Paul State: MN Zip: 55102			
Appellant/Applican	t: Louis Frillman	Em	Ifrillman@marquetteadvisors.com			
Phone Numbers: B	usiness 612-334-1274	Residence	Cell 612-865-6532			
Signature: May Meal CON BEHALF OF LOW FAILURE Date: Dec 09, 2011						
Name of Owner (if other than Appellant):						

Address (if not Appellant's):

Ρł	none Numbers: Business	Residence	Cell					
V	What Is Being Appealed and Why? Attachments Are Acceptable							
	Vacate Order/Condemnation/ Revocation of Fire C of O	·						
	Summary/Vehicle Abatement	1						
	Fire C of O Deficiency List							
X	Fire C of O: Only Egress Windows	Fire Inspection Deficie	Fire Inspection Deficiency List Ref.# 14750, Item 12 (Unit 4-2nd Bedroom - MSFC 1026.1)					
	Code Enforcement Correction Notice	e Bedroom - MSFC 102						
	Vacant Building Registration							
	Other							

Application for Appeal St. Paul City Clerk 310 City Hall 15 W Kellogg Blvd St. Paul., MN 55102

461 Holly Ave
Fire Inspection C of O Deficiency List Item 12
Unit 4 – 2<sup>nd</sup> Bedroom – MSFC 1026.1 Escape Window
Ref. #: 14750

The Owner appeals referenced item above for the following reason:

461 Holly is a home designated as an historic building by the Historic Preservation Commission. The home was designed by prominent local architect, Clarence Johnston, and designed in the Georgian Revival style.

A series of circular gable windows are prominent features on the building. One of those gable windows is a required egress window and does not meet the opening requirements as noted by the fire inspector's report ref. #14750, Deficiency List Item 12.

The Owner's architect met with the Building Official and a member of the HPC on November 30, 2011 to discuss the deficiency. The architect mentioned changing the existing double-hung to a casement window may possibly meet escape window requirements, though that would change the historic character of the window. HPC noted the prominent gable feature and mentioned the Owner can apply for an appeal.

The Owner appeals Item 12 to retain the existing historic window in keeping with the historic character of the existing gable windows.



CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806 Telephone: 651-266-8989 Facsimile: 651-266-8951 Web: www.stpaul.gov/dsi

November 18, 2011

LOUIS FRILLMAN 50 6TH ST STE 1370 MINNEAPOLIS MN 55402

RE: 461 HOLLY AVE

Ref. # 14750

Dear Property Representative:

Your building was re-inspected on November 15, 2011. A re-inspection will be made on or after December 15, 2011. At this time, all work must be completed to approved plans and be inspected and approved under permit. Any work plans for further extension must be approved in advance of this date.

Saint Paul Legislative Code provides that no building shall be occupied without a Certificate of Occupancy. In order to re-occupy the building, the following deficiencies (if applicable) must be corrected and a complete Certificate of Occupancy inspection will be required. Failure to immediately complete the following deficiency list or the building vacated may result in a criminal citation.

# **DEFICIENCY LIST**

- 1. Unit 1 SPLC 34.10 (7), 34.33 (6) Repair and maintain the walls and ceilings in an approved manner.-Repair water damaged areas.

  Arrange for final inspection and approval of this work under permit. Contact DSI at (651) 266-8989.
- 2. Unit 4 2nd Bedroom MSFC1026.1 Provide and maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI at (651)- 266-9090. Refer to the Escape Windows for Residential Occupanices handout for more information.-Existing double-hung window does not meet openable height requirement. Window had a clear opening area of 15 inches high by 28.5 inches wide and a glazed area of 37 inches high by 31 inches wide, 8 square feet. NOTE: This room was in use as an office at time of inspection and did not have a bed in room.

An Equal Opportunity Employer

3. Unit 4 - MSFC 1005.2 - Provide an approved additional means of egress due to an inadequate number of approved exits.-

This 3rd floor unit requires two exits. Second exit is a stairway which goes to the 1st floor roof and then ends with no landing, no guardrail and no means to further travel to grade level.

This work will require a building permit and plans. Contact DSI at (651) 266-8989.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8688) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: mitchell.imbertson@ci.stpaul.mn.us or call me at 651-266-8986 between 7:30 - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Mitchell Imbertson Fire Inspection

Ref. # 14750



CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220. Saint Paul, Minnesota 55101-1806

Telephone: 651-266-8989 Facsimile: 651-266-8951

elu Steve Johnson 651 48 9 9634 Pluler - 651 224 4771 Bell Walden - Stevenson

September 7, 2011

LOUIS FRILLMAN 50 6TH ST STE 1370 MINNEAPOLIS MN 55402 Ray rebad 617703 0313

# Revocation of Fire Certificate of Occupancy and Order to Vacate

RE:

461 HOLLY AVE

Ref. # 14750

Dear Property Representative:

Your building was inspected on September 7, 2011, for the renewal of the Certificate of Occupancy. Since you have failed to comply with the applicable requirements, it has become necessary to revoke the Certificate of Occupancy in accordance with Section 33.05 of the Saint Paul Legislative Code. A reinspection will be made on November 15, 2011 or the property vacated.

The Saint Paul Legislative Code further provides that no building shall be occupied without a Certificate of Occupancy. Failure to immediately complete the following deficiency list or the building vacated may result in a criminal citation.

# DEFICIENCY LIST

- 1. Basement - MSFC 703 - Provide and maintain fire rated wall construction with approved materials and methods. This work may require a permit(s). Call DSI at (651) 266-9090. The minimum rating must be: 1 hour. - Repair wall between basement utility area of unit 2 in an approved manner. Wall is not properly sealed or repaired to maintain fire resistance rating. Bathroom fan vent from unit 2 basement bathroom is run through firewall and venting into basement.
- 2. Unit 1 - SPLC 34.10 (7), 34.33 (6) - Repair and maintain the walls and ceilings in an approved manner. - Repair water damaged areas.
- 3. Unit 2 - Basement - Bathroom Fan - UMC 1002 - Repair, replace or install duct work in compliance with the mechanical code. This work may require a permit(s). Call DSI at (651) 266-9090.

An Equal Opportunity Employer

Kyeni

- Unit 2 Basement Bathroom Fan UMC 1104 Provide exhaust ducts to terminate 4. outside of the building and be equipped with back draft dampers.
- Unit 2 Dryer UMC 504.6 Provide, repair or replace the dryer exhaust duct. Exhaust ducts for domestic clothes dryers shall be constructed of metal and shall have a smooth interior finish. The exhaust duct shall be a minimum nominal size of four inches (102 mm) in diameter. This work will require a permit(s). Call DSI at (651) 266-8989.
- Unit 2 Kitchen MSFC 605.1 Remove unapproved exposed wiring and install in 6. accordance with the electrical code. This work will require a permit(s). Call DSI at (651) 266-9090. - Properly install exposed non-metallic wiring to garbage disposal.
- Unit 2 SPLC 34.10 (7), 34.33 (6) Repair and maintain the walls and ceilings in an 7. approved manner. - Repair as needed and paint where water-stained.
- Unit 3 Exterior Patio SPLC 34.09 (1) b,c, 34.32 (1) b,c Provide and maintain all Ponle. exterior walls free from holes and deterioration. All wood exterior unprotected surfaces must be painted or protected from the elements and maintained in a professional manner free from chipped or peeling paint.
  - Unit 3 SPLC 34.10 (7), 34.33 (6) Repair and maintain the ceiling in an approved manner. - Repair as needed and paint where water-stained.
  - Unit 4 1st Bedroom MSFC 1011.2 Remove the materials that cause an exit obstruction. Maintain a clear and unobstructed exitway.-Storage and furniture
- Unit 4 1st Bedroom MSFC 1003.3.1.8 Remove unapproved locks from the exit doors. The door must be openable from the inside without the use of keys or special knowledge or effort. - Remove double-keyed deadbolt lock from door to rear stairway, provide approved single-keyed deadbolt. 12.
  - Unit 4 2nd Bedroom MSFC1026.1 Provide and maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI at (651)- 266-9090. Refer to the Escape Windows for Residential Occupancies handout for more information. - Existing double-hung window does not meet openable height requirement. Window had a clear opening area of 15 inches high by 28.5 inches wide and a glazed area of 37 inches high by 31 inches wide, 8 square feet. NOTE: This room was in use as an office at time of inspection and did not have a bed in
- fair cur Unit 4 - MSFC 1005.2 - Provide an approved additional means of egress due to an inadequate number of approved exits.-This 3rd floor unit requires two exits. Second exit is a stairway which goes to the 1st floor roof and then ends with no landing, no guardrail This work will require a building permit. Contact DSI at (651) 266-8989.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8688) and must be filed within 10 days of the date of this order.


If you have any questions, email me at: mitchell.imbertson@ci.stpaul.mn.us or call me at 651-266-8986 between 7:30 - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Mitchell Imbertson Fire Inspection

Ref. # 14750


461 Holly Saint Paul, MN



Existing 3<sup>rd</sup> floor Unit 4 bedroom escape window 461 Holly Saint Paul, MN



Existing 3<sup>rd</sup> floor Unit 4 bedroom escape window



Existing double-hung with a clear area of 15" high by 28" wide and a glazed area of 37" high by 31" wide

# 461 Holly Saint Paul, MN