

 $\quad \ \Box \quad Vacant \ Building \ Registration$

□ Other

APPLICATION FOR APPEAL

RECEIVED
Saint Paul City Clerk
310 City Hall, 15 W. Kellogg Blvd.
Saint Paul, Minnesota 55100
Televi

dammer.	C	177		
*25 filing fee payable to the City of S (if cash: receipt number	eaint Paul Ter which	Tuesday, Time Location of	ARING Date and To San 32 1:30 prof Hearing: City Hall/Courthor	0/2 n
Address Being Appeal	ed:			
Number & Street: 1075 Ros	e Au E City:≤	StPaul	_State <u>nn_</u> Zip	:55106
Appellant/Applicant: MAureen	Jones	Email <u>Copp</u>	erjones5	OBYAhoo.
Phone Numbers: Business	Residence		Cell 6/2 -2 <	14-6781
Signature: Maure me (maureen K	Date	11/29/11	
Name of Owner (if other than Appellant):	MelvinKJ	ones (Tr) Cheric	: Jones
Address (if not Appellant's): 12603	-85th Pl 8	n. Map	leGrove, 1.	no 55368
Phone Numbers: Business	Residence		Cell 763-3	60-2245
What Is Being Appeale	d and Why	? Attachn	nents Are Acce	ptable
Vacate Order/Condemnation/ Revocation of Fire C of O □ Summary/Vehicle Abatement	1st 421	nd fle	for W	in dows
□ Fire C of O Deficiency List				
Fire C of O: Only Egress Windows				
□ Code Enforcement Correction Notice				



CITY OF SAINT PAUL Christopher B. Coleman, Mayor 375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806 Telephone: Facsimile:

651-266-8989 651-266-8951

Web: www.stpaul.gov/dsi

November 22, 2011

MELVIN JONES JR CHERIE JONES 12603 -- 85TH PL N MAPLE GROVE MN 55369-4765 Marker 1

FIRE INSPECTION CORRECTION NOTICE

RE:

1075 ROSE AVE E

Ref. #109930

Residential Class: C

Dear Property Representative:

Your building was inspected on November 18, 2011 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date.

A re-inspection will be made on December 16, 2011 at 10:00 am.

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

DEFICIENCY LIST

1. 1st Floor - MSFC1026.1 - Provide and maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI at (651)- 266-9090. Refer to the Escape Windows for Residential Occupanices handout for more information. Double hung window opening.

Height 19.5 in. - Width 27 in.

Glazed area.

Height 39 in. - Width 23.5 in.

An Equal Opportunity Employer

Jovanio

2. 2nd Floor - Bedroom - MSFC1026.1 - Provide and maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI at (651)- 266-9090. Refer to the Escape Windows for Residential Occupanices handout for more information. Double hung window opening.

Height 20 in. - Width 27 in.

Glazed area

Height 41 in. - Width 23 in.

3. 2nd Floor - MSFC 605.4 - Discontinue use of all multi-plug adapters.

4. 1st Floor - North bedroom - MSFC 605.1- All light fixtures shall be maintained with protective globes if originally equipped.

1st and 2nd Floor - MN State Statute 299F.50 Immediately provide and maintain an approved Carbon Monoxide Alarm in a location within ten (10) feet of each sleeping area. Installation shall be in accordance with manufacturers instructions.

6. Basement - South room - MSFC 605.6 - Provide electrical cover plates to all outlets, switches and junction boxes where missing.

7. Basement - South room - MSFC 605.1 - Remove unapproved exposed wiring and install in accordance with the electrical code. This work may require a permit(s). Call DSI at (651) 266-9090.

8. Basement - UMC 504.6 - Provide, repair or replace the dryer exhaust duct. Exhaust ducts for domestic clothes dryers shall be constructed of metal and shall have a smooth interior finish. The exhaust duct shall be a minimum nominal size of four inches (102 mm) in diameter. This work may require a permit(s). Call DSI at (651) 266-8989.-PERMIT REQUIRED AND INSPECTION BY WARM AIR / VENT INSPECTOR. CALL 266-9006

9. Bath - By tub - SPLC 34.10 (7), 34.33 (6) - Repair and maintain the walls in an approved manner.

Oh to repair susses fleet

10. SPLC 34.11 (6), 34.34 (3) - Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.

11. SPLC 39.02(c) - Complete and sign the provided smoke detector affidavit and return it to this office.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse,

J. Much

15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8688) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: mike.cassidy@ci.stpaul.mn.us or call me at 651-266-8984 between 7:30 a.m. - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Mike Cassidy Fire Inspector

Reference Number 109930