

APPLICATION FOR APPEAL

RECEIVED
FEB 0 3 2012
CITY CLERK

Saint Paul City Clerk

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8560

The City Clerk needs the following to pro	ocess your appeal:	
\$25 filing fee payable to the City of S	Saint Paul	
(if cash: receipt number)	for right ale	YOUR HEARING Date and Time:
Copy of the City-issued orders or let are being appealed	ter wiitch	Tuesday, 2-21-12
Attachments you may wish to include	le	Time 1:30
This appeal form completed		
□ Walk-In OR ☑ Mail-In		<u>Location of Hearing:</u> Room 330 City Hall/Courthouse
	•	
Address Being Appealed:		
Number & Street: 1228 Bradley St. City: St. Paul State: MN Zip: 55130		
Appellant/Applicant: WILLIAM I BONIN Email bonin Pusbeng. Com		
Phone Numbers: Business Residence 651-294-5685 Cell 651-307-6875		
Signature: W	•	Date: 31 Jan 12
Name of Owner (if other than Appellant): Karissa C. Baker		
Address (if not Appellant's): 284	Macalester St	St. Paul 55105
Phone Numbers: Business	Residence 651-2	294-5685 Cell 612-308-6824
What Is Being Appealed and Why? Attachments Are Acceptable		
Vacate Order/Condemnation/ Revocation of Fire C of O		
☐ Summary/Vehicle Abatement		
□ Fire C of O Deficiency List		
Fire C of O: Only Egress Windows	House is 1912 vintage	- windows in east bedroom Cannot open
□ Code Enforcement Correction Notice	more than 23 inc	hes. Access through window
□ Vacant Building Registration	meets code (20	5" and 27") if Isideways i.e.
□ Other	If looked at as	24" x zo" clear opening.



CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806

 Telephone:
 651-266-8989

 Facsimile:
 651-266-8951

 Web:
 www.stpaul.gov/dsi

January 25, 2012

KARISSA C BAKER WILLIAM J BONIN 284 MACALESTER ST ST PAUL MN 55105-2032

FIRE INSPECTION CORRECTION NOTICE

RE:

1228 BRADLEY ST

Ref. #110509

Residential Class: C

Dear Property Representative:

. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date.

A re-inspection will be made on February 28, 2012 at 1:00 pm.

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

DEFICIENCY LIST

- 1. 2nd Floor MN State Statute 299F.50 Immediately provide and maintain an approved Carbon Monoxide Alarm in a location within ten (10) feet of each sleeping area. Installation shall be in accordance with manufacturers instructions.
- 2. 2nd Floor East bedroom MSFC1026.1 Provide and maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI at (651)- 266-9090. Refer to the Escape Windows for Residential Occupanices handout for more information.-Double hung window opening.

Height 20.5 in. - Width 27 in.

Glazed area Height 57 in. - Width 23.5 in.

- 3. 2nd Floor Porch SPLC 34.09 (2) 34.32 (2) Provide an approved guardrail with intermediate ballustrade or rails 4 inches or less apart. This work may require a permit(s). Call DSI at (651) 266-9090.-Or block door.
- 4. Basement SPLC 34.10 (5), 34.33 (4), 34.16 Provide and maintain interior in a clean and sanitary condition.
- 5. Basement SPLC 34.10 (3) 34.33(2) Provide an approved guardrail. Intermediate ballustrade must not be more than 4 inches apart. Intermediate rails must be provided if the height of the platform is more than 30 inches.
- 6. Basement SPLC 34.10 (3), 34.33(2) Provide an approved handrail. The top of the handrail must be between 34 and 38 inches above the treads and run the entire length of the stair.
- 7. Basement UMC 504.6 Provide, repair or replace the dryer exhaust duct. Exhaust ducts for domestic clothes dryers shall be constructed of metal and shall have a smooth interior finish. The exhaust duct shall be a minimum nominal size of four inches (102 mm) in diameter. This work may require a permit(s). Call DSI at (651) 266-8989.-PERMIT REQUIRED AND INSPECTION BY WARM AIR / INSPECTOR CALL 266-9006
- 8. Living room MSFC 605.5 Discontinue use of extension cords used in lieu of permanent wiring.-Replace with power strip if needed.
- 9. Living room and kitchen. MSFC 605.4 Discontinue use of all multi-plug adapters.
- 10. SPLC 34.11 (6), 34.34 (3) Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8688) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: mike.cassidy@ci.stpaul.mn.us or call me at 651-266-8984 between 7:30 a.m. - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Mike Cassidy Fire Inspector