

□ Other

The City Clerk needs the following to process your appeal:

# APPLICATION FOR APPEAL

RECEIVED

APR 1 8 2012

CITY CLERK

# Saint Paul City Clerk

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8560

\$25 filing fee payable to the City of Saint Paul (if cash: receipt number) Copy of the City-issued orders or letter which are being appealed Attachments you may wish to include This appeal form completed  Walk-In OR Mail-In	YOUR HEARING Date and Time:  Tuesday, 4-34-12  Time 1:30 p. m,  Location of Hearing: Room 330 City Hall/Courthouse
Address Being Appealed:	
Number & Street: 762 Magnolia Due City: 37 Pal State: MN Zip:	
Appellant/Applicant: Told Anderson Connet RESEmail Told garnet res. Com	
Phone Numbers: Business 651 49 \$ 8005 Residence Cell 4651 492 5662	
Signature: Date:	
Name of Owner (if other than Appellant): Meiss A Meier	
Address (if not Appellant's): 467 Arlington Ave	
Phone Numbers: Business Residence	Cell <u>(461 774 (4877</u>
What Is Being Appealed and Why? Attachments Are Acceptable	
Vacate Order/Condemnation/ Revocation of Fire C of O	
□ Summary/Vehicle Abatement	
□ Fire C of O Deficiency List	· ·
Fire C of O: Only Egress Windows	And the second s
□ Code Enforcement Correction Notice	and the second section of the second section is a second of the second section of the second section is a second section of the section of the second section is a second section of the section of the second section is a second section of the s
□ Vacant Building Registration	



CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806 

 Telephone:
 651-266-8989

 Facsimile:
 651-266-8951

 Web:
 www.stpaul.gov/dsi

March 21, 2012

MELISSA MAIER C/O GARNET MANAGEMENT GROUP 305 GREELEY ST S, STE 200 STILLWATER MN 55082-7029

#### FIRE INSPECTION CORRECTION NOTICE

RE:

762 MAGNOLIA AVE E

Ref. #112798

Residential Class: C

# Dear Property Representative:

Your building was inspected on March 21, 2012 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date.

## A re-inspection will be made on April 20, 2012 at 9:30 am.

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

### **DEFICIENCY LIST**

1st Floor - Bath - SPLC 34.11, SBC 2902.1, SPLC 34.17, MPC 415.0220 - Repair or replace and maintain the plumbing fixture to an operational condition.-Toilet seat loose.

1st Floor - South bedroom - SPLC 34.10 (7), 34.33 (6) - Repair and maintain the ceiling in an approved manner.

3. 1st Floor - SPLC 34.12 (2), 34.35 (1) - Repair and maintain all required and supplied equipment in an operative and safe condition.-Missing hard wire smoke detector.

- 1st Floor MN State Statute 299F.50 Immediately provide and maintain an approved Carbon Monoxide Alarm in a location within ten (10) feet of each sleeping area. Installation shall be in accordance with manufacturers instructions.
- 5. 2nd Floor - North and South bedrooms - MSFC1026.1 - Provide and maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI at (651)- 266-9090. Refer to the Escape Windows for Residential Occupanices handout for more information.-Double hung window opening.

H 16 in. - W 21in.

Glazed area.

H 39 in. - W 18 in.

- 6. Basement - UMC 504.6 - Provide, repair or replace the dryer exhaust duct. Exhaust ducts for domestic clothes dryers shall be constructed of metal and shall have a smooth interior finish. The exhaust duct shall be a minimum nominal size of four inches (102 mm) in diameter.-Insulate dryer vent 3 feet from exterior wall.
- Exterior SPLC 34.09 (1) b,c, 34.32 (1) b,c Provide and maintain all exterior walls free from holes and deterioration. All wood exterior unprotected surfaces must be painted or protected from the elements and maintained in a professional manner free from chipped or peeling paint.

Repair siding rear and 2nd story East side. Also paint foundation rear.

- SPLC 34.11 (6), 34.34 (3) Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.
- SPLC 39.02(c) Complete and sign the smoke detector affidavit and return it to this
- SPLC 34.11(5), 34.34(2), SPC 4715.0200Q Provide adequate hot water between 120 degrees F and 130 degrees F.-Hot water 84 F.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8688) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: mike.cassidy@ci.stpaul.mn.us or call me at 651-266-8984 between 7:30 a.m. - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Mike Cassidy Fire Inspector

Reference Number 112798