

□ Other

APPLICATION FOR APPEAL

Saint Paul City Clerk

RECEIVED MAY 0 7 2012

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8560

S25 filing fee payable to the City of Saint Paul (if cash: receipt number) Copy of the City-issued orders or letter which are being appealed Attachments you may wish to include This appeal form completed Walk-In OR Mail-In	YOUR HEARING Date and Time: Tuesday, 5-15-12 Time
Address Being Appealed:	
Number & Street: 1622 Wellestey Are City: 54. Poul State: MN Zip: 55105	
Appellant/Applicant: Corey DeNicoln Email Chenicola@mainstreambortique, W	
Phone Numbers: Business (952) 891 - 1379 Residence	Cell (952) 818-0039
Signature: Date: 4/27/12	
Name of Owner (if other than Appellant):	
Address (if not Appellant's):	
Phone Numbers: Business Residence	Cell
What Is Being Appealed and Why? Attachments Are Acceptable	
Vacate Order/Condemnation/ Revocation of Fire C of O Summary/Vehicle Abatement	
□ Fire C of O Deficiency List	
Fire C of O: Only Egress Windows	
Code Enforcement Correction Notice	
□ Vacant Building Registration	

DEFICIENCY LIST

1. Double hung windows - MSFC1026.1 - Provide and maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI at (651)- 266-9090. Refer to the Escape Windows for Residential Occupancies handout for more information.Second floor - southwest

Second floor - southwest
21.5 h x 26 w Glazed 7.5 sq ft
Second floor north
17.5 h x 29 w Glazed 8.3 sq ft
First floor
17.5 h x 29 w Glazed 8.3 sq ft



CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806

 Telephone:
 651-266-8989

 Facsimile:
 651-266-8951

 Web:
 www.stpaul.gov/dsi

January 30, 2012

COREY DENICOLA 1622 WELLESLEY AVE ST PAUL MN 55105

RE: RE-INSPECTION FIRE CERTIFICATE OF OCCUPANCY WITH DEFICIENCIES

1622 WELLESLEY AVE

Dear Property Representative:

Your building was re-inspected for the Fire Certificate of Occupancy on January 30, 2012. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected immediately.

A reinspection will be made on February 29, 2012 at 1:00 PM.

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

DEFICIENCY LIST

1. Double hung windows - MSFC1026.1 - Provide and maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI at (651)- 266-9090. Refer to the Escape Windows for Residential Occupancies handout for more information.-

Second floor - southwest 21.5 h x 26 w Glazed 7.5 sq ft Second floor north 17.5 h x 29 w Glazed 8.3 sq ft First floor 17.5 h x 29 w Glazed 8.3 sq ft

2. Exterior - SPLC 34.09 (3), 34.32 (3) - Repair and maintain the window glass.

- 3. Exterior SPLC 34.09 (1) b,c, 34.32 (1) b,c Provide and maintain all exterior walls free from holes and deterioration. All wood exterior unprotected surfaces must be painted or protected from the elements and maintained in a professional manner free from chipped or peeling paint.-Repair damaged siding on west side of house.
- 4. Front door SPLC 34.09 (3), 34.32 (3) Repair and maintain the door in good condition.-Provide an approved door handle. Replace or repair in an approved manner.
- 5. Garage MSFC 605.6 Provide electrical cover plates to all outlets, switches and junction boxes where missing.
- 6. SPLC 34.11 (6), 34.34 (3) Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.
- 7. SPLC 39.02(c) Complete and sign the provided smoke detector affidavit and return it to this office.
- 8. SPLC 34.09 (3), 34.32 (3) Repair and maintain the window lock.-second floor windows
- 9. MN State Statute 299F.50 Immediately provide and maintain an approved Carbon Monoxide Alarm in a location within ten (10) feet of each sleeping area. Installation shall be in accordance with manufacturers instructions.
- 10. UMC 504.6 Provide, repair or replace the dryer exhaust duct. Exhaust ducts for domestic clothes dryers shall be constructed of metal and shall have a smooth interior finish. The exhaust duct shall be a minimum nominal size of four inches (102 mm) in diameter. This work requires a permit(s). Call DSI at (651) 266-8989.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8688) and must be filed within 10 days of the date of the original orders.

If you have any questions, email me at rick.gavin@ci.stpaul.mn.us or call me at 651-266-8994 between 7:30 a.m - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Rick Gavin Fire Inspector COREY DENICOLA 1622 WELLESLEY AVE ST PAUL MN 55105

RE: RE-INSPECTION FIRE CERTIFICATE OF OCCUPANCY WITH DEFICIENCIES

1622 WELLESLEY AVE

Dear Property Representative:

Your building was re-inspected for the Fire Certificate of Occupancy on January 30, 2012. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected immediately.

A reinspection will be made on February 29, 2012 at 1:00 PM.

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

DEFICIENCY LIST

1. Double hung windows - MSFC1026.1 - Provide and maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI at (651)- 266-9090. Refer to the Escape Windows for Residential Occupancies handout for more information.-

Second floor - southwest 21.5 h x 26 w Glazed 7.5 sq ft Second floor north 17.5 h x 29 w Glazed 8.3 sq ft First floor 17.5 h x 29 w Glazed 8.3 sq ft

- 2. Exterior SPLC 34.09 (3), 34.32 (3) Repair and maintain the window glass.
- 3. Exterior SPLC 34.09 (1) b,c, 34.32 (1) b,c Provide and maintain all exterior walls free from holes and deterioration. All wood exterior unprotected surfaces must be painted or protected from the elements and maintained in a professional manner free from chipped or peeling paint.-Repair damaged siding on west side of house.
- 4. Front door SPLC 34.09 (3), 34.32 (3) Repair and maintain the door in good condition.-Provide an approved door handle. Replace or repair in an approved manner.
- 5. Garage MSFC 605.6 Provide electrical cover plates to all outlets, switches and junction boxes where missing.
- 6. SPLC 34.11 (6), 34.34 (3) Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.
- 7. SPLC 39.02(c) Complete and sign the provided smoke detector affidavit and return it to this office.
- 8. SPLC 34.09 (3), 34.32 (3) Repair and maintain the window lock.-second floor windows
- 9. MN State Statute 299F.50 Immediately provide and maintain an approved Carbon Monoxide Alarm in a location within ten (10) feet of each sleeping area. Installation shall be in accordance with manufacturers instructions.
- 10. UMC 504.6 Provide, repair or replace the dryer exhaust duct. Exhaust ducts for domestic clothes dryers shall be constructed of metal and shall have a smooth interior finish. The exhaust duct shall be a minimum nominal size of four inches (102 mm) in

diameter. This work requires a permit(s). Call DSI at (651) 266-8989.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8688) and must be filed within 10 days of the date of the original orders.

If you have any questions, email me at <u>rick.gavin@ci.stpaul.mn.us</u> or call me at 651-266-8994 between 7:30 a.m - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Rick Gavin Fire Inspector