

The City Clerk needs the following to process your appeal:

APPLICATION FOR APPEAL

RECEIVED
MAY 1 4 2012

Saint Paul City Clerk

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8560

Revised 3/7/2011

CITY CLERK

\$25 filing fee payable to the City of S (if cash: receipt number) Copy of the City-issued orders or let are being appealed Attachments you may wish to includ This appeal form completed Walk-In OR Mail-In	YOUR HEARING Date and Time: ter which Tuesday, 5 - 3 3 - 12
Address Being Appeal	ed:
Number & Street: 1126 N. 0	Ox ford City: St. Pawl State: MN Zip: 55103
Appellant/Applicant:	lenley Email jdo semagen a) Charte 1432 Residence 231-869-2519 Cell - Date: 5/9/12
Phone Numbers: Business	Residence Cell
What Is Being Appeale	ed and Why? Attachments Are Acceptable
Vacate Order/Condemnation/ Revocation of Fire C of O	
□ Summary/Vehicle Abatement	
□ Fire C of O Deficiency List	
	No space for full-size wondow
□ Code Enforcement Correction Notice	The state of the s
□ Vacant Building Registration	
□ Other	



CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806

 Telephone:
 651-266-8989

 Facsimile:
 651-266-8951

 Web:
 www.stpaul.gov/dsi

April 16, 2012

JAMES HENLEY JANE DOSEMAGEN 925 2ND ST PENTWATER MI 49449-9564

FIRE INSPECTION CORRECTION NOTICE

RE: 1126 OXFORD ST N

Dear Property Representative:

Your building was inspected on April 16, 2012 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date.

A re-inspection will be made on May 29, 2012 at 1:15pm.

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

DEFICIENCY LIST

DAVE

1. Exterior - Screens - SPLC 34.09 (3), 34.32 (3) - Provide or repair and maintain the window screens.

Interior - Basement - UMC 504.6 - Provide, repair or replace the dryer exhaust duct. Exhaust ducts for domestic clothes dryers shall be constructed of metal and shall have a smooth interior finish. The exhaust duct shall be a minimum nominal size of four inches (102 mm) in diameter. This work requires a permit(s). Call DSI at (651) 266-8989.-Hire a licensed contractor to install the dryer vent to meet code.

Interior - Basement - MFGC 409.5 - Provide an approved gas shut off valve within 6 feet of the appliance in accordance with the mechanical code. This work may require a permit(s). Call DSI at (651) 266-8989.-Secure the gas line to the dryer.

An Equal Opportunity Employer

WWW. ST. PAW-GOS GAP AJS GOV. CITAL CHEAK

Interior - Basement - MSFC 605.5 - Discontinue use of extension cords used in lieu of permanent wiring.

Interior - Basement - MSFC 605.4 - Discontinue use of all multi-plug adapters.

Interior - Bathroom - SPLC 34.14 (2) c - Provide or replace the duplex convenience outlet with ground fault protection within 3 feet of the basin on an adjacent wall in all bathrooms. This work may require a permit(s). Call DSI at (651) 266-9090.-Repair the GGCI outlet in the bathroom that tested with an open ground wire.

> Interior - Egress Window - MSFC1026.1 - Provide and maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI at (651) - 266-9090. Refer to the Escape Windows for Residential Occupanices handout for more information.-The rear bedroom egress window measured 16H x 22W.

> Interior - Hand Rails - SPLC 34.10 (3), 34.33(2) - Provide an approved handrail. The top of the handrail must be between 34 and 38 inches above the treads and run the entire length of the stair.-Provide handrails to the basement and second floor to meet code.

> Interior - Locks - MSFC 1003.3.1.8 - Remove unapproved locks from the unit doors. The door must be openable from the inside without the use of keys or special knowledge or effort.-Remove all slide bolt locks from all doors.

> SPLC 34.11 (6), 34.34 (3) - Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8688) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: lisa.martin@ci.stpaul.mn.us or call me at .651-266-8988 between 6:30 a.m. - 8:30 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Lisa Martin Fire Inspector

DRIVATION 651 DIRECT BLD. 9090
266 9023 PHOLE VIRGIL THOMPS

7.

10.)