

APPLICATION FOR APPEAL

RECEIVED
MAY 1 4 2012
CITY CLERK

Saint Paul City Clerk

Revised 4/22/2011

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8560

	CITY CHEFTS
The City Clerk needs the following to process	
\$25 filing fee payable to the City of Saint (if cash: receipt number)	YOUR HEARING Date and Time:
Copy of the City-issued orders or letter w	Tuesday, 6-5-12
are being appealed Attachments you may wish to include	Tuesday, G. J. L.
Attachments you may wish to include This appeal form completed	Time
War in	Location of Hearing:
Walk-in OR Mail-in	Room 330 City Hall/Courthouse
	emuited 5-14-12 game
Address Being Appealed	•
Number & Street: 635 Black	AVR City: State: MN Zip: 35704
	hai Email Visulanthaice Gahoo, Com
Phone Numbers: Business 952 921 0911	Residence 65/ 340 580/ Cell 6/2 805 530 3
Signature: Sala Thai	Date: 5/9/12
Name of Owner (if other than Appellant):	NIA
Address (if not Appellant's):	
Phone Numbers: Business	Residence Cell
What Is Being Appealed and Why? Attachments Are Acceptable	
Vacate Order/Condemnation/	and so and a son And a mildely.
Revocation of Fire C of O	nurchase the property in 2003. And Remodeled.
□ Summary/Vehicle Abatement WIZ	to the permit and approved by the City of
☐ Fire C of O Deficiency List	and also had passed The inspections every year.
Fire C of O: Only Egress Windows	's a double hung Window, loop Square inches glass,
□ Code Enforcement Correction Notice Wh	John 100 Square inches more than the Regulemen
□ Vacant Building Registration	very costly to has it peplaced flease Reconsider
Other	The Matter please! Thank-you



CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806 Telephone: 651-266-8989 Facsimile: 651-266-8951

Web: www.stpaul.gov/dsi

April 26, 2012

LISALAN MAI THAI STEVEN T VANACO 1441 DEERWOOD LN EAGAN MN 55122-1809

FIRE INSPECTION CORRECTION NOTICE

RE:

635 BLAIR AVE

Ref. #103871

Residential Class: C

Dear Property Representative:

Your building was inspected on April 26, 2012 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date. A reinspection will be made on May 29, 2012 at 11:00 AM.

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LISTS OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

DEFICIENCY LIST

- Exterior Front SPLC 34.09 (1) b,c, 34.32 (1) b,c Provide and maintain all exterior 1. walls free from holes and deterioration. All wood exterior unprotected surfaces must be painted or protected from the elements and maintained in a professional manner free from chipped or peeling paint.-Scrape and paint the front door trim.
- Exterior Front Porch SPLC 34.09 (2), 34.32(2) Repair or replace the unsafe 2. stairways, porch, decks or railings in an approved manner. This work may require a permit(s). Call DSI at (651) 266-9090.-Repair or replace the bottom step and secure the loose porch railing.

- 3. Exterior SPLC 34.09 (3), 34.32 (3) Provide or repair and maintain the window screens, where broken or missing.
- 4. Exterior MSFC 605.1 Repair or replace damaged electrical fixtures. This work may require a permit(s). Call DSI at (651) 266-9090.-Repair side door and garage light fixtures in an approved manner.
- 5. Exterior SPLC 34.08 (1), 34.31 (1) All exterior property areas shall be maintained free from any accumulation of refuse, garbage or feces.-Remove debris stored by the garage. Clean up the window wells on the side of the house.
- 6. Garage SPLC 34.19 Provide access to the inspector to all areas of the building.
- 7. Garage SPLC 34.08 (5), 34.31 (3) Repair, replace and maintain all exterior surfaces on fences, sheds, garages and other accessory structures free from holes and deterioration. Provide and maintain exterior unprotected surfaces painted or protected from the elements.-Repair hole in the garage. Scrape and paint trim where needed. Repair or install fence in an approved manner. Work may require permit.
- 8. Interior Basement SPLC 34.10 (3), 34.33(2) Provide an approved handrail. The top of the handrail must be between 34 and 38 inches above the treads and run the entire length of the stair.
- 9. Interior Entry Doors SPLC 34.09 (3) i Provide and maintain an approved one-inch throw single cylinder deadbolt lock.-Replace the current five eights inch deadbolts with approved one inch deadbolt locks.
- 10. Interior First Floor Bedroom MN State Statute 299F.50 Immediately provide and maintain an approved Carbon Monoxide Alarm in a location within ten (10) feet of each sleeping area. Installation shall be in accordance with manufacturers instructions.
- 11. Interior Kitchen SPLC 34.11, SBC 2902.1, SPLC 34.17, MPC 415.0220 Repair or replace and maintain the plumbing fixture to an operational condition.-Repair the leak in the kitchen drain line.
- 12. Interior Porch MSFC 315.2.5 Fueled equipment, including but not limited to motorcycles, mopeds, lawn-care equipment and portable cooking equipment, shall not be stored, operator or repaired within a building.-Remove the grill and charcoal.
- 13. Interior Second Floor North Bedroom MSFC1026.1 Provide and maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI at (651)- 266-9090. Refer to the Escape Windows for Residential Occupancies handout for more information.-Double hung escape window located on the second level bedroom measured 23 inches wide by 22 inches high. The total net glazed area is 6.3 square feet.

- 14. SPLC 34.11 (6), 34.34 (3) Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.
- 15. SPLC 39.02(c) Complete and sign the smoke detector affidavit and return it to this office.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8688) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: Sebastian.Migdal@ci.stpaul.mn.us or call me at 651-266-8985 between 8:00 a.m. - 9:30 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Sebastian Migdal Fire Inspector

Reference Number 103871