

□ Other

APPLICATION FOR APPEAL

RECEIVED
JUL 2 0 2012
CITY CLERK

Saint Paul City Clerk

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8560

\$25 filing fee payable to the City of Saint Paul (if cash: receipt number) Copy of the City-issued orders or letter which are being appealed Attachments you may wish to include This appeal form completed Walk-In OR	YOUR HEARING Date and Time: Tuesday, (lugust 14 Time
Address Being Appealed:	
Number & Street: 265 Semmit Ave City: 51 Rave State: Mn Zip: 55102	
Appellant/Applicant: Jehn Contiss Email Jeontiss @ the network Phone Numbers: Business 957-476-0566 Residence Cell 612-325-4424	
No. of the contraction of the co	
Name of Owner (if other than Appellant): The Refacet Tohn Confiss President	
Address (if not Appellant's): 1221 Wayzata Blud. E. Wayzata, MN SS391	
Phone Numbers: Business See a love Residence	Cell
What Is Being Appealed and Why? Attachments Are Acceptable	
Vacate Order/Condemnation/ Revocation of Fire C of O Summary/Vehicle Abatement	
Fire C of O Deficiency List □ Fire C of O: Only Egress Windows	
□ Code Enforcement Correction Notice	
□ Vacant Building Registration	

RE: FIRE CERTIFICATE OF OCCUPANCY WITH DEFICIENCIES
265 SUMMIT AVENUE
Ref. #117893

Appeal:

1. Deficiency: 3rd Floor - West Center - MSFC1026.1 - Provide and maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI at (651)- 266-9090. Refer to the Escape Windows for Residential Occupanices handout for more information.-Double Hung, 17h x 41w Location: 3rd floor double hung meets 5 square feet of glazed area minimum. When opened is 18½" high x 29" wide which is 5½" short but 9" wider than required, therefore the overall opening area exceeds the standards.

Appeal: 3rd Floor - West Center - MSFC1026.1- double hung window meets 5 square feet of glazed area minimum. When opened is 17" high x 41" wide which is 7" short but 21" wider than required, therefore the overall opening area exceeds the standards.

2. Deficiency: Exterior - Guardrail - SPLC 34.09 (2) 34.32 (2) - Provide an approved guardrail with intermediate ballustrade or rails 4 inches or less apart. This work may require a permit(s). Call DSI at (651) 266-9090.

a. Front porch: 18h, 55 in drop

b. 1st Floor East: 32hc. 1st Floor West: 28hd. 3rd Floor East: 28he. 3rd Floor West: 31h

Appeal: Given the historical nature of this building and neighborhood we respectfully appeal these deficiency. Adding these guardrails would dramatically alter the historic character of this 130-year old building. It would be both expensive and very difficult to obtain approval by the Summit Hill Historical Society.

3. Exterior - Handrails - SPLC 34.09 (2) 34.32 (2) - Provide an approved handrail. The top of the handrail must be between 34 and 38 inches above the treads and run the entire length of the stair.

a. 1st Floor East: missingb. 1st Floor West: missing

Appeal: Given the historical nature of this building we respectfully appeal this deficiency. Adding these guardrails would dramatically alter the historic character of this 130-year old building. It would be both expensive and very difficult to obtain approval by the Summit Hill Historical Society.

4. Interior - Guardrails - SPLC 34.10 (3) 34.33(2) - Provide an approved guardrail. Intermediate ballustrade must not be more than 4 inches apart. Intermediate rails must be provided if the height of the platform is more than 30 inches:

a. Basement: 26.5h

Corrected: A new handrail to the basement has been installed.

b. 1st to 2nd Floor: needed at lower stairs along with handrail, 30h at landing, 28h at upper stairs.

Appeal: Given the historical nature and beauty of this grand staircase we respectfully appeal the request for any height and length extensions to this handrail.

c. Spiral ballustrades: greater than 8in apart.

Appeal: Given the historical nature and beauty of this 130-year old solid bronze spiral staircase we respectfully appeal the request for any additional ballustrades being welded to this historical work of art.

Corrections to Deficiency List:

1. Basement - SPLC 34.10 (3) 34.33(2) - New guardrail to the basement has been installed.

Additional information:

All fire extinguishers were inspected and marked with date of 7/17/12.

Sincerely,

John Ĥ. Curtiss President The Retreat

1221 Wayzata Blvd. East.

Wayzata, MN 55391

Cell: (612) 325-4424



CITY OF SAINT PAUL

Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Telephone: 651-266-8989 Saint Paul, MN 55101-1806

Fax: 651-266-8951

July 13, 2012

Community Of Recovering People Inc 1221 Wayzata Blvd E Wayzata MN 55391-1942

CORRECTION NOTICE - COMPLAINT INSPECTION

RE:

265 SUMMIT AVE

Ref. # 117893

Dear Property Representative:

An inspection was made of your building on July 13, 2012 in response to a referral. You are hereby notified that the following deficiency list must be corrected immediately. A reinspection will be made on July 19, 2012 at 10:00 am.

Failure to comply may result in a criminal citation or revocation of the Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

DEFICIENCY LIST

- 3rd Floor West Center MSFC1026.1 Provide and maintain an approved escape window from each 1. sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI at (651)- 266-9090. Refer to the Escape Windows for Residential Occupanices handout for more information.-Double Hung, 17h x 41w
- Basement SPLC 34.10 (3) 34.33(2) Provide an approved guardrail. Intermediate ballustrade must not be more than 4 inches apart. Intermediate rails must be provided if the height of the platform is more than 30 inches.-This handrail has been replaced. It is not continuous.
- Exterior Guardrail SPLC 34.09 (2) 34.32 (2) Provide an approved guardrail with intermediate 3. ballustrade or rails 4 inches or less apart. This work may require a permit(s). Call DSI at (651) 266-9090.-Front porch: 18h, 55 in drop

1st Floor East: 32h 1st Floor West: 28h 3rd Floor East: 28h 3rd Floor West: 31h

Exterior - Handrails - SPLC 34.09 (2) 34.32 (2) - Provide an approved handrail. The top of the handrail 4. must be between 34 and 38 inches above the treads and run the entire length of the stair.-1st Floor East: missing 1st Floor West: missing

5. Interior - Guardrails - SPLC 34.10 (3) 34.33(2) - Provide an approved guardrail. Intermediate ballustrade must not be more than 4 inches apart. Intermediate rails must be provided if the height of the platform is more than 30 inches.-Basement: 2July 13, 2012

Community Of Recovering People Inc 1221 Wayzata Blvd E Wayzata MN 55391-1942

CORRECTION NOTICE - COMPLAINT INSPECTION

RE: 265 SUMMIT AVE

Ref. # 117893

Dear Property Representative:

An inspection was made of your building on July 13, 2012 in response to a referral. You are hereby notified that the following deficiency list must be corrected immediately. A reinspection will be made on July 19, 2012 at 10:00 am.

Failure to comply may result in a criminal citation or revocation of the Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

DEFICIENCY LIST

- 1. 3rd Floor West Center MSFC1026.1 Provide and maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI at (651)- 266-9090. Refer to the Escape Windows for Residential Occupanices handout for more information.-Double Hung, 17h x 41w
- 2. Basement SPLC 34.10 (3) 34.33(2) Provide an approved guardrail. Intermediate ballustrade must not be more than 4 inches apart. Intermediate rails must be provided if the height of the platform is more than 30 inches.-This handrail has been replaced. It is not continuous.
- 3. Exterior Guardrail SPLC 34.09 (2) 34.32 (2) Provide an approved guardrail with intermediate ballustrade or rails 4 inches or less apart. This work may require a permit(s). Call DSI at (651) 266-9090.

Front porch: 18h, 55 in drop

1st Floor East: 32h 1st Floor West: 28h 3rd Floor East: 28h 3rd Floor West: 31h

- 4. Exterior Handrails SPLC 34.09 (2) 34.32 (2) Provide an approved handrail. The top of the handrail must be between 34 and 38 inches above the treads and run the entire length of the stair.-1st Floor East: missing 1st Floor West: missing
- 5. Interior Guardrails SPLC 34.10 (3) 34.33(2) Provide an approved guardrail. Intermediate ballustrade must not be more than 4 inches apart. Intermediate rails must be provided if the height of the platform is more than 30 inches.-Basement: 26.5h

1st to 2nd Floor: needed at lower stairs along with handrail, 30h at landing, 28h at upper stairs Spiral ballustrades: greater than 8in apart

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8688) and must be filed within 10 days of the date of the original orders.

If you have any questions, email me at: leanna.shaff@ci.stpaul.mn.us or call me at 651-266-8980 between 7:30 a.m. - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Leanna Shaff Fire Inspector

Ref. # 117893