

OtherOther

APPLICATION FOR APPEAL

RECEIVED

JUL 1 1 2012

CITY CLERK

Saint Paul City Clerk

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8560

\$25 filing fee payable to the City of State (if cash: receipt number 180) Copy of the City-issued orders or let are being appealed Attachments you may wish to include the City of State (if cash: receipt number 180) This appeal form completed	Saint Paul ter which	YOUR HEARING Date and Time: Tuesday, July 17, 200 Time 1:30 0 Location of Hearing: Room 330 City Hall/Courthouse
Address Being Appeal	ed:	
Number & Street: 869 BRG	ch Gl. City: S	Haul State: MN Zip: 55106
Phone Numbers: Business	25/2/3, WOO Residence	nail BinHhuyle@ amail.com Petbury, MN 55125 Cell 612-242-0073 Date: 7-10-2012
Name of Owner (if other than Appellant):		
Address (if not Appellant's):		
Phone Numbers: Business	Residence	Cell
What Is Being appeale Vacate Order/Condemnation/ Revocation of Fire C of O	ed and why?	Attachments Are Acceptable
□ Summary/Vehicle Abatement		1909
✗ Fire C of O Deficiency List	House was build in 1909, bedroom in upper-floor and	
Fire C of O: Only Egress Windows	basement are non comforming. Those are the only two yes vount in the house; measure height are go incl	
□ Code Enforcement Correction Notice	and 79.73 inches	respectively require height is 84!
□ Vacant Building Registration	Also, the window	was build at the same time who
□ Other	the horse was a	enstructed. Up ask salibly for



CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806

 Telephone:
 651-266-8989

 Facsimile:
 651-266-8951

 Web:
 www.stpaul.gov/dsi

June 18, 2012

BINH LE CHRISTINA LE PO BOX 251213 WOODBURY MN 55125

FIRE INSPECTION CORRECTION NOTICE

RE:

869 BEECH ST

Ref. #114868

Residential Class: C

Dear Property Representative:

Your building was inspected on June 14, 2012 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date.

A re-inspection will be made on July 27, 2012 at 1:30pm.

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

DEFICIENCY LIST

- 1. Basement Bathroom MSFC 605.1 Repair or replace damaged electrical fixtures. This work may require a permit(s). Call DSI at (651) 266-9090.-Contact a licensed electrical contractor to repair/replace the inoperable GFCI outlet.
- 2. Basement Bedroom MN Stat. 299F.362 Immediately provide and maintain a smoke detector located outside each sleeping area.

- 3. Basement Bedroom MN State Statute 299F.50 Immediately provide and maintain an approved Carbon Monoxide Alarm in a location within ten (10) feet of each sleeping area. Installation shall be in accordance with manufacturers instructions.
- 4. Basement Dryer Vent UMC 504.6 Provide, repair or replace the dryer exhaust duct. Exhaust ducts for domestic clothes dryers shall be constructed of metal and shall have a smooth interior finish. The exhaust duct shall be a minimum nominal size of four inches (102 mm) in diameter. This work requires a permit(s). Call DSI at (651) 266-8989.- Remove the unapproved flexible plastic dryer exhaust duct and install a code compliant dryer exhaust duct. This work must be done by licensed contractor under permit.
- 5. Basement Laundry Room SPLC 34.12 (2), 34.35 (1) Repair and maintain all required and supplied equipment in an operative and safe condition.-Replace the missing guards on the furnace.
- 6. Basement Stairway SPLC 34.10 (3) 34.33(2) Provide an approved guardrail. Intermediate balustrades must not be more than 4 inches apart. Intermediate rails must be provided if the height of the platform is more than 30 inches.-Provide the required guardrail on the basement stairway.
- 7. Basement and Upper Floor Bedrooms SPLC 34.13 (1) Provide and maintain all habitable areas with a ceiling height of 7 feet over 1/2 the floor area.

Upper Floor

West Bedroom

Ceiling height = 80 inches Total Area: $14 \times 12 = 178$ sf

Area above 5 feet: $11 \times 12 = 132 \text{ sf}$

Area of ceiling height at 80 inches = $12 \times 9 = 108 \text{ sf}$

Basement

Bedroom

Ceiling height = 79 inches and 73 inches

Total Area: $13 \times 9 + 7 \times 7 = 166 \text{ sf}$

Area of ceiling height at 79 inches = $13 \times 9 = 117 \text{ sf}$

Area of ceiling height at 73 inches = $7 \times 7=49 \text{ sf}$

8. Basement and Upper Floor - Stairway - SPLC 34.10 (3), 34.33(2) - Provide an approved handrail. The top of the handrail must be between 34 and 38 inches above the treads and run the entire length of the stair.-Provide the required handrail on the stairways.

- 9. Exterior Driveway SPLC 34.08 (7) All parking spaces shall be paved with asphalt, concrete, or durable dustless surfacing. Before any existing spaces may be paved, site plan approval must be obtained as specified in the St. Paul Zoning Code. Contact DSI Zoning at 651-266-9090.-The driveway consists of class 5. Class 5 is not an approved surface for driveway/parking surface. Provide an approved surface for the driveway/parking surface.
- 10. Exterior East Entrance SPLC 34.14 (2) f Provide and maintain an minimum of 1 foot candle at the grade level of exterior exits and entryways for security. This work may require a permit(s). Call DSI at (651) 266-9090.-Provide the required illumination at the east entrance.
- 11. Garage Address SPLC 71.01 Provide address numbers on building per HN-1 handout.-Provide address numbers on the alley side of the garage. Garage numbers must be at least 3 inches in height, contrast with the background, and be reflective or illuminated at night.
- 12. Garage Exterior Surfaces SPLC 34.08 (5), 34.31 (3) Repair, replace and maintain all exterior surfaces on fences, sheds, garages and other accessory structures free from holes and deterioration. Provide and maintain exterior unprotected surfaces painted or protected from the elements.-Scrape all flaking/chipped paint. Maintain all exterior surfaces in a good state of repairs and protected against elements of the weather.
- 13. Main Floor Bathroom SPLC 34.09 (3), 34.32 (3) Repair and maintain the door in good condition.-Repair/replace the door that is not closing/latching.
- 14. Main Floor Bathroom SPLC 34.09 (3), 34.32 (3) Provide or repair and maintain the window screen.
- 15. Main Floor Bathroom SPLC 34.11, SBC 2902.1, SPLC 34.17, MPC 415.0220 Repair or replace and maintain the plumbing fixture to an operational condition.-Repair/replace the inoperable sink stopper.
- 16. Main Floor Kitchen SPLC 34.12 (2), 34.35 (1) Repair and maintain all required and supplied equipment in an operative and safe condition.-Repair/replace the burners that are not igniting on the gas range.
- 17. Upper Floor Bathroom SPLC 34.10 (7), 34.33 (6) Repair and maintain the cabinets in an approved manner.-Repair/replace the damaged base cabinet under the sink.
- 18. Upper Floor Bathroom SPLC 34.11, SBC 2902.1, SPLC 34.17, MPC 415.0220 Repair or replace and maintain the plumbing fixture to an operational condition.-Secure the loose toilet.

19. Upper Floor - Southeast Bedroom - SPLC 34.13 (3) - Every room occupied for sleeping purposes by one (1) occupant shall have a minimum gross floor area of at least seventy (70) square feet and every room occupied for sleeping purposes by two (2) or more occupants shall have a minimum gross floor area of fifty (50) square feet per occupant thereof.

Room Dimension:

Ceiling height: 81 inches.

Total area: 12 feet x 9 feet = 108 square feet. Area above 5 feet: 6 feet x 9 feet = 54 square feet.

Ceiling area at 81 inches: 3 feet x 9 feet = 27 square feet.

The occupiable area for this room is 54 square feet which is not large enough to be used as a sleeping area. Immediately remove the bed and discontinue using this room as a sleeping room.

- 20. Upper Floor Southeast and West Bedroom SPLC 34.09 (3), 34.32 (3) Repair and maintain the window in good condition.-Repair/replace the windows that are not staying in the open position in the upper floor southeast and west bedroom. Replace the broken glass in the west bedroom.
- 21. Upper Floor West Bedroom MSFC 1003.3.1.8 Remove unapproved locks from the unit doors. The door must be openable from the inside without the use of keys or special knowledge or effort.-Remove the unapproved slide bolt lock.
- 22. SPLC 34.11 (6), 34.34 (3) Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.
- 23. SPLC 39.02(c) Complete and sign the smoke detector affidavit and return it to this office.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo.

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8688) and must be filed within 10 days of the date of this order.


If you have any questions, email me at: wayne.spiering@ci.stpaul.mn.us or call me at 651-266-8993 between 7:30 a.m. - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,


Wayne Spiering Fire Inspector

Reference Number 114868











810-1 1500

