



CITY OF SAINT PAUL
Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220
Saint Paul, Minnesota 55101-1806

Telephone: 651-266-8989
Facsimile: 651-266-8951
Web: www.stpaul.gov/dsi

May 15, 2013

GERENZA PROPERTIES
1437 MARSHALL AVE
ST PAUL MN 55104

FIRE INSPECTION CORRECTION NOTICE

RE: 715 LAFOND AVE

Dear Property Representative:

Your building was inspected on January 22, 2013 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date.

A re-inspection will be made on June 10, 2013 at 9 am.

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional re-inspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

DEFICIENCY LIST

1. Exterior - Garage - SPLC 71.01 - The address posted is not visible from street/alley.- Provide reflective numbers or background or illuminate at night.
2. Exterior - House and Garage - SPLC 34.09 (1) b,c, 34.32 (1) b,c - Provide and maintain all exterior walls free from holes and deterioration. All wood exterior unprotected surfaces must be painted or protected from the elements and maintained in a professional manner free from chipped or peeling paint.
3. Exterior - House and Garage - SPLC 34.09 (1) e, 34.32 (1) d - Provide and maintained the roof weather tight and free from defects.

4. Exterior - Screens - SPLC 34.09 (3), 34.32 (3) - Provide or repair and maintain the window screens.
5. Exterior - Storm Doors - SPLC 34.09 (3), 34.32 (3) - Repair and maintain the door in good condition.-Repair the storm doors to close.
6. Exterior - SPLC 34.14 (2), 34.34 (5) - Provide an approved electrical service adequate to meet the buildings needs. This work requires a permit(s), call DSI at (651) 266-9090.- Hire a licensed electrician to repair the electrical in the garage to meet code and to provide an outlet for the freezer located in the kitchen.
7. Interior - Basement - MN Stat. 299F.362 - Immediately provide and maintain a smoke detector located outside each sleeping area.
8. Interior - Main Floor - MN State Statute 299F.50 Immediately provide and maintain an approved Carbon Monoxide Alarm in a location within ten (10) feet of each sleeping area. Installation shall be in accordance with manufacturers instructions.
9. Interior - UMC 504.6 - Provide, repair or replace the dryer exhaust duct. Exhaust ducts for domestic clothes dryers shall be constructed of metal and shall have a smooth interior finish. The exhaust duct shall be a minimum nominal size of four inches (102 mm) in diameter. This work requires a permit(s). Call DSI at (651) 266-8989.
10. Interior - SPLC 34.11, SBC 2902.1, SPLC 34.17, MPC 4715.0200.C - Provide an approved number and type of plumbing fixtures.-Replace the broken kitchen faucet, and repair the low water pressure to the bathroom sink on the second floor.
11. Interior - SPLC 34.10 (3), 34.33(2) - Repair or replace the damaged handrail in an approved manner.
12. Interior - MSFC 605.1 - Repair or replace damaged electrical fixtures. This work may require a permit(s). Call DSI at (651) 266-9090.-Repair or replace the hanging light fixture in the bedroom on the second floor.
13. Interior - MSFC 605.6 - Provide electrical cover plates to all outlets, switches and junction boxes where missing.-Repair or replace the damaged and missing outlet and cover at the top of the stairs.
14. Interior - MSFC 1011.2 - Remove the materials that cause an exit obstruction. Maintain a clear and unobstructed exitway.-Move all items blocking the bedroom escape windows.
15. Interior - SPLC 34.11, SBC 2902.1, SPLC 34.17, MPC 415.0220 - Repair or replace and maintain the plumbing fixture to an operational condition.-The bathroom sink is clogged. Repair.
16. Interior - MSFC 605.1- All light fixtures shall be maintained with protective globes if originally equipped.

17. Interior - MSFC 605.4 - Discontinue use of all multi-plug adapters.-You must plug the freezer direct into an outlet.
18. Interior - SPLC 34.11(5), 34.34(2), SPC 4715.0200Q - Provide adequate hot water between 120 degrees F and 130 degrees F.-Turn the water heater down so the tenants will not get burned.
19. SPLC 34.11 (6), 34.34 (3) - Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.
20. SPLC 39.02(c) - Complete and sign the smoke detector affidavit and return it to this office.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: <http://www.stpaul.gov/cofo>

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8585) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: lisa.martin@ci.stpaul.mn.us or call me at 651-266-8988 between 6:30 a.m. - 8:30 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Lisa Martin
Fire Inspector