

CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806 

 Telephone:
 651-266-8989

 Facsimile:
 651-266-9124

 Web:
 www.stpaul.gov/dsi

# **Code Compliance Report**

November 19, 2013

Ted Ries 8124 Clifford Cir Inver Grove Heights MN 55076-4571 \* \* This Report must be Posted on the Job Site \* \*

Re: 673 Jessamine Ave E File#: 11 261407 VB2

Dear Property Owner:

The following is the Code Compliance report you requested on October 03, 2013.

Please be advised that this report is accurate and correct as of the date November 19, 2013. All deficiencies identified by the City after this date must also be corrected and all codes and ordinances must be complied with. This report is valid for 365 days from November 19, 2013. This report may be used in lieu of a Truth in Housing Report required in St Paul Legislative Code 189. This building must be properly secured and the property maintained at all times.

In order to sell or reoccupy this property the following deficiencies must be corrected:

### **ZONING**

- 1. This property is in a(n) RT1 zoning district.
- 2. This property was inspected as a Single Family Dwelling.

#### BUILDING Inspector: Jim Seeger Phone: 651-266-9046

- Insure basement cellar floor is even, is cleanable, and all holes are filled.
- Install plinth blocks as needed under posts in basement & ensure adequate footing for load imposed.
- Dry out basement and eliminate source of moisture.
- Permanently secure top and bottom of support posts in an approved manner.
- Install handrails (34 inches 38 inches above each nosing) and guardrails (36 inch minimum) at all stairways, and return hand rail ends into a newel post or wall per attachment.
- Repair or Replace any deteriorated window sash, broken glass, sash holders, re-putty, etc as necessary.

Re: 673 Jessamine Ave E

November 19, 2013

Page 2

## **BUILDING Inspector: Jim Seeger Phone: 651-266-9046**

- Provide complete storms and screens, in good repair for all door and window openings.
- Provide functional hardware at all doors and windows
- Repair or replace damaged doors and frames as necessary, including storm doors.
- Weather seal exterior doors, threshold and weather-stripping.
- Repair walls, ceiling and floors throughout, as necessary.
- Prepare and paint interior and exterior as necessary. Observe necessary abatement procedures (EPA, MPCA and St. Paul Legislative Code, Chapter 34 for additional information) if lead base paint is present.
- Any framing members that required repair or do not meet code (where wall and ceiling covering is removed, members that are over-spanned, over-spaced, not being carried properly, door and window openings that are not adequately supported, etc.) are to be reconstructed in an approved manner.
- Air-seal and insulate attic/access door.
- Install Smoke Detectors/Carbon Monoxide Detectors per MN Conservation Code and the MN Dept. of Labor and Industry: Install per code where feasible.
- Provide major clean-up of premises.
- Repair siding, soffit, fascia, trim, etc. as necessary.
- Provide proper drainage around house to direct water away from foundation of house.
- Provide proper drainage around house to direct water away from foundation of garage.
- Install flashing in an approved manner at the intersection of the roof with walls, chimneys, and other conjoined surfaces.
- Repair chimney in an approved manner.
- Provide general rehabilitation of garage.
- Install address numbers visible from street and on the alley side of garage.
- Remove trees which are against foundation of home and garage.
- Grade must drain away from foundation of dwelling. Maintain 6 inch clearance between wood and soil.
- Repair chimney brick.
- Replace front steps.
- Repair or replace gate and fence.
- Hire asbestos abating company to clean up asbestos and surrly paper work from company. (someone removed old forced air heating system) Asbestos parts all over the floor.
- Install vapor barrier in crawl space.
- Replace kitchen counter top at sink.
- Install safety glass in window over 1st floor bath tub and in window on stairs to attic.
- New front steps poured without permits or inspections. Double fee and inspections required.
- New roof covering on house and garage all work done without permits or inspections, both roofs not installed per manufacture's recommendations. Double fee applies and roof covering needs to be properly installed.
- A building permit is required to correct the above deficiencies.

Re: 673 Jessamine Ave E

November 19, 2013

Page 3

#### **ELECTRICAL** Inspector: Randy Klossner Phone: 651-266-9032

- Provide a complete circuit directory at service panel indicating location and use of all circuits
- Close openings in service panel/junction boxes with knockout seals, breaker blanks, and/or junction box covers
- Properly strap cables and conduits in basement/ service conduit on the exterior of the house.
- Repair or Replace all broken, missing or loose light fixtures, switches and outlets, covers and plates
- Check all outlets for proper polarity and verify ground on 3-prong outlets
- Install hard-wired, battery backup smoke detector and other smoke detectors as required by the IRC. Also, Install carbon monoxide detector(s) within 10 feet of all bedrooms
- Remove and or/ re-wire all illegal, improper or hazardous wiring in basement/garage/attic
- Replace all painted-over receptacles.
- Replace electrical service due to corrosion and wire to current NEC.
- Based on repair list purchase permit for a service and 6 circuits.
- All added receptacles must be grounded, tamper-resistant and be on an Arc-Fault Circuit Interrupter-protected circuit.
- Any open walls or walls that are opened as part of this project must be wired to the standards of the current NEC.
- All electrical work must be done by a Minnesota-licensed electrical contractor under an electrical permit.

#### PLUMBING Inspector: Steve Fernlund Phone: 651-266-9052

- Basement Water Heater T and P relief discharge piping incorrect (MPC 2210 Subp. 4)
- Basement Water Heater Vent must be in chimney liner (MFGC 501.12)
- Basement Water Heater Water piping incorrect (MPC 1730 Subp. 1)
- Basement Water Heater gas venting incorrect (MFGC 503)
- Basement Water Heater not fired or in service (MPC 2180)
- Basement Water Meter meter is removed or not in service (MPC 4715.1700)
- Basement Water Meter support meter properly (MPC 2280)
- Basement Water Piping boiler fill water line requires backflow assembly or device (MPC 2100)
- Basement Water Piping repair or replace all corroded, broken or leaking piping (MPC 4715.1720)
- Basement Water Piping run 1 inch water line from meter to first major take off (SPRWS Water Code)
- Basement Gas Piping dryer gas shutoff; connector or piping incorrect (MFGC 411)
- Basement Gas Piping run dryer vent to code (MFGC 614.1 614.7)
- Basement Soil and Waste Piping improper connections, transitions, fittings or pipe usage (MPC 2420)
- Basement Soil and Waste Piping no front sewer clean out (MPC 1000)
- Basement Soil and Waste Piping no soil stack base clean out

Re: 673 Jessamine Ave E November 19, 2013 Page 4

### PLUMBING Inspector: Steve Fernlund Phone: 651-266-9052

- Basement Soil and Waste Piping replace the floor drain cover or clean out plug (MPC 1300)
- Basement Laundry Tub incorrectly vented (MPC 2500)
- Basement Laundry Tub provide a vacuum breaker for the spout (MPC 2000 B) raise faucet above spill line.
- Basement Laundry Tub waste incorrect (MPC 2300)
- First Floor Gas Piping range gas shut off; connector or piping incorrect (MFGC 411)
- First Floor Lavatory waste incorrect (MPC 2300)
- First Floor Lavatory water piping incorrect (MPC 0200 P.)
- First Floor Toilet Facilities incorrectly vented (MPC 2500)
- First Floor Toilet Facilities reset the toilet on a firm base (MPC 0870)
- First Floor Tub and Shower incorrectly vented (MPC 2500)
- First Floor Tub and Shower provide anti-scald valve (MPC 1380. Subp. 5)
- All the above corrections to waste, vent, water, and gas piping shall be per the Minnesota Plumbing Code Chapter 4715 & Chapter 326, the Minnesota Mechanical Code, the Minnesota Fuel Gas Code, and the Saint Paul Regional Water Code. All plumbing must be done by a plumbing contractor licensed in the State of Minnesota and the City of St. Paul under an approved permit.

#### **HEATING** Inspector: Maureen Hanson Phone: 651-266-9043

- Provide support for gas lines to code
- Plug, cap and/or remove all disconnected gas lines
- Provide a window in the bathrooms with an aggregate glazing area of not less than 3 square feet, one-half of which must be openable or provide exhaust system vented to outside. A mechanical ventilation permit is required if an exhaust system is installed.
- Install a heating system to code under appropriate permits.

#### **Notes:**

- See attachment for permit requirements and appeals procedure.
- Interior of garage not available for inspection. Repair per applicable codes.

This is a registered vacant building. In order to sell or reoccupy this building, all deficiencies listed on this code compliance report must be corrected in accordance with the Minimum Housing Standards of the St. Paul Legislative Code (Chapter 34) and all required permits must receive final approval within six (6) months of the date of this report. One (1) six-month time extension may be requested by the owner and will be considered if it can be shown that the code compliance work is proceeding and is more than fifty (50) percent complete in accordance with Legislative Code Section 33.03(f).

Re: 673 Jessamine Ave E November 19, 2013

Page 5

You may file an appeal to this notice by contacting the City Clerk's Office at 651-266-8688. Any appeal must be made in writing within 10 days of this notice. (You must submit a copy of this notice when you appeal, and pay a filing fee.)

If you have any questions regarding this inspection report, please contact Jim Seeger between 7:30 - 9:00 AM at 651-266-9046 or leave a voice mail message.

Sincerely,

James L. Seeger Code Compliance Officer Department of Safety and Inspections City of Saint Paul 375 Jackson Street, Suite 220 Saint Paul MN 55101

Phone: 651-266-9046

Email: jim.seeger@ci.stpaul.mn.us

JLS:ml Attachments