

We need the following to process your appeal:

# **APPLICATION FOR APPEAL**

# Saint Paul City Council - Legislative Hearings

RECEIVED DEC 16 2013

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8585

Revised 5/31/2013

CITY CLERK

\$25 filing fee payable to the City of (if cash: receipt number	r being appealed de	HEARING DATE & TIME (provided by Legislative Hearing Office) Tuesday, Jan. 2, 2014  Time 9:00 a.m. Location of Hearing: Room 330 City Hall/Courthouse
Address Being Appealed:		
Number & Street: 750 BUSDAUE City: St PAUL State: MP Zip: 55106		
Appellant/Applicant: SRINIVAS PUTARI Email SRINIPUTE GNAIL CON		
Phone Numbers: Business (952) 200 6741 Residence Cell (952) 200 0 741		
Signature: Know w		Date:
Name of Owner (if other than Appellant):		
Mailing Address if Not Appellant's: 15582 LILAC DR, EDEN PLAIRIE, MN 55347		
Phone Numbers: Business Residence Cell		
What Is Being Appealed and Why? Attachments Are Acceptable  Vacate Order/Condemnation/		
Revocation of Fire C of O		
□ Summary/Vehicle Abatement		
□ Fire C of O Deficiency List		
□ Code Enforcement Correction Notice		
<b>Vacant Building Registration</b>	ADDRESSED ALL THE	REPORTE D ISSUES, AND DEDERED
Cother	A GORE COMPLIANC	E INSPECTION. It'S aTIMING THING
		GET CLOSED SODINER Revised 5/31/2013



CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806

Telephone: 651-266-8989 Facsimile: 651-266-9124

Web: www.stpaul.gov/dsi

#### Code Compliance Report

December 09, 2013

SRINIVAS PUJARI 15582 LILAC DRIVE EDEN PRAIRIE MN 55347 \* \* This Report must be Posted on the Job Site \* \*

Re: 750 Bush Ave File#: 13 235396 VB2

Dear Property Owner:

The following is the Code Compliance report you requested on November 12, 2013.

Please be advised that this report is accurate and correct as of the date December 09, 2013. All deficiencies identified by the City after this date must also be corrected and all codes and ordinances must be complied with. This report is valid for 365 days from December 09, 2013. This report may be used in lieu of a Truth in Housing Report required in St Paul Legislative Code 189. This building must be properly secured and the property maintained at all times.

In order to sell or reoccupy this property the following deficiencies must be corrected:

#### **ZONING**

- 1. This property is in a(n) I1 zoning district.
- 2. This property was inspected as a Single Family Dwelling.

#### **BUILDING** Inspector: Jim Seeger Phone: 651-266-9046

- Remove mold, mildew and moldy or water damaged materials.
- Install handrails (34 inches 38 inches above each nosing) and guardrails (36 inch minimum) at all stairways, and return hand rail ends into a newel post or wall per attachment.
- Repair or Replace any deteriorated window sash, broken glass, sash holders, re-putty, etc as necessary.
- Prepare and paint interior and exterior as necessary. Observe necessary abatement procedures (EPA, MPCA and St. Paul Legislative Code, Chapter 34 for additional information) if lead base paint is present.
- Provide major clean-up of premises.
- Repair siding, soffit, fascia, trim, etc. as necessary.

Re: 750 Bush Ave December 9, 2013 Page 2

#### BUILDING Inspector: Jim Seeger Phone: 651-266-9046

- Any framing members that required repair or do not meet code (where wall and ceiling covering
  is removed, members that are over-spanned, over-spaced, not being carried properly, door and
  window openings that are not adequately supported, etc.) are to be reconstructed in an approved
  manner.
- Charred building components shall be scraped or sandblasted completely clean and water-damaged components replaced. A determination of necessary fire damage corrective measures shall be made by this department or by a registered structural engineer as to replacement, repairs, etc. All smoke damaged and charred members shall be cleaned, sealed and deodorized.
- Install Smoke Detectors/Carbon Monoxide Detectors per MN Conservation Code and the MN Dept. of Labor and Industry: Install per code where feasible.
- Provide proper drainage around house to direct water away from foundation of house.
- Provide proper drainage around house to direct water away from foundation of garage.
- Install rain leaders to direct drainage away from foundation.
- Provide general rehabilitation of garage.
- Install address numbers visible from street and on the alley side of garage.
- Grade must drain away from foundation of dwelling. Maintain 6 inch clearance between wood and soil.
- Replace rear retaining wall. (requires engineering plans)
- Replace garage roof covering and remove tree.
- Replace garage service door and moldy drywall on lower ceiling.
- Install safety glass in window over 2nd floor bathtub.
- Repair fascia and soffits.
- Install counter flashing on chimney.
- Install gutters and downspouts on east side of garage and house.
- Still need to address corrections for past open permits.
- A building permit is required to correct the above deficiencies.

## ELECTRICAL Inspector: Randy Klossner Phone: 651-266-9032

- Bond around water meter with a copper wire sized for the electrical service per Article 250 of the NEC
- Provide a complete circuit directory at service panel indicating location and use of all circuits
- Close openings in junction boxes with knockout seals, breaker blanks, and/or junction box covers.
- Properly strap cables and conduits in basement all conduit on the exterior of the house.
- Ground bathroom lights and kitchen sink light and disconnect receptacle on fixture.
- Repair or Replace all broken, missing or loose light fixtures, switches and outlets, covers and plates
- Check all outlets for proper polarity and verify ground on 3-prong outlets
- Install hard-wired, battery backup smoke detector and other smoke detectors as required by the IRC. Also, Install carbon monoxide detector(s) within 10 feet of all bedrooms
- Properly wire exterior lights.
- Remove and or/ re-wire all illegal, improper or hazardous wiring in basement/garage.

Re: 750 Bush Ave December 9, 2013 Page 3

#### ELECTRICAL Inspector: Randy Klossner Phone: 651-266-9032

- Replace all painted-over receptacles.
- Repair S3 switching in stairway to second floor.
- Protect or rewire NM cable in basement to NEC.
- Protect NM cable below Electrical panel to NEC.
- Based on repair list purchase permit for 6 circuits.
- All added receptacles must be grounded, tamper-resistant and be on an Arc-Fault Circuit Interrupter-protected circuit.
- Any open walls or walls that are opened as part of this project must be wired to the standards of the current NEC.
- All electrical work must be done by a Minnesota-licensed electrical contractor under an electrical permit.

#### PLUMBING Inspector: Steve Fernlund Phone: 651-266-9052

- Basement Water Heater Water piping incorrect (MPC 1730 Subp. 1)
- Basement Water Heater not fired or in service (MPC 2180)
- Basement Remove saddle fitting at four inch main stack in basement.
- Basement Gas Piping run dryer vent to code (MFGC 614.1 614.7)
- Basement Soil and Waste Piping no front sewer clean out (MPC 1000)
- Basement Soil and Waste Piping no soil stack base clean out
- Basement Laundry Tub provide a vacuum breaker for the spout (MPC 2000 B)
- Basement Laundry Tub unvented (MPC 0200 E)
- Basement Laundry Tub waste incorrect (MPC 2300)
- First Floor Toilet Facilities fixture is broken or parts missing (MPC 0200 0.)
- Second Floor Lavatory faucet is missing, broken, or parts missing (MPC 0200.P.)
- Second Floor Lavatory waste incorrect (MPC 2300)
- Second Floor Tub and Shower incorrectly vented (MPC 2500)
- Second Floor Tub and Shower provide anti-scald valve (MPC 1380, Subp. 5)
- Second Floor Tub and Shower waste incorrect (MPC 2300)
- All the above corrections to waste, vent, water, and gas piping shall be per the Minnesota Plumbing Code Chapter 4715 & Chapter 326, the Minnesota Mechanical Code, the Minnesota Fuel Gas Code, and the Saint Paul Regional Water Code. All plumbing must be done by a plumbing contractor licensed in the State of Minnesota and the City of St. Paul under an approved permit.

## HEATING Inspector: Maureen Hanson Phone: 651-266-9043

- Clean and Orsat test furnac burner. Check all controls for proper operation. Check furnace heat exchanger for leaks; provide documentation from a licensed contractor that the heating unit is safe
- Install approved metal chimney liner
- Replace furnace flue venting to code.
- Connect furnace and water heater venting into chimney liner
- Vent clothes dryer to code

Re: 750 Bush Ave December 9, 2013 Page 4

### HEATING Inspector: Maureen Hanson Phone: 651-266-9043

- Provide adequate combustion air and support duct to code
- Provide support for gas lines to code
- Plug, cap and/or remove all disconnected gas lines
- Provide a window in the bathrooms with an aggregate glazing area of not less than 3 square feet, one-half of which must be openable or provide exhaust system vented to outside. A mechanical ventilation permit is required if an exhaust system is installed.
- All supply and return ducts for warm air heating system must be clean before final approval for occupancy. Provide documentation from a licensed duct-cleaning contractor that the duct system has been cleaned.
- Repair and/or replace heating registers as necessary
- Provide heat in every habitable room and bathrooms
- Provide a means of returning air from every habitable room to the furnace. Return air can not be taken from closets, bathrooms, toilet rooms, kitchen or mechanical rooms.
- Mechanical gas permit is required for the above work.

#### Notes:

- See attachment for permit requirements and appeals procedure.
- Most of the roof covering could not be inspected from grade. Recommend this be done before rehabilitation is attempted.

This is a registered vacant building. In order to sell or reoccupy this building, all deficiencies listed on this code compliance report must be corrected in accordance with the Minimum Housing Standards of the St. Paul Legislative Code (Chapter 34) and all required permits must receive final approval within six (6) months of the date of this report. One (1) six-month time extension may be requested by the owner and will be considered if it can be shown that the code compliance work is proceeding and is more than fifty (50) percent complete in accordance with Legislative Code Section 33.03(f).

You may file an appeal to this notice by contacting the City Clerk's Office at 651-266-8688. Any appeal must be made in writing within 10 days of this notice. (You must submit a copy of this notice when you appeal, and pay a filing fee.)

If you have any questions regarding this inspection report, please contact Jim Seeger between 7:30 - 9:00 AM at 651-266-9046 or leave a voice mail message.

Sincerely,

James L. Seeger, Code Compliance Officer

Phone: 651-266-9046 Email: jim.seeger@ci.stpaul.mn.us

JLS:ml Attachments