

## APPLICATION FOR APPEAL

## Saint Paul City Council – Legislative Hearings

RECEIVED APR 17 2015

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8585

\$25 filing fee (non-refundable) (payable to the City of Saint Paul (if cash: receipt number)  Copy of the City-issued orders/letter being appealed  Attachments you may wish to include  This appeal form completed  Walk-In OR   Mail-In	1) HEARING DATE & TIME (provided by Legislative Hearing Office) Tuesday, 4-17-15  Time 1:30 Location of Hearing: Room 330 City Hall/Courthouse
Address Being Appealed:	1 n. 1 c. mr 55705
Number & Street: 1263-7 Grand Are City: S  Appellant/Applicant: //cford norale/Same En	mail Victoria faded 760g ma
Signature:	Cell 6/2-6/6-3480
Name of Owner (if other than Appellant): <b>Eyecht</b> Mailing Address if Not Appellant's:	· Sterman
Phone Numbers: Business Residence	
What Is Being Appealed and Why?  Nacate Order/Condemnation/ Revocation of Fire C of O  Me Much	More fem / children
☐ Summary/Vehicle Abatement ☐ Fire C of O Deficiency List/Correction ☐ Observed	day and disabled
Code Enforcement Correction Notice	al had time.
Vacant Building Registration	
Other (Fence Variance, Code Compliance, etc.)	Revised 8/11/2014



CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806 Telephone: 651-266-8989 Facsimile: 651-266-8951 Web: www.stpaul.gov/dsi

April 16, 2015

Grand Heritage Properties Llc Po Box 16548 Saint Paul MN 55116-0548

## NOTICE OF CONDEMNATION UNFIT FOR HUMAN HABITATION ORDER TO VACATE RESIDENTIAL UNITS

RE:

1659 GRAND AVE

Ref. # 13194

Dear Property Representative:

Your building was inspected on April 16, 2015, in response to a complaint.

The building was found to be unsafe, unfit for human habitation, a public nuisance, a hazard to the public welfare or otherwise dangerous to human life. A Condemnation Placard has been posted on the building.

The following deficiency list must be completed or the building vacated by the re-inspection date.

A reinspection will be made on April 17, 2015 at 12:00pm.

CONDEMNATION OF THE BUILDING REVOKES THE CERTIFICATE OF OCCUPANCY.

Failure to complete the corrections may result in a criminal citation. The Saint Paul Legislative Code requires that no building be occupied without a Fire Certificate of Occupancy.

## **DEFICIENCY LIST**

- 1. INTERIOR RESIDENTIAL UNITS SPLC 34.23, MSFC 110.1 This occupancy is condemned as unsafe or dangerous. This occupancy must not be used until re-inspected and approved by this office. -Residential units are condemned due to multiple code violations including but not limited to; lack of basic facilities, unsanitary conditions, lack of smoke detectors, lack of fire separation, fire damage, overcrowding, and lack of egress.
- 2. EXTERIOR Ext. Door SPLC 34.09 (3), 34.33 (3) Repair and maintain the door in good condition. -Door leading to residential units was jammed.
- 3. EXTERIOR SPLC 34.08 (1), 34.31 (1) All exterior property areas shall be maintained free from any accumulation of refuse, garbage or feces.
- 4. EXTERIOR SPLC 34.09 (3), 34.32 (3) Repair and maintain the window in good condition. -Replace all broken windows
- 5. EXTERIOR SPLC 34.09 (3), 34.33 (3) -Provide or repair and maintain the window screens, where broken or missing.
- 6. INTERIOR RESIDENTIAL UNITS SPLC 34.10 (4), 34.33 (3) Provide a bathroom floor impervious to water.
- 7. INTERIOR RESIDENTIAL UNITS MN Stat 299F.18 Immediately remove and discontinue excessive accumulation of combustible materials.
- 8. INTERIOR RESIDENTIAL UNITS SPLC 34.10 (5), 34.33 (4), 34.16 Provide and maintain interior in a clean and sanitary condition. -Interior units are unsanitary. There is excess dust, plaster and covering some of the units.
- 9. INTERIOR RESIDENTIAL UNITS SPLC 34.10 (7), 34.34 (6) Repair and maintain the walls in an approved manner.
- 10. INTERIOR RESIDENTIAL UNITS SPLC 34.10 (7), 34.34 (6) Repair and maintain the floor in an approved manner.
- 11. INTERIOR RESIDENTIAL UNITS SPLC 34.10 (7), 34.34 (6) Repair and maintain the ceiling in an approved manner.
- 12. INTERIOR RESIDENTIAL UNITS SPLC 34.10 (7), 34.33 (6) Repair and maintain the cabinets in an approved manner.
- 13. INTERIOR RESIDENTIAL UNITS SPLC 34.11, SBC 2902.1, SPLC 34.17, MPC 4715.0200.C Provide an approved number and type of plumbing fixtures. -Units missing plumbing and bathroom fixtures.

- 14. INTERIOR RESIDENTIAL UNITS SPLC 34.11(4), 34.34(1) SPC 4715.0200A Provide an adequate water supply to all water closets, sinks, showers and tubs. -Restore water to units that no longer have running water.
- 15. INTERIOR RESIDENTIAL UNITS MN Stat. 299F.362 Immediately provide and maintain a smoke detector located outside each sleeping area. -Units were lacking required smoke detectors.
- 16. INTERIOR RESIDENTIAL UNITS SPLC 34.09 (3) i Provide and maintain an approved one-inch throw single cylinder deadbolt lock.
- 17. INTERIOR RESIDENTIAL UNITS MN State Statute 299F.50 Immediately provide and maintain an approved Carbon Monoxide Alarm in a location within ten (10) feet of each sleeping area. Installation shall be in accordance with manufacturer's instructions.-All units were lacking CO detectors.
- 18. INTERIOR SECOND FLOOR MSFC 703 Provide, repair or replace the fire rated door and assembly. The minimum rating must be: 20minutes. -Several units doors are damaged.
- 19. INTERIOR SECOND FLOOR MSFC 703 Repair and maintain the required fire resistive construction with approved materials and methods. This work may require a permit(s). Call DSI at (651) 266-9090. -Several fire rated walls were removed and repaired with improper materials
- 20. INTERIOR UNIT 3 SPLC 34.13 (2), (3), SPLC 34.17 (2) Reduce and maintain the number of occupants.-There were five occupants in the one bedroom apartment. Illegal bedroom without necessary escape window.
- 21. INTERIOR UNIT 3 MSFC 1026.1 Provide and maintain an approved escape window from each sleeping room or area, or discontinue use of area as a sleeping room. This work may require permit(s). Call DSI at (651) 266-8989.-Interior room not intended for sleeping purposes was in use as a bedroom.
- 22. INTERIOR MSFC 605.6 Provide electrical cover plates to all outlets, switches and junction boxes where missing.
- 23. INTERIOR MSFC 605.6 Provide all openings in junction boxes to be sealed.
- 24. INTERIOR MSFC 605.6 Provide all electrical splices within junction boxes.
- 25. INTERIOR MSFC 605.1 Repair or replace damaged electrical fixtures. This work may require a permit(s). Call DSI at (651) 266-8989.
- 26. INTERIOR MSFC 605.1 Remove unapproved exposed wiring and install in accordance with the electrical code. This work may require a permit(s). Call DSI at (651) 266-8989.

- 27. INTERIOR MSFC 605.5 Discontinue use of extension cords used in lieu of permanent wiring.
- 28. INTERIOR MSFC 1028.3 Remove the materials that cause an exit obstruction. Maintain a clear and unobstructed exitway. -Remove the construction materials and items in the exit stairwells.
- 29. INTERIOR MSFC 1003.3.1.8 Remove unapproved locks from the exit doors. The door must be openable from the inside without the use of keys or special knowledge or effort. -Remove double keyed locks and chains marked exit doors.
- 30. INTERIOR MSFC 901.6 Provide required annual maintenance of the fire extinguishers by a qualified person and tag the fire extinguishers with the date of service.
- 31. INTERIOR MSFC 308.2.1 No person shall throw or place, or cause to be thrown or placed, a lighted match, cigar, cigarette, matches, or other flaming or glowing substance or object on any surface or article where it can cause an unwanted fire. -Several cigarette butts scattered throughout the buildings common areas.
- 32. INTERIOR SPLC 34.11, MSBC 2902.1, SPLC 34.17, MSPC 415.0220 Repair or replace and maintain all parts of the plumbing system to an operational condition.-Identify the source of the leaky plumbing and repair under permit.
- 33. INTERIOR RESIDENTIAL UNITS SPLC 34.10 (7), 34.33 (6) Repair or replace and maintain the woodwork in an approved manner.
- 34. STAIRWELL SPLC 34.09 (2), 34.32(2) Repair or replace the damaged handrail in an approved manner.
- 35. SPLC 34.11 (6), 34.34 (3) Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.
- 36. SPLC 39.02(c) Complete and sign the smoke detector affidavit and return it to this office.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8585) and must be filed within 10 days of the date of the original orders.

If you have any questions, email me at: adrian.neis@ci.stpaul.mn.us or call me at 651-266-8992 between 7:30 - 9:00 a.m. Please help make Saint Paul a safer place in which to live and work.

Sincerely,

A.J. Neis Fire Inspector Ref. # 13194

cc: Housing Resource Center

Force Unit