19. ADDITIONAL COMMENTS (1 through 18)

Item# Comments Specify location(s), where necessary BASEMENT/CELLAR В 1. B Missing handrail. Low guardrail (less than 1. Stairs and handrails _ 36" in height). Handrail not continuous. М Width of stairway less than 36". Openings in Υ guardrail(s) greater than 4". Stair landing 4. Evidence of dampness or staining _ Μ not properly supported. 5. First floor, floor system _ 3. B Missing mortar. Μ 6. Beams and columns _ 4. Efflorescence on walls. Stains on walls. 8. C Not able to see grounding clamp on street side of meter, covered by box. ELECTRICAL SERVICE(S) # of Services . ____1___ 12. B Missing vacuum breaker at exterior 7. Service size: Amps: 30 _____ 60 ____ 100_X_ 150____ Other ____ faucets. 14. B T & P discharge pipe terminates more than Volts: 115 ____ 115/220 _X 18" above floor. **BASEMENT ONLY:** 8. Electrical service installation/grounding ___ 9. Electrical wiring, outlets and fixtures _ PLUMBING SYSTEM 10. Floor drain(s) (basement). _ 11. Waste and vent piping (all floors)..... Μ 13. Gas piping (all floors) В 14. Water heater(s), installation Μ 15. Water heater(s), venting Μ 16. Plumbing fixtures (basement) _ HEATING SYSTEM(S) # of 17. Heating plant(s): Type: <u>Air</u> Fuel: <u>Gas</u> a. Installation and visible condition _ b. Viewed in operation (required in heating season) . . . _ c. Combustion venting The Evaluator is not required to operate the heating plant(s), except during heating season, between October 15 and April 15. 18. Additional heating unit(s) Type: _____ Fuel: ____ a. Installation and visible condition b. Viewed in operation _____ c. Combustion venting _____

Property Address: ______778 University Ave W

Rating Key: M = Meets minimum B = Below minimum C = See Comment H = Hazardous Y = Yes N = No NV = Not Visible/Viewed NA = Not Applicable
Where there are multiple rooms to a category, the Evaluator must specify the room to which a Comment is related.

Item # Comments

	Ite
KITCHEN	27
20. Walls and ceiling	
21. Floor condition and ceiling height	
22. Evidence of dampness or staining	
23. Electrical outlets and fixtures	
24. Plumbing fixtures	
25. Water flow	. <u>M</u> 53
26. Window size/openable area/mechanical exhau	st <u>M</u>
27. Condition of doors/windows/mech. exhaust LIVING AND DINING ROOM(S)	. <u>B</u>
28. Walls and ceiling	<i>M</i> 58
29. Floor condition and ceiling height	
30. Evidence of dampness or staining	
31. Electrical outlets and fixtures	
32. Window size and openable area	
33. Window and door condition	
HALLWAYS, STAIRS AND ENTRIES	
34. Walls, ceilings, floors	
35. Evidence of dampness or staining	•
36. Stairs and handrails to upper floors	
37. Electrical outlets and fixtures	
38. Window and door condition	•
39. Smoke detector(s)	
Properly located	
* Hard-wired (HWSD)	•
*if N or H in a single family home then SPFire Dept requi	ires HWSD installation
BATHROOM(S)	
40. Walls and ceiling	М
41. Floor condition and ceiling height	
42. Evidence of dampness or staining	•
43. Electrical outlets and fixtures	•
44. Plumbing fixtures	
45. Water flow	
46. Window size/openable area/mechanical exhau	•
SLEEPING ROOM(S)	•
48. Walls and ceiling	. <u>M</u>
49. Floor condition, area, and ceiling height	
50. Evidence of dampness or staining	
51. Electrical outlets and fixtures	
52. Window size and openable area	
53. Window and door condition ENCLOSED PORCHES AND OTHER	ROOMS
54. Walls, ceiling, and floor, condition	
55. Evidence of dampness or staining	
56. Electrical outlets and fixtures	
57. Window and door condition	. <u>NA</u>
ATTIC SPACE (Visible Areas)	
58. Roof boards and rafters	
59. Evidence of dampness or staining	. <u>N</u>
60. Electrical wiring/outlets/fixtures	
61. Ventilation	\/
62. ADDITIONAL COMMENTS (20 through 6	61) <u> </u>
CO Detector information reported here	•

CO Detector information reported here

EVALUATOR:_

27. B Sashes nailed / screwed shut.

- 36. B To attic: No guardrail at top of stairway.

 Tread depth less than 9". Low headroom (less than 6' 8"). Handrail missing. To 2nd floor:

 Handrail is not continuously graspable for the full length of the stairway.
- 53. B Missing sash locks at various windows. Some sashes nailed / screwed shut. Upper sashes painted shut. Missing / broken sash cords
- 58. C Charred rafters, evidence of fire in attic.
- 61. No soffit vents.

778 University Ave W Property Address:

Rating Key: M = Meets minimum B = Below minimum C = See Comment H = Hazardous Y = Yes N = No NV = Not Visible/Viewed NA = Not Applicable

	EXTERIOR (Visible Areas)			
63.	Foundation	M		
64.	Basement/cellar windows	B		
65.	Drainage (grade)	M		
	Exterior walls	M		
67.	Doors (frames/storms/screens)	M		
	Windows (frames/storms/screens)	B		
	69. Open porches, stairways and decks			
	Cornice and trim	M		
71.	Roof structure and covering	M		
	Gutters and downspouts	B		
	Chimneys	M		
74.	Outlets, fixtures and service entrance	M		
	GARAGE(S)/ACCESSORY STRUCTURE	E(S)		
75.	Roof structure and covering	ŃΑ		
	Wall structure and covering	NA		
77.	Slab condition	NA		
	Garage doors(s)	NA		
	Garage opener(s) - (see important notice #6)	NA		
	Electrical wiring, outlets and fixtures	NA_		
	ADDITIONAL COMMENTS (62 through 80).	NA		
	,			
	FIREPLACE/WOODSTOVES # of	0		
82.	Dampers installed in fireplaces			
83.	Installation			
84.	Condition			
••		••••		
SU	PPLEMENTAL INFORMATION No determina	tion is made		
wh	ether items meet minimum standards (Y/N, NA	, NV, only)		
	INSULATION Y/N Type In	ches/Depth		
85.	Attic Insulation Y cellulose	varies		
86.	Foundation Insulation NV			
	TZ 11 T 1 N/A			

Item# **Comments**

- 64. B Some windows boarded over at rear. Dirt / grade in contact with windows - east side.
- 68. B Windows decayed / rot visible at numerous windows - east side.
- 69. B Handrail is not graspable, decayed areas at front and rear steps.
- 72. B Downspout(s) lack extension(s).
- 85. Insulation depth varies.

INSULATION	Y/N	Type	Inches/Depth
85. Attic Insulation	Y_	cellulose	<u>varies</u>
86. Foundation Insulation	NV		
87. Kneewall Insulation	NA		
88 Rim Joist Insulation	Ν		

89. ADDITIONAL COMMENTS (81 through 88) NA

I hereby certify I prepared this report in compliance with the St. Paul Evaluator Guidelines and all other applicable policies and procedures of the Truth-in-Sale of Housing Board. I have utilized reasonable and ordinary care and diligence and I have noted all conditions found that do not conform to the minimum standards of maintenance.

952.915.6466 09/12/2015 Page <u>4</u> of <u>4</u> **Evaluator Signature** Phone Number Rev 3/2009 Date

George Ury **Printed Name:**

IMPORTANT NOTICES

- 1. Any single family residence in St. Paul must have at least one smoke detector connected to the electrical system (hard-wired). The detector must be located near sleeping rooms. For more information call Fire Prevention, 651-266-9090. (St. Paul Legislative Code, Chapter 58.)
- 2. Rainleaders connected to the sanitary sewer system must be disconnected. For more information call Public Works, Sewer Utility, (651) 266-6234.
- 3. A house built before 1978 may have lead paint on/in it. If children ingest lead paint, they can be poisoned. For more information call Ramsey County Public Health, 651-266-1199.
- 4. Neither the City of St. Paul nor the Evaluator is responsible for the determination of the presence of airborne particles such as asbestos, noxious gases such as radon, or other conditions of air quality that may be present, nor the conditions which may cause the above.
- 5. If this building is used for any purpose other than a single family dwelling, it may be illegally zoned. To help you determine legal uses under the zoning ordinance, contact the Zoning Administrator at 651-266-9008.
- 6. An automatic garage door should reverse upon striking an object. If it does not reverse it poses a serious hazard and should be immediately repaired or replaced.