

# City of Saint Paul

Department of Safety Inspections 375 Jackson Street, Suite 220 Truth- in- Sale of Housing Program File#: 15- 129276

Date of Evaluation: Jun 12, 2015

Address: 1642 BLAIR AVE
Owner: Dana Demaster
Client Name: Marc Anders
Client Contact: 612-963-5758

Evaluator Name: Brice Staeheli American Central In

Evaluator Phone: Work: 651-238-1314
Evaluator Email: brice.staeheli@gmail.com

## Truth- in- Sale of Housing Disclosure Report

# This Report:

- is intended to provide basic information to the home buyer and seller prior to the time of sale.
   This report WILL NOT be used to enforce the requirements of the Legislative Code; however, this evaluation form will be used to determine if there is compliance with the requirements for a hard- wired smoke detectors.
- 2. is based on the current Truth-in-Sale of Housing Evaluator Guidelines and is based upon different standards than the lender, Federal Housing Administration (FHA) or Veterans Administration (VA).
- 3. is not warranted, by the City of Saint Paul nor by the evaluator for the condition of the building component, nor of the accuracy of this report.
- 4. covers only the items listed on the form and only those items visible at the time of the evaluation. The Evaluator is not required to operate the heating plant (except during the heating season), use a ladder to observe the condition of the roofing, disassemble items or evaluate inaccessible areas.
- 5. is valid for one year from the date of issue and only for the owner named on this report.

Questions regarding this report should be directed to the evaluator. Complaints regarding this report should be directed to Department of Safety and Inspections, Truth- in- Sale of Housing Program, Phone 651- 266- 8989.

## IMPORTANT NOTIFICATIONS AND WARNINGS

For questions on these items, call the City's information and Complaint Line at 651-266-8989.

#### **Description/Comment:**

This property was evaluated as Single Family Dwelling

This property is NOT within a designated historical preservation district, nor is it a specifically designated historical property.

SD Present: Y SD Properly Located: Y SD HardWired: Y

SD Comment: No data entered.

This property has No Moratorium Warning.

This property has no sewer warning, or confirmed problem, known to the Sewer Utility. To obtain more information regarding your private sewer pipe, please call the City of Saint Paul's Sewer Utility Service Desk at 651-266-6234 and/or have your private sewer pipe televised.

This property has No Open Permits.

This property IS NOT a Registered Vacant Building.

Property address: 1642 Blair Ave

Rating Key: M Meets minimum B Below minimum C See comment H Hazardous Y Yes N No NV Not Visible NA Not applicable

		<u> Item #</u>	Comments
			Specify locations(s), where necessary
В	ASEMENT/CELLAR		
1. 2. 3. 4. 5. 6.	Stairs and Handrails  Basement/cellar floor  Foundation  Evidence of dampness or staining  First floor, floor system  Beams and columns	B M B Y. B B	Items marked as "M" are based on what is readily visible at time of Inspection, Home furnishings, belongings and possessions limits view,  1 B - Uneven rise and run, Improper guardrail, Low headroom,  3 B - Small cracks, Peeling finish,  4 C - Evidence of past dampness and/or staining,  5 B - Deteriorated joists,  6 B - Temporary columns in use,
E	LECTRICAL SERVICES(S) # of Service	es1	
7. BAS	Service size: Amps: 3060100_X150other Volts: 115115/220X_ SEMENT or METER LOCATION(S) ONLY		
8.	Electrical service installation /grounding.	M	
	Electrical wiring, outlets and fixtures	В	9 B - Improper routing of romex,
P	LUMBING SYSTEM		
10.	Floor drain(s) (basement)	M	
		В	11 B - Improper material and design,
			13 B - Old brass shutoffs in use,
13.	Gas piping (all floors)	В	,
14.	Water heater(s) installation	M	15, 17c H - Venting into attic space, chimney does not penetrate
15.	Water heater(s) venting	H	roof line.
16.	Plumbing fixtures (basement)	M	15 B - Missing screws on flue line, no metal liner, improper venting.
Н	IEATING SYSTEM(S) # of	1	
			17a B - Dirty, rusted unit.
17.	Heating plant(s): Fuel: GAS Type: Gravity	y	- · · · · · · · · · · · · · · · ·
	a. Installation and visible condition	В	17c B - Missing screws on flue line, no metal liner,
	b. Viewed in operation (required during heating season)	)N	$\beta$
	c. Combustion venting	Н	
	Evaluator is not required to operate the heating the heating season, between October 15 an		pt

	18.	/Additional	heating	unit(s)	Fuel:	GAS	Type:
--	-----	-------------	---------	---------	-------	-----	-------

- a. Installation and visible condition
- b. Viewed in operation.....
- c. Combustion venting.....

# 19. ADDITIONAL COMMENTS (1 THROUGH 18)...M

EVALUATOR: American Central Inspections, Brice Staeheli DATE: 06-12-15

Property address: 1642 Blair Ave
Rating Key: M Meets minimum B Below minimum C See comment H Hazardous Y Yes N No NV Not Visible NA Not applicable Where there are multiple rooms under same category, the evaluator must specify the room to which the comment is related

Item # Comments

		Item #	Comments
KITCHEN			
20. Walls and ceiling	M	Itams marked as "	M" are based on what is readily visible at time of
21. Floor condition and ceiling height	M		M" are based on what is readily visible at time of
22. Evidence of dampness or staining	N	Inspection, Home	furnishings, belongings and possessions limits view,
23. Electrical outlets and fixtures	M		
24. Plumbing systems	M		
25. Water flow	M		
26. Window size and openable area	M		
27. Window and door condition	В		
LIVING AND DINING ROOM(S)	_		B - All Windows have some deterioration, top sashes
28. Walls and ceiling	M	painted shut.	
29. Floor condition and ceiling height	M		
30. Evidence of dampness or staining	N		
31. Electrical outlets and fixtures	M		
32. Window size and openable area	M		
33. Window and door condition	В		
HALLWAYS, STAIRS AND ENTRIES	ь		
	М	36 B - Improper h	andrail, low headroom.
34. Walls, ceilings and floors	M		,
35. Evidence of dampness or staining	N		
36. Stairs and handrails to upper floors	В		
37. Electrical outlets and fixtures	M		
38. Window and door condition	В		
39. Smoke detector(s)	Y		
Properly located  Hard-wired (HWSD)	Y *Y		
*if N or H in a single family home then SPFire Dept re		VSD installation	
BATHROOMS(S)	quirea ii i	155 Instanction	
40. Walls and ceiling	M		
41. Floor condition	M		
42. Evidence of dampness or staining	N		
43. Electrical outlets and fixtures	M		
44. Plumbing fixtures	M		
45. Water Flow	M		
46. Window size /openable area or mechanical exhaus			
47. Condition of windows/mechanical exhaust/doors.			
SLEEPING ROOM(S)	Б		
` '	М		
48. Walls and ceiling	M M		
50. Evidence of dampness or staining 51. Electrical outlets and fixtures	N M		
	M		
52. Window size and openable area	В	52 B - Windows d	o not meet the current egress code,
53. Window and door condition	B		
ENCLOSED PORCHES AND OTHER ROC			
54. Walls and floor condition	M		
55. Evidence of dampness or staining	N		
56. Electrical outlets and fixtures	M		
57. Window and door condition	В		
ATTIC SPACE (Visible Areas)	-	<b>50 5</b> - :	
58. Roof boards and rafters	В		roof boards and rafters
59. Evidence of dampness or staining	Y	59 B - Typical water	
60. Electrical wiring/outlets/fixtures	C	60 C - None seen fr	om access point.
61. Ventilation	Y		
62. ADDITIONAL COMMENTS (20 through 61)	M		

CO Detector information reported here

Property Address: 1642 Blair Ave

Rating Key: M Meets minimum B Below minimum C See comment H Hazardous Y Yes N No NV Not Visible NA Not applicable

Item #

**Comments** 

E	EXTERIOR (Visible Areas)		
63.	Foundation	C	
64.	Basement/cellar windows	В	63 C -Foundation is not fully visible, Areas covered by finished
65.	Drainage (grade)	В	materials
66.	Exterior walls	В	64 B - Light deterioration noted
67.	Doors (frames/storms/screens)	M	65 B - Areas lack drainage/pitch away from home
68.	Windows (frames/storms/screens)	M	66 B -Chalking paint, Weathered siding,
69.	Open porches, stairways and decks	В	69 B - Improper handrail,
70.	Cornice and trim	В	70 B - Weathered in areas, Peeling paint,
71.	Roof covering and flashing	В	71 B - Weathered/worn roofing,
72.	Gutters and downspouts	В	72 B - Missing leaders,
73.	Chimneys	В	73 B - Venting into attic space, chimney does not penetrate roof line.
	Outlets, fixtures and service entrance	M	, o 2 chang into anat space, change y does not penduate root and
C	ADACE (S) / ACCESSODY STDUCTUD	F ( <b>S</b> )	
G	ARAGE (S) / ACCESSORY STRUCTURI	ī (S)	75-80 No Garage
75.	Roof structure and covering	C	
76.	Wall structure and covering	C	
	Slab condition	C	
78.	Garage doors	C	
79.	Garage opener- (see important notice #6) .	C	
80.	Electric wiring, outlets and fixtures	C	
81.	Additional Comments(63 through 80)		
	FIREPLACE/WOODSTOVES # OF		0
82.	Dampers installed in fireplaces		
	Installation		
84.	Condition		
e e e	PPLEMENTAL INFORMATION – No de	• • • • •	
			ons made whether
пеп	n meet minimum standards (Y/N, N/A, NV, Y/N	Type	Inches/ depth
	INSULATION	Турс	menes/ depui
85.	Attic insulation V	Celli	uose 8" - 10"
	Foundation insulation N		
	Kneewall Insulation NV		
88.	Rim Joist Insulation N		
			th the Saint Paul Evaluator Guidelines and all other applicable policies and procedures of

I hereby certify that I prepared this report in compliance with the Saint Paul Evaluator Guidelines and all other applicable policies and procedures of the Truth –in-sale of Housing Board. I have utilized reasonable and ordinary care and diligence and that I have noted all conditions found that do not conform to the minimum standards of maintenance.

Porise Statel

 Evaluator Signature
 Phone Number
 Date
 Rev
 3/2009

 Printed name
 Brice Staeheli

### IMPORTANT NOTICES

- 1. All single family residence in St. Paul must have at least one smoke detector connected to the electrical system (hard-wired). The detector must be located near sleeping rooms. For more information call Fire Prevention, 651-266-9090. (St. Paul Legislative Code Chapter 58.)
- 2. Rainleaders connected to the sanitary sewer system must be disconnected. For more information call Public Works, Sewer Division, (651) 266-6234.
- 2. A house built before 1978 may have lead paint on/in it. If children ingest lead paint, they can be poisoned. For more information call Saint Paul Ramsey County Public Health, (651) 266-1199.
- 3. Neither the City of St. Paul nor the Evaluator are not responsible for the determination of the presence of airborne particles such as asbestos, noxious gases, such as radon or other conditions of air quality that may be present, nor the conditions which may cause the above.
- 4. If this building is used for any purpose other that a single family dwelling, it may be illegally zoned. To help you determine legal uses under the zoning ordinance, contact the Zoning Administrator at (651) 266-9008.
- 5. An automatic garage door should reverse upon striking an object. If it does not reverse, it poses a serious hazard and should be repaired or replaced immediately.