

Melanie	
2227 Beech St	
St Paul MN	

Estimate

Date	Estimate No.
02/08/16	1876

Lic: 20632023

Description	Quantity	Cost	Total
Scope for general rehab to bring the home to a marketable condition and achieve code compliance:			
Mold remediation of lower level: -Remove and discard all building material in lower level including all walls, ceilings and complete bathroom with Hepa filtered air scrubbingHepa vacuuming, antimicrobial disinfecting of complete lower levelCoat complete lower level with antimicrobial mold encapsulantFinal air clearance testing for city code compliance showing home is mold free.		5,984.00	5,984.00
Framing repairs: -Leveling of sagging floor joist, properly flash and attach side deck to home, replace rotten framing around front door etc		875.00	875.00
Exterior minimum repairs: -Fix Grading around complete home -Remove roof from side deck -Rood repairs: chimney flashing and other Mis flashing as needed (roof was snow covered at time of inspection) -Calk and touch up paint exterior of home as needed -Paint facia on complete home -Install new front door (door with side light)		4,850.00	4,850.00
		Total	



Melanie
2227 Beech St
St Paul MN

Estimate

Date	Estimate No.
02/08/16	1876

Lic: 20632023

Description	Quantity	Cost	Total
Doors and windows (Exterior):		8,950.00	8,950.00
-Install new front door (door with side light)			
-Install new vinyl windows (14 total)			
Interior Upper level Bathroom:		2,950.00	2,950.00
-Remove and replace vanity, toilet, tile on floor and tub			
surround			
-Repair all plumbing to code and install new plumbing			
fixtures			
-Refinish tub			
Kitchen:		4,822.00	4,822.00
-Clean and refinish cabinets		1,022.00	1,022.00
-Replace formica counter tops			
-Install new sink and fixtures			
-Install new stainless steel appliances (Fridge, range and			
Microwave)			
·			
Trim and interior doors:		2,150.00	2,150.00
-Refinish and repair trim as needed			
-Replace all interior doors			
-Add graspable handrails to all stairs as needed			
Flooring:		2,977.00	2,977.00
-Remove and replace all flooring in main level (carpet in living			
room and bedrooms and sheet vinyl in kitchen area)			
		Total	



Melanie	
2227 Beech St	
St Paul MN	

Estimate

Date	Estimate No.
02/08/16	1876

Lic: 20632023

Description	Quantity	Cost	Total
Paint (interior): -Stain blocker prim all walls and ceilings -Paint walls and ceilings (walls up to two colors and ceilings to be bright white) -This includes drywall repair as needed and the removal of wallpaper in 3 rooms		2,900.00	2,900.00
Hardware: -Install new hardware throughout home including Door knobs, Door stops, cabinet hardware, bathroom accessories,		495.00	495.00
Unfinished Drywall areas (Per code compliance): -Install drywall on all exterior walls and fire tape per code -Repair and replace drywall on garage ceiling as needed fire tape per code		1,995.00	1,995.00
Electrical: -Remove and Replace all light fixtures throughout homecode compliance repairs: 1. Properly wire dishwasher/disposal to current NEC. Ensure cord is an appliance cord 2. Install box extensions on devices mounted in wood paneling. Article 314.20, NEC 3. Install hard-wired, battery backup, Carbon Monoxide smoke detector as specified in Chapter 58 of the Saint Paul Legislative Code, and other smoke detectors and carbon		7,250.00	7,250.00
		Total	



Melanie	
2227 Beech St	
St Paul MN	

Estimate

Date	Estimate No.
02/08/16	1876

Lic: 20632023

Description	Quantity	Cost	Total
monoxide detectors as required by the Minnesota State			
Building Code. SPLC 58, IRC			
4. Ensure/Properly wire furnace/AC unit to current NEC.			
5. Ensure/Install a receptacle for sump pump. Article 400.8,			
NEC			
6. Ensure/rewire all electrical associated with NM cables dated			
after 2002 to current NEC. An electrical permit was never			
purchased for that wiring. SPLC 33.03 (d)			
7. Repair the electrical service grounding conductor to the			
metallic water piping system. Install a conductor sized to			
Table 250.66 (NEC) from the electrical service to within 5' of			
the entrance point of the water service, and bond around the			
water meter. Article 250, NEC			
8. Provide a complete circuit directory at service panel			
indicating location and use of all circuits. Article 408.4, NEC			
9. Replace circuit breakers in electrical panel that are not listed			
for that panelboard with proper breakers. Article 110.3 (B)			
10. Ensure/Verify that fuse/circuit breaker amperage matches			
wire size in panel. Replace improperly sized overcurrent			
devices. Article 240.4, NEC No access in panel			
11. Electrical Panel -NEC 110.26 Provide access into			
electrical panel. Panel is covered in areas by the paneling.			
12. Electrical Panel -No power at time of inspection. Test all			
electrical outlets and ensure all luminaires (light fixtures) are			
working properly when power is restored. Note - Main			
breaker was in the off position in Panel.			
		Total	
		Total	



Melanie	
2227 Beech St	
St Paul MN	

Estimate

Date	Estimate No.
02/08/16	1876

Lic: 20632023

Description	Quantity	Cost	Total
13. Throughout -Properly strap and support cables and/or			
conduits. Chapter 3, NEC			
14. Throughout -Remove all cord wiring used as a substitute			
for fixed wiring. Article 400.8, NEC			
15. Throughout -Repair or replace all broken, painted over,			
corroded, missing or loose receptacles, luminaires (light			
fixtures), switches, covers and plates to current code. Article			
406.4(D) & Article 410, NEC			
16. Throughout -Check all receptacles for proper polarity			
(including 2-prong) and verify ground on 3-prong			
receptacles. Ensure all GFCI receptacles are functioning			
properly. Rewire and/or replace receptacles that are			
improperly wired or not functioning properly. Article			
406.4(D), NEC			
17. Throughout -Remove and/or rewire all illegal, improper or			
hazardous wiring to current NEC. This will include Basement,			
garage, and above drop ceiling			
18. Throughout -NEC 410.90 Remove adapters in light fixtures			
19. Throughout -Close openings in service panel/junction			
boxes with knockout seals, breaker blanks, proper cable			
clamps, and/or junction box covers. Article 110.12 (A), NEC			
All electrical work must be done by a Minnesota-licensed			
electrical contractor			
Plumbing:		4,900.00	4,900.00
		Total	
		Total	



Melanie	
2227 Beech St	
St Paul MN	

Estimate

Date	Estimate No.
02/08/16	1876

Lic: 20632023

Description	Quantity	Cost	Total
-Code compliance repairs:			
1. Basement -Gas Piping -(MFGC 614.1-614.7) Vent			
clothes dryer to code.			
2. Basement -Sump Pump/Basket -(MPC 2400 Subp.4)			
Provide a properly secured cover.			
3. Basement -Sump Pump/Basket -(MPC 2440) Run the			
clear water sump water to the outside of the building.			
4. Basement -Sump Pump/Basket -(MPC 2440) Install the			
correct code complaint materials and piping.			
5. Basement -Toilet Facilities -(MPC 0200 P) Install the water			
piping to code.			
6. Basement -Tub and Shower -(MPC 0200 E & MPC 2500)			
Install a proper fixture vent to code.			
7. Basement -Tub and Shower -(MPC 1380 Subp.5) Install			
an anti-scald control device, ASSE Standard 1016.			
8. Basement -Water Heater -(MPC 2210 Subp.4) Correct the			
pressure and temperature relief valve discharge.			
9. Basement -Water Heater -(MFGC 402.1) Install the gas			
shut off and the gas piping to code.			
10. Basement -Water Heater -(MPC 1730 Subp.1) Install the			
water piping for the water heater to code.			
11. Basement -Water Heater -(MPC 2180) The water heater			
must be fired and in service.			
12. Basement -Water Meter -(MPC MPC1700-SPRWS,			
Sec.88.10) The water meter must be installed and in service.			
13. Basement -Water Piping -(MPC 1720) Repair or replace			
		Total	
Pag			



Melanie	
2227 Beech St	
St Paul MN	

Estimate

Date	Estimate No.
02/08/16	1876

Lic: 20632023

Description	Quantity	Cost	Total
all the corroded, broken, or leaking water piping. 14. Basement -Water Piping -(SPRWS Water Code) Provide a one (1) inch water line to the first major take off. 15. Exterior -Lawn Hydrants -(MPC 2000) The lawn hydrant(s) require a backflow assembly or device. 16. First Floor -Toilet Facilities -(MPC 0870) Reset the toilet on a firm base. 17. First Floor -Toilet Facilities -(MPC 0200 O) Repair/replace the fixture that is missing, broken or has parts missing. 18. First Floor -Tub and Shower -(MPC 1380 Subp.5) Install an anti-scald control device, ASSE Standard 1016. All plumbing must be done by a plumbing contractor licensed in St Paul			
Heating: -Code compliance repairs: 1. Lever handle manual building shutoff gas valve must be in an accessible location ahead of the first brach tee 2. Clean and Orsat test furnace burner. Check all controls for proper operation. Check furnace heat exchanger for leak; provide documentation from a licensed contractor that the heating unit is safe 3. Vent clothes dryer to code 4. Provide support for gas lines to code 5. Plug, cap and/or remove all disconnected gas lines		1,810.00	1,810.00
		Total	



Melanie	
2227 Beech St	
St Paul MN	

Estimate

Date	Estimate No.
02/08/16	1876

Lic: 20632023

Description	Quantity	Cost	Total
6. Bathrooms require a means to ventilate the space. Provide			
a window with an aggregate glazing area of not less than 3			
square feet, one half of which must be operable. Alternative			
is a bath fan properly vented to the outside. A mechanical			
ventilation permit will be required for the bath fan.			
7. Provide all supply and return ducts for warm air heating			
system must be clean before final approval for occupancy.			
Documentation is required from a licensed			
duct-cleaning contractor that the duct system has been			
cleaned.			
8. Repair and/or replace heating registers as necessary			
9. Provide heat in every habitable room and bathrooms			
10. Verify that A/C system is operable, if not, repair, replace			
or remove and seal all openings.			
11. Mechanical permits are required for the above work.			
Options for more and nicer finishings:			
Lower level:			
-Finish lower level living areas including; installing drywall on			
ceiling, finish drywall on walls, paint trim interior doors and			
carpet. 8,500.00			
-Install bathroom in lower level (3/4 Bath) including: all new			
plumbing to code, Demo and pour back of concrete floor,			
tile, shower, pedestal sink, toilet and drywall. 5,100.00			
		Total	
		Total	
Page	2 R		



Melanie	
2227 Beech St	
St Paul MN	

Estimate

Date	Estimate No.		
02/08/16	1876		

Lic: 20632023

Kitchen: -Remove and replace cabinets -Upgrade to Graniet counter tops 7,500.00 Painting Options: -Enameling of all interior trim (upgrade price) 650.00 -Paining of complete exterior of home 4,500.00	Description	Quantity	Cost	Total
-Upgrade to Graniet counter tops 7,500.00 Painting Options: -Enameling of all interior trim (upgrade price) 650.00 -Paining of complete exterior of home 4,500.00				
Painting Options: -Enameling of all interior trim (upgrade price) 650.00 -Paining of complete exterior of home 4,500.00				
Painting Options: -Enameling of all interior trim (upgrade price) 650.00 -Paining of complete exterior of home 4,500.00				
-Paining of all interior trim (upgrade price) 650.00 -Paining of complete exterior of home 4,500.00	7,500.00			
-Paining of all interior trim (upgrade price) 650.00 -Paining of complete exterior of home 4,500.00	Painting Options:			
Total \$52,908.00	-Paining of complete exterior of home 4,500.00			
Total \$52,908.00				
			Total	\$52,908.00