

ð

□

APPLICATION FOR APPEAL

Saint Paul City Council – Legislative Hearings

RECEIVED

310 City Hall, 15 W. Kellogg Blvd.

Revised 8/11/2014

(provided by Legislative Hearing Office)

\$25 filing fee (non-refundable) (payable to the City of Saint Paul)

Copy of the City-issued orders/letter being appealed

(if cash: receipt number 794686

Attachments you may wish to include

	Saint Paul, Minnesota 55102
JUN 10 2016	Telephone: (651) 266-8585

HEARING DATE & TIME

Tuesday, June 21

☐ Attachments you may wish to include ☐ This appeal form completed		Time 11:30 or 2:30	
✓ Walk-In OR □ Mail-In		Location of Hearing:	
•	2 G Fay	Room 330 City Hall/Courthouse	
for abatement orders only: Email Ol	` u rax		
Address Being Appealed		·	
Number & Street: 1103 Jessam	ne ave. E. City: Se	intPaul State: MN Zip: 55/06	
Appellant/Applicant: Joe Spychalla	Em	ail Cub Joe @ gmail (on	
Phone Numbers: Business	_ Residence (S1)3	23-7474 Cell	
Signature: Justo Drychollo			
Name of Owner (if other than Appellant): Michele Spychalla			
Mailing Address if Not Appellant's:			
Phone Numbers: Business	Residence	Cell	
What Is Being Appealed a Vacate Order/Condemnation/ Revocation of Fire C of O	and Why?	Attachments Are Acceptable	
□ Summary/Vehicle Abatement			
☐ Fire C of O Deficiency List/Correction			
Code Enforcement Correction Notice			
□ Vacant Building Registration			
□ Other (Fence Variance, Code Compliance, etc.)			



CITY OF SAINT PAUL Christopher B. Coleman, Mayor 375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806 Telephone: 651-266-8989 Facsimile: 651-266-8951 Web: www.stpaul.gov/dsi

May 16, 2016 MICHELLE SPYCHALLA C/O JOSEPH SPYCHALLA 1103 JESSAMINE AVE E ST PAUL MN 55106-2713

RE: VACANT BUILDING DEFICIENCIES

1103 JESSAMINE AVE E

Ref. # 123764

An inspection was made on May 16, 2016 of your vacant building at the above-captioned address. You are hereby notified that the following list must be corrected immediately. A reinspection will be made on June 9, 2016 at 945 am.

Failure to comply may result in additional reinspection fees and a criminal citation.

DEFICIENCY LIST

- 1. EXTERIOR-FRONT STEPS-SPLC 34.09 (2), 34.32(2) Repair or replace the unsafe stairways, porch, decks or railings in an approved manner. This work may require a permit(s). Call DSI at (651) 266-9090.-The front steps are not connected to the house, needs to be maintained in a professional manner
- 2. EXTERIOR-GLASS WINDOWS-SPLC 34.09 (3), 34.32 (3) Repair and maintain the window glass.-Repair or replace the broken glass on the windows
- 3. EXTERIOR-PATIO SCREENS-SPLC 34.09 (3), 34.33 (3) -Provide or repair and maintain the window screen.-Repair or replace the torn screens on the patio windows
- 4. EXTERIOR-SHED-SPLC 34.08(5), 34.32(3) All accessory structures including, but not limited to, detached garages, sheds and fences shall be maintained structurally sound and in good repair. Provide and maintain exterior unprotected surfaces painted or protected from the elements.-Provide and maintain the shed, broken door and missing section in back. Needs to be maintained
- 5. INTERIOR-BATHROOM FLOORING-SPLC 34.10 (4), 34.33 (3) Provide a bathroom floor impervious to water.-Provide and maintain bathroom flooring on the upper level
- 6. INTERIOR-CEILING PAINT-SPLC 34.10 (7), 34.34 (6) Repair and maintain the ceiling in an approved manner.-Paint the ceiling, Peeling and flaking paint in the upper hallway, needs to be maintained

- 7. INTERIOR-CO DETECTORS-MN State Statute 299F.50 Immediately provide and maintain an approved Carbon Monoxide Alarm in a location within ten (10) feet of each sleeping area. Installation shall be in accordance with manufacturers instructions.-Provide and maintain CO detectors on both levels of the house, main and upper.
- 8. INTERIOR-DEAD BOLT-SPLC 34.09 (3) i Provide and maintain an approved one-inch throw single cylinder deadbolt lock.-Repair or replace the dead bolt
- 9. INTERIOR-DOORS-Ext. Door SPLC 34.09 (3), 34.33 (3) Repair and maintain the door in good condition.-Repair or replace the bathroom door upper level and bedroom door knob is busted.
- 10. INTERIOR-DRYER VENT-MSMC 504.6 Provide, repair or replace the dryer exhaust duct. Exhaust ducts for domestic clothes dryers shall be constructed of metal and shall have a smooth interior finish. The exhaust duct shall be a minimum nominal size of four inches (102 mm) in diameter and installed in accordance with the mechanical code. This work may require a permit(s). Call DSI at (651) 266-8989.
- 11. INTERIOR-EXTINGUISHER-MSFC 901.6 Provide required annual maintenance of the fire extinguishers by a qualified person and tag the fire extinguishers with the date of service.-Maintain extinguisher or remove it
- 12. INTERIOR-EXTINGUISHER-MSFC 906.1, MN Stat. 299F.361 Provide approved fire extinguishers in accordance with the following types, sizes and locations.-Provide one minimum 1A10BC fire extinguisher within each apartment unit or a minimum 2A10BC not be more than 50' travel distance from each apartment entrance. They must be permanently mounted between 3 and 5 feet high in readily visible and easily accessible locations. Mount or remove the extinguisher
- 13. INTERIOR-FRONT PORCH-MSFC 315.2 Provide and maintain orderly storage of materials.-Reduce storage of front porch area by 50%
- 14. INTERIOR-FUEL HEAT TEST-SPLC 34.11 (6), 34.34 (3) Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.
- 15. INTERIOR-FUELS-MSFC 315.2.5 Fueled equipment, including but not limited to motorcycles, mopeds, lawn-care equipment and portable cooking equipment, shall not be stored, operator or repaired within a building.-Remove the propane torches from the basement area, gas can in porch
- 16. INTERIOR-GLOBES-MSFC 605.1- All light fixtures shall be maintained with protective globes if originally equipped.-Provide and maintain globes on the light fixture and ceiling fans that are missing them
- 17. INTERIOR-KITCHEN CABINETS-SPLC 34.10 (7), 34.33 (6) Repair and maintain the cabinets in an approved manner.-Repair or replace the damaged or missing door, in the kitchen

- 18. INTERIOR-KITCHEN SINK-SPLC 34.11, MSBC 2902.1, SPLC 34.17, MSPC 415.0220 Repair or replace and maintain all parts of the plumbing system to an operational condition.-Repair or replace and maintain an approved kitchen sink. This work may require a permit(s). Call LIEP at (651) 266-9090.
- 19. INTERIOR-OUTLET COVERS-MSFC 605.6 Provide electrical cover plates to all outlets, switches and junction boxes where missing.-
- 20. INTERIOR-SANITARY-SPLC 34.10 (5), 34.33 (4), 34.16 Provide and maintain interior in a clean and sanitary condition.-Through out the house, porch and basement
- 21. INTERIOR-STOVE KNOB MISSING-SPLC 34.12 (2), SPLC 34.36 (1) Repair and maintain all required and supplied equipment in an operative and safe condition to properly and safely perform their intended function in accordance with the provisions of the applicable code. -Provide and maintain a knob for the stove that is missing
- 22. INTERIOR-TOILET-SPLC 34.11, MSBC 2902.1, SPLC 34.17, MSPC 415.0220 Repair or replace and maintain all parts of the plumbing system to an operational condition.- Repair or replace and maintain an approved private toilet, toilet is loose and needs to be tight to floor to prevent water damage to bathroom flooring
- 23. INTERIOR-WINDOW ACCESS-MSFC 1028.3 Remove the materials that cause an exit obstruction. Maintain a clear and unobstructed exitway.-Rearrange the lower bedroom to allow access to the windows
- 24. SPLC 39.02(c) Complete and sign the smoke detector affidavit and return it to this office.

For an explanation or information on some of the violations contained in this report, please visit our web page at: http://www.ci.stpaul.mn.us/index.aspx?NID=211

If you have any questions, email me at Jonathan.Gaulke@ci.stpaul.mn.us or call me at 651-266-8994 between 7:30 a.m - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely, Jonathan Gaulke Fire Inspector Ref. # 123764