DOCUMENT 00 40 00

BID DOCUMENT

1 Submit bids in compliance with Document 00 21 00-Instructions to Bidders. Fill in blanks which pertain

	to the project or indicate N/A. The Owner reserves the right to document is not part of the Contract Documents, unless specific Agreement.	-	•
2	Project Name & Address: New O'Reilly Auto Parts Store #3252 Brick Removal and replacement St. Paul, MN	- -	
3	Contractor Name & Address: G. M. Northrup Corporataion 15950 Franklin Trail S. E. Prior Lake, MN 55372	- - -	
4	Bid is to be provided by both individual sections and by lump su accepted and bid rejected. Refer to division sections for summer		
	a. Division 1 - General Requirements: (1) General Conditions	Total_	\$5,450.00
	b. Division 2 - Existing Conditions: (1) Demolition	\$4,500.00	
	(2) Asbestos & Hazardous Material Work		
	(3) Site Preparation (Sub)		
	(4) Soil Testing (Compaction)		
	(5) Pavement Sub Base		
	(6) Slab Sub Base		
	(7) Driven Piles		
	(8) Bored and Belled Concrete Piers		
	(9) Concrete Paving a. Parking Lot		
	b. Misc. Slab on Grade		
	c. Concrete Curb		
	(10) Storm Drainage System		

(11) Fencing	·	
(12) Striping Lot		
(13) Landscaping		
	Total_	\$4,500.00
c. Division 3 - Concrete: (1) Footings, Piers, Foundation an	d Slab on Grade:	
(2) Post-Tension Slab on Grade: a. Concrete Testing	-t	
	Total_	\$0.00
d. Division 4 - Masonry:	Total_	\$11,900.00
e. Division 5 - Metals:	Total_	\$650.00
f. Division 6 - Wood and Plastics:	Total_	\$1,500.00
g. Division 7 - Thermal and Moisture Protectio	n Total_	
h. Division 8 - Doors and Windows (1) Doors and Frames		
(2) Sectional Overhead Doors		
(3) Aluminum Storefronts & Glazin	g	
	Total_	\$0.00
i. Division 9 - Finishes (1) Dry Wall		
(2) Acoustical Ceiling		
(3) Resilient Flooring		
(4) Painting	\$2,000.00	
(5) EIFS		
	Total	\$2,000.00

j. Divisi	on 10 - Specialties	Total	
k. Divisi	ion 13 - Special Construction (1) Metal Building Systems (a) Butler Metal Building Package	(Value by Owner)	
	(b) Metal Building Erection		
	(c)Metal Building Insulation	(Value by Owner)	
		Total	\$0.00
I. Divisio	on 20, 21, 22, 23, & 25 - Mechanical (1) Plumbing		
	(2) HVAC (Excluding owner supplied equipment)		
		Total	\$0.00
m. Divis	sion 26 - Electrical	Total	
5 Profit ar	nd Overhead	Total	\$2,600.00
6 Grand	Total	_	\$28,600.00
	id: The Bidder proposes to perform all work required by punt of (fill in words and numbers)	the Contract Documents fo	r
Dollars	(words) Twenty eight thousand six hundred and	i no/100	
the Wor	tes - 01 23 00: If an Alternate is selected by the Owner, rk required by the Contract Documents by increasing or wing amount:		
	a. Alternate No. 1 - 32 11 26 - Hot Mixed Asphalt P Decrease Base Bid by:	aving:	
	b. Alternate No. 2 - 32 80 00 - Irrigation Systems Increase Base Bid by:		
8	Unit Prices - 31 00 00 Earthwork: Any earth excava to that required by the drawings and specifications prices and shall include overhead and profit:		

a. Solid rock excavation, per cu. yd:	
b. Trench rock excavation, per cu. yd:	***
c. Pit rock excavation, per cu. yd:	
d. Trench and pier excavation, per cu. yd:	
e. Trench and pier backfill, per cu. yd:	
f. Mass earth excavation, per cu. yd:	
g. Mass earth backfill, per cu. yd:	
h. Remove and Replace, per cu. yd:	
I. Soil Stabilization, per cu. yd:	
Contractor to list type and method proposed:	
9 Unit Prices - 31 63 00 Bored and Belled Concrete Piers: Drill, Case, Steel Reinforceme Concrete, per L.F. including overhead and profit:	ent,
10 Unit Prices - 03 30 00 Cast-In-Place Concrete: Any concrete, steel reinforcement and f work for foundation footings, walls, and slabs in addition to that required by the drawing specifications shall be paid for at the following unit price, including overhead and profit:	gs and
a. Concrete, steel reinforcement and form work, per cu. yd:	
b. Concrete, steel reinforcement (grade beam), per cu. yd:	
 c. Concrete, steel reinforcement and form work for exterior flat work, per cu. yd: 	
11 By submitting this bid Form, the Bidder certifies that Bidder has visited the project site, aware of existing conditions which affect the work, and has reviewed the Contract Documents, including the following Addenda:	is
(List addenda received)	
12 Time:The Bidder agrees to substanially complete the Work within (fill in) calendar days from the date of Notice to Proceed. (Note: The time stipulated shall not exceed ninety (90) calendar days.)	
13 If awarded the contract, Bidder agrees to enter into and execute a Contract on the basi bid, and to furnish proof of insurance in accordance with the Instructions to Bidders and General Conditions of the Contract for Construction	

14	Firm Name and Addres G. M. Northrup Corpora	
	15950 Franklin Trail S.	F
	Prior Lake, MN 55372	
	952-226-3090	
	Name:	
	Title:	
	Date:	
15	If Bidder is partnership	, list name and title of each partner:
16	If Bidder is a corporation	n, complete the following:
	State and License Num	nber:
	Affix Corporate Seal he	ere (seal):
17	Sub-Contractor Informa	ation:
	A. Demolition	
	B. Sitework	
	C. Landscape	
	D. Asphalt	
	E. Concrete	
	F. Masonry	
	G. Carpentry	
	H. Drywall	
	ı. EIFS	
	J. Glass	
	K. Storefront	
	L. Painting	
	M. Ceilina	


N. PEMB Erection		
O. Plumbing		
P. HVAC	·	
Q. Electrical		
R. Insulation		
S. Asbestos Removal		
Qualifications/Exclusio		

END OF DOCUMENT



FIELD REPORT

(Photos and Drawings must be submitted with Field Report) LOCATION: Store #: 3252 Work Order: 3252-115-B Address: <u>1209 West Seventh Street</u> Coordinator: _Seth Cryer City: __St. Paul Email: scryer@oreillyauto.com State: Minnesota Phone: 417-872-2674 ext 8966 SCOPE OF WORK: Service Type(s): HVAC **ELECT** PLUMB DOOR GLASS CONCRETE **ASPHALT** ROOF PAINT BUILD LNDSCP **FENCE** Violation: Date of Notice: <u>10</u> /_03_/13__ Date of Compliance: <u>12</u> / <u>16</u> /<u>13</u> Y_X__ N (Notify Corporate Immediately of any Safety Concerns) Work Order Description: Provide quote to bring building into compliance **Contractor Findings:** Found missing treads/replaced and refastened loose handrail. Found standing water in the basement and the wooden posts are deteriorating from sitting in water. See Attached photos: Basement floors are dirt - no concrete. **Proposal Details:** (attach quote with itemized breakdown of each corrective item) 1. Replace wooden support columns with steel. 2. Sump out basement (one time), seal and grade exterior of building. 3. Installation of permanent drain field (350 lineal ft around perimeter of basement) and sump. 4. Re-tuck point around building as needed. May 1, 2014 5. Painting of exterior walls at front of store to even out orange color. May 1, 2014 Store Manager Signature: __ Date: <u>12 / 06 / 13</u> Contractor Signature: _____ Date: ____/____/____



Violations:

- Basement Structural Members SPLC 34.10 (2), 34.33 Repair and maintain the damaged structural member. This repair requires a building permit, call DSI at (651) 266-9090.-Replace the damaged/rotted structural posts in the basement with approved material. This work must be done under permit. Contact DSI at 65-266-8989
- Exterior Wall SPLC 34.09 (1) b,c, 34.32 (1) b,c Provide and maintain all exterior walls free from holes and deterioration. All wood exterior unprotected surfaces must be painted or protected from the elements and maintained in a professional manner free from chipped or peeling paint.-The exterior brick wall is damaged/deteriorated. There is missing bricks and mortar. Repair and maintain the exterior wall in an approved manner. This work may require a permit. Contact DSI at 65-266-8989.

Additional Work:

- Sump water out of basement, install drain field and sump pump, connect to city storm sewer system. This work may require a permit. Contact DSI at 65-266-8989.
- Grade and Seal exterior of building at basement wall to eliminate water intrusion

Proposal Details:



Ascential

2200 South Street, Racine 53404 Phone # 800-280-7383 Fax # 262-752-9140 http://www.Ascential.net Client PO # WO-3252-115-A

SERVICE LOCATION


Oreilly Auto Parts Location: 3252 1209 7th St. West St. Paul. MN 55102


SERVICE DESCRIPTION

- 1. Replace wooden support columns with steel.
 - 1 Crew labor for replacing support columns w/ steel
 - 17 Galvanized steel columns and plates
- 2. Sump out basement (one time), seal and grade exterior of building.
- 3. Installation of permanent drain field (350 lineal ft around perimeter of basement) and sump.
 - 1 Crew labor to seal and grade exterior of building
 - 1 crew labor for install in 350 lf of drain field
 - 1 Sealing and grading materials caulk, seed, soil
 - 1 Material for drian field holding tank, pvc, etc.
- 4. Re-tuck point around building as needed.
 - 350 sq ft tuck pointing labor
- 5. Painting of exterior walls at front of store to even out orange color.
 - 1 Crew labor for painting to even out orange color
 - 1 Paint, primer, etc.

Note: Permits are required for proposed work.

Photos:







O'Reilly Auto Parts



FM

NOV 1 3 2013

Invoice # **1114179**

Invoice Date 11/12/2013 Our W/O # 441833

Order Type Exhaust Fan Category HVAC

PØ # WO-3252-118-A

λQ_#_Seth−

BILL TO

2200 South Street

Racine, WI 53404

http://www.Ascential.net

Oreilly Auto Parts 233 S. Patterson Springfield, MO 65802 Phone # 417-862-3694 Fax # 417-747-7153

Phone # 800-280-7383 Fax # 262-752-9140

SERVICE LOCATION

Oreilly Auto Parts Location: 3252 1209 7th St. West St. Paul, MN 55102 Phone # 651-222-1041 Fax #

SERVICE DESCRIPTION

Proposal to remount exhaust fan in men's restroom as needed per qoute. Includes all labor, material and permits.

LABO	R and MATERIALS					
Qty	Description			Man Hour	Unit Price	Total Tax
1	Labor, material, permits	i		1.00	1,296.00	1,296.00
	Required by fire Marshal.					
_	· Remove section of Orop ceiling	ვ _ :	_			
~	Rework/extend exhaust per	code (v	ent)			
-	mount é remire exhaust in de	rop cei ii <u>ng</u>	5			
_	Permit note: includes initial frip.					
•	Vendor#Due	_PO#		Process L	evel	
	Acct Unit G/L Acct. # Activity 3252 78003 SM 6	Category HVAC	Asset Tem		Amount /296.00	
				بدعده هري		
	1/1	,			SC A	n_ 1.
	To	29	선생 교육 기자 유민	en e		2 1213
	Figure OR and Return 10.					,
				s	ubtotal	1,296.00
					Tax	0.00
					Total	1,296.00



SIGN OFF SHEET

44183302



Service Date 11/5/2013 Client PO # WO-3752-118-A Priority Emergency

Order Type Exhaust Fan

2200 South Street Racine, WI 53404 Phone + 900-200-7383 Few # 252-752-91#0 http://www.Ascential.net

SERVICE LOCATION

Only Auto Paris Location 3257 1209 7th St. West 31 Paul MN 55102 Fhone#551-222-0417 Fax#

Service description

PLEASE PHONOE SERVICE TO INSTALL AN EXHAUST FAN IN THE MER'S REST ROOM PER FIRE MARSHAUL

Store Mabager's Signature Print Notae Maj

PO Currem #

SERVICE / INVOICE REQUIREMENTS

- All service instructions must be compiled with to receive credit and proper payment of your invoice.
- This form along with your invoice must be received within 10 days of campithum of work.
- Payment terms are net 45 days from when Ascential receives completed and correct paperwork.
- Invoices and proposals must have a labor at a material breaknown with hourly rate listed.
- Only one invotor will be allowed per work order and the Ascential work order number must be listed an your invoice.
- Your invoices and this signed and store stamped work order must be sent to one of the following:
 - O Email: accig@ascertisl.ret
 - O Fex: 252-581-5050
 - Mail: Ascenda) Service Corporation 2200 South Street, Racine WI 53404

Print Date: 11/05/13

Page 1 of 1



Phone # 800-280-7383 Fax # 262-752-9140

SIGN OFF SHEET

44183304



Service Date 11/7/2013

Client PO # WO-3252-118-A

Priority Emergency

Order Type Exhaust Fan

SERVICE LOCATION

https://www.ascential.net

22/10 South Street

Rzcire, WI 53404

Oreilly Auto Perts Location: 3252 1209 7th St. West St. Paul MN 56102 Phone # 651-222-1041 Fax# (3252)

SERVICE DESCRIPTION

Proposal to remount exhaust tan in men's restroom. Includes all labor, material and permits.

	•
Store Manager's Signature	STORE STAMP
Print Name Date	Mandatory
WO-3757-1/8-A PO Confirm #	
SERVICE / INVOICE REQUIR	FMFNYC
 All service instructions must be compiled with to receive credit and pro This form along with your invoice must be received within 10 days of c Payment terms are net 45 days from when Ascential receives complete Invoices and proposars must have a labor and material breakdown with Only one invoice will be allowed per work order and the Ascential work Your invoices and this signed and store stamped work order must be set Email: accty@ascential.net O Fax: 262-681-5050 	per payment of your invoice. ompletion of work. I and correct paperwork. I hourly rate listed. order number must be listed on your invoice. and to one of the following:
O Mail: Ascential Service Corporation 2200 South Stre	eet, Racine WI 53404

Print Date: 11/08/13

Page 1 of 1



PROPOSAL # 137845

Ascential

2200 South Street, Racine 53404 Phone # 800-280-7383 Fax # 262-752-9140 http://www.Ascential.net

SERVICE LOCATION

Oreilly Auto Parts Location: 3252 1209 7th St. West St. Paul, MN 55102 Phone # 651-222-1041 Fax #

Client PO # Pending Start Date 01/28/14 Quote Date Paperwork Date Order Type HVAC Ref # 455857

SERVICE DESCRIPTION

We offer this proposal to duct the existing fan to the outside per the inspectors request. Includes coverage of additional previous meeting with the inspector to discuss his requirements.

includes all labor and material.

CLIENT PRICING

Description

Proposed

Qty

Qty	Description	Man Hr	Unit Price	Total Ta
1	Labor, Materials, Permit, Inspection	1.00	1,680.00	1,680.00 [
			Sub Total	1,680.00
			Tax	0.00
1			Total	1,680.00

Subtotal 1,680.00 7.625 % Tax 0.00 Grand Total 1,680.00

Print Date: 01/28/14 Linda Juzenas



233 S. Patterson Springfield, MO 65802

Workorder #: WO-3252-115-A Date Issued: 10/14/2013

WORK ORDER REQUEST

Store Information

Store Number

1000

Address

1209 WEST SEVENTH STREET

ST PAUL, MN 55102-3900

Manager

ERIC SHOALS

Phone

(651)-222-1041

Requestor Information

Name

Seth Crver

Phone

(417)-862-2674 Ext.8966

Fax

(417)-874-7153

Email

scrver@oreillyauto.com

Vendor Information

Name

ASCENTIAL - RACINE, WI

Attn:

RYAN RIGGS

Address

2200 South Street

Racine, WI 53404

Phone

(800)-280-7383 (262)-752-9140

Fax Email

service@ascential.net

Billing Information

Preferred Method - Email: PAYMEMAINT@MAIL.COM

Or Mail/Fax to:

O'Reilly Auto Parts

Attention: Store Maintenance Department

233 S. Patterson Springfield, MO 65802

Con /447) 074 7450

Fax (417)-874-7153

Email scryer@oreillyauto.com

Description of Request

Requested Completion Date: 10/18/2013

· Urgency: 2/3 day

· If work cannot be completed by above date please call Corporate Office Immediately!

· Request Type: Building | Remodel

· Location: Showroom

Description: Requested by Fire Marshal - (1) Repair basement stair tread that is damaged - (2)Secure loose handrail in basement stairwell - (3) Assess and quote replacement of wooden basement support columns with steel post (provide photos of existing) - (4) Assess and quote tuck pointing exterior of building and painting the front of the building to match existing

Additional Requirements

Not to Exceed \$1,000.00

DO NOT perform any work beyond the scope described without contacting the Maintenance Department for further approval. Any work that exceeds the "Not to Exceed" amount will not be paid without prior approval. Service Order Documentation or Work Order must be stamped by the manager on duty and accompany the invoice for prompt payment. By performing the work contained on this Work Order, Contractor is agreeing to the terms and conditions of our independent contractor indemnification agreement incorporated herein by reference. Contractor agrees to furnish all labor and materials necessary to perform and complete the Services. Contractor's Services shall be performed within the limits prescribed by O'Reilly in a manner consistent with the level of care, skill and judgment exercised by other professional contractors in performing services of a similar nature under similar circumstances. Contractor shall maintain at all times during the performance of Services hereunder statutory worker's compensation and employer's liability insurance. Contractor and O'Reilly will comply with all applicable federal, state, and local laws including environmental laws, in effect at the time series are performed.

BROADMEW

BUILDERSINC

February 25, 2013 2014

O'Reilly Auto Parts 233 S Patterson Springfield, MO 65801 A Commercial Contractor
Working For Your Business

Attn: Seth Cryer

scryer@oreillyauto.com

p 417-862-2674 ext 8966

800-288-6661 ext 8966

f 417-878-7153

Re: O'Reilly Auto Parts

1209 West Seventh Street

St Paul, MN

Sub: Exterior wall repair and basement water repair

WO-3252-115-B

Dear Seth.

Thank you, for the opportunity to price your project. This proposal is for your consideration and the following scope of work itemizing the project for your review.

Description:

General Conditions, permits, insurance, proper trash removal, job specific support. This quote is to include only the items noted below and is not intended to bring the remainder of the building to code. This quote does not include engineering and/or testing. No SAC and Wac fees are Included, if they are required. Existing debris in basement is to remain as instructed by owner. All mechanical, electrical and structural issues to be address separately, if required. Existing stair to remain (no work) as directed by owner.

Replace wooden post with new post on existing pads. Engineering required to size post (allowance \$2,500.00).

\$24,558.00



Done Right. Right Now. www.minercorp.com

BILLTO

INVOICE

Miner Fleet Mgmt Group Ltd. 17319 San Pedro Suite 500 San Antonio, TX 78232 (210) 892-1001

MAY 1 3 2016

Invoice No:	MFM-1184156-IN
Date:	5/6/2014

	CUIDTO	
Part of the second of the seco	SHIPHUN	

Customer Number: 90-0201437 O'REILLY AUTO PARTS 645 E. MISSOURI AVE ATTN: STORE ADMIN PHOENIX, AZ 85012

Order Number: 0332693 ★ 096N € A>D

O'REILLY AUTO PARTS 3252 1209 W SEVENTH ST SAINT PAUL, MN 55102

CUSTOMER4	P-9-34 (A)	CUSTOMER	REFERENC	EAL	WORK.COM	MPLETED OF		TERMS		
WO-3252-117	7-A	S.0	RYER		1/18/2014			STANDARD 30		
PEM	NUMBERAN	DESCRIPTION			ORDERED	SHIPPED	e B/O	PRICE	TOTAL	
TROUBLESHOT LOCK								14-24-14-15-15-15-15-15-15-15-15-15-15-15-15-15-	The Charles of the Ch	
AND FOUND THE FOLL PANIC DEVICE	LOWING PRO	BLEMS:								
THE FOLLOWING	G WORK V	VAS PERFORM	ED:			1		1		
]		
TESTED LOCK FOR PR THE STORE MANAGER	R OPE R OPER/ R.	ATION. CHECKED O	HTIW TU		i i					
LABOR SERVICE					6.00	6.00	0.00	85.00	510.00	
MATERIALS				:	1.00	1.00	0.00	279.50	279.50	
LABOR TO FURNISH AND INSTALL (1) 32" CLEAR ANO PULL BAR AND (1) MORTISE DUMMY CYLINDER ON THE DOOR, LABOR TO FURNISH AND INSTALL (1) PADDLE AND (1) THUMBTURN COMBO SET ON THE DOOR AT THIS LOCATION.						;	West of the Control o			
		Ä	Peguired	by Ci	ty.	1				
Ve	endor#	Due)	PO :	<u> </u>	Pr	oress Level			
A	cct Unit	G/L Acct.#	Activity	Categ	orv Asse	l Tempi	Ame	unt		
	3252	780000	Sm5				1	82		
										
_							*			
To	`		ate 69		ital & Data i	inoroved	25	angung pangganan an mandah yar		
			=	6	üai & Date /	J.P.P. 0 100				
Ple	ease OK a	and Return To:						,		
			Б.				1			
			1	remit to: iner Fleet	Management (Group	Net In Less Dis		\$789.50	
			17	'319 San P	edro, Ste. 500			s Tax:	\$0.00 \$21.32	
				n Antonio	o, TX 78232 1		Invoice 1		\$810.82	



Date Beuer 118/2013 O SELENALITO MATA SIG Kequered Cover Page FUE BUILD THE SAID FASTERSHE INVOLUE AND DROMADEL FOR PARMENT 10-51 Br 30-01 021 E PAMIC DEVICE, WEED INSTALLED, WEED TO KEWET naliyay vesterile ooga keeds gereh gan katalled keeds to be able 70 de lockeb, chaq bolt SEMOVED. on door to back alley, the cora ethert hide hollow wetal doub may seed bank devole and obnic Check in with Minmar at Damage des Abuse 3rd Ferty Democ Wester/Researin Daires productive modulo uchien reside begindriep is the seconnermon that in the seconnerm of the second second second OBTAIN SIGNATURE FROM HOLD ACCUPTING THE YORK PERFORMED TO GATHFACTION CHECK DUT TITE HIGH RAY THE THE WAS A CONTROL Hasandalah a Avi 💎 Tuc Kobho Avi Time in: Miner Fleet Merzgement dirury 800-342-6835 fex: 210-818-4384 Sensus father EC@nifrerorp.com



2200 South Street
Racine, WI 53404
Phone # 800-280-7383 Fax # 262-752-9140
http://www.Ascential.net

BILL TO

Oreilly Auto Parts 233 S. Patterson Springfield, MO 65802 Phone # 417-862-3694 Fax # 417-747-7153 Invoice # **1148341**

Invoice Date 8/5/2014 Our W/O # 436595

Order Type Misc. Exterior Repair Category General Repair

PO # WO-3252-115-**&**

WO # Seth

SERVICE LOCATION

Oreilly Auto Parts Location: 3252 1209 7th St. West St. Paul, MN 55102 Phone # 651-222-1041 Fax #

SERVICE DESCRIPTION

Provided service to complete the following as needed per quote:

- 1. Replaced wooden support columns with steel.
- 2. Sump out basement (one time), sealed and graded exterior of building.
- 3. Installation of permanent drain field (350 lineal ft around perimeter of basement) and sump.
- 4. Re-tuck pointed around building as needed.
- 5. Painted exterior walls at front of store to even out orange color.

Includes all additional work approved.



LABO	R and MATERIALS			
Qty	Description	Man Hour	Unit Price	Total Tax
1	350 sq ft tuck pointing labor	1.00	1,596.00	1,596.00
1	crew labor for install in 350 lf of drain field	1.00	2,400.00	2,400.00
1	Crew labor for painting to even out orange color	1.00	1,876.00	1,876.00
1	Crew labor for replacing support columns w/ steel	1.00	4,760.00	4,760.00
1	Crew labor to seal and grade exterior of building	1.00	1,900.00	1,900.00
1	Incurred Labor	3.00	45.00	135.00
1	Labor for rebuilding handrail and stair tread	6.00	60.00	360.00
1	Labor/Material	1.00	2,206.00	2,206.00
17	Galvanized steel columns and plates		160.00	2,720.00
1	Material for drian field - holding tank, pvc, etc.		1,200.00	1,200.00
1	Materials for handrail and tread repair.		210.00	210.00
1	Paint, primer, etc.	-,	580.00	580.00
1	Sealing and grading materials - caulk, seed, soil		560.00	560.00
1	Overhead & Profit		2,460.36	2,460.36
				· •
	4 1 2 \$ 1			

Print Date: 08/11/14 Heidi Robedeau

75.565	Acot Unit G/L Acot 325 2 1600		# 3252-115-C Pro egory Asset Tempi	Amount
	-			_ 23,365
		Photographic Action		

•

· 1



2200 South Street Racine, WI 53404 Phone # 800-280-7383 Fax # 262-752-9140 http://www.Ascential.net

BILL TO

Oreilly Auto Parts 233 S. Patterson Springfield, MO 65802 Phone # 417-862-3694 Fax # 417-747-7153 Invoice # **1148341**

Invoice Date 8/5/2014 Our W/O # 436595

Order Type Misc. Exterior Repair

Category General Repair

PO # WO-3252-115-A

WO # Seth

SERVICE LOCATION

Oreilly Auto Parts Location: 3252 1209 7th St. West St. Paul, MN 55102 Phone # 651-222-1041 Fax #

 Subtotal
 22,963.36

 7.625 % Tax
 401.84

 Total
 23,365.20