

CITY OF SAINT PAUL Christopher B. Coleman, Mayor 375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806 *Telephone:* 651-266-8989 *Facsimile:* 651-266-9124 *Web:* <u>www.stpaul.gov/dsi</u>

Code Compliance Report

May 31, 2013

JOHN SCHUSTER GROUP 2201 E OLD SHAKOPEE RD BLOOMINGTON MN 55420-2172 * * This Report must be Posted on the Job Site * *

Re: 106 King St E File#: 13 180054 VB2

Dear Property Owner:

The following is the Code Compliance report you requested on May 08, 2013.

Please be advised that this report is accurate and correct as of the date May 31, 2013. All deficiencies identified by the City after this date must also be corrected and all codes and ordinances must be complied with. This report is valid for 365 days from May 31, 2013. This report may be used in lieu of a Truth in Housing Report required in St Paul Legislative Code 189. This building must be properly secured and the property maintained at all times.

In order to sell or reoccupy this property the following deficiencies must be corrected:

<u>ZONING</u>

- 1. This property is in a(n) RT1 zoning district.
- 2. This property was inspected as a Single Family Dwelling.

BUILDING Inspector: Jim Seeger

Phone: 651-266-9046

- Dry out basement and eliminate source of moisture.
- Remove mold, mildew and moldy or water damaged materials.
- Install handrails (34 inches 38 inches above each nosing) and guardrails (36 inch minimum) at all stairways, and return hand rail ends into a newel post or wall per attachment.
- Repair or Replace any deteriorated window sash, broken glass, sash holders, re-putty, etc as necessary.
- Provide complete storms and screens, in good repair for all door and window openings.
- Provide functional hardware at all doors and windows
- Weather seal exterior doors, threshold and weather-stripping.
- Install floor covering in bathroom and kitchen that is impervious to water.
- Repair walls, ceiling and floors throughout, as necessary.
- Provide fire block construction as necessary and seal chases in basement ceiling.

Re: 106 King St E May 31, 2013 Page 2

BI	UILDING Inspector: Jim Seeger	Phone: 651-266-9046	
٠	• Prepare and paint interior and exterior as necessary. Observe necessary abatement		
	procedures (EPA, MPCA and St. Paul Legislative Code, Chapter 34 for additional		
	information) if lead base paint is present.		
٠	Air-seal and insulate attic/access door.		
٠	Install Smoke Detectors/Carbon Monoxide Detectors per MN Conservation Code and the		
	MN Dept. of Labor and Industry: Install per code where feasi	ble.	

- Provide major clean-up of premises.
- Repair siding, soffit, fascia, trim, etc. as necessary.
- Provide proper drainage around house to direct water away from foundation of house.
- Provide proper drainage around house to direct water away from foundation of garage.
- Install downspouts and a complete gutter system.
- Provide general rehabilitation of garage.
- Install address numbers visible from street and on the alley side of garage.
- Provide ground cover capable of controlling sediment and erosion.
- Openings in stair risers must be less than 4 inches.
- Grade must drain away from foundation of dwelling. Maintain 6 inch clearance between wood and soil.
- Install wall in west side yard to remove water from against foundation and around building.
- Remove south side brickwork by window and repair framing window and trim before brick reinstalled. (Install weather barrier on sheathing.)
- Replace decayed post in basement.
- Replace kitchen ceiling after removing old one. Call for inspections.
- Replace all siding on east side of porch.
- Replace steps from yard to garage.
- Remove trash from behind garage.
- Provide 6 inch clearance from garage to wood on garage.
- Replace or repair overhead garage door.
- Replace all decayed studs, trim, framing and fascia on garage.
- Repair garage roof covering as needed and replace house roof covering.
- A building permit is required to correct the above deficiencies.

ELECTRICAL Inspector: Steve Reimers Phone: 651-266-9037

- Bond around water meter with a copper wire sized for the electrical service per Article 250 of the NEC
- Provide a complete circuit directory at service panel indicating location and use of all circuits
- Verify that fuse/circuit breaker amperage matches wire size
- Close openings in service panel/junction boxes with knockout seals, breaker blanks, and/or junction box covers
- Properly strap cables and conduits in basement/ service conduit on the exterior of the house.
- Remove all cord wiring
- Check all outlets for proper polarity and verify ground on 3-prong outlets
- Remove any 3-wire ungrounded outlets and replace with 2-wire or ground 3-wire to code

Re: 106 King St E May 31, 2013 Page 3

ELECTRICAL Inspector: Steve Reimers

Phone: 651-266-9037

- Repair or Replace all broken, missing or loose light fixtures, switches and outlets, covers and plates
- Install hard-wired, battery backup smoke detector and other smoke detectors as required by the IRC. Also, Install carbon monoxide detector(s) within 10 feet of all bedrooms
- Properly wire exterior lights at front/side/back door
- Remove and or/ re-wire all illegal, improper or hazardous wiring in basement/garage
- Replace all painted-over receptacles.
- Purchase permit for 10 circuits.
- All added receptacles must be grounded, tamper-resistant and be on an Arc-Fault Circuit Interrupter-protected circuit.
- Any open walls or walls that are opened as part of this project must be wired to the standards of the current NEC.
- All electrical work must be done by a Minnesota-licensed electrical contractor under an electrical permit.

PLUMBING Inspector: Troy McManus Phone: 651-266-9053

- Basement Water Heater Vent must be in chimney liner (MFGC 501.12)
- Basement Water Heater not fired or in service (MPC 2180)
- Basement Water Meter raise meter to a minimum 12 inches above floor (MPC 2280)
- Basement Water Piping pipe sizing incorrect (MPC 4715.1730)
- Basement Water Piping repair or replace all corroded, broken or leaking piping (MPC 4715.1720)
- Basement Water Piping run 1 inch water line from meter to first major take off (SPRWS Water Code)
- Basement Soil and Waste Piping replace the floor drain cover or clean out plug (MPC 1300)
- First Floor Gas Piping replace corroded piping (MMC 103)
- First Floor Gas Piping replace improper piping or fittings (MFGC 411)
- First Floor Sink waste incorrect (MPC 2300)
- Second Floor Toilet Facilities reset the toilet on a firm base (MPC 0870)
- Second Floor Tub and Shower Provide a vacuum breaker for the handheld shower (MPC 2000 B)
- Second Floor Tub and Shower faucet is missing, broken or parts missing (MPC 0200. P.)
- Second Floor Tub and Shower provide anti-scald valve (MPC 1380. Subp. 5)
- Second Floor Tub and Shower provide stopper (MPC 1240)
- Exterior Lawn Hydrants Requires backflow assembly or device (MPC 2000)
- Exterior Piping Vents improper location (MPC 2530 Subp. 3)
- All the above corrections to waste, vent, water, and gas piping shall be per the Minnesota Plumbing Code Chapter 4715 & Chapter 326, the Minnesota Mechanical Code, the Minnesota Fuel Gas Code, and the Saint Paul Regional Water Code. All plumbing must be done by a plumbing contractor licensed in the State of Minnesota and the City of St. Paul under an approved permit.

HEATING Inspector: Gary Stevens Phone: 651-266-9045

- Clean and Orsat test furnace burner. Check all controls for proper operation. Check furnace heat exchanger for leak; provide documentation from a licensed contractor that the heating unit is safe
- Vent clothes dryer to code
- Provide adequate combustion air and support duct to code
- Provide support for gas lines to code
- Plug, cap and/or remove all disconnected gas lines
- All supply and return ducts for warm air heating system must be clean before final approval for occupancy. Provide documentation from a licensed duct-cleaning contractor that the duct system has been cleaned.
- Repair and/or replace heating registers as necessary
- Provide heat in every habitable room and bathrooms
- Mechanical permits are required for the above work.
- Provide return air from habitable rooms on 2nd floor according to code

Notes:

- See attachment for permit requirements and appeals procedure.
- Interior of garage not available for inspection. Repair per applicable codes.

This is a registered vacant building. In order to sell or reoccupy this building, all deficiencies listed on this code compliance report must be corrected in accordance with the Minimum Housing Standards of the St. Paul Legislative Code (Chapter 34) and all required permits must receive final approval within six (6) months of the date of this report. One (1) six-month time extension may be requested by the owner and will be considered if it can be shown that the code compliance work is proceeding and is more than fifty (50) percent complete in accordance with Legislative Code Section 33.03(f).

You may file an appeal to this notice by contacting the City Clerk's Office at 651-266-8688. Any appeal must be made in writing within 10 days of this notice. (You must submit a copy of this notice when you appeal, and pay a filing fee.)

If you have any questions regarding this inspection report, please contact Jim Seeger between 7:30 - 9:00 AM at 651-266-9046 or leave a voice mail message.

Sincerely,

James L. Seeger, Code Compliance Officer Phone: 651-266-9046 Email: jim.seeger@ci.stpaul.mn.us