

а п п

🖯 Other (Fence Variance, Code Compliance, etc.)

APPLICATION FOR APPEAL

Saint Paul City Council – Legislative Hearings

RECEIVED NOV 30 2017

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8585

	VIIY CLE	*** I ~	
We need the following to process yo	ur appeal:	K.	
\$25 filing fee (non-refundable) (paya (if cash: receipt number) etter being appealed clude	HEARING DATE & TIM (provided by Legislative Tuesday, Decemb Time 11:30 a.m Location of Hearing: Room 330 City Hall/Cou	Hearing Office)
Address Being Appe	ealed:		
Number & Street: 1464 MM Appellant/Applicant: Ryan Ke	rehala frew City:51	Paul State: MA	Zip: 55/04
Appellant/Applicant: 1140 110	En En	nail MINOCO 1	Live, wig
Phone Numbers: Business	Residence	Cell 612.	986-1896
Signature:		Date: 11/30/	17
lame of Owner (if other than Appellar	nt):		
Mailing Address if Not Appellant's:			
hone Numbers: Business	Residence	Cell	
Vhat Is Being Appear Vacate Order/Condemnation/ Revocation of Fire C of O Summary/Vehicle Abatement Fire C of O Deficiency List/Corrections	Wereed more we need more on vacate	Attachments Are Active to fix	sceptable itons Roomstes to
Code Enforcement Correction Notice	ce Zuaing needs	more time to	re zne to
Vacant Building Registration			Lublet



CITY OF SAINT PAUL Christopher B. Coleman, Mayor 375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806 Telephone: 651-266-8989 Facsimile: 651-266-8951 Web: www.stpaul.gov/dsi

November 27, 2017

Ryan Kempenich 1464 Minnehaha Ave West St. Paul, MN 55104-1950

NOTICE OF CONDEMNATION UNFIT FOR HUMAN HABITATION ORDER TO VACATE

RE:

1464 MINNEHAHA AVE W

Ref. #

Dear Property Representative:

Your building was inspected on November 22, 2017.

The building was found to be unsafe, unfit for human habitation, a public nuisance, a hazard to the public welfare or otherwise dangerous to human life. A Condemnation Placard has been posted on the building.

The following deficiency list must be completed or the building vacated by the re-inspection date.

A re-inspection will be made on December 11, 2017 at 3:00 PM.

CONDEMNATION OF THE BUILDING REVOKES THE CERTIFICATE OF OCCUPANCY.

Failure to complete the corrections may result in a criminal citation. The Saint Paul Legislative Code requires that no building be occupied without a Fire Certificate of Occupancy.

DEFICIENCY LIST

1. SPLC 34.23, MSFC 110.1 - This occupancy is condemned as unfit for human habitation. This occupancy must not be used until re-inspected and approved by this office. Building has been condemned for multiple code violations including; use as an illegal rooming and boarding house, attic unit illegally constructed without permit, basement in use as a sleeping area without necessary egress.

2. Interior - Dwelling - SPLC 62.101 - Use of this property does not conform to zoning ordinance. Discontinue unapproved use or call DSI Zoning at (651) 266-8989 to convert to legal use.

Per Zoning Enforcement Notice dated June 29, 2015:

In order to bring the property into zoning compliance you must: Remove the illegal dwelling units and operate the property as a single family dwelling with no more than a total of four (4) unrelated adults. All applicable building permits must be obtained prior to conducting the required work. The sinks, cabinets, and appliances must be removed from all the additional units. The utilities (gas, water, 220v electric) in the rooms with the additional kitchens must be capped at the source. The property could be used as a duplex but will require a variance from the Board of Zoning Appeals due to the proximity to the lot line. There is an application to be submitted, a filing fee, site and floor plans are required. In addition, construction plans and permits will be required for all the work to be completed as a duplex.

- 3. 1aInterior Dwelling MSBC 1300.022 Subp. 3 The occupancy group or use division of this building has been changed from that previously approved.

 Discontinue the unapproved occupancy or use, or contact the Building Official at 651-266-8989 with your code analysis and to comply with requirements for approved occupancy. Property sold in 2011 as single family home with unfinished attic.
- 4. Exterior Gas Heater in Garage SPLC 34.12 (2), SPLC 34.36 (1) Repair and maintain all required and supplied equipment in an operative and safe condition to properly and safely perform their intended function in accordance with the provisions of the applicable code.
 Property owner stated heater no longer works. Repair the heater to work or remove from garage with appropriate disconnection of gas lines.
- Exterior West Side Porch and Attic Apartment SPLC 34.09 (3), 34.33(2) Repair or replace the damaged guardrail in an approved manner. This work may require a permit(s). Call DSI at (651) 266-8989.Missing and broken guardrails on porch.
 Missing guardrail at attic stairway to second level.
- Exterior Window Opening to West Porch SPLC 34.09 (4), 34.33 (3) Repair and maintain the window glass. Door to west side porch, opens into window and window glass/frame are broke out of window.
- 7. Exterior Outside the Dwelling SPLC 34.08 (6) Remove the accumulation of exterior storage that creates a nuisance or harbors rodents.-Exterior excessive storage material including abandon vending machine, construction debris.
- 8. Exterior/Interior MSFC 603.6 Have the chimneys, fireplaces, and vents inspected for soundness, freedom from deposits, and correct clearances. Cleaning, maintenance, and repairs shall be done if indicated by the inspection.-

- 9. Interior Attic Stairwell SPLC 34.10 (3) 34.34(2) Provide an approved guardrail. Intermediate balustrade must not be more than 6 inches apart. Intermediate rails must be provided if the height of the platform is more than 30 inches.-
- 10. Interior Basement Clothes Dryer vent MMC 504.6 Provide, repair or replace the dryer exhaust duct. Exhaust ducts for domestic clothes dryers shall be constructed of metal and shall have a smooth interior finish. The exhaust duct shall be a minimum nominal size of four inches (102 mm) in diameter and installed in accordance with the mechanical code. This work requires a licensed contractor to obtain a permit(s) for the installation and contacting city inspection staff for an appointment to review the work and finalize the permit. Call DSI at (651) 266-8989.-
- 11. Interior Basement Stairs SPLC 34.10 (3), 34.34(2) Provide an approved handrail. The top of the handrail must be between 34 and 38 inches above the treads and run the entire length of the stair.-Provide handrail for basement stair case.
- 12. Interior Bathrooms SPLC 34.14 (3), MPC 4714.01 (T) Provide and maintain a window or approved ventilation system in all bathrooms.
 No openable window or exhaust fan duct to the exterior of the dwelling at basement bath, second floor bath.
- Interior Ceiling Lighting MSFC 605.6 Provide all electrical splices within junction boxes. Light fixtures hanging from wires in ceiling, no visible junction box, wires and wirenuts exposed.
- 14. Interior Check All NEC 410-8 (b) (1) Provide for the incandescent fixtures in closets to have a completely enclosed lamp.-
- 15. Interior Check Throughout SPLC 34.11 (1), MSBC 2902.1, SPLC 34.35 (1), MPC 301.1 Repair or replace and maintain all parts of the plumbing system to an operational condition.- Secure toilets throughout dwelling. Basement laundry sink faucet leak.
- 16. Interior Dwelling and Accessory Structures SPLC 34.24, MSFC 110.1 This occupancy is condemned as unsafe for human habitation. This occupancy must not be used until re-inspected and approved by this office.-
- 17. Interior Furnace testing SPLC 34.11 (6), 34.35 (3) Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.-

18. Interior - Main Floor - MSFC 803.1 - Wall and/or ceiling finishes exceed the code requirements for flame spread ratings. Remove or provide documentation of flame spread compliance.-

Foam installed on interior of door not approved for installing. Provide documentation that the material has been rated for installation on interior of dwelling or remove from door.

Material installed on walls in carriage house is not fire-rated. Carpet underlayment between floor joists in basement.

- 19. Interior Refrigeration Unit –Second Floor NEC 440.13 For cord-connected equipment such as: room air conditioners, household refrigerators and freezers, drinking water coolers, and beverage dispensers, a separable connector or an attachment plug and receptacle shall be permitted to serve as the disconnecting means. The appliance must plug directly into a permanent outlet.-
- 20. Interior See Comments SPLC 34.14 (2), 34.34 (5) Provide an approved electrical service adequate to meet the building's needs. This work will require a licensed contractor to obtain permit(s) and contact city inspection staff for an appointment to review the installations and finalize the permit. Call DSI at (651) 266-8989.

 Throughout dwelling to finished attic.

 Exterior mast location.
- 21. Interior See Comments MPC 312, 313 Provide approved support for all plumbing piping.Multiple water and sewer piping installed in basement without proper supports. Piping is spray painted in many areas, unable to determine dates.
- 22. Interior Throughout MN Stat. 299F.362 Immediately provide and maintain a hard wired smoke detector located within each unit.
 Leave detector wires visible for re-inspection. Once a unit is hard wired, it has to stay hard wired.
- 23. Interior Throughout MN State Statute 299F.50 Immediately provide and maintain an approved Carbon Monoxide Alarm in a location within ten (10) feet of each sleeping area. Installation shall be in accordance with manufacturers' instructions.-
- 24. Interior Throughout NEC 110-12 Provide for the electrical equipment to be installed in a neat and worker like manner.-Ceiling lighting observed in main floor dining area without junction box for splices, fixture hanging from wires.

Ceiling lighting in attic apartment bath with unsealed opening to fixture.

Wiring in basement not to electrical code (dated May 19, 2016), no permit associated with material dates.

Subpanel installed, no permit associated with dates.

Wiring bundled together with duct tape (romex, low voltage wire) not secured to structure, installed improperly.

Wiring wrapped around water line in laundry area, not secured to structure, outlet (non GFCI) not secured to structure.

- 25. Interior - Throughout - MSFC 315.3 - Provide and maintain orderly storage of materials.-Excess material located on 1st floor living room, hall way, and garage stairway.
- Interior Throughout MSFC 605.1- All light fixtures shall be maintained with 26. protective globes if originally equipped.-Multiple rooms are missing light fixture covers.
- Interior Throughout Dwelling MSFC 605.6 Provide electrical cover plates to all 27. outlets, switches and junction boxes where missing.-

Observed in second floor kitchen behind kitchen range.

Observed in garage.

Observed in carriage house.

Observed in basement.

- 28. Interior - Throughout Dwelling - MSFC 605.1 - Repair or replace damaged electrical fixtures. This work may require a permit(s). Call DSI at (651) 266-8989.
- 29. Interior - Throughout Dwelling - MSFC 605.4 - Discontinue use of all multi-plug adapters.-Observed in attic apartment. Second floor apartments.
- 30. Interior - Throughout Dwelling - MSFC 1030.2 - Remove the materials that cause an exit obstruction. Maintain a clear and unobstructed exit path..-South East Main floor bedroom- excess material block emergency window egress. Second floor unit has screws in window sash openings to prevent opening the window.
- 31. Interior - Throughout Dwelling - SPLC 34.09 (4), 34.33 (3) - Repair and maintain the window in good condition.-2nd Floor windows and South 1st Floor window, painted shut, check all.
- 32. Interior - Throughout Dwelling - SPLC 34.09 (4), 34.33 (3) - Repair and maintain the window sash.-2nd Floor bedroom- torn sash cords, check all.
- 33. Interior - Throughout Dwelling and Garage - MSFC 605.5 - Discontinue use of extension cords used in lieu of permanent wiring.-Attic apartment. Second floor efficiency unit for refrigeration. Basement crawlspace under porch.
- 34. Interior - Water Meter - MSFC 605.1 -Provide a grounding jumper around the water meter.-

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8585) and must be filed within 10 days of the date of the original orders.

If you have any questions, email me at: laura.huseby@ci.stpaul.mn.us or call me at 651-266-8998 between 7:30 - 9:00 a.m. Please help make Saint Paul a safer place in which to live and work.

Sincerely,

Laura Huseby Fire Inspector Ref. #

cc: Housing Resource Center

Force Unit



CITY OF SAINT PAUL

Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Telephone: 651-266-8989 Saint Paul. MN 55101-1806 Fax: 651-266-8951

November 9, 2017

CORRECTION NOTICE - COMPLAINT INSPECTION

Ryan Kempenich

RE: 1464 MINNEHAHA AVE W

St. Paul, MN 55104-1950

Ref. # 14641

Dear Property Representative:

An inspection was made of your building on November 9, 2017 in response to a referral. You are hereby notified that the following deficiency list must be corrected immediately.

A re-inspection will be made on November 22, 2017 at 10:00 AM.

Failure to comply may result in a criminal citation or revocation of the Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Certificate of Occupancy. The code also provides for the assessment of additional re-inspection fees.

DEFICIENCY LIST

- 1. Interior Dwelling and Accessory Buildings SPLC 34.19 Provide access to the inspector to all areas of the building.-
- 2. Interior Throughout MSFC 901.6 Have fire extinguisher recharged and tagged.-
- 3. Interior Throughout MN Stat. 299F.362 Immediately provide and maintain a smoke detector located outside each sleeping area.-
- 4. Interior Throughout MN State Statute 299F.50 Immediately provide and maintain an approved Carbon Monoxide Alarm in a location within ten (10) feet of each sleeping area. Installation shall be in accordance with manufacturer's instructions.-

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8585) and must be filed within 10 days of the date of the original orders.

If you have any questions, email me at: laura.huseby@ci.stpaul.mn.us or call me at 651-266-8998 between 7:30 a.m. - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Laura Huseby Fire Inspector

Ref. # 14641

INSPECTION REQUEST

Address this form to: MAILING LIST - FORM4 (District Chief, Deputy Chiefs and Yourself).

Date:	24 OCT 17			
Property Address:	1464 MINNEHAHA AVE			
Owner Name:	RYAN KEMPENICH			
Owner Phone:	612.986.1896			
Owner Address:	SAME			
Occupant Name:	SAME			
Occupant Phone:	SAME			
Check the following cor	rrections:			
☐Address Nos. ☐Exit Doors ☐Housekeeping ☐Keybox ☐Sprinkler System Check the type of	☐ Hydrants ☐ Hazardous Material ☐ Fire Alarm System ☐ Smoke Detector ☐ Standpipe ☐ Heating Plant ☐ Welding ☐ OTHER EXIT ☐ LIGHTING, EMERGENCY ☐ LIGHTING, HAND RAILS, ☐ MEANS OF EGRESS			
Check the type of property:	Single family or duplex Multi family (3 Units or more) Commercial			
Describe:	UPON ARRIVAL, S2 RECOGNIZED THE SINGLE FAMILY DWELLING HAS BEEN CONVERTED TO MULTIPLE APT UNITS. THERE APPEARS TO BE INCONSISTENT PLACEMENT OF SMOKE DETECTORS IN COMMON AREAS, LACK OF FIRE EXTINGUISHERS, EMERGENCY LIGHTING, EXIT SIGNS, HAND RAILS, AND POSSIBLY MAY NEED A KEY BOX.			
Name: DD JONES	Rank: CAPTAIN	Company: SQ2		
Response:				
Name:	Date:	Phone:		

Property Identification Number (PIN) 34.29.23.22.0001

Property Address 1464 Minnehaha Ave W Municipality St. Paul Watershed Capital Region W/S School District Number 625

Residential Property:

Year Built 1891

of Stories 2.00

Style Two Story

Exterior Wall Frame

Total Rooms 9

Total Family Rooms 0 Total Bedrooms 6

Full Baths 3 Half Baths 0

Attic Type Unfinished

Finished SQ Feet 2996

Foundation Size 1588

Basement Area Finished

Petra Kar Sein uft Petra en ift remen.



1464 Minnehaha Street Name: House#:

Last updated from Ramsey County data on: 11/18/2017

Click on "Other Application" links below to access GISmo, MapIT, and Ramsey County Info

1464 Minnehaha Ave W - 55104-1950 - Other Applications

PIN: 342923220001 Year Built: 1891

Census Track: 32200 Foundation Sq Feet: 2996

Census Block: 3004 Loan Company:

Council Ward: 4 Land Value: 45500

District Council Building Value:

ISP:

Units: 1

Ramsey County Usage: 520 - TWO FAMILY DWELLING, PLATTED LOT

Zoning: RT1

Heritage Preservation: HP Inventory #: RA-SPC-4621 / HP Property Name: Frederick M. Grant House / HP Date Built: 1891 / HP Address: 1464 Minnehaha Ave. W

Legal Desc: Mccaskeys Rearrangementof Bi Lots 1 And Lot 2 Bik 1

Ryan Kempenich/Kristal Kempenich 1464 Minnehaha Ave W Saint Paul MN 55104-1950 612-986-1890

6 77 6 Column State of the Column

	3.6		Office Use, ONLY;	
	oke detectors(s) M	St. Paul Truth-In-Sale of F	Tousing Date Recived.	
	operly located Mard-Wired * M	(Carefully read this entire re		
	ard-wired * .M f N or H see note on p.3, item 3		Page 1	of 4
" []			-	
	TICKTOUTH TITLE AND THIS	A WARRANTY, BY THE CITY OF ST. PA E FUTURE CONDITION OF ANY BUILDIN	EST THEFT FINANTIES REALISING	
	Notice: A copy of this Ret	port must be publicly displayed at the premises very must be provided to the buyer prior to the	when the house is shown to prospective buyer	rs, 🗧
	and a copy of this R	deport must be provided to the buyer prior to the	time of signing a Purchase Agreement.	Address
	Address of Evaluated	Dwelling: 1. 1464 MINNEH	AHA AVE WEST	
		2.		
	Owner's Name: RY			🚉
	Owner's Address: 14	464 MINNEHAHA AVE W		1464 Minnehaha Ave
	Realtor/Contact:			ha
	Current Hears of	gle Family Townhouse C	ondo* *For condominium units, this evaluation include	_{ss} ⊢ha
	this dwelling:	gle Family Townhouse C	ondo* *For condominium units, this evaluation include only those located within the residential units and does not include the common use area,	
	Comments		or other residential areas of the structure.	· è
	Comments: Duplex usage	e may not be legal. See below		— ∣≰
		:		West
			NY DEPORTATION	
	PROPERTY LOCA	TION AND POSSIBLE RESTRICTION information does not apply to this dwelling. This info	ON INFORMATION rmation is not quaranteed by the evaulator	r
	if a box is not checked then the son by the City of St. Paul.	information does not apply to this aweiting. Trees erefor	11000 000 1000 0000 00 000 00 00000000 00	•
	According to information	provided to Truth-In-Sale of Housing Evaluator	s by the City of St. Paul Office this property:	
	* IS A Registered Vacant	Building. The conditions applicable to a sale are differe	nt by category.	
	Even if this box is not now	marked this dwelling may become a vacant building before	the 1 year expiration date of this report	
	Cat. 1 : New owners n	nust re-register the building and pay all outstand	ing fees and obtain permission for occupancy	∤.
	Written permissio	n from the City of Saint Paul is required	before a Cat 2 or Cat 3 VB can be sold	
	=			
	: Requirements report, 4. submall code comp	s include: 1. register/re-register the building, 2. It nit for approval a rehab cost estimate from a lice liance work, 5. submit proof of financial respon	ensed contractor and a schedule for completionsibility acceptable to the City.	n of
	Cat. 3 : All above requi	irements And obtain a Certificate of Occupanc	v or Certificate of Code Compliance before	e sale
	MOTICE, A VP status on	d / or category can change at any time. You must cont	act the City's Vacant Buildings divison at	
	* NOTICE: A VB status and	you are fully informed of all the conditions and requi	rements that may affect the sale of this property.	
	031-200-1900 to be saic	you are fully informed of an die contactions that requi	Total Control	
		·		
	of exterior work (excluding t	ritage Preservation District or it is individually designated painting), modifications, additions and demolition is required	I by the Heritage Preservation Commission and city staff	proval f). Date
		questions regarding Heritage Preservation contact the City's		
	HAS Open Permits. Go to the D	OSI website (see below) click on "Look Up Property Informatestrictions or requirements may apply. Call 651-266-9090 for	permit information	Viewed
	-	dwelling is in use is a duplex and this is not checked, contact		ed
	for the most recent information. R	esearch into a property's history may incur a fee.		
	You may obtain a printout of all	this information by visiting the DSI website, then enter the	property address as directed:	5/9
	www.stpaul.gov>Goverment>I	Department of Saftey& Inspections, then click on "Look	Up Property Information"	5/9/2011
ſ	This Report:			—] <u>=</u>
	1. is intended to provide <u>basic in</u>	formation to the home buyer and seller prior to the time tive Code; however, this evaluation form will be used by the	of sale. This report WILL NOT be used to enforce	h
	the requirements for a hard-wire	ed smoke detectors.		_
	2. is based on the current Truth-in-	Sale of Housing Evaluator Guidelines and is based upon dif	ferent standards than the lender, Federal Housing	
	Administration (FHA) or Vete	of St. Paul nor by the evaluator for the condition of the build	ng component, nor of the accuracy of this report.	
	4 gavens only the items listed on the	he form and only those items visible at the time of the evalua	tion. The Evaluator is not required to operate the	Page 1 of 4
	heating plant(except during the l	heating season), use a ladder to observe the condition of the te of issue and only for the owner named on this report.	rooming, disassemble hearts of evaluate maccessible areas.	· [1
		should be directed to the evaluator.		of 4
	Complaints regarding this report	t should be directed to Department of Saftey and Inspect	ions, Truth-in-Sale of Housing Program,	
1	Phone No. (651) 266-1900		5/0/2011 Rev 3/2009	,
	Evaluator: Guy Borglund	Phone: (612-859-4663	5/9/20 <u>11</u> Rev 3/2009	<i>'</i>

RATING "M" = Meets minimum "B" = Below minimum "C" = Comment KEY Where there are multiple rooms to	"H" = Haza o a category	rdous "Y" = Yes "N" = No "NV" = Not Visible/Viewed "NA" = Not Applicable The Evaluator must specify the room to which a Comment is related.
		1 (B) less than 6"8' headroom
		2 (B) cracks
BASEMENT/CELLAR		3(B) scale and patching, loose dirt around porch 4 (y) past stains
1. Stairs and Handrails	В	4 (y) past stains
2. Basement/cellar floor	В	5 (C)mostly covered
3. Foundation	В	6 (B) adjustable post in use, not welded or peened
4. Evidence of dampness of staining	Y	
5. First floor, floor system	C	
6. Beams and columns	В	
ELECTRICAL SERVICE(S) # of Services	1	8(B) water meter missing grounding loop
7. Service size:		9(B) no GFCI in basement bathroom, metal pull chain over bath
Amps: 30 60 100 X 150 Othe	r 200	faucet
Volts: 115 115/230 X		
8. Electrical service installation/grounding	В	
9. Electrical wiring, outlets and fixtures	В	
PLUMBING SYSTEM		11 (B) saddle type fittings on waste pipes (C) corrosion on joints,laundry s trap leaks 12 (B) No back flow protection on side faucet,no back flow on
		laundry tubs (C) plastic water pipes in use
10. Floor drain(s) (basement)	M	13(C) kink in gas line on kitchen stove 16 (B) unvented bath and sinks
11. Waste and vent piping (all floors)	BC	
12. Water piping (all floors)	BC	
13. Gas piping (all floors)	В	
14. Water heater(s) installation	M	 17a(H) no backflow valve on water supply
15. Water heater(s) venting	M	(B) off season ,heater shut off
16. Plumbing fixtures (basement)	В	(H) corrosion on vent pipe, clearances from combustibles
	.,,	
HEATING SYSTEM(S) #of	1	
17. Heating plant(s): Fuel: naturalgas Type: hot water	-	
a. Installation and visible condition	HB	Garage heater18a(B) loose pipe and hangers
b. Viewed in operation (required to heating season)	N	b off season, heater shut off (H) vent pipe rusted through, loose
c. Combustion venting.	H	(17) York pipe ruesed triough, 10000
The Evaluator is not required to operate the heating plant(s), e	·	
during the heating season, between October 15 and April 15.	F	·
18. Additional heating unit(s): Fuel: natural ga Type: for	rced air	
a. Installation and visible condition	В	
b. Viewed in operation	N	
c. Combustion venting	Н	
19. ADDITIONAL COMMENTS (1 through 18)	NONE	17. C Heating Plant/s Carbon Monoxide and Heat Exchanger are not tested.
		Check with professionals in the field that meet your requirements.

Property Address: 1/64 MINITHA HA AVE WEST

RATING "M" = Meets minimum "B" = Below minimum "C" = See Comment "H" = Hazardous "Y" = Yes "N" = No "NV" = Not Visible/Viewed "NA" = Not Applicable Where there are multiple rooms to a category. The Evaluator must specify the room to which a Comment is related.

	where there are multiple roo	oms to a categ	ory. The Evaluator m	ust specify the room t	to which a Comment	is related.
20	KITCHEN Wells and seiting		Item #	Comme	ents	
	Walls and ceiling	M		-		
21.	Floor condition and ceiling height	B	21 (B) not cove	red with waterpro	of flooring	
22.	Evidence of dampness or staining	N				
	Electrical outlets and fixtures	<u>M</u>	24 (C) extra fau	cet in kitchen, no	t working	
	Plumbing fixtures	MC_	24 (C) extra faucet in kitchen, not working			
	Water flow	M	26 (C) exhaust vent through wall, not hooked up, up stairs vent			up stairs vent in
	Window size/openable area/mechanical exhaust	C	kitchenet not w	orking	• •	•
27.	Condition of windows/doors/mech.exhaust	В	27 (B) windows			
	LIVING AND DINING ROOM(S)		28(C) ceiling pa	tched		
28.	Walls and ceiling	C				
	Floor condition and ceiling height	M	30 (y) ceiling pa			
	Evidence of dampness or staining	Y	31 (B) minimual	outlets		
	Electrical outlets and fixtures	B	33 (B) broken sa	ash cords and top	windows painte	d shut
	Window size and openable area	M	throughout			
33.	Window and door condition	В	34-35 patching a	and fresh paint th	roughout	
	HALLWAYS, STAIRS AND ENTRIES	В	je i oo paloiiiig i	and noon paint at	roughout	
3/1			36 (B) front stair	s handrail low		
	Walls, ceilings and floors	C				
33. 26	Evidence of dampness or staining	N				
27	Stairs and handrails to upper floors Electrical outlets and fixtures	В				
		<u>M</u>				
	Window and door condition	<u>M</u>				
39.	Smoke detector(s)	M	40 (B) walls tile i	ouckling		
	Properly located	M				
•	Hard-wired (HWSD)* if N or H in a single family home then SPFire Dept requires HWSD installation	M	43 (B) GECI(S) +	rip manualy, outle	.4	ī
	BATHROOMS		44(B) Main floor	bath, stool overfi	et with open grou	na nan valva
40.	Walls and ceiling	В	(=)	2011, 0100, 010, 11	ow ord i lower u	ian valve
41.	Floor condition and ceiling height	M				
42.	Evidence of dampness or staining	N				
	Electrical outlets and fixtures	В				
44.	Plumbing fixtures	В		•		
45.	Water flow	M	48 (C) patching of	n walls and fresh	n paint	
46.	Window size/openable area/mechaical exhaust	M	' ' '			
47.	Condition of windows/doors/mech.exhaust	M	[54 (B) 11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			•
	OI EMPIRE OF COLUMN		51 (B) closet light 50 (B) sleeping re	ts lack protective	covers	
40	SLEEPING ROOM(S)	C	Do (b) sleeping it	Julis lack egrees	size windows	
48.	Walls and ceiling	M				
	Floor condition and ceiling height	M				
30. .	Evidence of dampness or staining					
	Electrical outlets and fixtures	В				
32.	Window size and openable area	B				
	Window and door condition	M	58(C)covered with	h insulation and r	olastic	ľ
]	ENCLOSED PORCHES AND OTHER ROOMS		60(B) surface mo	unted wiring,exte	nsion cord light	
	Walls ceiling and floor condition	NA		<u>.</u>	ŭ	
55. I	Evidence of dampness or staining	NA				
	Electrical outlets and fixtures	NA				
	Window and door condition	NA				1
. 1	ATTIC SPACE (Visible Areas)	·				
	Roof boards and rafters	С				
	Evidence of dampness or staining	NA	i	r		`
	Electrical wiring/outlets/fixtures	В				
61. V	Ventilation	Y				ľ
	DDITIONAL COMMENTS(20 through 61) tor-Guy Borgland CO Detector information reporated here	NONE				
Evalua	tor: Guy Borglund CO Detector information reporated here	1101115	5	5/9/2011	Rev 3/2009	Page 3 of 4

Property Address: 1404 f				nt "H" = Hazardo	dous "Y" = Yes "N " = No "NV" = Not Visible/Viewed "NA" = Not Applicable
EXTERIOR (Visible	ie Areas)	i			Item # Comments
63. Foundation				В	63(B) missing motar and minor cracks
64. Basement/cellar windo				В	64(B) missing glazing, decay
65. Drainage (grade)				В	65(B) low grade in spots
66. Exterior walls		**********		C	66 (C) siding patched, fresh paint 67(B) decay on some doors
67. Doors (Frames/storms/				В	68(B) lascks glazing and decay on some trim and windows
•				В	69 (B) missing steps on west exit,low guardrail
68. Windows (frames/storm				В	70 (B) some decay on trim, fresh paint
69. Open porches, stairway				B	-
70. Cornice and trim					-
71. Roof covering and covering				M	73(B) missing motar and metal flue liner not visible
72. Gutters and downspout				NA	/O(D) Illiooning motal and motal neo most not not not not not not not not not no
73. Chimneys				В	.
74. Outlets, fixtures and se				M	75(B) Flat roof worn, rolled roofing, not approved for flat roof,
GARAGE(S)/ACCES			E(S)	-	76(B) non approved fire rated wall/ceiling covering, adjustable
75. Roof structure and cove	~			В	posts in use,patched siding, no house numbers 77(B) cracked siab,low slab
76. Wall structure and cover	-			В	77(B) cracked siab,low siab 78(B) non fire rated door
77. Slab condition		,		В	79,(B) opener not hooked up
78. Garage doors				<u>B</u>	80 (B) surface mounted wiring, Fuse box lacks 'S' safety type
79. Garage opener(s)- (see				В	adapters/fuses, lights missing bulbs, main service wire low over
80. Electrical wiring, outlet				В	garage with roof access
81. ADDITIONAL COMP			л 80)		
FIREPLACE/WOOD	·cTAVF	20 Щ.		1	83(B) Mantel lacks proper clearance above firebox
82. Dampers installed in fir			*******	Y	84(C) only viewed first foot of chimney flue above damper, co
	-			В	not see light to top
04 0 1111				C	-
64. Collation	-			~	
UPPLEMENTAL INFORM	*	T No determ	ination i	· made	
hether items meet minimum s					·
INSULATION	Y/N	Туре		es/Depth	
85. Attic Insulation	Y	glass batts		3-6	
86. Foundation Insulation	N	na	N	NA	
87. Kneewall Insulation	N	na	- N	NA .	
88. Rim Joist Insulation				NA	
i	N	na	1	A	1
89. ADDITIONAL COMM	MENTS	(82 through	1 88)		
I hereby certify that this report Guidelines, and I have utilized re diligence and I have noted all con minimum standards of maintena	reasonable : onditions fo ance.	and ordinary ca	are and		
- Ly By !-				59-4663	5/9/2011 Page 4 c
Evaluator Signature		-	Phone N	Jumber	Date Viewed
Printed Name: Guy F		_ .			Rev 3/200
located near sleeping rooms. For a 2. Rainleaders connected to the sa	more informanitary sew	rmation call Fire I wer system must b	Prevention be discoun	on, (651) 266-9 nected. For mo	NOTICES unected to the electrical system. (hard wired) The detector must be 9090. (Saint Paul Legislative Code, Chapter 58) nore information call Public Works, Sewer Utility, 651-266-6234
County Public Health, (651)266-1 4. Neither the City of Saint. Paul nor	-1199. or the Evalua	ator is responsibl	ole for the d	determination	t, they can be poisoned. For more information call Ramsey n of the presence of airborne particles such as asbestos, noxious conditions which may cause the above.

6. An automatic garage door should reverse upon striking an object. If it does not reverse, it poses a scrious hazard and should be repaired or replaced immediately.

5. If this building is used for any purpose other than a single family dwelling, it may be illegally zoned. To help you determine legal uses under zoning ordinance, contact the Zoning Administrator at (651) 266-9008.



CITY OF SAINT PAUL Christopher B. Coleman, Mayor 375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806 Telephone: 651-266-8989 Facsimile: 651-266-9124 Web: www.stpaul.gov/dsi

June 29, 2015

Enforcement Notice

Ryan Kempenich 1464 Minnehaha Ave W. St Paul MN 55104

RE: 1464 Minnehaha Ave W.

Dear Mr. Kempenich:

This property is located in an RT-1, One and Two Family zoning district. A complaint was recently received regarding the use of the property. During an inspection the following was observed: there are three separate kitchens in addition to a kitchen in the basement, each of the six (6) bedrooms have keyed exterior locks, mini-refrigerators and sinks, and considerable construction work has been done in the building without any construction trade permits. The Truth-in-Sale of House report from 2011 stated the use of the house was a single family dwelling. It appears this property is being used as a rooming and boarding house which is first allowed in the RM1, Multiple Family zoning district. There is no license in City files as a rooming/boarding house or a certificate of occupancy.

In order to bring the property into zoning compliance you must:

Remove the illegal dwelling units and operate the property as a single family dwelling with no more than a total of four (4) unrelated adults. All applicable building permits must be obtained prior to conducting the required work. The sinks, cabinets, and appliances must be removed from all the additional units. The utilities (gas, water, 220v electric, etc.) in the rooms with the additional kitchens must be capped at the source. The exposed utility lines must be concealed inside the wall or floor and the openings created covered with a surface that matches the surrounding finish. Any key locks on doors separating the illegal unit must be removed and replaced with a doorknob that has no lock or the doorway refinished.

The property could be used as a duplex but will require a variance from the Board of Zoning Appeals due to the proximity to the lot line. There is an application to be submitted, a filing fee, site and floor plans required. In addition, construction plans and permits will be required for all the work to be completed as a duplex.

You may apply to the Planning Commission to rezone the property. This rezoning would constitute spot zoning, which is prohibited by State Law, the staff recommendation for approval would be slim.

This property must be brought into zoning compliance prior to August 1, 2015. Failure to comply with this order or repeat violations will result in further legal action by the office. If you have questions regarding this matter, you may contact me at 651.266.9084 or karen.zacho@ci.stpaul.mn.us.

Sincerely,

Karen Zacho

DSI Inspector - Zorling

1464 Minnehaha Ave W - ENF Page 2 6.29.15

c. Mike Barck, Building Inspector Aj Neis, Fire Inspector Enc.

You may appeal this order and obtain a hearing before the Board of Zoning Appeals. The application for appeals must be filed and fee submitted to the Zoning Administrator within ten (10) days of the date this order was mailed. No appeal may be filed after this date. Applications for the appeal or variance process are available at the Department of Safety & Inspections main office or the City website (www.stpaul.gov/dsi). You must submit a copy of this order with your application.

CITY OF SAIN	T PAUL REFERRAL/RI	esponse form
To: Zoning Dipi	DAT!	E: Gan. 21, 1986
BUILDING () FIRE () CITY ATTORNEY () HEAL () CITY COUNCIL () HOUS	() LICENSE TH () MAYOR'S I & C	() POLICE () PUBLIC WORKS () WATER () OTHER
LOCATION OF COMPLAINT 146	4W. Mihaha OCCUPANO	CY TYPE residential
NAME	ADDRESS (PHONE NUMBER
OWNER/AGENT/ Javri OPERATOR NAME	ADDRESS ADDRESS	PHONE NUMBER
	<u>COMMENTS</u>	
Mr. Paulso	n has insisted	his also has
of Rece to a	from a 5- ply	w/a certificate
has been tal	I the requires	menta necessari
to make apto.	unrentable.	Plesse make
the necessary d	range in your	reards Thanks
FROM:	REFERRAL REPORT BY	(NAME) Darnic Schmid
	PHONE NUMBER	
	N 10 DAYS OF ABOVE REPORT DATE):	e ur
		TREAL OF
		Miles Annual State
		21 KH •
RESPONSE BY (NAME)	DATE	S & & & & & & & & & & & & & & & & & & &
	र्थ करन हम्म करने करने हैंका संबंध संबंध करने हमा दला हैका जात हमा हमा हमा बहु हारते हमें हमा है	
SALMON - KEEP	WHITE & BLUE - RETURN W	HITE TO REFERRING AGENCY

MAY, 1984

WITHIN TEN (10) DAYS. 2ND REFERRAL