# Fco 18.71



## **APPLICATION FOR APPEAL**

Saint Paul City Council - Legislative Hearings RECEIVED

MAY 16 2018

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8585

Revised 5/15/2018

| We   | need the following to process your appeal TY CLERK   | (   |
|--|--|---|
| D O  | \$25 filing fee (non-refundable) (payable to the City of Saint Pau<br>(if cash: receipt number 60 96 )<br>Copy of the City-issued orders/letter being appealed<br>Attachments you may wish to include  | (provided by Legislative Hearing Office) Tuesday, MAY 33, 2018    |
| Ďa'  | This appeal form completed   | Time  |
|  | Walk-In OR d Mail-In   | Location of Hearing:<br>Room 330 City Hall/Courthouse             |
|  | for abatement orders only: Email OR - Fax  | Noom 330 City Hall/Courthouse                                     |
| Address Being Appealed:  |  |   |
| Number & Street: 1827 57. Antrony Autoing State:   |  |   |
| App  | ellant/Applicant: Kampa Jim @ 6 mail. Com  | Email   |
| Pho  | ne Numbers: Business Residence 65  | 7) 468-8351 Cell  |
| Sign   | nature: James Kupa   | Date:   |
| Nam  | e of Owner (if other than Appellant):  |   |
| Maili<br>450   | ng Address if Not Appellant's:  Ches Mar Dr. Eagan MN 55123  |   |
| Phor   | ne Numbers: Business Residence   | Cell  |
| According Value Sign Control Value V | nat Is Being Appealed and Why? ceptable acate Order/Condemnation/ evocation of Fire C of O ummary/Vehicle Abatement re C of O Deficiency List/Correction 9' Space Nerd to ode Enforcement Correction Notice acant Building Registration ther (Fence Variance, Code Compliance, etc.) | Attachments Are  Walk though one Believen To get to #1  Exit (15) |



CITY OF SAINT PAUL

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806 Telephone: 651-266-8989 Facsimile: 651-266-8951 Web: www.stpaul.gov/dsi

May 15, 2018

JAMES KAMPA 4500 CHES MAR DR. EAGAN MN 55123

### FIRE INSPECTION CORRECTION NOTICE

RE:

1827 ST ANTHONY AVE

Ref. #105629

Residential Class: B

#### Dear Property Representative:

Your building was inspected on April 6, 2018 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date.

#### A re-inspection will be made on May 18, 2018 at 2:00 PM.

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

#### **DEFICIENCY LIST**

1. Interior - Unit 1827 & 1829 - MNFSC 1014.2(1) Egress through intervening spaces. Egress through intervening space shall comply with this section. (3) Means of egress from dwelling units or sleeping areas shall not lead through other sleeping areas, toilet rooms or bathrooms. (4) Egress shall not pass through kitchens, storage rooms, closets or spaces used for similar purposes.-

4/6/18 Unit 1829: tenants must walk through one room used as sleeping room to access second room used as sleeping room.

4/6/18 Unit 1827: no beds set up in either second floor rooms, cannot determine sleeping areas. On second floor, tenant must walk through child's sleeping room to get to tenants sleeping room.

- 2. Exterior Unit 1827 SPLC 34.09 (4), 34.32 (3) Repair and maintain the door frame. Close the gap and provide a weather-proof framing around door.
- 3. Exterior Unit 1827 SPLC 34.09 (1)(2), 34.33 (1) Provide and maintain all exterior walls free from holes and deterioration. All wood exterior unprotected surfaces must be painted or protected from the elements and maintained in a professional manner free from chipped or peeling paint.4/6/18: bldg permit for this repair will be satisfied when building inspector finals permit. Siding on west side of the dwelling missing due to fire.
- Interior Deadbolt at Unit 1827 Backdoor SPLC 34.09 (3) i Repair and maintain an approved lock. 4/6/18: no strike plate in place, only hole in the wood.
   Latch and wood framing is gone and deadbolt no longer functions to lock.
- 5. Interior Unit 1827 MSFC 703.1 Provide and maintain fire rated wall construction with approved materials and methods. This work may require a permit(s). Call DSI at (651) 266-8989. The minimum rating must be 1 hour.
  Open space around the furnace duct must be enclosed in the wall or ceiling. No openings into the wall are allowed to provide the one-hour separation, gypsum board must be installed on both sides of the wall. If patching the hole in the wall or ceiling, 5/8th-inch fire-rated gypsum board must be used.
- 6. Interior Unit 1827 MSFC 703.1, 1106.1 Provide and maintain fire rated floor and/or ceiling construction with approved materials and methods. This work may require a permit(s). Call DSI at (651) 266-8989. The minimum rating must be hour.- Penetrations of the furnace duct into the wall space shall be patched or sealed with 5/8th inch fire-rated gypsum board.
- 7. Interior Unit 1829 MSFC 1030.2 Remove the materials that cause an exit obstruction. Maintain a clear and unobstructed exit path..Second floor room used as sleeping room, cannot enter room or reach windows in room due to personal items throughout the room. Remove the items obstructing the way to windows in this room.
- 8. Interior Unit 1829 SPLC 34.10 (4), 34.34 (3) Provide a bathroom floor impervious to water.Flooring and sub-floor of second floor bathroom in bad shape, damaged the kitchen ceiling on main floor of unit.
- 9. Interior Unit 1829 MSFC 315.3 Provide and maintain orderly storage of materials.-Basement cannot be inspected without stepping on personal items, combustible items stored in plastic bags or bins.

  Second floor room with large bed has personal items stored on the floor and in front of windows, cannot access windows in the room.

- 10. Interior Unit 1829 MN Stat 299F.18 Immediately remove and discontinue excessive accumulation of combustible materials.
  Basement of unit 1829 must reduce the combustible loading by 50%. These items may not be stored in other areas of the unit.

  Second floor room with large bed has personal, combustible items stored on the floor in piles, cannot access the windows in this room due to combustible load. Reduce the storage in this room by 50%.
- 11. Interior Unit 1829 SPLC 34.10 (7), 34.17 (5) Repair and maintain the ceiling in an approved manner.Kitchen ceiling damaged by leaking toilet above.
- Interior Unit 1829 MSFC 603.5.3 Provide 36 inches of clearance around all
  mechanical equipment. Basement gas water heater and gas clothes dryer have combustible personal items stored
  too close, check behind dryer.
- 13. Interior Unit 1829 SPLC 34.11 (1), MSBC 2902.1, SPLC 34.35 (1), MPC 301.1 Repair or replace and maintain all parts of the plumbing system to an operational condition. This work will require a licensed plumbing contractor to obtain a permit and contact city inspection staff for review of the work and finalizing of the permit.- Second floor toilet is not secure, rocks and slides, sub-floor is weak and gives in areas around toilet and bath tub. Leaking has damaged the kitchen ceiling, plastic taped to kitchen ceiling.
- 14. Interior Unit 1829 SPLC 34.11 (4), 34.35 (1), MPC 708.1- Connect or cap the sewer piping in accordance with the plumbing code. A licensed plumbing contractor is required to re-seat the toilet and contact city inspection staff for review of the work and finalizing of the permit.
  Toilet leaking and sub-flooring and kitchen ceiling damaged from leaking.
- 15. Interior Units 1827 & 1829 SPLC 34.10 (7), 34.17 (5) Repair and maintain the walls in an approved manner.-Check for holes throughout.
- 16. SPLC 39.02(c) Complete and sign the smoke detector affidavit and return it to this office.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8585) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: Laura.Huseby@ci.stpaul.mn.us or call me at 651-266-8998 between 7:30 a.m. - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Laura Huseby Fire Inspector

Reference Number 105629