

375 Jackson Street, Suite 220 Saint Paul, MN 55101-1806 Telephone: 651- 266- 8989 Facsimile: 651- 266- 9124 www.stpaul.gov/dsi

Code Compliance Report

October 19, 2017

* * This Report must be Posted on the Job Site * *

Hooyo Huno Housing LLC 1550 Larpenteur Ave W Falcon Heights MN 55113

Re: 610 St Albans St N File#: 14 325580 VB2

Dear Property Owner:

The following is the Code Compliance report you requested on September 06, 2017.

Please be advised that this report is accurate and correct as of the date October 19, 2017. All deficiencies identified by the City after this date must also be corrected and all codes and ordinances must be complied with. This report is valid for 365 days from October 19, 2017. This report may be used in lieu of a Truth in Housing Report required in St Paul Legislative Code 189. This building must be properly secured and the property maintained at all times.

In order to sell or reoccupy this property the following deficiencies must be corrected. A Legislative Code exemption (Chapter 33.03(f)) allows a Category 2 Vacant Building to be sold "as is" providing the buyer, prior to closing, completes an approval process. For further information, call Reid Soley at 651-266-9120.

ZONING

- 1. This property is in a(n) R4 zoning district.
- 2. This property was inspected as a Single Family Dwelling.

BUILDING Inspector: Jim Seeger Phone: 651-266-9046

- 1. Insure basement cellar floor is even, is cleanable, and all holes are filled. SPLC 34.10 (1)
- 2. Repair walls, ceiling and floors throughout, as necessary. SPLC 34.34 (6)
- 3. Prepare and paint interior and exterior as necessary. Observe necessary abatement procedures (EPA, MPCA and St. Paul Legislative Code, Chapter 34 for additional information) if lead base paint is present. SPLC 34.33 (1)

Re: 610 St Albans St N

October 19, 2017

Page 2

4. Any framing members that required repair or do not meet code (where wall and ceiling covering is removed, members that are over-spanned, over-spaced, not being carried properly, door and window openings that are not adequately supported, etc.) are to be reconstructed in an approved manner. SPLC 34.34 (1)

- 5. Re-level structure as much as is practical. SPLC 34.10 (2)
- 6. Provide fire block construction as necessary and seal chases in basement ceiling. MNRC Ch 1309 Sect. 602.8
- 7. Where wall and ceiling covering is removed install full thickness or codespecified insulation. MN Energy Code Ch. 1322.1101 (exept. 4)
- 8. Install Smoke Detectors/Carbon Monoxide Detectors per MN Conservation Code and the MN Dept. of Labor and Industry: Install per code where feasible. MNRC Ch 1309 Sect 313.2.1
- 9. Provide major clean- up of premises. SPLC 34.34 (4)
- 10. Install water- proof enclosure in shower area. MNRC Ch 1309 Sect. 307
- 11. Verify proper venting of bath exhaust fan to exterior. SPLC 34.14 (3)
- 12. Dry out basement and eliminate source of moisture. SPLC 34.10 (10)
- 13. Repair siding, soffit, fascia, trim, etc. as necessary. SPLC 34.09 (1)
- 14. Provide proper drainage around house to direct water away from foundation of house. SPLC 34.08 (2)
- 15. Provide proper drainage around house to direct water away from foundation of garage. SPLC 34.08 (2)
- 16. Provide general rehabilitation of garage. SPLC 34.32 (3)
- 17. Provide durable, dustless parking surface as specified in the zoning code. SPLC 34.08 (7)
- 18. Provide ground cover capable of controlling sediment and erosion. SPLC 34.08 (3)
- 19. Grade must drain away from foundation of dwelling. Maintain 6 inch clearance between wood and soil. MNRC Ch 1309- Sect. 404.1.6
- 20. Replace or sister decayed east side floor joist in basement ceiling.
- 21. Install 1 hour fire wall between garage and house.
- 22. Replace decayed floor and walls in kitchen.
- 23. Repair or Replace any deteriorated window sash, broken glass, sash holders, re-putty, etc as necessary. SPLC 34.09 (3)
- 24. Replace all decayed framing in garage. Replace garage flooring. level garage walls.
- 25. Remove or replace fence.
- 26. Install new garage doors.
- 27. Call for framing and insulation inspection before covering.
- 28. Replace or repair roof covering.
- 29. Repair drainage and grading on east side of house.
- 30. Provide complete storms and screens, in good repair for all door and window openings. SPLC 34.09 (3e)
- 31. Provide functional hardware at all doors and windows. SPLC 34.09 (3f)
- 32. Exit doors shall be capable of being opened from the inside, easily and without

Re: 610 St Albans St N

October 19, 2017

Page 3

the use of a key. Remove all surface bolts. SPLC 34.09 (3h)

- 33. Repair or replace damaged doors and frames as necessary, including storm doors. SPLC 34.09 (3f)
- 34. Weather seal exterior doors, threshold and weather-stripping. SPLC 34.09 (3f)
- 35. Install floor covering in bathroom and kitchen that is impervious to water. SPLC 34.10 (4)
- 36. A building permit is required to correct the above deficiencies. All work is to be done in a workmanship like manner. SPLC 33.03 (a)

ELECTRICAL Inspector: Dave Blank Phone: 651-266-9035

- 1. No power at time of inspection. Test all electrical outlets and ensure all luminaires (light fixtures) are working properly when power is restored.
- 2. Repair the electrical service grounding conductor to the metallic water piping system. Install a conductor sized to Table 250.66 (NEC) from the electrical service to within 5' of the entrance point of the water service, and bond around the water meter. Article 250, NEC (install ground rods).
- 3. Provide a complete circuit directory at service panel indicating location and use of all circuits. Article 408.4, NEC
- 4. Repair or replace all broken, painted over, corroded, missing or loose receptacles, luminaires (light fixtures), switches, covers and plates to current code. Article 406.4(D) & Article 410, NEC
- 5. Check all receptacles for proper polarity (including 2- prong) and verify ground on 3- prong receptacles. Ensure all GFCI receptacles are functioning properly. Rewire and/or replace receptacles that are improperly wired or not functioning properly. Article 406.4(D), NEC
- 6. Install hard-wired, battery backup, Carbon Monoxide smoke detector as specified in Chapter 58 of the Saint Paul Legislative Code, and other smoke detectors and carbon monoxide detectors as required by the Minnesota State Building Code. SPLC 58, IRC
- 7. Remove and/or rewire all illegal, improper or hazardous wiring to current NEC.
- 8. All electrical work must be done by a Minnesota-licensed electrical contractor under an electrical permit.

PLUMBING Inspector: Jim Kaufer Phone: 651-266-9054

- 1. Basement Gas Piping (MFGC 411) Install an approved shut off; connector and gas piping for the dryer.
- 2. Basement Gas Piping (MFGC 614.1-614.7) Vent clothes dryer to code.
- 3. Basement Laundry Tub (MPC .0100 & 901) Install a proper fixture vent to code.
- 4. Basement Laundry Tub (MPC 701) Install the waste piping to code.
- 5. Basement Laundry Tub (MPC .0100 P & Q & 419.2) Install the water piping to code.
- 6. Basement Soil and Waste Piping (MPC 709.1) Install a front sewer clean out.
- 7. Basement Soil and Waste Piping (MPC .0100 L & M & 708.1) Plug all open

Re: 610 St Albans St N October 19, 2017

Page 4

- piping and properly pitch all piping.
- 8. Basement Soil and Waste Piping (MPC .0100 M) Replace all corroded cast iron, steel waste or vent piping.
- 9. Basement Soil and Waste Piping (MPC 707.4) Install a clean out at the upper terminal at each horizontal drainage pipe.
- 10. Basement Water Heater (MPC 504.4, & 504.5, & 504.6) A pressure and temperature relief valve is required.
- 11. Basement Water Heater (MPC 507.5) Correct the pressure and temperature relief valve discharge.
- 12. Basement Water Heater (MFGC 409) Install the gas shut off and the gas piping to code.
- 13. Basement Water Heater (MFGC 501.12) The water heater venting requires a chimney liner.
- 14. Basement Water Heater (MPC 501)Install the water piping for the water heater to code.
- 15. Basement Water Heater (MPC .0100 Q)The water heater must be fired and in service.
- 16. Basement Water Meter (MPC 609.11) Support the water meter to code.
- 17. Basement Water Meter (MPC 606.2) The service valves must be functional and installed to code.
- 18. Basement Water Meter (SPRWS Sec. 94.04 & 94.16(g)) The water meter must be removed from the pit.
- 19. Basement Water Piping (MPC 301.1 (3))Repair or replace all the corroded, broken, or leaking water piping.
- 20. Basement Water Piping (MPC 610) Replace all the improperly sized water piping.
- 21. Basement Water Piping (MPC .0100 P & Q) Provide water piping to all fixtures and appliances.
- 22. Basement Water Piping (SPRWS 93.07) Provide a one (1) inch water line to the first major take off.
- 23. Exterior Lawn Hydrants (MPC 301.1) Repair or replace the lawn hydrants that are broken or have parts missing.
- 24. Exterior Lawn Hydrants (MPC 603.5.7) The lawn hydrant(s) require a backflow preventer.
- 25. First Floor Sink (MPC .0100 E & 901) Install a proper fixture vent to code.
- 26. First Floor Sink (MPC 701) Install the waste piping to code.
- 27. First Floor Sink (MPC .0100 P & Q & 419.2) Install the water piping to code.
- 28. First Floor Toilet Facilities (MPC .0100 P & Q & 419.2) Install the water piping to code.
- 29. Second Floor Gas Piping (MFGC 411) Install an approved shut off; connector and gas piping for the range.
- 30. Second Floor Laundry Tub (MPC .0100 & 901) Install a proper fixture vent to code.
- 31. Second Floor Laundry Tub (MPC 701) Install the waste piping to code.
- 32. Second Floor Laundry Tub (MPC .0100 P & Q & 419.2) Install the water piping

Re: 610 St Albans St N October 19, 2017 Page 5

to code.

- 33. Second Floor Laundry Tub (MPC 301.1) Repair/replace the fixture that is missing, broken or has parts missing.
- 34. Second Floor Laundry Tub (MPC 301.1) Repair/replace the faucet that is missing, broken or has parts missing.
- 35. Second Floor Laundry Tub (MPC .0100 B) Provide the proper potable water protection for the faucet spout.
- 36. Second Floor Lavatory (MPC .0100 E & 901) Install a proper fixture vent to code.
- 37. Second Floor Lavatory (MPC 701) Install the waste piping to code.
- 38. Second Floor Lavatory (MPC .0100 P & Q & 419.2) Install the water piping to code.
- 39. Second Floor Toilet Facilities (MPC .0100 E & 901) Install a proper fixture vent to code.
- 40. Second Floor Toilet Facilities (MPC 701) Install the waste piping to code.
- 41. Second Floor Tub and Shower (MPC .0100 E & 901)Install a proper fixture vent to code.
- 42. Second Floor Tub and Shower (MPC 701) Install the waste piping to code.
- 43. Second Floor Tub and Shower (MPC .0100 P & Q & 419.2) Install the water piping to code.
- 44. Second Floor Tub and Shower (MPC 408.3) Install scald and thermal shock protection, ASSE Standard 1016.
- 45. Second Floor Tub and Shower (MPC 409.4) Install a hot water temperature limiting device, ASSE Standard 1070.
- 46. Second Floor Tub and Shower (MPC 401.1 & 409.2) Replace the waste and overflow.
- 47. All the above corrections to waste, vent, water, and gas piping shall be per the Minnesota Plumbing Code Chapter 4714, Minnesota Rules Chapter 326, 4716, 1300, the Minnesota Mechanical Code, the Minnesota Fuel Gas Code, and Saint Paul Regional Water Services Water Code. All plumbing must be done by a plumbing contractor licensed in the State of Minnesota and the City of St. Paul by a plumber licensed in the State of Minnesota who also possess a City of Saint Paul Competency Card and after obtaining an approved City of Saint Paul Plumbing Permit.

Heating Inspector: Christi Dick Phone: 651-266-9045

- 1. Install approved lever handle manual gas shutoff valve ahead of the boiler and remove unapproved valve
- 2. Install approved automatic gas valve for boiler
- 3. Install approved lever handle manual building shutoff gas valve in an accessible location ahead of the first branch tee
- 4. Clean and Orsat test boiler burner. Check all controls for proper operation.
- 5. Provide thirty (30) inches of clearance in front of boiler for service
- 7. Install approved metal chimney liner

Re: 610 St Albans St N October 19, 2017 Page 6

- 8. Replace boiler flue venting to code
- 9. Connect boiler and water heater venting into chimney liner
- 10. Provide adequate clearance from flue vent pipe on boiler to combustible materials or provide approved shielding according to code
- 11. Vent clothes dryer to code
- 12. Provide adequate combustion air and support duct to code
- 13. Provide support for gas lines to code
- 14. Plug, cap and/or remove all disconnected gas lines
- 15. Provide heat in every habitable room and bathrooms
- 16. Attach metal tag to expansion tank valve stating that this valve must be open at all times except when draining the expansion tank
- 17. Support supply and return piping from heating system according to code
- 18. Conduct witnessed pressure test on hot water heating system and check for leaks
- 19. Install boiler pressure relief valve and pipe discharge to within 18 inches of the floor
- 20. Install back flow preventer on city water fill line to hot water heating system and pipe vent as required.
- 21. Repair or replace fin tube radiation and covers as needed
- 22. Repair or replace radiator valves as needed
- 23. Mechanical gas & steam permits are required for the above work.

Notes:

- 1. See attachment for permit requirements and appeals procedure.
- 2. Provide plans and specifications for any portion of the building that is to be rebuilt.
- 3. Most of the roof covering could not be inspected from grade. Recommend this be done before rehabilitation is attempted.
- 4. There was considerable storage/clutter within property at the time of the inspection. Property is to meet appropriate codes when complete.
- 5. Interior of garage not available for inspection. Repair per applicable codes.

This is a registered vacant building. In order to sell or reoccupy this building, all deficiencies listed on this code compliance report must be corrected in accordance with the Minimum Housing Standards of the St. Paul Legislative Code (Chapter 34) and all required permits must receive final approval within six (6) months of the date of this report. One (1) six-month time extension may be requested by the owner and will be considered if it can be shown that the code compliance work is proceeding and is more than fifty (50) percent complete in accordance with Legislative Code Section 33.03(f).

Re: 610 St Albans St N

October 19, 2017

Page 7

You may file an appeal to this notice by contacting the City Clerk's Office at 651-266-8688. Any appeal must be made in writing within 10 days of this notice. (You must submit a copy of this notice when you appeal, and pay a filing fee.)

If you have any questions regarding this inspection report, please contact Jim Seeger between 7:30 - 9:00 AM at 651-266-9046 or leave a voice mail message.

Sincerely,

James L. Seeger
Code Compliance Officer
Department of Safety and Inspections
City of Saint Paul
375 Jackson Street, Suite 220
Saint Paul MN 55101

Phone: 651-266-9046

Email: jim.seeger@ci.stpaul.mn.us

Attachments