RLH FC0 18-207

CITY OF SPINITED AND THE HEAD OF THE SPINITED AND THE HEAD OF THE SPINITED AND THE SPINITED

APPLICATION FOR APPEAL

Saint Paul City Council – Legislative Hearings

RECEIVED

DEC 21 2018

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8585

CITY CLERK

We	need the following to process your appeal:	
	\$25 filing fee (non-refundable) (payable to the City of Saint Paul) (if cash: receipt number # 64 U9	HEARING DATE & TIME (provided by Legislative Hearing Office)
0	Copy of the City-issued orders/letter being appealed	Tuesday, JAN. 8, 2019
Õ	Attachments you may wish to include	
0	This appeal form completed	Time
0	Walk-In •R • Mail-In	<u>Location of Hearing:</u> Room 330 City Hall/Courthouse
	for abatement orders only:	Room 550 City Hum Courthouse
A	ddress Being Appealed:	
Number & Street: 1211 REAVEY City: St PAUL State: MN Zip: 15106		
Appellant/Applicant: Tenny McDonougn Email terry Mcdonougle edinarealty		
Phone Numbers: Business 953.938.5709 Residence Cell 612.790-3664		
Signature: Jerry M. Org Date: 12/19/18		
Nar	me of Owner (if other than Appellant):	
Mai	iling Address if Not Appellant's:	
Pho	ne Numbers: Business Residence	Celi
0 1	That Is Being Appealed and Why? Vacate Order/Condemnation/ Comments: Revocation of Fire C of O	Attachments Are Acceptable
	Summary/Vehicle Abatement	
	,	
	7.617 40	
	Code Enforcement Correction Notice	
O	Vacant Building Registration	
00	Other (Fence Variance Code Compliance etc.)	



CITY OF SAINT PAUL

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806
 Telephone:
 651-266-8989

 Facsimile:
 651-266-8951

 Web:
 www.stpaul.gov/dsi

November 27, 2018

SLAR, LLC C/O TERENCE J MCDONOUGH 300 W FLORAL DRIVE SHOREVIEW MN 55126-2307

FIRE INSPECTION CORRECTION NOTICE

RE: 1211 REANEY AVE

Ref. #102124

Residential Class: C

Dear Property Representative:

Your building was inspected on November 27, 2018 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date. A reinspection will be made on December 27, 2018 at 11:00A.M..

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

DEFICIENCY LIST

- 1. Basement SPLC 34.10 (4), 34.34 (3) Provide a bathroom floor impervious to water. -
- 2. Bathroom Basement SPLC 34.10 (7), 34.17(5) Repair and maintain the floor in an approved manner. -Repair or replace the floor tile.

- 3. Pantry SPLC 34.08 (1), 34.34 (4), 34.16 Provide and maintain interior in a clean and sanitary condition. Remove dog feces. -
- 4. Upstairs Middle bedroom MSFC 308 Immediately, discontinue the use of all unapproved open flames. Do not stick incent in the wall for burning purposes. -
- 5. Upstairs Middle bedroom MSFC 605.4 Discontinue use of all multi-plug adapters. -
- 6. Upstairs bedrooms MSFC SECTION 1014.2 (3) MEANS OF EGRESS FROM DWELLING UNITS OR sleeping areas SHALL NOT LEAD THROUGH OTHER sleeping areas toilet rooms or bathrooms. -Bedrooms upstairs run north to south with one hallway for exiting through to the only exit in the south bedroom for all three bedrooms
- 7. MSFC 605.5 Discontinue use of extension cords used in lieu of permanent wiring. -
- 8. MSFC 313.1 Fueled equipment, including but not limited to motorcycles, mopeds, lawn-care equipment and portable cooking equipment, shall not be stored, operator or repaired within a building. -
- 9. SPLC 200.02 (a) No person shall own, harbor, keep or maintain in the City and dog over three months of age without a license. Provide written documentation of current license to the Fire Inspector. To obtain a dog license, contact DSI at 651-266-8989-
- 10. MMC 504.6 Provide, repair or replace the dryer exhaust duct. Exhaust ducts for domestic clothes dryers shall be constructed of metal and shall have a smooth interior finish. The exhaust duct shall be a minimum nominal size of four inches (102 mm) in diameter and installed in accordance with the mechanical code. This work Shall require a permit(s). Call DSI at (651) 266-8989.-Dryer exhaust duct is busted at the seams and is the wrong material
- 11. SPLC 34.16 (2) Properly dispose all your garbage in the owner-provided containers. -

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8585) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: james.thomas@ci.stpaul.mn.us or call me at 651-266-8983 between 7:30 a.m. - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

James Thomas Fire Inspector

Reference Number 102124