


1/23/19



Ahmad Al-Hawwari

770 Liliun Trl

Medina Mn 55340

Re: 888 Maryland Ave E. ST. Paul

Misc. repairs for code compliance

1. Remove exterior window coverings and replace all damaged thermal pane glass panels and re-caulk as needed Total - \$900.00
2. Repair front main egress door to building to like new condition with like kind and quality materials. Total - \$800.00
3. Replace all damaged ceiling grid system pieces with like kind and quality material to a as new condition. Total - \$2000.00
4. Repair minor roof problems with like kind and quality products to a leak free condition and do appropriate maintenance as needed Total - \$850.00

TERMS: Net balance upon completion and billing

Respectfully

Glen A. Oval

***Ovall Roofing & Construction***

6730 - 213 Avenue N.W., Elk River, MN 55330 • 763-753-2959  
State #2017344