

APPLICATION FOR APPEAL

Saint Paul City Council – Legislative Hearings RECEIVED 310 City Hall, 15 W. Kellogg Blvd.

MAR 29 2019

Saint Paul, Minnesota 55102 Telephone: (651) 266-8585

CITY CLERK

We need the following to process your ap	peal:	`
\$25 filing fee (non-refundable) (payable to (if cash: receipt number # 8 20 6) Copy of the City-issued orders/letter Attachments you may wish to include	53) being appealed	HEARING DATE & TIME (provided by Legislative Hearing Office) Tuesday, APRIL 9, 2019 Time 1:30
This appeal form completed		Location of Hearing:
Walk-In OR O Mail-In		Room 330 City Hall/Courthouse
for abatement orders only: O Email	OR O Fax	
Address Being Appealed:		
Number & Street: 456 W. Lawson ave City: St. Paul State: MN Zip: 55103		
Appellant/Applicant: Bernetta Romero, Jaime Romero, Angela Skaggs Email baby.angel.silverwings24@gmail.com		
Phone Numbers: Business	Residence	Cell
Signature: Bernetta Romer	0	Date: 3-26-19
Name of Owner (if other than Appellant):Contract for deed purchase in progress as of July 2012		
Mailing Address if Not Appellant's: 80 W. Delos st. St. Paul MN 55107		
Phone Numbers: Business		
What Is Being Appealed and Why? Attachments Are Acceptable		
O Vacate Order/Condemnation/ Revocation of Fire C of O	Comments:	enactor is being to bareh on us and
O Summary/Vehicle Abatement	We all feel this fire inspector is being to harsh on us and some of these repairs are completely out of bounds. one example (the yard is muddy) this inspector gave us things to correct that were impossible to correct due to the cold winter months like (repair the roof and pave the back parking area) when city code enforcement came to the house on Friday March,22 2019 he informed Angela that the only reason that we are being treated as a rental property is that the sellers have not filed the paperwork with the county.	
© Fire C of O Deficiency List/Correction © Code Enforcement Correction Notice O Vacant Building Registration		
Other (Fence Variance, Code Compliance, etc.)		

Ricardo X. Cervantes, Director

SAINT PAUL AAAA CITY OF SAINT PAUL

375 Jackson Street, Suite 220 St Paul, Minnesota 55101-1806

 Telephone:
 651-266-8989

 Facsimile:
 651-266-9124

Web: www.stpaul.gov/dsi

March 21, 2019

JAMIE O ROMERO & ANGELA SKAGG 456 LAWSON AVENUE W SAINT PAUL MN 55117-4737

RE: RE-INSPECTION FIRE CERTIFICATE OF OCCUPANCY WITH DEFICIENCIES 456 LAWSON AVE W

Ref. # 122368

Dear Property Representative:

Your building was re-inspected for the Fire Certificate of Occupancy on March 19, 2019. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected immediately.

A reinspection will be made on April 19, 2019 at 10:15 AM.

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

DEFICIENCY LIST

- 1. Exterior Back Stairs SPLC 34.09 (3), 34.33(2) Repair or replace the unsafe stairways, porch, decks or railings in an approved manner. This work may require a permit(s). Call DSI at (651) 266-8989.-The guardrail for the back stairs has completely broken off and the steps are deteriorated and damaged.
- 2. Exterior Back Yard SPLC 34.08 (3) Provide and maintain suitable ground cover on all exterior areas to control erosion. -The back yard is all muddy and there are broken and uneven pavers.

- 3. Exterior Fences & Fence Gates SPLC 34.08(5), 34.32(3) All accessory structures including, but not limited to, detached garages, sheds and fences shall be maintained structurally sound and in good repair. Provide and maintain exterior unprotected surfaces painted or protected from the elements. -The fence and fence gates for the property are in disrepair.
- 4. Exterior House SPLC 34.09 (2), 34.33 (3) Provide and maintain foundation elements to adequately support this building at all points.
- 5. Exterior House SPLC 34.09 (1)(2), 34.33 (1) Provide and maintain all exterior walls free from holes and deterioration. All wood exterior unprotected surfaces must be painted or protected from the elements and maintained in a professional manner free from chipped or peeling paint.
- 6. Exterior House SPLC 34.09 (2), 34.33 (1) Provide and maintained the roof weather tight and free from defects.
- 7. Exterior Parking Surface SPLC 34.08 (7) All parking spaces shall be paved with asphalt, concrete, or durable dustless surfacing. Before any existing spaces may be paved, site plan approval must be obtained as specified in the St. Paul Zoning Code. Contact DSI Zoning at 651-266-8989.
- 8. Exterior Window Screens SPLC 34.09 (4), 34.33 (3) -Provide or repair and maintain the window screen.
- 9. Exterior Interior Windows SPLC 34.09 (4), 34.33 (3) Repair and maintain the window in good condition.
- 10. Exterior Interior Doors SPLC 34.33 (3) Repair and maintain the door in good condition.Exterior The front and back entry doors and screen doors are in disrepair. The frames

for the doors are in bad shape and were installed improperly.

- Interior There are interior doors that are in disrepair.
- 11. Interior Basement MSFC 605.1 -Provide a grounding jumper around the water meter.
- 12. Interior Basement NEC 110-12 Provide for the electrical equipment to be installed in a neat and worker like manner. -Contact a licensed electrical contractor to properly repair the wiring from the dryer to the electrical panel. This work will require a permit.
- 13. Interior Basement MMC 504.6 Provide, repair or replace the dryer exhaust duct. Exhaust ducts for domestic clothes dryers shall be constructed of metal and shall have a smooth interior finish. The exhaust duct shall be a minimum nominal size of four inches (102 mm) in diameter and installed in accordance with the mechanical code. This work may require a permit(s). Call DSI at (651) 266-8989.-The dryer exhaust duct is broken and must be replaced.

- 14. Interior Basement MPC 507.5 Provide pressure relief valve for hot water heater piped to within 18 inches of the floor.
- 15. Interior Basement Stairs SPLC 34.10 (3), 34.34(2) Repair or replace the unsafe stairway in an approved manner. -The basement stairs are wobbly.
- 16. Interior Bathroom SPLC 34.11 (1), MSBC 2902.1, SPLC 34.35 (1), MPC 301.1 Repair or replace and maintain all parts of the plumbing system to an operational condition.

The bath tub is missing a handle.

The hand sink has a loose handle.

The toilet is loose.

- 17. Interior Bedrooms MSFC 1030.2 Remove the materials that cause an exit obstruction. Maintain a clear and unobstructed exit path. -There are household items blocking the walking path to the bedroom window.
- 18. Interior Cabinets SPLC 34.10 (7) Repair and maintain the cabinets in an approved manner.
- 19. Interior Ceilings SPLC 34.10 (7), 34.17 (5) Repair and maintain the ceiling in an approved manner.
- 20. Interior Floors SPLC 34.10 (7), 34.17(5) Repair and maintain the floor in an approved manner.
- 21. Interior Kitchen SPLC 34.14 (2) c Repair or replace the duplex convenience outlet with ground fault protection within 3 feet of the basin on an adjacent wall in all bathrooms. This work may require a permit(s). Call DSI at (651) 266-8989.-The kitchen GFCI outlet does not trip when tested. and does not work.
- 22. Interior Light Fixtures MSFC 605.1 Repair or replace damaged electrical fixtures. This work may require a permit(s). Call DSI at (651) 266-8989.-There are light fixtures that are not properly installed and secured.
- 23. Interior Light Fixtures MSFC 605.1- All light fixtures shall be maintained with protective globes if originally equipped.
- 24. Interior Smoke Alarms MN Stat. 299F.362 Immediately provide and maintain a smoke detector located outside each sleeping area. -There are missing hard-wired smoke alarms. Provide and maintain hard-wired smoke alarms with battery back-up.
- 25. Interior Stairs SPLC 34.10 (3), 34.34(2) Provide an approved handrail. The top of the handrail must be between 34 and 38 inches above the treads and run the entire length of the stair. -The handrails for the stairs and basement stairs are of the incorrect type.

- 26. Interior Throughout MSFC 605.6 Provide electrical cover plates to all outlets, switches and junction boxes where missing.
- 27. Interior Throughout MSFC 315.3 Provide and maintain orderly storage of materials.
- 28. Interior Throughout MN Stat 299F.18 Immediately remove and discontinue excessive accumulation of combustible materials.
- 29. Interior Throughout SPLC 34.10 (7), 34.17 (5) Repair or replace and maintain the woodwork in an approved manner.
- 30. Interior Upstairs Area SPLC 34.19 Provide access to the inspector to all areas of the building. -There is a small doorway on the second floor that has been covered up by gypsum board. Remove the board and provide access to this room.
- 31. Interior Walls SPLC 34.10 (7), 34.17 (5) Repair and maintain the walls in an approved manner.
- 32. SPLC 39.02(c) Complete and sign the smoke detector affidavit and return it to this office.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8585) and must be filed within 10 days of the date of the original orders.

If you have any questions, email me at Efrayn.Franquiz@ci.stpaul.mn.us or call me at 651-266-8955 between 7:30 a.m. - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Efrayn Franquiz Fire Safety Inspector Ref. # 122368