

APPLICATION FOR APPEAL

Saint Paul City Council - Legislative Hearings

RECEIVED

NOV C8 2019

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8585

- Common		
We need the following to process your appe	al: CITY CLER	<
\$25 filing fee (non-refundable) (payable to the (if cash: receipt number 95045) Copy of the City-issued orders/letter be Attachments you may wish to include This appeal form completed Walk-In OR O Mail-In for abatement orders only: O Email	he City of Saint Paul)	
Address Being Appealed:		
Number & Street: 2034 REANEY AVE E. City: St. PAUL State: MN Zip: 55119		
Appellant/Applicant: DANIEL WARDIT Email BOWARD 50 @ gmail: com		
Phone Numbers: Business 612 607 7710 Residence Cell 612 607 7710		
Signature: Date: NOV 6, 2019		
Name of Owner (if other than Appellant):		
Mailing Address if Not Appellant's: 1769 Lexington DVE N. Suite 460 Roseville 55113		
Phone Numbers: Business	Residence	Cell
What Is Being Appealed and Why? Attachments Are Acceptable		
	omments:	
Revocation of Fire C of O	1, Chimney Swee	p can't get chimney cleaned until
O Summary/Vehicle Abatement	DEC 26th.	, = 1 1,
Fire C of O Deficiency List/Correction	5. Weather will	not allow me to paint outdoors
X Code Enforcement Correction Notice		l 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
O Vacant Building Registration	3. I have aggree	pate material scheduled to be delivered
Other (Fence Variance, Code Compliance, etc.)	at the end of	thanksgiving holiday for erosion control irs.
	under front sto	to to extend the repair time to
	4. I would like	Revised 4/10/2017

allow me to get things complete, Prie to my recent health problems,

Revised 4/10/2017

Ricardo X. Cervantes, Director

CITY OF SAINT PAUL

375 Jackson Street, Suite 220 St Paul, Minnesota 55101-1806 Telephone: 651-266-8989 Facsimile: 651-266-9124

Web: www.stpaul.gov/dsi

October 30, 2019

Daniel Ward 1769 Lexington Ave N Ste 460 Roseville MN, 55113USA

Revocation of Fire Certificate of Occupancy and Order to Vacate

RE:

2034 REANEY AVE

Ref. # 123417

Dear Property Representative:

Your building was inspected on October 30, 2019, for the renewal of the Certificate of Occupancy. Since you have failed to comply with the applicable requirements, it has become necessary to revoke the Certificate of Occupancy in accordance with Section 40.06 of the Saint Paul Legislative Code.

A reinspection will be made on November 22, 2019 at 12:30 pm. Failure to comply will result in the enforcement of the revocation and order to vacate by November 30th, 2019

The Saint Paul Legislative Code further provides that no building shall be occupied without a Certificate of Occupancy. Failure to immediately complete the following deficiency list or the building vacated may result in a criminal citation.

DEFICIENCY LIST



Alley garage - SPLC 34.08(5), 34.32(3) - All accessory structures including, but not limited to, detached garages, sheds and fences shall be maintained structurally sound and in good repair. Provide and maintain exterior unprotected surfaces painted or protected from the elements.-Vehicle door missing panel.



Bedrooms and hallway. - SPLC 34.12 (2), SPLC 34.36 (1) - Repair and maintain all required and supplied equipment in an operative and safe condition to properly and safely perform their intended function in accordance with the provisions of the applicable code.-Smoke detectors have no batteries.



EXTERIOR - BACK STAIRWAY - SPLC 34.08(5), 34.32(3) - All accessory structures including, but not limited to, detached garages, sheds and fences shall be maintained structurally An Equal Opportunity Employer

sound and in good repair. Provide and maintain exterior unprotected surfaces painted or protected from the elements.-Retaining walls have cracks on the alley side by stairway to garage.

1945

- 4. EXTERIOR BACK STAIRWAY SPLC 34.09 (3) 34.33 (2) Provide an approved handrail. The top of the handrail must be between 34 and 38 inches above the treads and run the entire length of the stair.-Handrail is missing on the stairway by the garage.
- ma sai Gu
- 5. EXTERIOR HOUSE & GARAGE SPLC 34.12 (2), SPLC 34.36 (1) Repair and maintain all required and supplied equipment in an operative and safe condition to properly and safely perform their intended function in accordance with the provisions of the applicable code. Gutters are rotting deteriorating, and disconnected. Leaves and debris inside the gutters.

DANKET

6. EXTERIOR - THROUHGOUT - SPLC 34.09 (3), 34.33(2) - Repair or replace the unsafe stairways, porch, decks or railings in an approved manner. This work may require a permit(s). Call DSI at (651) 266-8989.-Front concrete steps have cracks and there are holes underneath the steps. Rear concrete steps are leaning and have cracks. Front wooden steps need risers and erosion control.

Entry stairs to rear of building - SPLC 34.08(5), 34.32(3) - All accessory structures including, but not limited to, detached garages, sheds and fences shall be maintained structurally sound and in good repair. Provide and maintain exterior unprotected surfaces painted or protected from the elements.

PANIEL

8. INTERIOR - BASEMENT - NEC 408.4 <u>Circuit Directory</u> - Every electrical circuit shall be legibly identified as to its clear, evident, and specific purpose or use.-

MANIES

- 9. INTERIOR BASEMENT SPLC 34.10 (7), 34.17 (5) Repair and maintain the ceiling in an approved manner.-Multiple holes in ceiling throughout the basement.
- 10. INTERIOR BASEMENT SPLC 34.11 (1), MSBC 2902.1, SPLC 34.35 (1), MPC 301.1 Repair or replace and maintain all parts of the plumbing system to an operational condition.-Drain piping is not connected, possibly has a slow leak because of it.

PANIE

11. INTERIOR - BASEMENT STAIRWAY - SPLC 34.10 (3) 34.34(2) - Provide an approved guardrail. Intermediate balustrade must not be more than 6 inches apart. Intermediate rails must be provided if the height of the platform is more than 30 inches.-

DANIEL

- 12.) INTERIOR <u>FIREPLACE</u> MSFC 603.6 Have the chimneys, fireplaces, and vents inspected for soundness, freedom from deposits, and correct clearances. Cleaning, maintenance, and repairs shall be done if indicated by the inspection.-
- 13. INTERIOR THROUGHOUT MSFC 605.6 Provide electrical cover plates to all outlets, switches and junction boxes where missing.-Throughout the basement and under kitchen sink.

14. INTERIOR - THROUGHOUT - MSFC 605.1 - Repair or replace damaged electrical fixtures. This work may require a permit(s). Call DSI at (651) 266-8989.-BASEMENT: Outlet is not secured to the wall. MAIN LEVEL: Dining room light fixture is missing.

DANIES

15. INTERIOR - THROUGHOUT - SPLC 34.10 (7), 34.17 (5) - Repair or replace and maintain the woodwork in an approved manner.-Baseboard is missing in the basement, living room kitchen/dining room north bedroom & south bedroom. West bedroom access panel in closet is missing.

DANTE

16. INTERIOR - THROUGHOUT - MMC 2103 - All equipment, appurtenances, devices, and piping must be installed in a workmanlike manner.-<u>Vent covers are missing in the dining</u> room, south bedroom and basement.

TRIAN

ş:

17. Rear yard - SPLC 34.08 (1), 34.32 (1) - All exterior property areas shall be maintained free from any accumulation of refuse, garbage or feces.-Trash bags full of dirt.

South bedroom - MN Stat 299F.18 - Immediately remove and discontinue excessive accumulation of combustible materials.-

SPLC 39.02(c) - Complete and sign the smoke detector affidavit and return it to this office.

20. -Revocation is due to long term non-compliance with the Fire Certificate of Occupancy Orders.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8585) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: mike.cassidy@ci.stpaul.mn.us or call me at 651-266-9022 between 7:30 - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Mike Cassidy Fire Inspector

Ref. # 123417



Daniel Ward II <doward50@gmail.com>

Chimney Cleaning and Inspection

1 message

Kristen Arnesen <kristen@ablechimneysweeps.com>
To: doward50@gmail.com

Fri, Nov 8, 2019 at 2:41 PM

Dear Daniel,

On Thursday, December 26th at 3pm we will come to your property at 2034 Reaney Ave E and do a Level 2 cleaning and inspection. A Level 2 includes a cleaning and an inspection with a closed circuit camera system to inspect the condition of the interior of the flue. You will receive a detailed written report outlining any areas of concern.

Due to this being the high season for chimney businesses, we will not be able to come to your property before the date you are scheduled for. If I have a cancellation I will call you and get you rescheduled.

Thank you for your call.

--

Best, Kristen Arnesen

Able Chimney Sweep

(612) 867-4252

www.ablechimneysweeps.com

