SAINT PAUL CITY OF SAINT PAUL

375 Jackson Street, Suite 220 St Paul, Minnesota 55101-1806 

 Telephone:
 651-266-8989

 Facsimile:
 651-266-9124

 Web:
 www.stpaul.gov/dsi

August 25, 2020

PBK Properties LLC PO BOX 32255 FRIDLEY MN 55432 USA

RE: RE-INSPECTION FIRE CERTIFICATE OF OCCUPANCY WITH DEFICIENCIES 49 COOK AVE W

Ref. # 110843

Dear Property Representative:

Your building was re-inspected for the Fire Certificate of Occupancy on August 20, 2020. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected immediately.

## A reinspection will be made on September 1, 2020 before 4:00 PM.

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

## **DEFICIENCY LIST**

- 1. 49 Cook Exterior House SPLC 34.09 (1)(2), 34.33 (1) Provide and maintain all exterior walls free from holes and deterioration. All wood exterior unprotected surfaces must be painted or protected from the elements and maintained in a professional manner free from chipped or peeling paint. -There is a section of the fascia cover that is missing.
- 2. Exterior Back Stairs SPLC 34.09 (3), 34.33(2) Repair or replace the damaged handrail in an approved manner. This work may require a permit(s). Call DSI at (651) 266-8989.-The new handrail for the back stairs do not have the return pieces on them.
- 3. Exterior Fences SPLC 34.08(5), 34.32(3) All accessory structures including, but not limited to, detached garages, sheds and fences shall be maintained structurally sound and in good repair. Provide and maintain exterior unprotected surfaces painted or protected from the elements. -The small fence at the front of the property is still in disrepair.

- 4. Exterior Parking Surface SPLC 34.08 (7) All parking spaces shall be paved with asphalt, concrete, or durable dustless surfacing. Before any existing spaces may be paved, site plan approval must be obtained as specified in the St. Paul Zoning Code. Contact DSI Zoning at 651-266-8989.-The lower section of the parking surface is in disrepair with very large sections broken and deteriorated.
- 5. Exterior Windows SPLC 34.09 (4), 34.33 (3) Repair and maintain the window in good condition. -There are windows on the East side of the house that has chipping and peeling paint and the seal around the window is worn and/or missing
- 6. SPLC 39.02(c) Complete and sign the smoke detector affidavit and return it to this office.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8585) and must be filed within 10 days of the date of the original orders.

If you have any questions, email me at Efrayn.Franquiz@ci.stpaul.mn.us or call me at 651-266-8955 between 7:30 a.m. - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Efrayn Franquiz Fire Safety Inspector Ref. # 110843