

CITY OF SAINT PAUL, MN

DEPARTMENT OF SAFETY AND INSPECTIONS

Steve Magner, Manager of Code Enforcement

375 Jackson Street, Suite 220

Truth-in-Sale of Housing Report

Saint Paul, MN 55101-1806 This is a visual disclosure report based on the current City of Saint Paul Truth-in-Sale of Housing Evaluator Guidelines and is valid for one year from the date of issuance and for the owner named.

Phone: 651-266-8989 Fax: 651-266-1919 Web: www.stpaul.gov/dsi

Property Address: 1235 MARGARET ST

Date of Evaluation: Apr 17, 2020 Date of Expiration: Apr 17, 2021

This report is intended to provide basic information to the home buyer and seller prior to the time of sale.

This report WILL NOT be used to enforce the requirements of the Legislative Code; however, it will be used to determine if there is compliance with the requirements for sale within the City of Saint Paul, MN.



MAJOR NOTIFICATIONS AND WARNINGS

For questions on these items, call the City's Information and Complaint Line at 651-266-8989

- Residential Type: Single Family Dwelling
- Smoke Detectors:
 - Smoke Detector Present: Y
 - Smoke Detector Properly Located: Y
 - Smoke Detector Hard Wired (required in Single Family Homes): Y
 - Smoke Detector Comments:
- Open Permits:

This property has No Open Permits.

- Registered Vacant Building
 - Visit <u>www.stpaul.gov/dsi</u> or call 651-266-8989

BELOW MINIMUM

Basement/Cellar

- Basement/Cellar Floor
- First Floor, Floor System
- Foundation
- · Stairs and Handrails

Bathroom(s)

Plumbing fixtures

Enclosed Porches and Other Roc

· Walls, ceiling and floor condition

Exterior Space

- Chimney(s)
- Cornice and trim(s)
- Drainage (grade)
- Foundation

Hallways, Stairs and Entries

Stairs and handrails to upper floors

Plumbing System

• Water heater(s), installation

Report Rating Key (Where there are multiple rooms to a category, the Evaluator must specify the room to which a Comment is rela				n to which a Comment is related)
	H: Hazardous Condition	B: Below Minimum	C: See Comments	M: Meets Minimum
	Y: Yes	N: No	NV: Not Visible	NA: Not Applicable

CITY OF SAINT PAUL TRUTH-IN-SALE OF HOUSING REPORT

Address: 1235 MARGARET ST File Number: File#: 20-027032 Owner: 1235 Margaret Street Llc Date of Evaluation: Apr 17, 2020 Client Name: Travis Senenfelder Zoning District: RT1

Client Contact: Travis Senenfelder 651-216-94 Present Occupancy: R-Single Family Dwelling

Number of Units Evaluated: Single Family Evaluator Name: Dan Brausen InnerSpec Dwelling Evaluator Contact: Work: 651-483-8407

danbrowsin@msn.com

Basement/Cellar

1. Stairs and Handrails В 1. B - Headroom less than 6 feet 8 inches.B -Stairway(s) less than 36 inches.

2. Basement/Cellar Floor В 2. B - Crawl space vapor barrier is missing/incomplete.

3. Foundation В 3. B - Loose/missing mortar.C - Limited view of

crawl space(s).

4. Evidence of Dampness or Υ 4. C - Surface spalling noted in areas. Staining

5. First Floor, Floor System R 5. B - Wood lacks 18 inch clearance over dirt in crawl space(s).C - Limited view of crawl space(s).

6. Beams and Columns Μ 6. C - Limited view of crawl space(s).

Electrical Services

7a. Number of Electrical Services 1

7b. Amps 100

7c. Volts 120-240

Basement Only

8. Electrical service M installation/grounding 9. Electrical wiring, outlets and Μ

fixtures

Plumbing System

10. Floor drain(s) (basement) M 10. C - No floor drain located. 11. Waste and vent piping (all Μ 11. C - Main cleanout not located.

floors)

12. Water piping (all floors) Μ 13. Gas piping (all floors) Μ

14. Water heater(s), installation В 14. B - Rust noted on water heater jacket.

15. Water heater(s), venting M 15. C - Tape restricts view of connection screws.

16. Plumbing fixtures M (basement)

Heating System(s)

The Evaluator is not required to operate the heating plant(s) except during the heating season, between October 15 and April 15.

17a. Number of Heating

Systems

1235 MARGARET ST Apr 17, 2020 Evaluator: Dan Brausen InnerSpec Page # 3 Report Rating Key (Where there are multiple rooms to a category, the Evaluator must specify the room to which a Comment is related) H: Hazardous Condition B: Below Minimum C: See Comments M: Meets Minimum N: No NV: Not Visible NA: Not Applicable Y: Yes

17b. Type	Forced Air	
17c. Fuel	Gas	
18. Installation and visible condition	M	
19. Viewed in operation (required in heating season)	Υ	
20. Combustion venting	М	
21a. Additional heating unit(s):	NA	
Type 21b. Additional heating unit(s): Fuel	NA	
21c. Installation and visible condition	NA	
21d. Viewed in operation	NA	
21e. Combustion venting	NA	
Kitchen		
22. Walls and ceiling	M	
23. Floor condition and ceiling height	М	
24. Evidence of dampness or staining	N	
25. Electrical outlets and fixtures	M	
26. Plumbing fixtures	M	
27. Water flow	М	
28. Window size/openable area/mechanical exhaust	M	
29. Condition of doors/windows/mechanical exhaust	M	
Living and Dining Room(s)		
30. Walls and ceiling	M	
31. Floor condition and ceiling height	M	
32. Evidence of dampness or staining	N	32.
33. Electrical outlets and fixtures	M	
34. Window size and openable area	M	
35. Window and door condition	М	
Hallways, Stairs and Entries		
36. Walls, ceilings, floors	M	
37. Evidence of dampness or	N	
staining 38. Stairs and handrails to upper floors	В	38. B - Head room less than 6 feet 8 inches.B - Steps: Improper Rise (7-3/4" max).B - Uneven risers.
39. Electrical outlets and fixtures	M	1100101

1235 MARGARET ST Apr 17, 2020 Evaluator: Dan Brausen InnerSpec

Report Rating Key (Where there are multiple rooms to a category, the Evaluator must specify the room to which a Comment is related) H: Hazardous Condition B: Below Minimum C: See Comments M: Meets Minimum NV: Not Visible N: No NA: Not Applicable Y: Yes

40. Window and door conditions	M			
Smoke Detectors				
41a. Present	Υ			
41b. Properly Located 41c. Hard-Wire	Y Y			
Bathroom(s)	'			
42. Walls and ceiling	М			
43. Floor condition and ceiling	M			
height	IVI			
44. Evidence of dampness or staining	Υ	44. C - Stain noted on ceiling.(1st)		
45. Electrical outlets and fixtures	M			
46. Plumbing fixtures	В	46. B - Improper putty repairs on drain assembly.		
47. Water flow	M			
48. Windows size/openable area/mechnical exhaust	M			
49. Condition of windows/doors/mechanical exhaust	M			
Sleeping Room(s)				
50. Walls and ceilings	M			
51. Floor condition, area and ceiling height	М			
52. Evidence of dampness or staining	N			
53. Electrical outlets and fixtures	М			
54. Window size and openable area	M			
55. Window and door condition	M			
Enclosed Porches and Other Ro	oms			
56. Walls, ceiling and floor condition	В	56. B - Room settled - out of level.		
57. Evidence of dampness or	N			
staining 58. Electrical outlets and fixtures	М			
59. Window and door condition	М			
Attic Space				
60. Roof boards and rafters	NV	60. C - No attic access located - attic not viewed.		
61. Evidence of dampness or	NV			
staining 62. Electrical	NV			
wiring/outlets/fixtures 63. Ventilation	NV			
	. 4 V			
Exterior Space 64. Foundation	D	64 P. Damagod areas on coment costing. C		
04. FOULIGATION	В	64. B - Damaged areas on cement coating. C - Deck/skirting restrict view.		

1235 MARGARET ST Apr 17, 2020 Page # 5 Evaluator: Dan Brausen InnerSpec

Report Rating Key (Where there are multiple rooms to a category, the Evaluator must specify the room to which a Comment is related)				
H: Hazardous Condition	B: Below Minimum	C: See Comments	M: Meets Minimum	
Y: Yes	N: No	NV: Not Visible	NA: Not Applicable	

: Yes		N: No		NV: Not Visible	NA: Not Applicable
	65. Basement/cellar	windows	M		
	66. Drainage (grade	e)	В	66. B - Walks/patio cracked Grade in areas does not pro	
	67. Exterior walls		М	Grade in areas aces not pro	mote proper dramage.
	68. Doors		М		
	(frames/storms/scr 69. Windows (frames/storms/scr		М		
	70. Open porches, s deck(s)	stairways and	М	70. C - Snow cover restricts deck components.	s view. C - Weathered
	71. Cornice and trin	n(s)	В	71. B - Weathered in areas.	C - Some peeling paint.
	72. Roof structure a	and covering	M		
	73. Gutters and dov	vnspouts	M		
	74. Chimney(s)		В	74. B - Missing mortar.	
	75. Outlets, fixtures entrance	s and service	М		
Ga	rage(s)/Accessor	y Structure(s	s)		
	76. Roof structure a	and covering	NA		
	77. Wall structure a	nd covering	NA		
	78. Slab condition		NA		
	79. Garage door(s)		NA		
	80. Garage opener(s	s)	NA		
	81. Electrical wiring fixtures	, outlets and	NA		
Fir	eplace/Woodstov	e			
	82. Number of Units	S	NA		
	83. Dampers install	ed	NA		
	84. Installation		NA		
	85. Condition		NA		
Ins	sulation				
	86a. Attic Insulation	n: Present	NV		
	86b. Attic Insulation	n: Type	NV		
	86c. Attic Insulation	n: Depth	NV		
	87a. Foundation Ins	sulation:	N		
	87b. Foundation Ins Type		NA		
	87c. Foundation Ins Depth		NA		
	88a. Knee Wall Insu Present		NV		
	88b. Knee Wall Insu	•	NV		
	88c. Knee Wall Insu	•	NV		
	89a. Rim Joist Insula	ation:	NV		

1235 MARGARET ST Apr 17, 2020

NV

89b. Rim Joist Insulation: Type

Present

Report Rating Key (Where there are multiple rooms to a category, the Evaluator must specify the room to which a Comment is rela				n to which a Comment is related)
	H: Hazardous Condition	B: Below Minimum	C: See Comments	M: Meets Minimum
	Y: Yes	N: No	NV: Not Visible	NA: Not Applicable

89c. Rim Joist Insulation: Depth

General

90. Carbon Monoxide Alarm Μ

General Comments

1235 MARGARET ST Apr 17, 2020 Evaluator: Dan Brausen InnerSpec Page # 7

LEGAL NOTICES:

Chapter 189 of the Saint Paul Legislative Code requires all single family, duplex, condo, townhouse and co-op homes for sale in the city to have a Truth-in-Sale of Housing disclosure report prepared and available to prospective buyers. A Truth-in-Sale of Housing disclosure report must be done for Contract-For-Deed sales.

A Truth-in-Sale of Housing (TISH) Disclosure Report in the City of Saint Paul is intended to provide basic information to the home buyer and seller prior to the time of sale. Failure to obtain a Truth-in-Sale of Housing disclosure report or failure to make that disclosure report available to prospective buyers, is a violation of law and is punishable as a misdemeanor carrying up to 90 days in jail and/or a \$1,000.00 fine.

A valid Truth-in-Sale of Housing disclosure report must be conspicuously displayed at the premises for all prospective buyers. TISH disclosure reports are also available online: https://online.stpaul.gov/web/portal/public-search

- This report WILL NOT be used to enforce the requirements of the Legislative Code; however, this
 evaluation form will be used to determine if there is compliance with the requirements for a hardwired smoke detectors.
- This TISH report is based on the current Truth-in-Sale of Housing Evaluator Guidelines and is based upon different standards than the lender, Federal Housing Administration (FHA) or Veterans Administration (VA).
- This TISH is not warranted, by the City of Saint Paul nor by the evaluator for the condition of the building component, nor of the accuracy of this report.
- This TISH report covers only the items listed on the form and only those items visible at the time of the evaluation.
- The Evaluator is not required to operate the heating plant (except during the heating season), use a ladder to observe the condition of the roofing, disassemble items or evaluate inaccessible areas.
- This TISH report is valid for one year from the date of issue and only for the owner named on this report.
- If this building is used for any purpose other than a single family dwelling, it may be illegally zoned. To help you determine legal uses under the zoning ordinance, contact the Zoning Administrator at (651) 266-9008.
- Automatic garage doors should reverse upon striking an object. If it does not reverse, it poses a serious hazard and should be repaired or replaced immediately.
- All single family residences in Saint Paul must have at least one smoke detector connected to the electrical system (hard-wired). The detector must be located near sleeping rooms. For more information call Fire Prevention, (651)228-6230. (Saint Paul Legislative Code, Chapter 58.)
- Rainleaders connected to the sanitary sewer system must be disconnected. For more information call Public Works, Sewer Utility, and (651)266-6234.
- A house built before 1950 may have lead paint on/in it. If children ingest lead paint, they can be poisoned. For more information call Ramsey County Public Health, (651)292-6525.
- Neither the City of Saint Paul nor the Evaluator is responsible for the determination of the presence of airborne particles such as asbestos, noxious gases such as radon, or other conditions of air quality that may be present, nor the conditions which may cause the above.

Questions regarding this report should be directed to the evaluator. If you desire a reinspection and amended report, please contact your evaluator. They will perform a reinspection and file an amended report with the City of Saint Paul. The TISH evaluator may charge for this reinspection. Complaints regarding this report should be directed to Department of Safety and Inspections, Truth-in-Sale of Housing Program, Phone 651-266-8989.

1235 MARGARET ST Apr 17, 2020

Evaluator Statement:

I hereby certify I prepared this report in compliance with the Saint Paul Evaluator Guidelines, City of Saint Paul City Ordinance 189 and all other applicable policies and procedures of the Truth-in_Sale of Housing Board. I have utilized reasonable and ordinary care and diligence and I have noted all conditions found that do not conform to the minimum standards of maintenance. The report covers only those problems listed and reasonably visible at the time of my evaluation and does not warrent future useful life of any house component or fixture. I have included all required information pages with this report. Evaluator Name: Dan Brausen InnerSpec

Phone: Work: 651-483-8407 Evaluation Date: Apr 17, 2020

1235 MARGARET ST Apr 17, 2020 Evaluator: Dan Brausen InnerSpec