

Saint Paul Fire Department FIRE INCIDENT DISPOSITION



INCIDENT NUMBER:	20-20690	DATE OF INCIDENT: 6-9-2020	
TIME OF INCIDENT:	0441 Hours	POLICE CASE #: n/a	
INVESTIGATOR (s) :	Blank, J		
INCIDENT ADDRESS:	9 Acker St W #1 Saint Paul, MN 55117		
OCCUPANT NAME:	Peng M Her	PHONE: n/a	
OWNER NAME:	Dong Yang	PHONE: 651-210-5952	
ADDRESS OF OWNER:	1510 Clarence St St Paul, MN 55106		
PROPERTY DAMAGED:	Up/Down Duplex	AREA OF ORIGIN: East Side of Living Room 1 st Fl	
DAMAGE ESTIMATE:	Building \$40,000	Vehicle \$n/a	Other (Describe) \$n/a
VALUE:	Building \$111,000	Vehicle \$n/a	Other (Describe) \$n/a
Damage Estimate CONTENTS ONLY:	\$5,000		
INJURY/DEATH (if yes, explain)	<input type="checkbox"/> No <input checked="" type="checkbox"/> Yes Minor burns to adult male occupant who refused transport to hospital		
SMOKE DETECTOR, SPRINKLER, and CARBON MONOXIDE INFORMATION:	Smoke Detector Present: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Unknown Detector Functioning: <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Unknown Sprinkler System Present: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Unknown Sprinkler Heads activated: <input type="checkbox"/> Yes # <input checked="" type="checkbox"/> No <input type="checkbox"/> Unknown C.O Detector Present: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Unknown		
FIRE CAUSE CLASSIFICATION:	<input checked="" type="checkbox"/> Accidental <input type="checkbox"/> Juvenile/Incendiary <input type="checkbox"/> Incendiary <input type="checkbox"/> Child (under 10 years old) <input type="checkbox"/> Natural <input type="checkbox"/> Undetermined <input type="checkbox"/> Under Investigation		
SYNOPSIS:	The Fire Department was called to a report of a dwelling fire. Firefighters arrived to find a fire burning on the 1 st floor on the east side of the living room and quickly extinguished it. The occupant reports awakening to glass breaking and fire burning in the living room near the window. The occupant denies smoking or use of candles. The gas service to the home is not turned on but the home has electric service. There was an extension cord and fan plugged in in the area of origin and no other sources of ignition. The ignition source was probably electrical energy. The first fuel ignited was common combustible material in the area. The action that brought these items together was probably due to an electrical arc. The classification of fire cause is accidental.		
DISPOSITION:	<input type="checkbox"/> E-mail only <input type="checkbox"/> Hold Scene until approved <input type="checkbox"/> DO NOT DEMOLISH until approved <input checked="" type="checkbox"/> Scene Released <input type="checkbox"/> Analysis of Evidence Pending <input checked="" type="checkbox"/> Report to Follow		