Saint Paul Fire Department FIRE INCIDENT DISPOSITION



INCIDENT NUMBER:	20-02862/20-02863	DATE OF INCIDENT: 01/22/2020	
TIME OF INCIDENT:	2115/2134 Hours	POLICE CASE #: 20-015-175	
INVESTIGATOR(s):	B. Riewe		
INCIDENT ADDRESS:	535 Forest Street, Saint Paul, MN 55106		
OCCUPANT NAME:	None	PHONE: N/A	
OWNER NAME:	Vanna Yean Malika N. Keo	PHONE: 651-699-6190	
ADDRESS OF OWNER:	PO Box 25463, Woodbury, MN 55125-2841		
PROPERTY DAMAGED:	Single Family Dwelling	AREA OF ORIGIN: Multiple points	
DAMAGE ESTIMATE:	Building \$2,000	Vehicle \$	Other(Describe) \$
VALUE :	Building \$63,600	Vehicle \$	Other(Describe) \$
Damage Estimate CONTENTS ONLY:	\$ 500		
INJURY/DEATH (if yes, explain)	🛛 No 🗌 Yes		
SMOKE DETECTOR, SPRINKLER, and CARBON MONOXIDE INFORMATION:	Smoke Detector Present:YesNoUnknownDetector Functioning:YesNoUnknownSprinkler System Present:YesNoUnknownSprinkler Heads activated:Yes #NoUnknownC.O Detector Present:YesNoUnknown		
FIRE CAUSE CLASSIFICATION:	Accidental Juvenile/Incendiary Incendiary Child (under 10 years old) Natural Undetermined Under Investigation		
SYNOPSIS:	The Saint Paul Fire Department was dispatched to the report of a mattress fire outside of a vacant home. Firefighters arrived on scene to find an extinguished mattress fire located in the side yard of a home. The home was posted vacant and found unsecured. Investigation and interviews conducted on scene determined squatters were living in the vacant home and starting fires on the floor in multiple rooms to remain warm. The ignition source was most likely an open flamed device. The first fuel ignited was most likely wood and/or paper. The act that brought these two together was most likely an intentional human act. The classification of fire cause is incendiary.		
DISPOSITION:	E-mail only Hold Scene until approved DO NOT DEMOLISH until approved Scene Released Analysis of Evidence Pending Report to Follow		