

Other (Fence Variance, Code Compliance, etc.)

APPLICATION FOR APPEAL

Saint Paul City Council - Legislative Hearings

RECEIVED NOV 24 2020 310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8585

- Cultivis			
We need the following to process your a	SERK		
\$25 filing fee (non-refundable) (payable (if cash: receipt number ASNET) Copy of the City-issued orders/letter Attachments you may wish to include This appeal form completed Walk-In OR OMail-In for abatement orders only: © Email	to the City of Saint Paul) S. C. C. C. Decide Decing appealed de		tive Hearing Office) 1, 2020 N Courthouse
Address Being Appeal	ed:		
Number & Street: 474 Blo			1
Appellant/Applicant: Shalanda Nathane	William Em	ail Lashal 6	38 @ g mo.1.
Phone Numbers: Business	Residence	Cell <u>6</u>	5/36/9/92
Signature:		Date: 11-1	5-20
Name of Owner (if other than Appellant):			
Mailing Address if Not Appellant's: 15	04 128 Ave 1	1E Blane	hu S3449
Phone Numbers: Business	Residence	Cell	6513619192
What Is Being Appeale	ed and Why?	Attachments A	re Acceptable
O Vacate Order/Condemnation/ Revocation of Fire C of O	Comments: Howe body gesting recht +	liven	
O Summary/Vehicle Abatement	Sale	c sail	
O Fire C of O Deficiency List/Correction) seed		
Code Enforcement Correction Notice			
O Vacant Building Registration			



CITY OF SAINT PAUL

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806

 Telephone:
 651-266-8989

 Facsimile:
 651-266-8951

 Web:
 www.stpaul.gov/dsi

November 5, 2020

SHALANDA WILLIAMS SHALANDA WILLIAMS 1504 128TH AVE NE BLAINE MN 55449 USA

FIRE INSPECTION CORRECTION NOTICE

RE:

474 BLAIR AVE

Ref. #125546

Residential Class: C

Dear Property Representative:

Your building was inspected on November 5, 2020 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date. A reinspection will be made on December 9, 2020 at 2:30PM.

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

DEFICIENCY LIST

- 1. Exterior Southside SPLC 34.09 (3), 34.33(2) Repair or replace the unsafe stairways, porch, decks or railings in an approved manner. This work may require a permit(s). Call DSI at (651) 266-8989.-Repair or replace deteriorated deck planks and maintain unprotected wood surfaces.
- 2. Exterior Throughout SPLC 34.09 (4), 34.33 (3) Repair and maintain the window glass. -Repair or replace broken window glass.

- 3. Exterior Throughout SPLC 34.09 (4), 34.33 (3) -Provide or repair and maintain the window screen. -Repair or replace missing or torn window screens.
- 4. Interior Kitchen SPLC 34.12 (2), SPLC 34.36 (1) Repair and maintain all required and supplied equipment in an operative and safe condition to properly and safely perform their intended function in accordance with the provisions of the applicable code. -Repair or replace front burner on kitchen stove.
- 5. Interior Throughout MSFC 605.1- All light fixtures shall be maintained with protective globes if originally equipped. -**Provide missing globes.**
- 6. Interior Throughout SPLC 34.10 (7), 34.17 (5) Repair and maintain the ceiling in an approved manner. -Repair living room, Southeast and Northeast bedrooms ceilings.
- 7. Interior Basement MN Stat 299F.18 Immediately remove and discontinue excessive accumulation of combustible materials. -Reduce excessive materials by 50% in the basement.
- 8. Interior Basement MSFC 605.1 -Provide a grounding jumper around the water meter. Provide missing water meter jumper wire.
- 9. Interior Basement NEC 110.26 Provide and maintain a minimum of 36 inches clearance in front of all electrical panels. -Remove materials from blocking panel in basement.
- 10. Interior Bathroom SPLC 34.10 (4), 34.34 (3) Provide a bathroom floor impervious to water. -Repair or replace bathroom floor.
- 11. Interior Bathroom SPLC 34.11 (1), MSBC 2902.1, SPLC 34.35 (1), MPC 301.1 Repair or replace and maintain all parts of the plumbing system to an operational condition. -Replace or repair missing parts of upstairs bathroom.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8585) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: Torrance.Harriel@ci.stpaul.mn.us or call me at 651-266-8941 between 7:30 a.m. - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Torrance Harriel Fire Safety Inspector

Reference Number 125546