

CITY OF SAINT PAUL, MN

DEPARTMENT OF SAFETY AND INSPECTIONS

Steve Magner, Manager of Code Enforcement Vicki Sheffer, Truth-in-Sale of Housing Manager

375 Jackson Street, Suite 220 Saint Paul, MN 55101-1806

Phone: 651-266-8989 Fax: 651-266-1919 Web: <u>www.stpaul.gov/dsi</u>


Truth-in-Sale of Housing Report

This is a visual disclosure report based on the current City of Saint Paul Truth-in-Sale of Housing Evaluator Guidelines and is valid for one year from the date of issuance and for the owner named.

Property Address: 963 WATSON AVE Date of Evaluation: Feb 8, 2021 Date of Expiration: Feb 08, 2022

This report is intended to provide basic information to the home buyer and seller prior to the time of sale.

This report WILL NOT be used to enforce the requirements of the Legislative Code; however, it will be used to determine if there is compliance with the requirements for sale within the City of Saint Paul, MN.



MAJOR NOTIFICATIONS AND WARNINGS

For questions on these items, call the City's Information and Complaint Line at 651-266-8989

- Residential Type: Single Family Dwelling
- Smoke Detectors:
 - Smoke Detector Present: Y
 - Smoke Detector Properly Located: Y
 - Smoke Detector Hard Wired (required in Single Family Homes): Y
 - Smoke Detector Comments:
- Open Permits:

This property has No Open Permits.

- Registered Vacant Building
 - Visit www.stpaul.gov/dsior call 651-266-8989

BELOW MINIMUM

Exterior Space

- Basement/cellar windows
- Drainage (grade)
- Gutters and downspouts

Report Rating Key (Where there are multiple rooms to a category, the Evaluator must specify the room to which a Comment is related			
H: Hazardous Condition	B: Below Minimum	C: See Comments	M: Meets Minimum
Y: Yes	N: No	NV: Not Visible	NA: Not Applicable

CITY OF SAINT PAUL TRUTH-IN-SALE OF HOUSING REPORT

Address: 963 WATSON AVE File Number: File#: 21-236296
Date of Evaluation: Feb 8, 2021 Owner: Mx Properties Llc

Zoning District: R4 Client Name: MX Properties LLC
Present Occupancy: Client Contact: MX Properties LLC

Number of Units Evaluated: Single Family Evaluator Name: George Ury Structure Tech Hon

Evaluator Contact: Cell: 952-334-7980

4. C - Evidence of dampness or staining.

george@structuretech.com

3. C - Vertical cracks

Basement/Cellar

Dwelling

Stairs and Handrails
 Basement/Cellar Floor
 M

3. Foundation M

4. Evidence of Dampness or Y Staining

5. First Floor, Floor System6. Beams and ColumnsM

Electrical Services

7a. Number of Electrical Services 1

7b. Amps 100

7c. Volts 120-240

Basement Only

8. Electrical service Minstallation/grounding

9. Electrical wiring, outlets and M

fixtures

Plumbing System

10. Floor drain(s) (basement) M11. Waste and vent piping (all M

floors)

12. Water piping (all floors) M

13. Gas piping (all floors) M

14. Water heater(s), installation M

15. Water heater(s), venting M

16. Plumbing fixtures M

(basement)

Heating System(s)

The Evaluator is not required to operate the heating plant(s) except during the heating season, between October 15 and April 15.

17a. Number of Heating

Systems

17b. Type Hot

Water

17c. Fuel Gas

963 WATSON AVE Evaluator: George Ury Structure Tech Home Inspections Feb 8, 2021

Report Rating Key (Where there are multiple rooms to a category, the Evaluator must specify the room to which a Comment is related)

H: Hazardous Condition

B: Below Minimum

C: See Comments

M: Meets Minimum

Y: Yes

N: No

NV: Not Visible

NA: Not Applicable

condition 19. Viewed in operation (required in heating season) 20. Combustion venting	/ / // //
19. Viewed in operation (required in heating season) 20. Combustion venting	ΛI
20. Combustion venting	
21a Additional booting unit(s).	NΑ
Type 21b. Additional heating unit(s): Fuel	NΑ
	NΑ
	NΑ
21e. Combustion venting	NΑ
Kitchen	
9	Λl
23. Floor condition and ceiling height	Λl
	N
	V
26. Plumbing fixtures	VI
27. Water flow	VI
area/mechanical exhaust	VI
29. Condition of Noncommon doors/windows/mechanical exhaust	√l
Living and Dining Room(s)	
	V
31. Floor condition and ceiling Neight	VI
32. Evidence of dampness or staining	N
	VI
34. Window size and openable Narea	V
	V
Hallways, Stairs and Entries 36. Walls, ceilings, floors	Л
	v. V
staining	√I
upper floors	√I
fixtures 40. Window and door conditions N	Λ

963 WATSON AVE Evaluator: George Ury Structure Tech Home Inspections

Report Rating Key (Where there are multiple rooms to a category, the Evaluator must specify the room to which a Comment is related)				
H: Hazardous Condition	B: Below Minimum	C: See Comments	M: Meets Minimum	
Y: Yes	N: No	NV: Not Visible	NA: Not Applicable	
Smoke Detectors				

41a. Present 41b. Properly Located 41c. Hard-Wire	Y Y Y
Bathroom(s) 42. Walls and ceiling	М
43. Floor condition and ceiling height44. Evidence of dampness or	M N
staining 45. Electrical outlets and	М

fixtures 46. Plumbing fixtures

M

47. Water flow	M
48. Windows size/openable area/mechnical exhaust	M
49. Condition of	Μ

49. Condition of windows/doors/mechanical exhaust

Sleeping Room(s)

50. Walls and ceilings	Μ
51. Floor condition, area and ceiling height	M
52. Evidence of dampness or	Ν
staining	
53. Electrical outlets and	M
fixtures	
54. Window size and openable	M
area	
55. Window and door condition	Μ

Enclosed Porches and Other Rooms

56. Walls, ceiling and floor	M
condition	
57. Evidence of dampness or	Ν
staining	
58. Electrical outlets and	Μ
fixtures	
59. Window and door condition	М

Attic Space

ic Space	
60. Roof boards and rafters	Μ
61. Evidence of dampness or	Ν
staining 62. Flectrical	М
wiring/outlets/fixtures	171
63. Ventilation	Υ

Exterior Space

•	
64. Foundation	M

65. Basement/cellar windows B

65. B - Peeling paint

963 WATSON AVE Evaluator: George Ury Structure Tech Home Inspections Report Rating Key (Where there are multiple rooms to a category, the Evaluator must specify the room to which a Comment is related) B: Below Minimum C: See Comments M: Meets Minimum Y: Yes N: No NV: Not Visible NA: Not Applicable

66. Drainage (grade) 66. B - Grade in areas doesn't allow surface water В to drain away from building. 67. Exterior walls Μ 68. Doors Μ (frames/storms/screens) 69. Windows M (frames/storms/screens) 70. Open porches, stairways and M deck(s) 71. Cornice and trim(s) M 72. Roof structure and covering Μ 73. Gutters and downspouts В 73. B - Down spouts lack proper extension.B -Uncapped gutter drain to sewer - gutter drainage to sewer no longer allowed. 74. Chimney(s) M 75. Outlets, fixtures and service M entrance Garage(s)/Accessory Structure(s) 76. Roof structure and covering NA 77. Wall structure and covering NA 78. Slab condition NA 79. Garage door(s) NA 80. Garage opener(s) NA 81. Electrical wiring, outlets and NA fixtures Fireplace/Woodstove 82. Number of Units NA 83. Dampers installed NA 84. Installation NΑ 85. Condition NA Insulation 86a. Attic Insulation: Present Υ 86b. Attic Insulation: Type 86b. C - Blown cellulose Loose fiberglas S 86c. Attic Insulation: Depth NA 87a. Foundation Insulation: NA Present 87b. Foundation Insulation: NA Type 87c. Foundation Insulation: NA Depth 88a. Knee Wall Insulation: NA Present 88b. Knee Wall Insulation: Type NA

963 WATSON AVE Evaluator: George Ury Structure Tech

88c. Knee Wall Insulation: Depth

NA

Home Inspections

Report Rating Key (Where there are multiple rooms to a category, the Evaluator must specify the room to which a Comment is related			
H: Hazardous Condition	B: Below Minimum	C: See Comments	M: Meets Minimum
Y: Yes	N: No	NV: Not Visible	NA: Not Applicable

89a. Rim Joist Insulation:

nsulation: NA

Present

89b. Rim Joist Insulation: Type NA89c. Rim Joist Insulation: Depth NA

General

90. Carbon Monoxide Alarm M

General Comments

963 WATSON AVE Evaluator: George Ury Structure Tech Home Inspections Feb 8, 2021

LEGAL NOTICES:

Chapter 189 of the Saint Paul Legislative Code requires all single family, duplex, condo, townhouse and co-op homes for sale in the city to have a Truth-in-Sale of Housing disclosure report prepared and available to prospective buyers. A Truth-in-Sale of Housing disclosure report must be done for Contract-For-Deed sales.

A Truth-in-Sale of Housing (TISH) Disclosure Report in the City of Saint Paul is intended to provide basic information to the home buyer and seller prior to the time of sale. Failure to obtain a Truth-in-Sale of Housing disclosure report or failure to make that disclosure report available to prospective buyers, is a violation of law and is punishable as a misdemeanor carrying up to 90 days in jail and/or a \$1,000.00 fine.

A valid Truth-in-Sale of Housing disclosure report must be conspicuously displayed at the premises for all prospective buyers. TISH disclosure reports are also available online: https://online.stpaul. gov/web/portal/public-search

- This report WILL NOT be used to enforce the requirements of the Legislative Code; however, this evaluation form will be used to determine if there is compliance with the requirements for a hardwired smoke detectors.
- This TISH report is based on the current Truth-in-Sale of Housing Evaluator Guidelines and is based upon different standards than the lender, Federal Housing Administration (FHA) or Veterans Administration (VA).
- This TISH is not warranted, by the City of Saint Paul nor by the evaluator for the condition of the building component, nor of the accuracy of this report.
- This TISH report covers only the items listed on the form and only those items visible at the time of the evaluation.
- The Evaluator is not required to operate the heating plant (except during the heating season), use a ladder to observe the condition of the roofing, disassemble items or evaluate inaccessible areas.
- This TISH report is valid for one year from the date of issue and only for the owner named on this
- If this building is used for any purpose other than a single family dwelling, it may be illegally zoned. To help you determine legal uses under the zoning ordinance, contact the Zoning Administrator at (651) 266-9008.
- Automatic garage doors should reverse upon striking an object. If it does not reverse, it poses a serious hazard and should be repaired or replaced immediately.
- All single family residences in Saint Paul must have at least one smoke detector connected to the electrical system (hard-wired). The detector must be located near sleeping rooms. For more information call Fire Prevention, (651)228-6230. (Saint Paul Legislative Code, Chapter 58.)
- Rainleaders connected to the sanitary sewer system must be disconnected. For more information call Public Works, Sewer Utility, and (651)266-6234.
- A house built before 1950 may have lead paint on/in it. If children ingest lead paint, they can be poisoned. For more information call Ramsey County Public Health, (651)292-6525.
- Neither the City of Saint Paul nor the Evaluator is responsible for the determination of the presence of airborne particles such as asbestos, noxious gases such as radon, or other conditions of air quality that may be present, nor the conditions which may cause the above.

Questions regarding this report should be directed to the evaluator. If you desire a reinspection and amended report, please contact your evaluator. They will perform a reinspection and file an amended report with the City of Saint Paul. The TISH evaluator may charge for this reinspection. Complaints regarding this report should be directed to Department of Safety and Inspections, Truth-in-Sale of Housing Program, Phone 651-266-8989.

963 WATSON AVE Feb 8, 2021 Page #8

Evaluator: George Ury Structure Tech

Evaluator Statement:

I hereby certify I prepared this report in compliance with the Saint Paul Evaluator Guidelines, City of Saint Paul City Ordinance 189 and all other applicable policies and procedures of the Truth-in_Sale of Housing Board. I have utilized reasonable and ordinary care and diligence and I have noted all conditions found that do not conform to the minimum standards of maintenance. The report covers only those problems listed and reasonably visible at the time of my evaluation and does not warrent future useful life of any house component or fixture. I have included all required information pages with this report. Evaluator Name: George Ury Structure Tech Home Inspections

Phone: Cell: 952-334-7980 Evaluation Date: Feb 8, 2021

963 WATSON AVE Feb 8, 2021 Evaluator: George Ury Structure Tech

Home Inspections