## Saint Paul Fire Department FIRE INCIDENT DISPOSITION



INCIDENT NUMBER:	20-32467	DATE OF INCIDENT: 8-26-2020	
TIME OF INCIDENT:	0716 Hours	POLICE CASE #:	n/a
INVESTIGATOR(s):	Blank, J		
INCIDENT ADDRESS:	1047 Wakefield Ave Saint Paul, MN 55106		
OCCUPANT NAME:	Patrick S McNally	<b>PHONE:</b> 651-347-9656	
OWNER NAME:	Stepping Stones Supportive Services Llc	<b>PHONE:</b> 612-309-3322	
ADDRESS OF OWNER:	1361 Wellesley Ave St Paul, MN 55105		
PROPERTY DAMAGED:	Residential Treatment House	AREA OF ORIGIN: South side of exterior	
DAMAGE ESTIMATE:	<b>Building \$</b> 45,000	<b>Vehicle \$</b> n/a	Other (Describe) \$n/a
VALUE:	Building \$217,200	Vehicle \$n/a	Other (Describe) \$n/a
Damage Estimate CONTENTS ONLY:	<b>\$</b> 5,000		
INJURY/DEATH (if yes, explain)	⊠ No □ Yes		
SMOKE DETECTOR, SPRINKLER, and CARBON MONOXIDE INFORMATION:	Smoke Detector Present:  Yes  No Unknown  Detector Functioning:  Yes  No Unknown  Sprinkler System Present:  Yes  No Unknown  Sprinkler Heads activated:  Yes # No Unknown  C.O Detector Present:  Yes  No Unknown		
FIRE CAUSE CLASSIFICATION:	Accidental Juvenile/Incendiary Incendiary Child (under 10 years old) Natural Undetermined Under Investigation		
SYNOPSIS:	The Fire Department was called to a report of a porch and house on fire by a passerby. Firefighters arrived to find a large fire on the exterior of a dwelling that was extending into the interior of the structure at the roofline. Occupants of the residence admit to having a plastic smoking recepticle located in the area of origin and a history of discarding cigarettes on the ground. The ignition source was a cigarette butt. The first fuel ignited was plastic. The action that brought these items together was due to improper disposal of smoking materials. The classification of fire cause is accidental.		
DISPOSITION:	☐ E-mail only ☐ Hold Scene until approved ☐ DO NOT DEMOLISH until approved ☐ Scene Released ☐ Analysis of Evidence Pending ☐ Report to Follow		