

CITY OF SAINT PAUL, MN

Truth-in-Sale of Housing Report

This is a visual disclosure report based on the current City of Saint Paul Truth-in-Sale of Housing Evaluator Guidelines and is valid for one year from the date of issuance and for the owner named.

DEPARTMENT OF SAFETY AND INSPECTIONS

Steve Magner, Manager of Code Enforcement Vicki Sheffer, Truth-in-Sale of Housing Manager

375 Jackson Street, Suite 220 Saint Paul, MN 55101-1806

Phone: 651-266-8989 Fax: 651-266-1919 Web: <u>www.stpaul.gov/dsi</u>

Property Address: 1965 BERKELEY AVE Date of Evaluation: May 17, 2021 Date of Expiration: May 17, 2022

This report is intended to provide basic information to the home buyer and seller prior to the time of sale.

This report WILL NOT be used to enforce the requirements of the Legislative Code; however, it will be used to determine if there is compliance with the requirements for sale within the City of Saint Paul, MN.



MAJOR NOTIFICATIONS AND WARNINGS

For questions on these items, call the City's Information and Complaint Line at 651-266-8989

- Residential Type: Single Family Dwelling
- Smoke Detectors:
 - Smoke Detector Present: Y
 - Smoke Detector Properly Located: Y
 - Smoke Detector Hard Wired (required in Single Family Homes): Y
 - Smoke Detector Comments:
- Open Permits:
 - This property has No Open Permits.

HAZARDOUS

Basement Only

Electrical service installation/grounding

• Electrical wiring, outlets and fixtures Bathroom(s)

• Electrical outlets and fixtures Living and Dining Room(s)

• Electrical outlets and fixtures Plumbing System

• Water heater(s), installation Sleeping Room(s)

• Electrical outlets and fixtures

BELOW MINIMUM

Basement/Cellar

- Foundation
- Stairs and Handrails

Bathroom(s)

- Walls and ceiling
- Water flow

Exterior Space

- Basement/cellar windows
- Doors (frames/storms/screens)
- Drainage (grade)
- Exterior walls
- Open porches, stairways and deck(s)
- Windows (frames/storms/screens) Hallways, Stairs and Entries
 - Stairs and handrails to upper floors

Heating System(s)

Installation and visible condition
Kitchen

- Walls and ceiling
- Water flow

Plumbing System

• Plumbing fixtures (basement)

Report Rating Key (Where there are multiple rooms to a category, the Evaluator must <u>specify the room</u> to which a Comment is related)			
H: Hazardous Condition	B: Below Minimum	C: See Comments	M: Meets Minimum
Y: Yes	N: No	NV: Not Visible	NA: Not Applicable

CITY OF SAINT PAUL TRUTH-IN-SALE OF HOUSING REPORT

Address: 1965 BERKELEY AVE Date of Evaluation: May 17, 2021 Zoning District: R4 Present Occupancy: Number of Units Evaluated: Single I Dwelling Basement/Cellar	Family	File Number: File#: 21-263309 Owner: Kenneth D Tupper Client Name: KEN TUPPER Client Contact: 3679 94TH ST E,IGH,MN 55076 Evaluator Name: Mike Moser M. J. Moser Evaluator Contact: Cell: 612-386-4995 gusbas@aol.com
1. Stairs and Handrails	D	
	В	1. B - Uneven stair-tread risers.
2. Basement/Cellar Floor	M	
3. Foundation	В	 B - damp and stained .areas damaged . Only partially visible(areas finished)
 Evidence of Dampness or Staining 	Y	
5. First Floor, Floor System	NV	5. C - finished in areas and not visible
6. Beams and Columns	М	
Electrical Services 7a. Number of Electrical Services	1	
7b. Amps	Other	7b. C - Panel not marked
7c. Volts	120-240	
Basement Only		
8. Electrical service installation/grounding 9. Electrical wiring, outlets and	н н	8. H - Missing cover on panel / exposed live wires,9. H - hanging lights from ceiling in areas /
fixtures		exposed wires
Plumbing System		
10. Floor drain(s) (basement)	Μ	
11. Waste and vent piping (all floors)	Μ	
12. Water piping (all floors)	Μ	
13. Gas piping (all floors)	Μ	
14. Water heater(s), installation	Н	14. H - no operational water heater
15. Water heater(s), venting	NA	
16. Plumbing fixtures (basement)	В	16. H - Toilet in bsmt is not functionalB -no hot water
Heating System(s)		Water
The Evaluator is not required to heating plant(s) except during to season, between October 15 an	the heating	
17a. Number of Heating	1	
Systems 17b. Type	Hot Water	

Report Rating Key (Where there ar	e multiple rooms	s to a categor	y, the Evaluator must <u>specify the</u>	room to which a Comment is related)
H: Hazardous Condition	B: Below Minim	um	C: See Comments	M: Meets Minimum
Y: Yes	N: No		NV: Not Visible	NA: Not Applicable
17c. Fuel		Gas		
18. Installation and visible condition 19. Viewed in operation		B	18. B - Lacks maintenan	ice / dirty boiler
(required in heating 20. Combustion ver	season)	M		
	21a. Additional heating unit(s):			
21b. Additional hea Fuel	ting unit(s):	NA		
21c. Installation and condition	d visible	NA		
21d. Viewed in oper	ration	NA		
21e. Combustion ve	enting	NA		
Kitchen				
22. Walls and ceiling	g	В	22. B - Damaged ceiling	(s).
23. Floor condition height	and ceiling	Μ		
	24. Evidence of dampness or			
fixtures				
26. Plumbing fixtur	es	Μ		
27. Water flow		В	27. B -no hot water	
28. Window size/openable area/mechanical exhaust 29. Condition of doors/windows/mechanical exhaust		M M		
Living and Dining R	oom(s)			
30. Walls and ceiling	g	Μ		
31. Floor condition height	31. Floor condition and ceiling height			
32. Evidence of dan staining	npness or	Ν		
	33. Electrical outlets and		33. H - ungrounded 3 p	rong outlets
area				
35. Window and do	or condition	Μ		
Hallways, Stairs and 36. Walls, ceilings, f		М		
37. Evidence of dam	37. Evidence of dampness or			
staining 38. Stairs and hand upper floors	rails to	В	38. B - Guardrail missing	
	39. Electrical outlets and		atticB - Handrail(s) missing. attic	
40. Window and door conditions		Μ		

Report Rating Key (Where ther	e are multiple room	s to a cateç	gory, the Evaluator must <u>specify t</u>	he room to which a Comment is related)
H: Hazardous Condition	B: Below Minim	um	C: See Comments	M: Meets Minimum
Y: Yes	N: No		NV: Not Visible	NA: Not Applicable
Smoke Detectors				
41a. Present 41b. Properly Located 41c. Hard-Wire		Y Y Y		
Bathroom(s)				
42. Walls and cei	iling	В	42. B - Damaged area	(s).B - Damaged wall(s).
43. Floor condition and ceiling height		Μ		
44. Evidence of c staining		Ν		
45. Electrical out fixtures		H	45. H - outlets not GF	CI protected
46. Plumbing fixtures		M		
47. Water flow		B M	47. B - no hot water	
area/mechnical e	48. Windows size/openable area/mechnical exhaust			
	49. Condition of windows/doors/mechanical exhaust			
Sleeping Room(s)				
50. Walls and cei	llings	Μ		
51. Floor conditi ceiling height		Μ		
staining	52. Evidence of dampness or staining			
fixtures			53. H - ungrounded 3	prong outlets
54. Window size area 55. Window and		M		
Enclosed Porches				
56. Walls, ceiling condition	and floor	Μ		
	57. Evidence of dampness or			
58. Electrical out fixtures		Μ		
59. Window and	door condition	Μ		
Attic Space				
60. Roof boards	and rafters	Μ		
61. Evidence of c staining	61. Evidence of dampness or staining			
62. Electrical wiring/outlets/fi	xtures	М		
63. Ventilation		Υ		
Exterior Space				
64. Foundation		М		
65. Basement/ce	llar windows	В	65. B - Deteriorated b	asement windows.

		, the Evaluator must <u>specify the room</u> to which a Comment is related		
H: Hazardous Condition B: Below Minim Y: Yes N: No	ium	C: See Comments M: Meets Minimum NV: Not Visible NA: Not Applicable		
66. Drainage (grade)	В	66. B - Grade doesn't allow surface water to drain		
67. Exterior walls		away from building.		
	В	67. B - Damaged/missing stucco.		
68. Doors (frames/storms/screens)	В	68. B - weathered areas		
69. Windows (frames/storms/screens)	В	 69. B - weathered trim and frames on windows, decay present 		
70. Open porches, stairways and deck(s)	В	70. B - weathered wood components , missing hand rail on steps with more than 3 risers.		
71. Cornice and trim(s)	Μ			
72. Roof structure and covering	Μ			
73. Gutters and downspouts	Μ			
74. Chimney(s)	Μ			
75. Outlets, fixtures and service entrance	Μ			
Garage(s)/Accessory Structure	(S)			
76. Roof structure and covering	Μ			
77. Wall structure and covering	NV	77. C - stored items limit view in garage.		
78. Slab condition	NV	78. C - stored items limit view in garage.		
79. Garage door(s)	Μ			
80. Garage opener(s)	Y			
81. Electrical wiring, outlets and fixtures	Μ			
Fireplace/Woodstove				
82. Number of Units	1			
83. Dampers installed	NV	83. C - stored items limit view / fireplace blocker / soot prevents evaluation of fireplace .		
84. Installation	NV			
85. Condition	NV			
Insulation				
86a. Attic Insulation: Present	NV	86a. C - concealed by floor boards ,not visible		
86b. Attic Insulation: Type	NA	-		
86c. Attic Insulation: Depth	NA			
87a. Foundation Insulation: Present	Y	87a. C - some areas are not visible.		
87b. Foundation Insulation: Type	Fiberglas s roll			
87c. Foundation Insulation:	3-6			
Depth 88a. Knee Wall Insulation:	inches NA			
Present	NA			
88b. Knee Wall Insulation: Type	NA			
88c. Knee Wall Insulation: Depth	NA			
89a. Rim Joist Insulation: Present	NV			
89b. Rim Joist Insulation: Type	NA			

Report Rating Key (Where there	are multiple roor	ns to a catego	ory, the Evaluator must <u>specify t</u>	he room to which a Comment is related)
H: Hazardous Condition	B: Below Minir	num	C: See Comments	M: Meets Minimum
Y: Yes	N: No		NV: Not Visible	NA: Not Applicable
89c. Rim Joist Ins	ulation: Depth	NA	1	
General				
90. Carbon Mono	xide Alarm	М		
General Comments M		Μ	The house is in condition of needing repairs . No water heater and most areas worn or damaged . Did not appear to be occupied at time of evaluation	

LEGAL NOTICES:

Chapter 189 of the Saint Paul Legislative Code requires all single family, duplex, condo, townhouse and co-op homes for sale in the city to have a Truth-in-Sale of Housing disclosure report prepared and available to prospective buyers. A Truth-in-Sale of Housing disclosure report must be done for Contract-For-Deed sales.

A Truth-in-Sale of Housing (TISH) Disclosure Report in the City of Saint Paul is intended to provide basic information to the home buyer and seller prior to the time of sale. Failure to obtain a Truth-in-Sale of Housing disclosure report or failure to make that disclosure report available to prospective buyers, is a violation of law and is punishable as a misdemeanor carrying up to 90 days in jail and/or a \$1,000.00 fine.

A valid Truth-in-Sale of Housing disclosure report must be conspicuously displayed at the premises for all prospective buyers. TISH disclosure reports are also available online: <u>https://online.stpaul.gov/web/portal/public-search</u>

- This report WILL NOT be used to enforce the requirements of the Legislative Code; however, this evaluation form will be used to determine if there is compliance with the requirements for a hard-wired smoke detectors.
- This TISH report is based on the current Truth-in-Sale of Housing Evaluator Guidelines and is based upon different standards than the lender, Federal Housing Administration (FHA) or Veterans Administration (VA).
- This TISH is not warranted, by the City of Saint Paul nor by the evaluator for the condition of the building component, nor of the accuracy of this report.
- This TISH report covers only the items listed on the form and only those items visible at the time of the evaluation.
- The Evaluator is not required to operate the heating plant (except during the heating season), use a ladder to observe the condition of the roofing, disassemble items or evaluate inaccessible areas.
- This TISH report is valid for one year from the date of issue and only for the owner named on this report.
- If this building is used for any purpose other than a single family dwelling, it may be illegally zoned. To help you determine legal uses under the zoning ordinance, contact the Zoning Administrator at (651) 266-9008.
- Automatic garage doors should reverse upon striking an object. If it does not reverse, it poses a serious hazard and should be repaired or replaced immediately.
- All single family residences in Saint Paul must have at least one smoke detector connected to the electrical system (hard-wired). The detector must be located near sleeping rooms. For more information call Fire Prevention, (651)228-6230. (Saint Paul Legislative Code, Chapter 58.)
- Rainleaders connected to the sanitary sewer system must be disconnected. For more information call Public Works, Sewer Utility, and (651)266-6234.
- A house built before 1950 may have lead paint on/in it. If children ingest lead paint, they can be poisoned. For more information call Ramsey County Public Health, (651)292-6525.
- Neither the City of Saint Paul nor the Evaluator is responsible for the determination of the presence of airborne particles such as asbestos, noxious gases such as radon, or other conditions of air quality that may be present, nor the conditions which may cause the above.

Questions regarding this report should be directed to the evaluator. If you desire a reinspection and amended report, please contact your evaluator. They will perform a reinspection and file an amended report with the City of Saint Paul. The TISH evaluator may charge for this reinspection. Complaints regarding this report should be directed to Department of Safety and Inspections, Truth-in-Sale of Housing Program, Phone 651-266-8989.

Evaluator Statement:

I hereby certify I prepared this report in compliance with the Saint Paul Evaluator Guidelines, City of Saint Paul City Ordinance 189 and all other applicable policies and procedures of the Truth-in_Sale of Housing Board. I have utilized reasonable and ordinary care and diligence and I have noted all conditions found that do not conform to the minimum standards of maintenance. The report covers only those problems listed and reasonably visible at the time of my evaluation and does not warrent future useful life of any house component or fixture. I have included all required information pages with this report. Evaluator Name: Mike Moser M. J. Moser Phone: Cell: 612-386-4995

Evaluation Date: May 17, 2021