

Legislation Text

File #: ALH 10-363, Version: 1

Appeal of Linda Bell to a Egress Window Non-Compliance Determination at **1036 DALE STREET NORTH**.

1036 Dale Street North

The failed height dimension can be reduced from 8 inches to 7 inches with little expense. To meet the city requirements, the homeowner will need to pay for full frame removal, re-rout the outlet wires by a licensed electrician, rebuild the exterior siding and brick mould, and rebuild and stain/polyurethane the new interior woodwork. Total cost to homeowner will be \$1,045 above the standard window cost.

October 5, 2010

[Enter Summary Here]