
## RLH FCO 25-54



## APPLICATION FOR APPEAL

Saint Paul City Council - Legislative Hearings

RECEIVED

SEP 0 2 2025

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8585

	legislativehearings@ci.stpaui.mn.us
We need the following to process your appeal  \$25 filing fee (non-refundable) (payable to the City of Saint Paul) (if cash: receipt Check be number 1006	CLERKING DATE & TIME  (provided by Legislative Hearing staff)  Tuesday, September 9, 2025  Location of Hearing:
Copy of the City-issued orders/letter being appealed & any attachments you may wish to include	Telephone: you will be called between 2:00 p.m. & 4:00 p.m.
Walk In Mail Email Appeal taken by:	In person (Room 330 City Hall) at:  (required for all condemnation orders and Fire C of O revocations and orders to vacate)
Address Being Appealed:	•
Number & Street:	St. Paul Mn. 55104 City:State:Zip:
Appellant/Applicant:	pataware588@gmail.com
763-244-6365	same same
Signature: Hat Ware	8-29-25 Date:
DRB # 24 Name of Owner (if other than Appellant): PO Box 16595 Mailing Address if Not Appellant's:	, LLC 5 St. Paul, Mn. 55116
Phone Numbers: Business 612-720-1451	Residence same Cell same
What is being appealed and why? Attachment Vacate Order/Condemnation/ Revocation of Fire C of O  Summary/Vehicle Abatement	ts Are Acceptable related to the original complaint and have no impact on the unit the initial complaint was about.
Fire C of O Deficiency List/Correction	* 3%
	See 5 with a good a good a good and for the good and for
	ited that are unralated to the original
	tral complaint was about

Revised 1/31/2023



## Fire Inspection Report

City of Saint Paul
Department of Safety and Inspections
375 Jackson Street — Suite 220
Saint Paul MN 55101-1806

	DRB#24LLC	License
ROT - And Could be The Land Religion of E	* PO Box 16595	Complaint)
City State Zip	51. Bul, MU 55716	Caro
Baltin God Annual Corporation 15	763-244-6365	Date 4/24/25
P. Green Conductor Co.	ldress: 673 Charles Au	<u> </u>
made after the r unreasonable, yo obtained at the ( orders.	notified to remedy the conditions stated belo cinspection date stated below. If you consid ou may appeal to the Legislative Hearing Of City Clerks Office, 310 City Hall 651-266-85	er any of these code requirements to be ficer. Applications for appeals may be 85 within 10 days of the date of the origina
Code	Conditions to b	
51% 344Q <u> </u>	water damage to walk+ceils.	eg in upstairs bedroom.
MBFC ILD7-8	Missing smoke alarm upstal	
884_3401	Roof shall be weather to	
RU 3401	Roof shall be weather the root door framing missing leaving	
1 3409 F	cont door framing missing leaving	
984 94 69 1 34 69 1	ront door-framing missing leaving appervious to weather.	int. aps be educts + 10t
984 3409 11 3401 ( 14 3409 5	ront door framing missing leaving appervious to weather. Siding missing under front usindo	At.  April Mark of Mar
\$84.34.09 11 34.09 F 11 34.09 S 34.09 P	ront door framing missing leaving mpervious to weather.  Taking missing under front windo  lissing point luxuetherproofing	on front window
\$84.34.09 1. 34.09 1. 34.09 34.09 10.34.10 10.34.10	ront door framing missing leaving appervious to weather.  Tabling missing under front windo lessing paint/weatherproofing old in year stairwell when	on front window  E Stat floor bethroom is
\$84.3409 1.3409 1.3409 34.09 10 84.34.10 84.34.08 64.34.08	ront door framing missing leaving appervious to weather.  Siding missing under front withdo lessing point/weatherproofing ole in wall in rear stairwell when	ervious to weather.
984.34.09 1 34.09 1 34.09 34.09 10 34.08 10 34.08 10 34.08	ront door framing missing leaving mpervious to weather  billing missing under front using livesing paint lucatherproofing set in wall in rear stainvell when aimse in disrepair or not impairing side of	en front window:  chief floor bethroom is  evines to weather.  home.
SEL 34.09  1 34.09  1 34.09  74.09  RL 34.09  RL 34.08  RL 34.08	ront door framing missing leaving appervious to weather.  Siding missing under front withdo lessing point/weatherproofing ole in wall in rear stairwell when	en front window:  chief their bethroom is  evines by weather.  home.
\$84.34.09 11.34.09 5 34.09 6 34.09 6 86.34.10 H 86.34.08 6 11.34.08 6 11.34.08 6	ront door framing missing leaving mpervious to weather  billing missing under front using livesing paint lucatherproofing set in wall in rear stainvell when aimse in disrepair or not impairing side of	en front window:  chief floor bethroom is  evines to weather.
\$84.34.09 11.34.09 5 34.09 6 34.09 6 86.34.10 H 86.34.08 6 11.34.08 6 11.34.08 6	mont door framing missing leaving mpervious to weather.  Talling missing funder front windously point weathersproofing old in wall in rear stainwell when armose in disrepair or not impossing sidewalk on side of sekyard missing ground cover cressentative Signature	gaps for radants of soft  on front window  thist floor bethroom is  ervious to weather.  home  atting armsion, duet, a mud.