Date:	**June 23, 2010**	**HP District:**	
File #:	**10 - 511807**	**Property Name:**	
Folder Name:	**755 ANDREW ST**	**Survey Info:**	
PIN:	**082822410090**		

South and east sides

West side, posting

East and north sides, garage

Garage, north and west sides

Front posting



South and east sides, posting

Date:	**May 10, 2011**	**HP District:**	
File #:	**10 - 511807**	**Property Name:**	
Folder Name:	**755 ANDREW ST**	**Survey Info:**	
PIN:	**082822410090**		

Rot damaged window sash, trim, framing

Rot damaged door trim, threshold, framing

Locked gas meter

Missing siding, unapproved flashing

Deteriorated eave covering

Missing siding, open wall

Date:	**May 10, 2011**	**HP District:**	
File #:	**10 - 511807**	**Property Name:**	
Folder Name:	**755 ANDREW ST**	**Survey Info:**	
PIN:	**082822410090**		

Garage

Open siding, water damaged open eave

Electric meter buried in roof installation

Unapproved flashing

Open siding, deteriorated siding, water damaged open eave

North and east sides house and garage

Date:	**May 10, 2011**	**HP District:**	
File #:	**10 - 511807**	**Property Name:**	
Folder Name:	**755 ANDREW ST**	**Survey Info:**	
PIN:	**082822410090**		

South and east sides