

We need the following to process your appeal:

# **APPLICATION FOR APPEAL**

## Saint Paul City Council – Legislative Hearings

RECEIVED

JAN 28 2022

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8585

CITY CLERK

\$25 filing fee (non-refundable) (payable to the City of Sa Paul)(if cash: receipt number	
Copy of the City-issued orders/letter being appeale	
Attachments you may wish to include	Location of Hearing: Telephone: you will be called between
▼ This appeal form completed	
Walk-In OR □ Mail-In  for abatement orders only: □ Email OR □ Fa	In person (Room 330 City Hall) at: (required for all Fire C of O revocation & vacate; Condemnation orders)
Address Being Appealed:	
Number & Street: 1673 Princeton City: St. Paul State: MN zip: 55705	
Appellant/Applicant: Macalester College Email Septanen Macalester edu	
Phone Numbers: Business 651-696-6305 Residence Cell 651-274-6523	
Signature: Sama Seppar Date: 1/28/22	
Name of Owner (if other than Appellant):	
Mailing Address if Not Appellant's:	
Phone Numbers: Business Residence	ce Cell
What Is Being Appealed and Why? Attachments Are Acceptable	
Vacate Order/Condemnation/ Revocation of Fire C of O  Ref #102105	
- Summary/Vehicle Abatement Ttem #3 on deficiency list	
Fire C of O Deficiency List/Correction Distalay motorevcles in house	
□ Code Enforcement Correction Notice	
- Vacant Building Registration Dease see attached for more information	
□ Other (Fence Variance, Code Compliance, etc.)	

To: Legislative Hearing Officer, City of St. Paul

From: Deanna Seppanen, Macalester College, Director of the High Winds Fund

Date: January 28, 2022

Re: Fire Inspection Correction Notice, Ref. #102105

Along with the tenant residing at 1673 Princeton, we would like to appeal item #3 on the deficiency list. MSFC 313.1

Our tenant, Paul Aslanian, has three antique motorcycles on display on the main floor of the property at 1673 Princeton. Two of these motorcycles have been on display since 1984 and the third since 1996. These are not fueled equipment. They do not have batteries and there is no gasoline in the tanks, which are also capped. They are not being worked on, fueled or defueled within the space and are not rideable in their current condition. One of the motorcycles has old oil that drips from it now and then which is why there is still a drip pan to protect the floors underneath. No part of these motorcycles is explosive or would be considered combustible or have a higher rate of accelerant than any normal piece of furniture or artwork. The motorcycles are also located as to not block any path of egress from the house. They are truly for display and the enjoyment of viewing by Paul, a collector of antique bikes and cars.

We ask that the motorcycles be allowed to stay on display as artwork in the house.

We would be happy to answer any questions or address any concerns. The replacement of the GCFI outlet and the smoke detector in the basement are both being corrected. Thank you.





CITY OF SAINT PAUL

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806 

 Telephone:
 651-266-8989

 Facsimile:
 651-266-8951

 Web:
 www.stpaul.gov/dsi

January 10, 2022

DEANNA SEPPANEN HIGH WINDS FUND 1600 Grand Ave St. Paul, MN 55105

### FIRE INSPECTION CORRECTION NOTICE

RE:

1673 PRINCETON AVE

Ref. #102105

Residential Class: B

#### Dear Property Representative:

Your building was inspected on January 6, 2022 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date. A reinspection will be made on February 4, 2022 at 1:00 pm.

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

#### DEFICIENCY LIST

1. Interior - Basement - MSFC 1103.8 Location of smoke alarms- Building constructed/remodeled before 8/1/1989, located in hallways outside sleeping rooms. On each level and in the basement. On ceiling or wall (less than 12 inches below ceiling). Smoke alarms can be battery powered; no interconnection is required. -Maintain Hard-Wired smoke alarm in the basement.

- 2. Interior Bathroom NEC 406.4(D)(3) GFCI outlets shall be provided where replacements are made at outlets that are required to be so protected elsewhere in this Code. -Fix the fault in the bathroom GFCI.
- 3. Interior Dining Room MSFC 313.1 Fueled equipment, including but not limited to motorcycles, mopeds, lawn-care equipment, and portable cooking equipment, shall not be stored, operator or repaired within a building. -Remove the 3 motorcycles from the dining room and store in the garage or other area outside of the living space.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8585) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: Jack.Toeller@ci.stpaul.mn.us or call me at 651-266-8950 between 7:30 a.m. - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Jack Toeller Fire Inspector

Reference Number 102105