Project 701 East Maryland Ave. mgunter@visi.com Name as of October 24, 2011 Completion Date Revised Value Change Orders Scheduled Value Contractor Item **Description of Work Hard Costs Outside** May 1, 2012 0.00 2.000.00 2.000.00 1.00 Exterior: Repair/Paint, Doors, Window Mohr/Gunter May 1, 2012 5.000.00 5,000.00 0.00 2.00 Concrete/Stucco/Brick/Retaining Wall Repairs Mohr/Gunter February 29, 2012 2.000.00 2,000.00 0.00 3.00 Garage/Back Stairway Repairs Mohr/Gunter 1,000.00 1,000.00 0.00 4.00 Contingency **Hard Costs Inside** 400.00 0.00 400.00 5.00 Trash removal Mohr/Gunter February 29, 2012 500.00 500.00 0.00 Mohr/Gunter 6.00 Sheetrock/Paint February 29, 2012 11,050.00 11.050.00 0.00 7.00 Mechanical Repair: boiler Rascher February 29, 2012 17.450.00 Rascher 17.450.00 0.00 8.00 Plumbing February 29, 2012 5.200.00 0.00 5,200.00 Apex 9.00 Electrical February 29, 2012 2.500.00 2,500.00 0.00 10.00 Fire Alarm/Extinguisers Gerry's February 29, 2012 0.00 1.500.00 1,500.00 11.00 Carpet/Flooring Refinish/Repair Mohr/Gunter February 29, 2012 0.00 2.000.00 2,000.00 12.00 Kitchen/Bathroom Cabinet/Misc. Repairs Mohr/Gunter February 29, 2012 1,000.00 1.000.00 0.00 13.00 Appliance Repairs Mohr/Gunter May 1, 2012 5,000.00 5,000.00 0.00 Mohr/Gunter 14.00 Building Materials May 1, 2012 0.00 5,000.00 5.000.00 15.00 Independent Labor Mohr/Gunter 7,000.00 7.000.00 0.00 16.00 Contingency **Soft Costs** 0.00 500.00 17.00 Utilities: gas/electric/water 500.00 November 30, 2011 5,000.00 5.000.00 0.00 18.00 Legal and Accountant Fees McClay-Alton May 1, 2012 2,200.00 0.00 2,200.00 19.00 City Permits/Inspection Fees November 30, 2011 400.00 0.00 400.00 20.00 Closing Costs November 30, 2011 20,000.00 20,000.00 0.00 21.00 Acuisition 3,400.00 May 1, 2012 3,400.00 0.00 1st Comm Bank 22.00 Financing Costs November 30, 2011 410.00 0.00 410.00 23.00 Real Estate Taxes - Prorated 2011 November 30, 2011 2.000.00 2,000.00 0.00 24.00 Insurance Vaaler Ins. 0.00 1,500.00 1,500.00 25.00 Contingency 104,010.00 104.010.00 \$ TOTAL 0.00 78,000.00 78,000.00 Loan Funds (Original) 26.010.00 26,010.00 **Equity Funds** 104,010.00 104,010.00 **Total Funds to Complete**

BILL RASCHER MECHANICAL INC.



245 E. MARIE AVE. SUITE 760 WEST ST. PAUL, MN 55118 (651)450-6622 (651) 450-6644

BILL@BILLRASCHERMECH.COM

DATE: Proposal # October 17, 2011

110326

FOR: Plumbing work and

heating work

For:

Mark Gunter

Location:

701 E. Maryland Ave. St. Paul, Mn

DESCRIPTION	AMOUNT
Plumbing	
Code corrections items on list	
Basement area	
gas piping to dryer (1) valve and connector	
new dryer vent to exterior (1)	
laundry sink drain and vent corrected	
aundry faucet sport corrected	
new CO's at base of stacks (3)	
new floor drain covers (2)	
new water heater relief drop pipe	
new gas shut off for water heater	
new water heater piping	
new meter installed provided by SPRWS	1
new meter valves	Į.
replace stolen copper water piping	ľ
boiler fill water with RPZ	
assumes the following:	
no gas pressure test of existing piping system	
no leaks on existing piping system	į
no water isolation valves per unit	
water heater works properly does not leak	
water heater needs no repairs	
water piping in walls have no leaks	
Labor and materials	\$2,900.00
Code corrections for drain vent and water piping in bathrooms	
new anti scald shower faucets provided and installed	
re use all other fixtures and faucets	1
Labor and materials per bathroom	\$5,100.00
assumes no leaks on water piping in walls	
Code corrections for drain vent and water piping in kitchens	
re use all sinks and faucets	
Labor and materials per kitchen	\$3,450.0
assumes no leaks on water piping in walls	Ì
no ice maker, dishwasher or garbage disposer	
Gas connectors for stoves	
new gas valves and flex connectors	#050 O
labor and materials per stove	\$350.0

	1		
<u>Heating</u>			
Code corrections items on list			
clean and service boiler.	}		
fill and purge heating system			
test fire boiler			
ORSAT test on boiler and combustion report to city			
new gas shut off valve on boiler			
new main gas shut off valve at main supply into house			
new metal chimney liner 8"			
new boiler and water heater vent connectors			
new combustion air			
gas piping system supports	Į į		
strip and cap old unused gas piping			
heating piping system supports			
permit test inspection			
assumes the following:			
no repairs needed to fire boiler			
boiler and piping system has no leaks			
system holds water/air test			
boiler passes ORSAT test without needing repairs			
8" metal liner will fit inside brick chimney			
demo of chimney in basement and patch for liner by others			
demo of exterior wall for combustion air by others			
every room has hydronic heat in it. Unsure of which rooms/conditions sited in code correction	Í		
wiring of boiler is in working condition]		
unknown conditions do not effect heating system operation.			
Labor and Materials	\$11,050.00		
	ł		
install bath fan and ducting for bathroom			
Labor and materials per bathroom	\$475.00		
	1		
install new radiator valves on radiators as needed to make operable			
Labor and materials per radiator	\$375.00		
Price includes: One year priority workmanship warranty,			
Permit Test and inspection <u>Prices do not include</u> opening or parching of walls, floors, or ceilings			
Prices do not include opening of parching of walls, noors, or central visites			
Power or control wiring We propose hereby to furnish materials and labor in accordance with these specifications for the sum of :	SEE ABOVE		
This proposal is valid for thirty (30) days from the above date.	OLL ADD TL		
Payable as follows: 30% down payment, billed as job progresses, balance due in full upon completion.			
Authorized Signature: Wm. S. Rascher Pres.			
Authorized digitation. Typic losserial trial.			

All material is guaranteed to be as specified. All work to be completed in a workmanlike manner according to standard practices. Any alteration or deviation from above specifications involving extra costs will only be executed upon written orders, and will become an extra charge over and above this estimate. All agreements contingent upon strikes, accidents, natural causes or delays are beyond our control. Owner to carry fire, tornado, and other necessary insurance. We are fully licensed, bonded, and insured. Our workers are fully covered by Worker's Compensation insurance. Our workers are all OSHA 10 certified.

ACCEPTANCE OF PROPOSAL - The prices, specifications and conditions are satisfactory and are hereby accepted. You are authorized to do the work as specified. Payment will be made as outlined above.

Signature	Date
-----------	------



31255 Foliage Ave, Northfield, MN 55057 Office: (952) 891-4999 - (507) 645-0170

Fax: (507) 645-4097

Email: apex@myclearwave.net
Website: apex4electrical.com

Customer Service Above All

REPAIRS AT 701 MARYLAND AVE E, ST.PAUL MINNESOTA

#69 AND $\#70\,$ - REPLACE WATER BOND JUMPERING WATER METER AS IT ENTERS THE BUILDING. INSTALL PROPER CONDUCTOR AND CLAMPS. \$200.00

#71 LABEL ELECTRICAL PANELS. VERIFY LOCATIONS OF OUTLETS, LIGHTS, ETC. RELABEL ACCORDINGLY \$400.00

#72 INSTALL TWO NEW LAUNDRY CIRCUITS IN BASEMENT INSTALL 2 20AMP CIRCUITS WITH GFI'S \$400.00

#73 VERIFY BREAKERS ARE CORRECT RATING INSPECT WIRE SIZE AND VERIFY WITH CODE \$100.00

#74 CLOSE ALL BOXES AND KNOCK-OUTS ETC. INSPECT ALL JUNCTION BOXES, LIGHTING, PIPING, ETC. INSTALL REQUIRED COVERS, CLOSURES, ETC. \$75.00

#75 GROUND BATH AND KITCHEN LIGHTS OVER SINKS ON $1^{\rm ST}$ AND $2^{\rm ND}$ FLOOR. VERIFY GROUNDING OF FIXTURE, ADD ADDITIONAL GROUNG IF NEEDED. \$450.00

#76 ENCLOSE ALL CLOSET FIXTURES. VERIFY CLEARANCES AND REINSTALL \$60.00 EACH

#77 REPLACE ANY BROKEN SWITCHES OUTLETS ETC. VISUALLY INSPECT AND REPLACE \$50.00 EACH

	Page 1 of 2		
Customer Initials:		Date:	



VIA Email October 24, 2011

To whom it may concern:

We have been contacted by our customer, Mr. Mark Gunter concerning an investment that he is intending to pursue. Mr. Gunter has been a valued customer of our bank for many years, and has engaged in a series of real estate investments.

He has asked us to confirm that Mr. Gunter would have available an amount of funds sufficient for the purchase and renovation of 701 E. Maryland in St. Paul, MN. Based on the amounts currently on deposit with our bank, and funds available as indicated in Mr. Gunter's most recent financial statement, we believe he has the funds required to complete this transaction. Please contact us if you have any further questions.

Sincerely

Brian R. Wagner

Senior Vice President - Business Development

Mark Gunter

From: "SAM SONTOYA" <samson8595@yahoo.com>

To: <mgunter@visi.com>

Sent: Friday, October 21, 2011 10:18 AM

Subject: use this letter

Mark Gunter 10-20-11

To Whom It May Concern:

I am a St.Paul Police Sergeant on the city's East Side. In my dealings with Mr.Gunter he has been extremely helpful and is always willing to contribute to problem solving issues. I know he attends community meetings and meetings with police and is always willing to help out with whatever he can.

I along with some of the East F.O.R.C.E Officers partnered with Mr.Gunter to problem solve this summer which turned out to be extremely productive. I also know Mr.Gunter has worked with Officer Sam Sontoya of the Central District F.O.R.C.E Unit and again worked in conjunction with police to problem solve with issues in the neighborhood.

In closing, it is my personal opinion that Mr.Gunter is a good property owner and will work with the police and the community to keep his property and neighborhood a great place to live.

Please contact me with any questions.

Sergeant Jake Bobrowski Officer Sam Sontoya 367 Grove St. St.Paul MN 55101 651-266-5866

No virus found in this message. Checked by AVG - www.avg.com

Version: 2012.0.1831 / Virus Database: 2092/4564 - Release Date: 10/20/11

#78 CHECK ALL OUTLETS FOR PROPER POLARITY. CHECK AND CORRECT \$50.00 EACH

#79 INSTALL EXTERIOR FIXTURES ON FRONT AND BACK OF HOUSE. INSTALL NEW (6 FIXTURES \$600.00)

#80 REMOVE OR REWIRE AND HAZARDOUS WIRE IN BASEMENT/GARAGE. NO WIRING LOCATED IN GARAGE. \$200.00

#81 ADD ADDITIONAL OUTLETS (PULL NEW WIRE INSTALL ARC FAULT BREAKERS AND TAMPER-PROOF OUTLETS OF EACH ADDITIONAL OUTLET, LIGHT)

UNIT 1 OUTLET IN BEDROOM \$250.00 UNIT 2 OUTLET IN LIVING ROOM AND DINING ROOM (TWO SEPARATE CIRCUITS

\$500.00)

UNIT 3 OUTLET IN BEDROOM (\$325.00) UNIT 4 OUTLET IN BEDROOM (\$325.00) UNIT 5 OUTLETS IN 3 BEDROOMS (\$650.00)

#82 MOVE BATH LIGHTS IN UNIT 3 AND 4 (MOVE LIGHTING BOX FROM ABOVE SHOWER AREA AND REHANG. (\$300.00)

#83 CHECK FOR PROPER WATTAGE IN FIXTURE INSTALL PROPER LIGHT BULB (\$30.00)

#84, 85, 86 PROPER WIRING METHODS

	Page 2 of 2		
Customer Initials:		Date:	