



CITY OF SAINT PAUL

375 Jackson Street, Suite 220  
St Paul, Minnesota 55101-1806

Telephone: 651-266-8989  
Facsimile: 651-266-9124  
Web: [www.stpaul.gov/dsi](http://www.stpaul.gov/dsi)

- Yog hais tias koj tsis to taub tsab ntawv no, hu rau tus txhais lus ntawm (651) 266-8989. Nws yog pab dawb xwb.
- Si necessita un traductor, por favor llamanos al (651)266-8989. No costo.

356

**November 20, 2018**

Victor Nenghimobo Clement  
467 Ivy Ave E  
St Paul MN 55130-3414

## CORRECTION NOTICE

Date: **November 20, 2018**

RE: **467 IVY AVE E**

File #: **18-124393**

Dear Sir or Madam:

The City of Saint Paul, Department of Safety and Inspections has inspected the above referenced property on **November 20, 2018** and has determined that the following deficiencies exist in violation of the Saint Paul Legislative Code<sup>1</sup> (see footnote 1, below).

1. SPLC 34.09 **FOUNDATION:** Provide and maintain foundation elements to adequately support this building at all points. Repair deteriorated or defective foundation in a professional state of maintenance and repair. The foundation shall be free of holes, breaks, loose or rotting boards or timbers and any other conditions which might admit dampness to the interior portions of the wall or to the interior spaces of structures. Permit may be required
2. SPLC 34.09 **EXTERIOR WALLS:** The exterior walls and/or trim of the house and/or garage has defective or peeling paint, or unpainted wood surfaces. Maintain in a professional state of maintenance and repair.
3. SPLC 34.09 **EAVES:** The eaves and soffits are in a state of disrepair or deterioration. Repair all defects, holes, breaks, loose or rotting boards, to a professional state of maintenance. Permit may be required.
4. SPLC 34.09 **ROOF:** Provide and maintained the roof weather tight and kept in a professional state of maintenance and repair, impervious to water and have no defects which admit water or dampness to the interior of the building
5. SPLC 34.09 **WINDOWS:** Repair and maintain the window in good condition including the glass, sash, frame and screens. Windows shall be without cracks or holes, sashes shall be in sound conditions, the window shall be easily opened and

maintain the open position. All screens shall be maintained in a professional state of maintenance and repair.

6. SPLC 34.09 **CHIMNEY**: The chimney is defective, deteriorated or in a state of disrepair. Replace all missing or defective bricks, tuck point as needed to restore the chimney to a professional state of maintenance and repair. Permit may be required.

You are hereby notified to correct these deficiencies in accordance with the appropriate codes. The Enforcement Officer will re-inspect these premises on or after **April 05, 2019**, by which date the violations noted must be corrected. **Failure to correct these deficiencies may result in the issuance of criminal charges<sup>2</sup>** and/or a civil lawsuit, and possible abatement/assessment by the City. All repairs and new installations must be made in accordance with the appropriate codes. Permits may be obtained by calling 651-266-8989.

You may file an appeal to this notice by contacting the City Clerk at 651-266-8585. Any appeal must be made in writing within 10 days of this notice. (You must submit a copy of this Notice when you appeal and pay a filing fee.)

**If you have any questions or request additional information, please contact me. To arrange an appointment or request an extension of time to complete repairs, you will need to speak directly to me at 651-266-1947.**

Sincerely,

**James Hoffman**  
**Badge # 356**

**CODE ENFORCEMENT OFFICER**

Footnotes:

<sup>1</sup> To see the Legislative Code go to [www.stpaul.gov](http://www.stpaul.gov) on the internet, click on "Departments", then click on "Department of Safety and Inspections", scroll down the page for the "Codes". Most Correction Notices derive from Chapter 34.

<sup>2</sup> Criminal charges can be brought on the day the violation is observed, but generally we allow time to correct unless this is a repeat violation.

jh

**WARNING:** Code inspection and enforcement trips cost the taxpayers money. If the violations are not corrected within the time period required in this notice, the city's costs in conducting a reinspection for compliance after the due date will be collected from the owner rather than being paid for by the taxpayers of the City. If additional new violations are discovered within the next following 12 months, the city's costs in conducting additional inspections at this same location within said 12 months will be collected from the owner rather than being paid for by the taxpayers of the City. Any such future costs will be collected via assessment against the real property and are in addition to any other fines or assessments which may be levied against you and your property.

November 20, 2018  
467 IVY AVE E  
Page **3** of **3**