

07/12/2021

Oudam Tun Tea 657 Sherburne Ave Saint Paul MN 55104-2706

Re: Verification of Account(s), Routing Number and Balance

This letter serves as TCF's verification that account(s) with balance noted at the time 11:31 of this inquiry:

Oudam Tun Tea

Tcf Free Checking account #

Balance 17,600.30

is a customer who holds the following

TCF's routing number is

If you have any further questions, please contact the account owner.

Sincerely,

Fabio Moro

In Store Customer Experience Banker

Phone: 612-317-4819 Fax: 952-920-4273

TCF National Bank
JUL 12 2021 Banking Center 4200 291070001

What's in it for we

Tea Oudam Tun

TCF Free Checking

Ledger balance: Current balance:		Today's activity: Total Holds:	11,359.00 0.00
Account available balance:	17,600.30	Float:	11,459.00
Total accessible balance:		Unused PRA:	
Closing balance:	29,059.30	Related available balance:	0.00
Last statement:	06/19/2021		

5 Transactions from 07/01/2021 to 07/12/2021

Date C	heck	<u>Debit</u>	Credit	Other D	<u>escription</u>	Status	Balance
07/12/2021	image		11,709.00		750 - Deposit	Pending	
07/12/2021		350.00			800 - Check	Pending	
07/06/2021	Image		1,000.00		600 - Deposit		
07/06/2021	1			750.00	586 - Available Float		
07/06/2021	1			1,000.00	580 - Collectable Float		

ACTIVE - Hold exists on DP

ACTIVE - Mail has been returned for OUDAM TUN TEA please verify address information.

ACTIVE - DP is not set up to receive electronic statements. ACTIVE - DP is not set up to receive electronic statements.

Close Message Area

Financial Account

Deposit Category

Refresh

Account Status
Open

Banking Center Number

4200

Transactions @

Clear

			Prev Page	Next Page
Tran Code Filter	Pending/Posted	Proc Date From	Proc Date To	
All	₩ All	₩.	Ħ	苗

T... 🗸 Description **New Balance Proc Date** Status 🗸 Notes **Amount** -\$350.00 \$0.00 07/12/2021 800 PENDING CHECK 0 07/12/2021 DEPOSIT \$11,709.00 \$0.00 750 PENDING 0 07/06/2021 POSTED \$1,000.00 \$17,700.30 600 DEPOSIT 0 362 POSTED -\$3.00 \$16,700.30 06/19/2021 SERVICE CHARGE 0 PAPER STATEMENT 06/10/2021 954 POSTED TRANSFER DEBIT 0 -\$500.00 \$16,703.30 06/10/2021 952 POSTED WITHDRAWAL -\$200,00 \$17,203.30 0 06/09/2021 DEPOSIT \$2,116.00 \$17,403.30 600 POSTED 0 POSTED -\$500.00 06/07/2021 TRANSFER DEBIT \$15,287.30 954 0 06/07/2021 952 **POSTED** -\$100.00 \$15,787.30 WITHDRAWAL 0 05/27/2021 952 **POSTED** WITHDRAWAL 0 -\$200.00 \$15,887.30 405@ustoner Search 954 Quick Nimstred -\$400.00 \$16,087.30 TRANSFER DEBIT 0

05/25/2021	600	POSTED	DEPOSIT	0		\$400.00	\$16,487.30
05/20/2021	952	POSTED	WITHDRAWAL	0		-\$200.00	\$16,087.30
05/19/2021	362	POSTED	SERVICE CHARGE	0	PAPER STATEMENT	-\$3.00	\$16,287.30
05/19/2021	952	POSTED	WITHDRAWAL	0		-\$200.00	\$16,290.30
05/13/2@mancial Ac	co800	POSTED	CHECK	198		-\$2,948.00	\$16,490.30
05/10/2021	600	POSTED	DEPOSIT	0		\$1,116.00	\$19,438.30
05/95/A02tegory	952 A	ccouRQSTED	WITH ผลผู้Adenter N	urAber	•	-\$400.00	\$18,322.30
B/04/2021	₉₅₄ O	perposted	TRANSPOR DEBIT	0		-\$400.00	\$18,722.30
05/04/2021	952	POSTED	WITHDRAWAL	0		-\$100.00	\$19,122.30
04/30/2021	235	POSTED	CKCD DEBIT	0	ST PAUL WATER UTILITY IV ME	-\$215.18	\$19,222.30
04/21/2021	954	POSTED	TRANSFER DEBIT	0		-\$200.00	\$19,437.48
. 04/19/2021	362	POSTED	SERVICE CHARGE	0	PAPER STATEMENT	-\$3.00	\$19,637.48
04/19/2021	800	POSTED	CHECK	194		-\$5,000.00	\$19,640.48
04/16/2021	111	POSTED	CKCD REFUND	0	MERCHANT REFUND TERMIN	\$53.44	\$24,640.48
04/12/2021	600	POSTED	DEPOSIT	0		\$2,514.00	\$24,587.04
03/25/2021	754	POSTED	TRANSFER CREDIT	0	•	-\$2,000.00	\$22,073.04
03/24/2021	235	POSTED	CKCD DEBIT	0	DOMINO S 1945 MERCHANT	-\$11.86	\$20,073.04
03/24/2021	227	POSTED	POS DEBIT	0	BP#9272907NICOLLET BP POS	-\$29,28	\$20,084.90
03/24/2021	235	POSTED	CKCD DEBIT	0	DOUBLE DRAGON FOODS IN	-\$16.18	\$20,114.18
03/24/2021	952	POSTED	WITHDRAWAL	0		-\$200.00	\$20,130.36
03/23/2021	227	POSTED	POS DEBIT	0	DOLLAR GENERAL # 1433 E P	-\$37.00	\$20,330.36
03/23/2021	235	POSTED	CKCD DEBIT	0	DAIRYLAND MERCHANT PUR	-\$95.66	\$20,367.36
03/23/2021	235	POSTED	CKCD DEBIT	0	WENDY S 410 MERCHANT PU	-\$9.55	\$20,463.02
03/22/2021	368	POSTED	SERVICE CHARGE	0	NONTCF ATM BAL INQ	-\$2.00	\$20,472.57
03/22/2021	261	POSTED	ATM BALANCE IN	0	BALANCE INQUIRY TERMINAL	-\$0.00	\$20,474.57
03/22/2021	235	POSTED	CKCD DEBIT	0	HOLIDAY STATIONS 0372 MER	-\$30.00	\$20,474.57
03/22/2021	235	POSTED	CKCD DEBIT	0	DOUBLE DRAGON FOODS IN	-\$15.83	\$20,504.57
4 ⁰³ /Customer Search	³⁶⁸ Qu	iick POSTED	SERVICE CHARGE	0 -	NON TCF ATM	-\$3.00	\$20,520.40



Account Balance Verification and Verification of Deposit and Loan Requests

Deposit Account Verifications:

Customers may request account balances or verification of deposit for themselves, a government agency or another third party such as:

- · Credit Card Companies
- Financial Institutions
- Mortgage Companies
- Loan Companies
- · Probate Court or Friend of the Court
- Landlord
- · College or University

Customer Account Balance Verification Request:

In the interest of customer service, any banking center team member may complete the Account Balance Verification form in the banking center for a customer. Authenticate customer through Regional CRM before completing the form below.

3rd Party Account Balance Verification Request:

Third party requests for DEPOSIT verification are completed by the research department. Banker should verify if the customer has a Signature Card on file prior to submitting a research request. Customer must provide the verification form in person, via e-mail, or fax. Banker/Agent emails the verification form with Consent to Release Information signed by our customer, to Deposit Services Research at Research. DepositServices@tcfbank.com or third party may send directly by fax to 989-633-5137. Deposit Services Research will respond back to the third party directly. If a signature card is not on file, deposit services will have to send an email to the Banking Center of the account requesting that they contact the customer to verify the request. The Banking Center will obtain new documentation if necessary.

Mortgage and Loan Verifications:

Mortgage and Loan Verifications must be completed by the credit bureau team in Loan Servicing. For all mortgage, revolving, commercial and installment loan verifications, send the request with the signed borrower's authorization to LNSVCRMA@tcfbank.com or fax 763-337-8965. The LSC team will reply with the requested information within 24-48 hours and there is no fee for mortgage and loan verifications.

WORK PLAN - BREAKDOWN COST OF REHABILATION

(To be done in accordance with the Code Compliance Inspection Report) Address: 3/8 Edmund

100710	EK	TACIZO	CONTED / CEOD	Cl. 3° /B.M. / * 3	3 7 1 1		X7 T 6
l .	F	TASKS	CONTRACTOR	Supplies/Materials	Needed	Owner/Developer	Value of
		240.00	A.5. 0. 10-4. 051	on hand (if any)	Supplies/Materials	Labor	Cost
July		BUILDING	RIE CONSTRUCTO	0 -		BOTH	8.514.
	دد	ELZGRICAL	LAWE PLUMBLE	- 0 -	_ 0 -	CONTRACT	2,00.50
ずん	20	PLUMBING	LANE PLUMBAZ	_ 3 -	_ 0 -	CONTRACT	5 995 00
- Jul	25	HEAT	NEIL HEATING	_ 0 '		CONTRACTS	\$11,000-
	-						
							
1							

Total Project Cost: § 28, 009.

Note:	(Code Enforcement	Officers estimate the cost to repair	this structure is \$	to \$).
-------	-------------------	--------------------------------------	----------------------	-------	----

11) organism karley, de korket merkembere bere luber servendelt, is zembetant is verb Tallet des rither praduct bestell 1977 (1


and the state of the second

Encolanie d. Éindusil

PLUMBING WORK ORDER / INVOICE

LANKE TILL TILL

		FOBOX 23 HANOV	Y R		
CHECK LIST	QTY ITEM OR PART DESCRIPTION UNIT PRICE	, , , , , , , , , , , , , , , , , , , ,	0 7		
WATER HEATER A ELEMENTS THERMOSTAT		MN 55341	9	00139	
RELIEF VALVE DIP TUBE ELECTRICAL CONN.		p# 612-1 366-18	80 DATE	E OBORDEO	2/
GAS WATER HEATER THERMOCOUPLE BURNER		NAMEUDAM TUN TEA	DAIE	E SCHEDULED	. よし
CONTROL (GAS) FLUE PIPE RELIEF VALVE		ADDRESS 18 Edmand Ave.			
TOILET BALL COCK FLAPPER		St Paul MM MAKE MODEL SE	RIAL #	⊒ CONTRACT ⊒ SERVICE CONTRAC ⊒ NORMAL ⊒ RES, □ COMM,	ст
SUPPLY LINE WAX SEAL & CLOSET BOLTS	TOTAL MATERIALS. /		83-9690		
DRAIN CLEANING KITCHEN SINK WASHER LINE	Bid For Cody Complia	nee on Plusting other	eus Tio		
MAIN LINE LAVATORY LINE TUB OR SHOWER	Funs h Fix two waste Vent	water pipe entine ho	use To		
☐ KITCHEN SINK	CO de MAN 10 2021, 1 Set FA	Lange		.]	
SINK FAUCET SINK DRAIN	A Twill supply all plaine & Fr	Advas, Notre fetr		-	
GARBAGE DISPOSAL GARBAGE DISPOSAL GARBAGE DISPOSAL CONNECTIONS	D. ANY ECTRA about bit will	be dong ATIM 150	you for hi	Z.	
TUB & SHOWER	+ makists	1 1 - 1 1 211			
D TUB VALVE D TRIP LEVER SHOWER DIVERTER	price To INclude Lobor, Ma	steriols Tod 3 Plbg Peru	2.K.S)	
TUB OR SHOWER DRAIN NEW CONSTRUCTION	LABOR - HRS RATE AMOUNT	I HEREBY AUTHORIZE THE ABOVE WORK TO BE DON) 1	
CRAWL SPACE ROUGH		ORDERED AND OUTLINED ABOVE, IT IS AGREED THAT WILL RETAIN TITLE TO ANY EQUIPMENT OR MATERIA	t t	1	
DRAINAGE		UNTIL COMPLETE PAYMENT HAS BEEN MADE. IF SET		1	
DRAINAGE		NOT MADE AS AGREED, THE SELLER HAS THE RIGHT EQUIPMENT AND MATERIAL WITHOUT BEING HELD F	9		
PSI TOP OUT DRAINAGE		For any damages resulting from the remov/ Ment.	AL OF EQUIP-		-
PSI D SEWER OR SEPTIC	TOTAL LABOR	WORK ORDERED BY	TOTAL MATERIALS	****	
DRAINAGE DWATER PSI	REG@MMENDATI@NS	ABOVE ORDERED WORK HAS BEEN COMPLETED AND I ACKNOWLEDGE RECEIPT OF MY COPY.	TOTAL LABOR	//4000	
PRESSURE REGULATOR BOOSTER PUMP FINAL		X CUSTOMER SIGNATURE DATE	TAX	*tentur	·····
COMMERCIAL REPAIR			OTHER		
☐ FLOOR DRAINS ☐ WASHER BOOSTER ☐ GREASE TRAF		Thank You	CHARGES TOTAL	5,995,	



CONSTRUCTION ESTIMATE

Estimate Submitted To: Oudam Tun Tea

Date: 07/09/2021

5761 33rd Ave. S. Unit 11

Job Location: 318 Edmund Ave.

Minneapolis, Mn 55417

Attn: Oudam Tun Tea

CONSTRUCTION WORK DESCRIPTION AS PER CODE COMPLIANCE REPORT:

BUILDING INSPECTOR: Nathan Bruhn

• To complete all items from 1. Thru 30. Total amount due \$ 8,514.00

ELECTRICAL INSPECTOR: Randy Klossner

• To complete all items from 1. Thru 3. Total amount due \$ 2,500,50

PLUMBING INSPECTOR: Pasul Zellmer

To complete all items from 1. Thru 12. Total amount due \$ 5,995.00

Heating Inspector: Erik Witt

To complete all items from 1. Thru 17. Total amount due \$ 11,000.00

PROPOSED COST: \$ 28,009.50

I hereby, estimate to furnish labor and materials in complete accordance with the above specifications

This is a budget estimate for completing the project described above. There maybe a final price fluctuation after the work is completed. This estimate is solely based on our evaluation and does not include any permits, material or labor price increases that may occur prior to signing.

Acceptance of Estimate: The above is satisfactory and are hereby accepted

Aychocun Tru

7-12-202

Signature

Date



CITY OF SAINT PAUL

375 Jackson Street, Suite 220 Saint Paul, MN 55101-1806

Telephone: 651-266-8989 Facsimile: 651-266-9124 www.stpaul.gov/dsi

Code Compliance Report

May 10, 2021

* * This Report must be Posted on the tob Site * *

OUDAM TUN TEA 5761 33RD AVE S Apt 11 MINNEAPOLIS MN 55417

Re:

318 Edmund Ave

File#: 12 112621 VB3

Dear Property Owner:

The following is the Code Compliance report you requested on April 14, 2021.

Please be advised that this report is accurate and correct as of the date May 10, 2021. All deficiencies identified by the City after this date must also be corrected and all codes and ordinances must be complied with. This report is valid for 365 days from May 10, 2021. This report may be used in lieu of a Truth in Housing Report required in St Paul Legislative Code 189. This building must be properly secured and the property maintained at all times.

In order to sell or reoccupy this property the following deficiencies must be corrected. A Legislative Code exemption (Chapter 33.03(f)) allows a Category 2 Vacant Building to be sold "as is" providing the buyer, prior to closing, completes an approval process. For further information, call Reid Soley at 651-266-9120.

ZONING

- 1. This property is in a(n) RT1 zoning district.
- 2. This property was inspected as a Single Family Dwelling.

BUILDING Inspector: Nathan Bruhn

1. Install handrails (34 inches - 38 inches above each nosing) and guardrails (36 inch minimum) at all stairways, and return hand rail ends into a newel post or wall per attachment. MNRC Ch 1309 Sect. 311 & 312

Phone: 651-266-9033

2. Prepare and paint interior and exterior as necessary. Observe necessary abatement procedures (EPA, MPCA and St. Paul Legislative Code, Chapter 34 for additional information) if lead base paint is present. SPLC 34.33 (1)

3. Any framing members that required repair or do not meet code (where wall and

Re: 318 Edmund Ave

May 10, 2021

Page 3

30. A building permit is required to correct the above deficiencies. All work is to be done in a workmanship like manner. SPLC 33.03 (a)

ELECTRICAL Inspector: Randy Klossner Phone: 651-266-9032

1. House has had new wiring installed throughout without any inspections. Wire the entire home to the current NEC standards.

2. Wire garage and outbuilding to current NEC.

3. All electrical work must be done by a Minnesota-licensed electrical contractor under an electrical permit.

PLUMBING Inspector: Paul Zellmer Phone: 651-266-9048

- 1. Attic Soil and Waste Piping (MPC 313) Install proper pipe supports.
- 2. Basement Soil and Waste Piping (MPC .0100 L & M & 708.1) Plug all open piping and properly pitch all piping.
- 3. Basement Water Heater (MFGC 409) Install the gas shut off and the gas piping to code.
- 4. Basement Water Heater (MPC .0100 Q)The water heater must be fired and in service.
- 5. First Floor Gas Piping (MFGC 411) Install an approved shut off; connector and gas piping for the range.
- 6. First Floor Lavatory (MPC 301.1) Repair/replace the ficture that is missing, broken or has parts missing.
- 7. First Floor Plumbing General (MN Rules Chapter 1300.0120) Obtain permits and provide tests/inspections for any plumbing performed without permits.
- 8. First Floor Sink (MPC 301.1) Repair/replace the fixture that is missing, broken or has parts missing.
- 9. First Floor Toilet Facilities (MPC 301.1) Repair/replace the fixture that is missing, broken or has parts missing.
- 10. First Floor Tub and Shower (MPC 401.1 & 409.2) Replace the waste and overflow.
- 11. First Floor Tub and Shower (MPC 301.1) Repair/replace the faucet that is missing, broken or has parts missing.
- 12. All the above corrections to waste, vent, water, and gas piping shall be per the Minnesota Plumbing Code Chapter 4714, Minnesota Rules Chapter 326, 4716, 1300, the Minnesota Mechanical Code, the Minnesota Fuel Gas Code, and Saint Paul Regional Water Services Water Code. All plumbing must be done by a plumbing contractor licensed in the State of Minnesota and the City of St. Paul by a plumber licensed in the State of Minnesota who also possess a City of Saint Paul Competency Card and after obtaining an approved City of Saint Paul Plumbing Permit.

Heating Inspector: Erik Witt Phone: 651-266-9045

1. Install approved level handle manual gas shutoff valve on furnace/boiler and

An Equal Opportunity Employer

Re: 318 Edmund Ave

May 10, 2021

Page 2

ceiling covering is removed, members that are over-spanned, over-spaced, not being carried properly, door and window openings that are not adequately supported, etc.) are to be reconstructed in an approved manner. SPLC 34.34 (1)

- 4. Provide fire block construction as necessary and seal chases in basement ceiling. MNRC Ch 1309 Sect. 602.8
- 5. Where wall and ceiling covering is removed install full thickness or codespecified insulation. MN Energy Code Ch. 1322.1101 (exept. 4)
- 6. Air-seal and insulate attic/access door. MN Energy Code Ch 1322.1102.4
- 7. Install Smoke Detectors/Carbon Monoxide Detectors per MN Conservation Code and the MN Dept. of Labor and Industry: Install per code where feasible. MNRC Ch 1309 Sect 313.2.1
- 8. Provide major clean- up of premises. SPLC 34.34 (4)
- 9. Install water- proof enclosure in shower area. MNRC Ch 1309 Sect. 307
- 10. Provide weather sealed, air sealed and vermin sealed exterior. SPLC 34.32 (2)
- 11. Replace or repair landing and stairway per code. SPLC 34.09 (2)
- 12. Strap or support top of stair stringers for structural stability. MNRC Ch 1309
 Sect 311.1
- 13. Provide proper drainage around house to direct water away from foundation of house. SPLC 34.08 (2)
- 14. Provide proper drainage around house to direct water away from foundation of garage. SPLC 34.08 (2)
- 15. Install downspouts and a complete gutter system. SPLC 34.33 (1d)
- 16. Provide general rehabilitation of garage. SPLC 34.32 (3)
- 17. Openings in stair risers must be less than 4 inches. MNRC Ch. 1309 Sect. 311/312
- 18. Grade must drain away from foundation of dwelling. Maintain 6 inch clearance between wood and soil. MNRC Ch 1309- Sect. 404.1.6
- 19. Remove and replace rear deck to code.
- 20. Provide plans and engineering specifications for new rooms created, and show how converted porch will meet energy code.
 - 21. Stairs to second floor need to be rebuilt to code.
 - 22. Roof rafters undersized, must be corrected.
 - 23. Repair or Replace any deteriorated window sash, broken glass, sash holders, re-putty, etc as necessary. SPLC 34.09 (3)
 - 24. Provide complete storms and screens, in good repair for all door and window openings. SPLC 34.09 (3e)
 - 25. Provide functional hardware at all doors and windows. SPLC 34.09 (3f)
 - 26. Exit doors shall be capable of being opened from the inside, easily and without the use of a key. Remove all surface bolts. SPLC 34.09 (3h)
 - 27. Repair or replace damaged doors and frames as necessary, including storm doors. SPLC 34.09 (3f)
 - 28. Install floor covering in bathroom and kitchen that is impervious to water. SPLC 34.10 (4)
 - 29. Repair walls, ceiling and floors throughout, as necessary. SPLC 34.34 (6)

Re: 318 Edmund Ave May 10, 2021

Page 4

remove unapproved valve.

2. Install approved lever handle manual building shutoff gas valve in an accessible location ahead of the first branch tee.

- 3. Clean and Orsat test furnace/boiler burner. Check all controls for proper operation. Check furnace heat exchanger for leak; provide documentation from a licensed contractor that the heating unit is safe.
- 4. Install approved metal chimney liner.
- 5. Replace furnace/boiler flue venting to code.
- 6. Connect furnace/boiler and water heater venting into chimney liner.
- 7. Vent clothes dryer to code.
- 8. Provide adequate combustion air and support duct to code.
- 9. Provide support for gas lines to code.
- 10. Plug, cap and/or remove all disconnected gas lines.
- 11. Provide heat in every habitable room and bathrooms.
- 12. Attach metal tag to expansion tank valve stating that this valve must be open at all times except when draining the expansion tank.
- 13. Support supply and return piping from heating system according to code.
- 14. Conduct witnessed pressure test on hot water heating system and check for leaks.
- 15. Install boiler pressure relief valve and pipe discharge to within 18 inches of the
- 16. Install back flow preventer on city water fill line to hot water heating system and pipe vent as required.
- 17. Mechanical permits are required for the above work.

Notes:

- 1. See attachment for permit requirements and appeals procedure.
- 2. This property is designated by the Vacant Buildings Department as a Category #3 which requires a \$5,000.00 Performance Bond or Deposit at the time the permit is issued.
- 3. Provide plans and specifications for any portion of the building that is to be rebuilt.
- 4. Interior of garage not available for inspection. Repair per applicable codes.

This is a registered vacant building. In order to sell or reoccupy this building, all deficiencies listed on this code compliance report must be corrected in accordance with the Minimum Housing Standards of the St. Paul Legislative Code (Chapter 34) and all required permits must receive final approval within six (6) months of the date of this report. One (1) six-month time extension may be requested by the owner and will be considered if it can be shown that the code compliance work is proceeding and is more than fifty (50) percent complete in accordance with Legislative Code Section 33.03(f).

Re: 318 Edmund Ave

May 10, 2021

Page 5

You may file an appeal to this notice by contacting the City Clerk's Office at 651-266-8688. Any appeal must be made in writing within 10 days of this notice. (You must submit a copy of this notice when you appeal, and pay a filing fee.)

If you have any questions regarding this inspection report, please contact Nathan Bruhn between 7:30 - 9:00 AM at 651-266-9033 or leave a voice mail message.

Sincerely,

Nathan Bruhn Code Compliance Officer Department of Safety and Inspections City of Saint Paul 375 Jackson Street, Suite 220 Saint Paul MN 55101

Phone: 651-266-9033

Email: nathan.bruhn@ci.stpaul.mn.us

Attachments