

375 Jackson Street, Suite 220 Saint Paul, MN 55101-1806 Tel: 651-266-8989 | Fax: 651-266-9124

- Yog hais tias koj tsis to taub tsab ntawv no, hu rau tus txhais lus ntawm (651) 266-8989. Nws yuav pab dawb xwb.
- Si necessita un traductor, por favor llamanos al (651)266-8989. No costo.

May 14, 2024

Anh Pham 12125 Martin St NW Coon Rapids MN 55448-1999

CORRECTION NOTICE

Date: May 15, 2024

RE: 705 MARYLAND AVE E

File #: 24-032541

Dear Sir/Madam:

The City of Saint Paul, Department of Safety and Inspections has inspected the above referenced property on **May 14, 2024** per the Legislative Hearing, we determined that the following deficiencies exist in violation of the Saint Paul Legislative Code¹ (see footnote 1, below).

1. SPLC 34.08. - PARKING: Parked or stored vehicles. All existing parking spaces shall consist of asphalt, concrete, gravel rock, or other durable and dustless surfaces. Existing parking surfaces must be maintained in a professional state of repair and may be maintained with like materials without additional approval from the city. Existing parking surfaces must be contained to eliminate migration onto other adjacent surfaces and must be clearly delineated. In all residential districts, off street parking shall not be located within any front yard or non-interior side yard. Before any existing parking spaces or driveways may be expanded upon, site plan approval must be obtained as specified in the Saint Paul Zoning Code and the lot must be developed in conformance with such approval.

PLEASE OBTAIN AN APPROVED PARKING SITE PLAN FROM ZONING TO ALLOW PARKING IN THE BACK OF THE PROPERTY AND CORRECTION MADE. IF NOT APPROVED REMOVE ALL VEHICLES PARKED IN THE BACK YARD AND RESTORE GROUND COVER. THANK YOU.

You are hereby notified to correct these deficiencies in accordance with the appropriate codes. The Enforcement Officer will re-inspect these premises on or after **June 28, 2024**, by which date the violations noted must be corrected. Failure to correct these deficiencies may result in an abatement and/or additional fees for re-inspection.

May 15, 2024 705 MARYLAND AVE E Page **2** of **2**

You may file an appeal to this notice by contacting the City Clerk at 651-266-8585. Any appeal must be made in writing within 10 days of this notice. (You must submit a copy of this Notice when you appeal and pay a filing fee.)

If you have any questions or request additional information, please contact me. To arrange an appointment or request an extension of time to complete repairs, you will need to speak directly to me at 651-266-9066.

Sincerely,

Andrew McCullough
Badge # 322
CODE ENFORCEMENT OFFICER

Footnote:

To see the Legislative Code go to www.stpaul.gov on the internet, click on "Departments", then click on "Department of Safety and Inspections", scroll down the page for the "Codes". Most Correction Notices derive from Chapter 34.

WARNING: Code inspection and enforcement trips cost the taxpayers money. If the violations are not corrected within the time period required in this notice, the city's costs in conducting a reinspection for compliance after the due date will be collected from the owner rather than being paid for by the taxpayers of the City. If additional new violations are discovered within the next following 12 months, the city's costs in conducting additional inspections at this same location within said 12 months will be collected from the owner rather than being paid for by the taxpayers of the City. Any such future costs will be collected via assessment against the real property and are in addition to any other fines or assessments which may be levied against you and your property.