Joanna Zimny

From: Randall Naiman < Randall@naimanlaw.com>

Sent: Wednesday, July 19, 2023 5:31 PM

To: Joanna Zimny

Cc: *CI-StPaul_LegislativeHearings; Pam Sundsmo; Clint Zane; Joe Yannarelly; Robert

Humphrey; Steve Magner; Vicki Sheffer; Tracy Band; Randall Naiman; Krystina Britt

Subject: 871 Stickney Street, Saint Paul, MN

Attachments: Proposed schedule 871 Stickney Ave St. Paul.pdf; Affidavit of Funds to Be Utilized - 871

Stickney Street, St. Paul, MN.pdf; VB PERFORMANCE DEPOSIT FORM 2020.pdf; Check Copy.pdf; June 6, 2023 - Solid Rock Construction Cure City Violations.pdf; June 30, 2023

- Scope of Repair.pdf

Think Before You Click: This email originated outside our organization.

Dear Ms. Zimny:

I am writing to provide you with the necessary documents related to the upcoming repairs planned for the property located 871 Stickney Street, Saint Paul, MN. Please find the following attachments:

- 1. <u>Performance Bond</u>. Enclosed is the completed performance bond application, and a \$5,000 check made payable to the City of Saint Paul. The performance bond application and check were sent via Federal Express to the Department of Safety & Inspections on Monday, July 19, 2023. Kindly confirm that the Performance Bond has been issued.
- 2. <u>Affidavit</u>. We have included a signed and notarized affidavit from Shawn Shorkey, Vice President at Hudson Homes Management, LLC. This affidavit confirms that the allocated finances will be used exclusively for completing the project and will not be diverted until a code compliance certificate is issued. Hudson Homes Management, LLC, acts as attorney-infact for U.S. Bank Trust, as Trustee for LSF9 Master Participation Trust, the owner of the property.
- 3. <u>Schedule for Project Completion</u>. Attached is a schedule for project completion provided by our client's general contractor, Solid Rock Construction. This document outlines the timeline for the project.
- 4. <u>Scope of Repair and Breakdown of Costs.</u> We have included the scope of repair and a detailed breakdown of costs for the project, prepared by Solid Rock Construction. This document provides an overview of the repairs required and associated expenses.

During the rehabilitation process, we assure you that the property will be adequately maintained to ensure compliance with relevant property maintenance standards. Furthermore, as confirmed on July 11, 2023, there is no need for an amendment to the original Code Compliance Report. The compliance period has been extended by an additional 120 days, starting from June 29, 2023, and ending on October 28, 2023. As stated on page 4 of the Code Compliance Report, our client has the option to request a six-month extension to complete the project if it is shown that the code

compliance work is proceeding and is more than fifty (50) percent complete in accordance with Legislative Code Section 33.03(f).

Please let us know if you require any further information or if there are additional documents that you need.

We appreciate your attention to this matter and look forward to your response.

Sincerely yours,

Randall D. Naiman, Esq. | Managing Director

NAIMAN LAW GROUP, PC | 4660 La Jolla Village Drive, Suite 650 | San Diego, CA 92122

T 858-224-6800 | F 858-224-6801 | randall@naimanlaw.com | http://www.naimanlaw.com

Privileged And Confidential Communication. This electronic transmission, and any documents attached hereto, (a) are protected by the Electronic Communications Privacy Act (18 USC §§ 2510-2521), (b) may contain confidential and/or legally privileged information, and (c) are for the sole use of the intended recipient named above. If you have received this electronic message in error, please notify the sender and delete the electronic message. Any disclosure, copying, distribution, or use of the contents of the information received in error is strictly prohibited.

Fair Debt Collection Practices Act Disclosure: To comply with the Fair Debt Collection Practices Act, we inform you that this is a communication from a debt collector. This may be an attempt to collect a debt and any information obtained will be used for that purpose. However, if you are in bankruptcy or received a bankruptcy discharge, no attempt is being made to collect a debt and any information will be obtained for informational purposes only.

From: Joanna Zimny < joanna.zimny@ci.stpaul.mn.us>

Sent: Monday, July 17, 2023 8:15 AM

To: Randall Naiman < Randall@naimanlaw.com > **Subject:** RE: 871 Stickney St.US Bank R-R Ltr.7-14-23

CAUTION: This email originated from outside of the organization. Do not click links or open attachments unless you recognize the sender and know the content is safe.

Mr. Naiman,

That all looks accurate. Regarding #2, yes, no change of ownership means no need for the City to review/approve any contracts.

Thanks, Joanna



14665 Buchanan St. NE #4 • Ham Lake, MN 55304 • Phone: 763-270-5058

Pam Sundsmo Phone: 612-412-6161

Job Address: 871 Stickney Ave St. Paul, MN 55107

Print Date: 6-16-2023

Cure City Violations

Thank you for the opportunity to provide you with this proposal!

We have partnered with **Venture** so a portion of the proceeds are building safe-houses for children in Nepal who have been rescued from trafficking.

Thank you for making a difference!

Please review below and let us know if you have any questions or concerns.

Description	Price
Permit and inspection fees TBD	\$0.00
Permanently secure top and bottom of support posts in an approved manner on deck	\$495.00
Where wall and ceiling covering is removed, install full thickness or code-specified insulation	\$2,880.00
Sheetrock insulate and seal attic door	\$310.00
Replace front step landing and stairway per code	\$3,600.00
Go over cement with green treated to get proper riser height and railings and landing	
Repair/replace gutters around perimeter with downspouts and 10' extensions	\$1,560.00
Replace service door to garage	\$765.00
Provide durable, dustless parking surface as specified in zoning code by placing 6"x87'x12' of gravel	\$3,600.00
Install 12' graspable handrail to lower level	\$320.00
Strap or support top of stair stringers for structural stability	\$750.00
Remove wood safety glass window by stairs	\$450.00
Replace (2) front and rear doors with (2) storm doors	\$2,450.00
Install sheet vinyl floor covering and seal vinyl edges in kitchen and bathroom	\$1,322.00

Description	Price
Prepare and paint interior and exterior as necessary	\$10,100.00
Observe necessary abatement procedures (EPA, MPCA and St. Paul legislative code, chapter 34 for additional information) if lead base is present	
Reframe and sheetrock adjacent stair wall	\$1,095.00
Install 16'x14' rear deck with new green treated stair stringers, green treated decking and green treated railings	\$12,750.00
Electrical safety inspection	\$375.00
Provide a complete circuit directory at service panel indicating location and use of all circuits	\$85.00
Install (4) hard-wired smoke detectors on main level and lower level	\$2,450.00
Install (2) CO detectors	
Throughout close openings in service panel/junction boxes with knockout seals, breaker blanks, proper cable clamps, and/or junction box covers	\$85.00
Rewire (2) switches and (4) outlets in lower level (2) bedrooms	\$990.00
Replace (5) GFCI outlets	\$675.00
Repair sheetrock after electrical wiring is complete, prep for paint	\$1,250.00
Vent clothes dryer to code	\$975.00
Test and start water heater	\$135.00
First floor piping vents - install required vent piping	\$3,600.00
First floor tub and shower - install proper fixture and vent to code	
Clean and Orsat test furnace/boiler burner	\$525.00
Check all controls for proper operation	
Check furnace heat exchanger for leak; provide documentation from a licensed contractor that the heating unit is safe	VALUE
Clean all supply and return ducts for warm air heating system	\$400.00
Replace (10) supply/returns	\$450.00

Total Price: \$54,442.00

2/3

By signing this Proposal you affirm your intent to enter into a contract with Solid Rock Construction for the products and services identified in the above scope of work. Upon receiving a signed copy of this Proposal, we will prepare and provide a complete and binding legal contract for your review and signature. This Proposal does not create or constitute any legally binding or enforceable obligations or liabilities.

The final estimated price reflects the entirety of the work. Alterations may change individual pricing. Quotes are subject to change after 15 days. This Proposal is valid until [Month] [Day], [Year].

*** MATERIAL AND/OR LABOR CHARGES MAY BE SUBJECT TO CHANGE. ***

CUSTOMER SERVICE COMMITMENT: Our goal for your job is to provide the best customer experience possible from

6/16/23, 3:03 PM Proposal Print

our professional, friendly, and courteous staff by doing things right the first time while respecting your home and property. We will also help you, the customer, feel part of the process with regular updates and excellent communication. Solid Rock Construction strives for excellence in all we do, however, construction is not a perfect process. If for some reasons our excellence does not meet your expectations, we still reserve the right to require full payment.

I confirm that my action here represents my electronic signature.							
Signature:							
Date:							
Print Name:							

				Sco	pe of Re	epair		
Broke	ers -	Use this	form to mark re	commended repairs items.	Check box if the repair i	s needed for fin	ancing.	
Conti	racto rials,	rs - Bid , equipm	on the scope of ent, appliances,	work as determined by the l etc. must be new. Obtain p	proker or field rep. Com ermits as required.	municate any o	versights to the broker for	consideration. All
Vend	or N	ame	Solid Rock Constru	uction	Loan Number	9804887041		
Vend	or Pl	hone	763-270-5058		Property Address	871 stickney st 87	1 stickney st	
Vend	or A	ddress	14665 Buchanan S	St	Agent Name	michael olsen		
Vend	or Ci	ity	Ham Lake		Agent Phone Number	6512098444		
Vend	or St	tate	MN		Utilities On?	No		
Vend	or Zi	р	55304		Lox Box Combination	lon		
Tax II)				SQFT			
Local	Tax	Rate	0.0000		Preservation			
	1)	Floor	ing				Total Flooring	\$
		Scope	Comments: Continued:	surface in high traffic areas. Floo	ring removal/prep should be l	isted separately un	der "Recommended Flaoring Rep	airs" section.
	1	Carpet !	Denlara	Price per yd	SQYD			<u> </u> \$
	1	Carpers	/ehighe	Weight	Brand			Ψ
				Color	Draino			
	2	Carpet F	Pad	Price per yd	SQYD			\$
		ourpor.		Weight				•
	3	Carpet (Comme						\$
	4	Carpet F Comme						\$

	5	Vinyl Replace	Price per yd.		Brand			\$
-	 		SQYD		<u></u>			
	1		Color		·			
	6	Vinyl Repair Comments						\$
Protect	7	Tile Flooring Replace	Tile Size		Tile SQFT		<u> </u>	\$
	 	The Flooring Propiess	Color		1			
[]	8	Tile Flooring Repair	Tile Size		Tile SQFT			\$
	 		Color					7
	9	Hardwood Replace	Square Footage		Color			\$
	1	Hardwood Repair/Refinish	Square Footage		Brand			\$
·	1		Color					
	11	Laminate Replace	Square Footage		Color			\$
	12	Laminate Repair	Square Footage		Color			\$
	13	Subfloor Replace Comments						\$
	1	Subfloor Replace	Square Footage					
	14	Subfloor Repair Comments						\$
		Subfloor Repair	Square Footage					
		Recommended Flooring Repairs						\$
	1						Flooring Subtotal	\$
							Flooring Tax Rate	\$
	2)	Wallpaper/Sheetro	ck			Tota	l Wallpaper/Sheetrock	: \$
	<u> </u>							
	Category Guidelines: Drywall repair to match existing finish. Drywall should be bid by the square foot. Remediation should include post remediation air clearar test and warranty. Cost of insulation should be listed in "Recommended Wallpaper/Sheetrock Repair Comments. Wallpaper removal pricincludes re-texture. Include amount of wallpaper removed.					emediation air clearance Pallpaper removal price		
		Scope Comments:			and the second s	1		

		Scope Continued:			
		Bid Comments:			
	1	Drywall Replace Comments			\$
		Drywall Repair Comments			\$
	3	Wallpaper Repair Comments			\$
	4	Wailpaper Replace Comments			\$
		Paneting Removat/Paint Comment			\$
		Remediation/ Clearance Comment			\$
		Recommended Wallpaper/Sheetrock Repair Comments			\$
· · · · · · · · · · · · · · · · · · ·				Wallpaper/Sheetrock Subtotal	\$
				Wailpaper/Sheetrock Tax Rate	

3)	Paint Interior/Exterior			Total	Paint Interior/ Exterior	\$
	Category Guidelines:	Interior: Walls: Neutral, Doors/Ti Details required; colors, finish, b sink.Exterior: Use semi-gloss lat	rim white, semi-gloss, Cellings: Wh rand, Touch-Up paint, min. 1 qt., fo lex. Confirm exterior color with HO,	nite, flat. Outlet or each color v A prior painting	/switch covers should be removed. rith each product labeled, left in kit 3.	replaced for painting. chen cabinet under
	Scope Comments:					
	Scope Continued:					
	Bid Comments:					
1	Complete Interior Paint	SQFT		Brand		\$
		Color(s)				
2	Walls Only Comments					\$
3	Doors/Trims/ Cabinets Comments					\$
4	Ceiling Only Comments					\$
5	Complete Exterior Paint	SQFT		Brand		\$
 		Color(s)				
6	Doors/Trim Only Comments					\$
7	Siding Only Comments					\$

	Ω	Decks Stain/Paint			\$
	O	Comments			
	9	Shutters Paint/Install Comments			\$
	10	Recommended Paint Repairs Comments			\$
	L			Paint Interior/ Exterior Subtotal	\$
				Paint Interior/ Exterior Tax Rate	\$
	4)	Appliances		Total Appliances	\$
		Guidelines:	Bid to include installation and disposal. Bid only builder grade unling Details required: brand, model, color. Range to be anchored. All granuals place in kitchen drawer.	ess otherwise specified. If bidding to repair, descr gas appliances must be installed by a licensed plu	ribe repair needed. Imber. Appliance owner's
		Scope Comments:			
		Scope Continued:			
		Bid Comments:			
	1	Range/Cooktop/Oven Replace	Brand		\$
			Color		
	2	Range/Cooktop/Oven Repair	Brand		\$
			Color		
	3	Vent Hood Replace	Brand		\$
			Color		
	4	Vent Hood Repair	Brand		\$
			Color		
	5	Microwave/Micro Hood Replace	Brand		\$
 			Color		

	6	Microwave/Micro Hood	Brand			\$
	<u> </u>	Repair	Color			
	7	Disposal Replace	Brand			\$
<u> </u>			Color			
	8	Disposal Repair	Brand			\$
			Color			
	9	Dishwasher Replace	Brand			\$
-			Calor			
	10	Dishwasher Repair	Brand			\$
			Color			
	11	Recommended Appliances	Brand			\$
			Color			
					Appliance Subtotal	
					Appliance Tax Rate	\$
	5)	Electrical			Total Electrical	\$
			I .			
		Guidelines:	Address litegal splicing, missing of fixture to be replaced. Upon or batteries to ensure property func	wires, etc. Price to include new bulbs and globes empletion, all light bulbs should be functioning. Ir tion. Install garage door opener with two remotes	s. Details required: number of fixtur nstall or replace Smoke/CO detecto s.	es, fixture type, location or per code or replace
		Scope Comments:				
		Scope Continued:				
		Bid Comments:				
	1	Breaker/Wiring Replace				\$
J						
	2	Breaker/Wiring Repair				\$
	3	Fixture Replace				\$

 	····	·		φ.
	Fixture Repair			\$
5	Outlets/Switches			\$
6	Wall Plates			\$
7	Smoke/CO2 Detectors			\$
8	Recommended Electrical Repairs			\$
 L			Electrical Subtotal	\$
			Electrical Tax Rate	
6)	HVAC			\$
	HVAC Guidelines:	Repair if possible. Always change filters after painting. Details required: brand, m filters and a spare filter for each unit to be left in closet.	Electrical Tax Rate Total HVAC	\$
		Repair if possible. Always change filters after painting. Details required: brand, m filters and a spare filter for each unit to be left in closet.	Electrical Tax Rate Total HVAC	\$
	Guidelines:	Repair if possible. Always change filters after painting. Details required: brand, m filters and a spare filter for each unit to be left in closet.	Electrical Tax Rate Total HVAC	\$
	Guidelines: Scope Comments:	Repair if possible. Always change filters after painting. Details required: brand, m filters and a spare filter for each unit to be left in closet.	Electrical Tax Rate Total HVAC	\$

	2	Condenser Repair			\$
E		Í			
					A.
	3	Furnace Replace			\$
-					
ļ	İ				
		Furnace Repair			\$
	"	i unace repair			•
					·
	5	Thermostat Replace			\$
_					
		Thermostat Repair			\$
	"	т пеннозы торы			*
Ì					
	7	Duct Work/Grill			\$
	8	Service Call Report			\$
	"	CONTROL CUIT TOPOR			•
		Recommended HVAC			\$
		Repairs			
				HVAC Subtotal	\$
				HVAC Tax Rate	
	7)	Plumbing/Bath	Total P	lumbing/Bath	\$
		Guidelines:	Address all line repairs, valve boxes, sewer clean outs, etc. Bid to replace missing/broken mirro	ors. Water heater to in	relude strapping to
			local code. Details required: Type of repair/replacement, location. Replace supply lines w/braid Replace shutoff valves, if inoperable. New Fluid Master (fill valve/flapper) and new toilet seats f	ed stainless steel (all	faucets and toilets).
			Replace shutoff valves, if inoperable. New Fluid Master (fill valve/flapper) and new toilet seats t	or all tollets.	
		Scope Comments:			

	Scope Continued:	
	Bid Comments:	
1	Interior Pipes Replace	\$
2	Interior Pipes Repair	\$
3	Exterior Pipes Replace	\$
4	Exterior Pipes Repair	\$
5	Water Heater Replace	\$
6	Water Heater Repair	\$
7	Mirror Replace	\$
8	Faucet	\$
9	Sink/Toilets	\$

	10	Shower/Tubs			\$
_					
П	11	Tile Surrounds Replace			\$
	12	Tile Surrounds Repair		<u> </u>	\$
	12	The Surrounds (Vepan		:	*
	13	Septic			\$
,,,,,					
		0.1		w	\$
	14	Well/Pump/Main Line			Φ
		·			
		Winterization/			\$
		Dewinterlzation			
					^
		Recommended Plumbing Repairs			\$
				Plumbing/Bath Subtotal	\$
				Plumbing/Bath Tax Rate	
	8)	Roofing		Total Roofing	\$
		Guidelines:			
		Guidelines.	All roofing to be performed per local code. Do not overlay more than one existing and meet HOA/local requirements. Specify linear footage, number of downspouls	and splash blocks for gutters. Bid	I to include tear off and
			permits. Details required: shingle brand, type, color, year, and number of squares	•	
	٠	Scope Comments			
		Coons Continued			
		Scope Continued:			

***************************************	Bid Comments:				
	Repair Leaks				\$
2	Replace Roof Squares				\$
3	Roof Decking/Sheathing Replace	# of Squares			\$
	Roof Decking/Sheathing Repair				\$
5	Flashing Replace				\$
6	Flashing Repair				\$
7	Roofing Certification				\$
8	Gutters				\$
 		Gutters LF			
9	Recommended Roof Repairs				\$
 	1	1		Roofing Subtotal	\$
			•	Roofing Tax Rate	\$

 9)	Structural	Total Structural \$	
 <u> </u>	Guidelines:	Structural Engineering Reports are required for visible defects. Only Licensed Specialty Vendors to bid the structural repairs per completed engineers report. Vendor to pull permits when required.	ď
	Scope Comments:		
	Scope Continued:		
	Bid Comments:		
1	Engineering Inspection	\$	
2	Grading	\$	
3	Foundation Underpin/Mud jack	\$	
4	Epoxy/Masonry	\$	
	Stucco Repair/Wash	\$ 	
6	Chimney Repair	\$	

		•							
	7	Recommended Structural Repairs							\$
								Structural Subto	
								Structural Tax R	ate \$
	10)	Carpentry Interior/	Exterior			To	tal Carp	entry Interior/Exteri	or \$
		Guidelines:	T	ounter bids must incle ach bedroom for egre Ilbox 's must be visib	ude material, c ess. Closet she le (per HOA C	color & size. Cabinet Knot slving 12" stock wire, repl CR) White Blinds 1"all wi	bs 1-1/4" ro lace only if ndows exc	ound brushed nickel, if needed needed. Install doorstops/hing apt picture windows, 3-1/2" ver	, One functioning window e stops as needed, ticals @ patio sliders.
-		Scope Comments:							
		Scope Continued:							
		Bid Comments:							
	1	Cabinet Replace	LF		Height				\$
			Color						
	- 2	Cabinets Repair	LF		Height				\$
			Color						
	3	Hardware Repair							\$
	4	Hardware Replace							\$
	5	Countertops	LF		Material				\$
			Color		<u> </u>	J			
	6	Interior Door/Hardware/ Trim Replace							\$

					 	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	Φ.
	7	Interior Door/Hardware/ Trim Repair					\$
	8	Exterior					\$
		Door/Hardware/Trim Replace					
П		Exterior Door/Hardware/Trim Repair					\$
		Exterior Trim/Siding Replace					\$
	11	Exterior Trim/Siding Repair					\$
	12	Garage Door Replace					\$
	13	Garage Door Repair					\$
		Deck/Fence/Gate Replace					\$
П	15	Deck/Fence/Gate Repair					\$
	16	Window Replace	Number of Windows		 		\$
		Window Replace Comments					

	17	Window Repair	Number of	Windows										\$	
屵		Window Repair	1			h									
		Comments													
1															
											···-			Φ	
	18	Screens Replace	Number of	Screens										\$	
		Screens Replace													
		Comments													
	40	Corcona Donair	Number of	Screens		I		,		························				\$	
	18	Screens Repair	INDITIDET OF	36166113										<u> </u>	
		Screens Repair Comments													
		Comments													

-	20	Recommended	 											\$	11
	-	Carpentry Repairs													
-	I		<u></u>							[y Subtotal	·	
-											(Carpentry	/ Tax Rate	\$	
L															
<u></u>									T	T-4-1	01	the sell of		¢	
	11)	Cleaning/Landscar	pe							Total	Clean	ing/Lar	ndscape	\$	
	11)	Cleaning/Landscar		repaired, hom	ne mus	st be deep o	cleaned, ir	cluding wi	ndows in:						00 -
	11)			s repaired, hom quired to impro	ne mus	st be deep or orb appeal.	cleaned, ir	ncluding wi	ndows in:					\$ e Allowance of \$50	00 -
	11)			s repaired, hom quired to impro	ne mus	st be deep orb appeal.	cleaned, ir	ncluding wi	ndows in:						00 -
	11)			repaired, hom quired to impro	ne mus	st be deep or the appeal.	cleaned, ir	ncluding wi	ndows in:						00 -
		Guidelines:		s repaired, hom quired to impro	ne mus	st be deep or appeal.	cleaned, ir	ncluding wi	ndows in:						00 -
				s repaired, hom quired to impro	ne mus	st be deep or appeal.	cleaned, ir	ncluding wi	ndows in:						00 -
		Guidelines:		s repaired, hom quired to impro	ne mu	st be deep orb appeal.	cleaned, ir	acluding wi	ndows in:						90 -
		Guidelines:		s repaired, hom quired to impro	ne mus	st be deep on the appeal.	cleaned, ir	acluding wi	indows in:						00 -
		Guidelines:		repaired, hom quired to impro	ne mus	st be deep on the appeal.	cleaned, ir	ncluding wi	ndows in						00 -
		Guidelines: Scope Comments:		s repaired, hom quired to impro	ne mus	st be deep (rb appeal.	Cleaned, ir	cluding wi	ndows in:						00 -
		Guidelines:		s repaired, hom quired to impro	ne mus	st be deep orb appeal.	cleaned, ir	ncluding wi	ndows in:						00 -
		Guidelines: Scope Comments:		s repaired, hom quired to impro	ne mus	st be deep on the appeal.	cleaned, ir	ncluding wi	ndows in:						00 -
		Guidelines: Scope Comments:		s repaired, hom quired to impro	ne mus	st be deep on the appeal.	cleaned, ir	acluding wi	ndows in:						00 -
		Guidelines: Scope Comments:		repaired, hom quired to impro	ne mus	st be deep on the appeal.	cleaned, ir	ncluding wi	ndows in:						00 -
		Guidelines: Scope Comments:		repaired, hom quired to impro	ne mus	st be deep orb appeal.	cleaned, ir	cluding wi	ndows in:						00 -
		Guidelines: Scope Comments: Scope Continued:		s repaired, hom quired to impro	ne mus	st be deep on the appeal.	cleaned, ir	ncluding wi	ndows in:						00 -
		Guidelines: Scope Comments: Scope Continued:		repaired, hom quired to impro	ne mus	st be deep on the appeal.	cleaned, ir	ncluding wi	ndows in:						00 -
		Guidelines: Scope Comments: Scope Continued:		repaired, hom quired to impro	ne mus	st be deep on the appeal.	cleaned, ir	acluding wi	ndows in:						00 -
		Guidelines: Scope Comments: Scope Continued:		repaired, hom quired to impro	ne mus	st be deep on the appeal.	cleaned, ir	ocluding wi	ndows in:						00 -
		Guidelines: Scope Comments: Scope Continued:		repaired, hom quired to impro	ne mus	st be deep orb appeal.	cleaned, ir	ncluding wi	ndows in:						00 -
		Guidelines: Scope Comments: Scope Continued:		repaired, hom quired to impro	ne mus	st be deep or appeal.	cleaned, ir	ncluding wi	ndows in:					e Allowance of \$50	00 -
		Guidelines: Scope Comments: Scope Continued:		repaired, hom	ne mus	st be deep on the appeal.	cleaned, ir	acluding wi	ndows in:					e Allowance of \$50	00 -
		Guidelines: Scope Comments: Scope Continued:		repaired, hom	ne mus	st be deep on the appeal.	cleaned, ir	acluding wi	ndows in:					e Allowance of \$50	00 -

	2	Landscape				\$
O	3	Exterior Clean/Power Wash				\$
	4	Pool Clean				\$
	5	Final Sales Clean		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		\$
	6	Recommended Clean				\$
			·			
					Cleaning/Landscape Subtotal	\$ \$
						Lib
					Cleaning/Landscape Tax Rate	
	12)	Other Recommend	ed Repairs	Tot	al Other Recommended Repair	
		Other Recommend				s \$ 54442.00
					al Other Recommended Repair	s \$ 54442.00
					al Other Recommended Repair	s \$ 54442.00
		Guidelines:			al Other Recommended Repair	s \$ 54442.00
					al Other Recommended Repair	s \$ 54442.00
		Guidelines:			al Other Recommended Repair	s \$ 54442.00
		Guidelines: Scope Comments:			al Other Recommended Repair	s \$ 54442.00
		Guidelines:			al Other Recommended Repair	s \$ 54442.00
		Guidelines: Scope Comments:			al Other Recommended Repair	s \$ 54442.00
		Guidelines: Scope Comments:			al Other Recommended Repair	s \$ 54442.00
		Guidelines: Scope Comments:			al Other Recommended Repair	s \$ 54442.00
		Guidelines: Scope Comments: Scope Continued:			al Other Recommended Repair	s \$ 54442.00
		Guidelines: Scope Comments: Scope Continued:			al Other Recommended Repair	s \$ 54442.00
		Guidelines: Scope Comments: Scope Continued:	Use this section to bid miscellaneous rep		al Other Recommended Repair	s \$ 54442.00
		Scope Comments: Scope Continued: Bid Comments:	Use this section to bid miscellaneous rep		al Other Recommended Repair	s \$ 54442.00 ents, etc.)
		Scope Comments: Scope Continued: Bid Comments:	Use this section to bid miscellaneous rep		al Other Recommended Repair	s \$ 54442.00 ents, etc.)

							
	2	Other Recommended Repa	irs -2				\$
	3	Other Recommended Repa	irs -3				\$
	4	Other Recommended Repa	irs -4		Walter (1997)		\$
	5	Other Recommended Repa	irs -5	Repair city violations to avoid dermolition			\$ 54442.00
t			· · · · · · · · · · · · · · · · · · ·			Other Recommended Repairs Subtotal	\$ 54442.00
						Other Repairs Tax Rate	\$ 0.00
·····				Grand Total For All Repairs			\$ 54442.00
		10000					
		Date of Bid	6/3	30/2023			- And the second se
		Contractor Signature					
	i	Servicer Signature	Ang	ela Cooper			

Waiver: If Contractor's bid is accepted by Hudson Homes Management, LLC, Contractor waives and releases any lien or claim of lien Contractor may have on the above referenced real property and improvements on account of labor and/or materials furnished or to be furnished pursuant to this bid (including any attachments), upon receipt of payment of the above-referenced "Grand Total for All Repairs" by Hudson Homes Management, LLC. Further, Contractor also agrees to indemnify and hold Hudson Homes Management, LLC harmless from and against any and all claims (including, any claim made or lien filed by any third party), expenditures or losses Hudson Homes Management, LLC incurs as a result of Contractor's failure to honor this waiver of mechanic's lien(s) or Contractor's failure to pay for materials and services when due.

Safety: As an independent contractor, you must take all appropriate precautions to ensure the health and safety of yourself, your employees and anyone who, in any way, works for you. In dealing with the property, you may come across health and safety issues that give cause for concern. These issues could include risks related to physical damage to the property, criminal activity, and environmental concerns, including toxic mold and hazardous substances. You should use reasonable judgment when dealing with health and safety issues. Do no enter upon the property if you believe that doing so will pose a risk to your health or safety.

/s	
1 (1	1
Contractor Signature \	
1	
	•