

Revised Work Plan of Buddy Code Compliance

Add: 1181 Edgerborn St.

| Week   | Task  | Contractor Labor | Owner labor | Material on hand      | Material needed                   | Cost of value |
|--------|---|------------------|-------------|-----------------------|-----------------------------------|---------------|
| Jan 1  | Repair, replace 9 windows   | No               | 900.00      | Windows               |                                   | 4000.00       |
| Dec 10 | Repair walls, ceiling and floors in Kitchen                       | No               | 400.00      | compound              | Paint, ceramic tile for the floor | 2000.00       |
| Jan 8  | Repair/replace 12 doors   | No               | 400.00      |                       | New doors                         | 750.00        |
| Dec 12 | Replace rear porch entry stairs                                   | No               | 500.00      | Treated lumbers       |                                   | 400.00        |
| Dec 20 | Insure basement cellar floor, fill holes, support posts and beams | No               | 400.00      |                       | Post, beam, concrete              | 200.00        |
| Dec 20 | Install plinth blocks, adequate footing                           | No               | 300.00      |                       | concrete                          | 200.00        |
| Dec 10 | Install new stair to basement                                     | No               | 100.00      | Treated lumbers       |                                   | 200.00        |
| Jan 20 | Repair wall throughout the house                                  |                  | 500.00      | Sheet rocks, compound |                                   | 600.00        |
| Jan 25 | Replace bathtub   | No               | 200.00      |                       | Bathtub                           | 900.00        |
| Jan 27 | Install handrails, guardrails                                     | No               | 100.00      |                       | Handrails, guardrails             | 200.00        |
| Jan 27 | Install smoke detectors   |                  | 100.00      |                       | Smoke detectors                   | 150.00        |
| Jan 1  | Repair siding, fascias. Replace roof hover hang on front porch    | yes              | no          |                       |                                   | 8000.00       |
| Jan 25 | Replace/repair floor throughout the house                         | no               | 700.00      | Bamboo floor          | carpet                            | 3000.00       |
| Feb 1  | Major clean up  | No               | 200.00      |                       | Cleaning product                  | 200.00        |