17-231



e-mail. -rrn

APPLICATION FOR APPEAL

Saint Paul City Council – Legislative Hearings

RECEIVED

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102

		DEC 20	2017	Telephone: (651) 266-8585
We need the following to proces	ss your appeal:	CITY CL	.ERK	
\$25 filing fee (non-refundable) ((if cash: receipt number	payable to the City of the Cit	of Saint Paul)	HEARING DAT (provided by Leg Tuesday, Time Location of Hea	gislative Hearing Office)
Address Being Appealed:				
Number & Street: 548	Simpson Street	21 City: 5	Stat	te: <u>MU</u> zip: <u>55164</u>
Appellant/Applicant: Jessic	a L. Teske /3	JT Enterpris	ies ail teskeho	mesægnen). Com
Phone Numbers: Business	Resid	dence	Cel	1651-246-5126
Signature: Q Dacu	8. 3hz		Date:)	a 18/17
Name of Owner (if other than Appellant): Same as applicant				
Mailing Address if Not Appellan	t's:		_ Jessica	L-Teske
Phone Numbers: Business			- Mound	atuyethe Lane
What Is Being Ap	pealed and	Why?	Attachment	s Are Acceptable
Vacate Order/Condemnation/ Revocation of Fire C of O		_		the busement waste
□ Summary/Vehicle Abatement			I have our	O 11
Fire C of O Deficiency List/Co	orrection These reg	Pairs have	voen present	1
□ Code Enforcement Correction	Notice are wo	Jary just	The JI i	would like to not
□ Vacant Building Registration	have to	pay to re	-do them	moil they are an
□ Other (Fence Variance, Code Complia			15.	
Also appealing the dryer vent See 12-2	#11 Th	e upstric	5 toiler is	y I will double

chock this and

Naylor, Racquel (CI-StPaul)

From:

Naylor, Racquel (CI-StPaul)

Sent:

Wednesday, December 20, 2017 2:18 PM

To:

'Jessica Teske'

Subject:

RE: 548 Simpson Street

I will add this item to your appeal. -Racquel

From: Jessica Teske [mailto:teskehomes@gmail.com]
Sent: Wednesday, December 20, 2017 2:14 PM

To: Naylor, Racquel (CI-StPaul) **Subject:** Re: 548 Simpson Street

Thank you Racquel,

Can you please add the dryer vent (Item #9) to the appeal. I believe this was completed per a previous CO inspection at the property.

On Wed, Dec 20, 2017 at 2:07 PM, Naylor, Racquel (CI-StPaul) < racquel.naylor@ci.stpaul.mn.us > wrote:

As you requested, your Legislative Hearing has been moved to Tuesday, January 9, 2018, 1:30 p.m. The location stays the same. I was informed that this hearing will not be rescheduled again, so make sure you or a representative is at the January 9 hearing.

Thank you and have a good day.

-Racquel

From: Naylor, Racquel (CI-StPaul)

Sent: Wednesday, December 20, 2017 10:50 AM

To: teskehomes@gmail.com

Cc: *CI-StPaul_LegislativeHearings (LegislativeHearings@ci.stpaul.mn.us)

Subject: 548 Simpson Street

Jessica L. Teske.

I have your Application for Appeal on the Correction Notice dated 12-8-17. Your Legislative Hearing is scheduled for Tuesday, December 26, 2017, 1:30 p.m. The hearing is located in the City Hall/Courthouse, 15 Kellogg Boulevard West, Room 330, Saint Paul, MN 55102.

Thank you.

Racquel Naylor

City Council Offices

Suite 310 City Hall

15 Kellogg Boulevard West

Saint Paul, MN 55102

651-266-8585

Jessica L. Teske J.T. Enterprises, LLC Phone: 651-246-5126 Fax: 952-392-4576



CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806

 Telephone:
 651-266-8989

 Facsimile:
 651-266-8951

 Web:
 www.stpaul.gov/dsi

Post Mork by 18th

December 8, 2017

JESSICA TESKE J T ENTERPRISES LLC 1772 LAFAYETTE LANE MOUND MN 55364

FIRE INSPECTION CORRECTION NOTICE

RE:

548 SIMPSON ST

Ref. #110008

Residential Class: C

Dear Property Representative:

Your building was inspected on December 7 & 8, 2017 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date.

A re-inspection will be made on January 12, 2018 at 11:00 AM.

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

DEFICIENCY LIST

- 1. Exterior Check All SPLC 34.09 (4), 34.33 (3) -Provide or repair and maintain the window screen.
 Main floor sleeping room missing screen.
- Exterior Public Sidewalk and Property Sidewalk and Stairs SPLC 113.02, MSFC 1030.3 –
 Remove the accumulation of snow or ice from the public and private sidewalk abutting this property.-

- 3. Exterior See Comments SPLC 34.09 (4), 34.33 (3) Repair and maintain the window glass.One window on north side of dwelling, facing west.
 One window on east side of dwelling.
- 4. Interior Back Porch NEC 440.13 For cord-connected equipment such as: room air conditioners, household refrigerators and freezers, drinking water coolers, and beverage dispensers, a separable connector or an attachment plug and receptacle shall be permitted to serve as the disconnecting means. The appliance must plug directly into a permanent outlet.
 Refrigeration unit plugged into extension cord from main floor to receptacle in basement.
- 5. Interior Back Porch Refrigeration Unit MSFC 605.5 Discontinue use of extension cords used in lieu of permanent wiring.-
- Interior Basement Waste Lines SPLC 34.11 (1), SBC 2902.1, SPLC 34.35 (1), MPC 301.1 Provide an approved number and type of plumbing fixtures.Repairs with rubber fittings are not compliant. Repair to code or contact a licensed plumber to make the repairs. Non-compliant repairs will require a licensed plumber to make repairs with permit and inspection by city inspection staff.
 - 7. Interior Charcoal on Back Porch Shelving MSFC 313.1 Fueled equipment, including but not limited to motorcycles, mopeds, lawn-care equipment and portable cooking equipment, shall not be stored, operator or repaired within a building.-
- 8. Interior Check All SPLC 34.09 (4), 34.33 (3) Repair and maintain the window sash.-Main floor sleeping room.
- Interior Clothes Dryer Vent MMC 504.6 Provide, repair or replace the dryer exhaust duct. Exhaust ducts for domestic clothes dryers shall be constructed of metal and shall have a smooth interior finish. The exhaust duct shall be a minimum nominal size of four inches (102 mm) in diameter and installed in accordance with the mechanical code. This work requires a licensed plumber to obtain a permit(s) and contact city inspection staff for review of the work and finalizing of the permit. Call DSI at (651) 266-8989.-
 - 10. Interior Second Floor Sleeping Room MSFC 605.1- All light fixtures shall be maintained with protective globes if originally equipped.- Missing in second floor sleeping room, check all.
- Interior Second Floor Toilet SPLC 34.11 (1), MSBC 2902.1, SPLC 34.35 (1), MPC 301.1 Repair or replace and maintain all parts of the plumbing system to an operational condition.
 Rocking, sliding, secure toilet. Not toler IS JUST IQ

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8585) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: laura.huseby@ci.stpaul.mn.us or call me at 651-266-8998 between 7:30 a.m. - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Laura Huseby Fire Inspector

Reference Number 110008