

□ Other

APPLICATION FOR APPEAL

RECEIVED
SEP 2 2 2011
CITY CLERK

Saint Paul City Clerk

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8560

The City Clerk needs the following to process your appeal: \$25 filing fee payable to the City of Saint Paul (if cash: receipt number) Copy of the City-issued orders or letter which are being appealed Attachments you may wish to include This appeal form completed Walk-In OR Mail-In	YOUR HEARING Date and Time: Tuesday, / \(\sigma - \lambda - \lambda \) Time \(\lambda \) \(\frac{30}{\text{Location of Hearing:}}{\text{Room 330 City Hall/Courthouse}} \)
Address Being Appealed:	
Number & Street: 705 Geranium Ave ECity: St Paul State: MN Zip: 55/19 Appellant/Applicant: Nick T. Carlson Email maxim carlson agmain	
Phone Numbers: Business 6/2-558-8008 Residence 6/2-558-8008 Cell 6/2-558-8008 Signature: Date: 9/22/11	
Name of Owner (if other than Appellant):	
Address (if not Appellant's):	
Phone Numbers: Business Residence	Cell
What Is Being Appealed and Why? Attachments Are Acceptable	
Vacate Order/Condemnation/ Revocation of Fire C of O	
□ Summary/Vehicle Abatement □ Fire C of O Deficiency List	
Fire C of O: Only Egress Windows	
Code Enforcement Correction Notice	
□ Vacant Building Registration	



CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806

 Telephone:
 651-266-8989

 Facsimile:
 651-266-8951

 Web:
 www.stpaul.gov/dsi

September 13, 2011

ALLISON M CARLSON NICK T CARLSON 2226 BOXWOOD AVE ST PAUL MN 55119-5665

FIRE INSPECTION CORRECTION NOTICE

RE:

705 GERANIUM AVE E

Ref. #104166

Residential Class: C

Dear Property Representative:

Your building was inspected on September 13, 2011 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date.

A re-inspection will be made on October 18, 2011 at 1:00 pm.

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

DEFICIENCY LIST

- 1. 1st Floor NEC 440.13 For cord-connected equipment such as room air conditioners, household refrigerators and freezers, drinking water coolers, and beverage dispensers, a separable connector or an attachment plug and receptable shall be permitted to serve as the disconnecting means. The appliance must plug directly into a permanent outlet.-A C on power strip.
- 2. 1st Floor MN Stat. 299F.362 Immediately provide and maintain a smoke detector located outside each sleeping area.

- 3. 1st Floor SPLC 34.11(5), 34.34(2), SPC 4715.0200Q Provide adequate hot water between 120 degrees F and 130 degrees F.-Water temperature 145 F
- 4. 1st Floor Bath SPLC 34.10 (7), 34.33 (6) Repair and maintain the ceiling in an approved manner.
- 5. 2nd Floor Bath SPLC 34.10 (7), 34.33 (6) Repair and maintain the ceiling in an approved manner.
- 6. 2nd Floor East bedroom SPLC 34.13 (4) Provide and maintain a minimum egress window sill height of 48 inches. Refer to provide handout EW-1 for more information.-Sill Height 59 in.
- 7. 2nd Floor East bedroom MSFC1026.1 Provide and maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI at (651)- 266-9090. Refer to the Escape Windows for Residential Occupanices handout for more information.-Double Hung window opening. Height 12 in Width 24 in. Glazed area Height 28.5 in Width 21 in.
- 8. 2nd Floor Kitchen MSFC 605.5 Discontinue use of extension cords used in lieu of permanent wiring.
- 9. 2nd Floor Kitchen SPLC 34.10 (7), 34.33 (6) Repair and maintain the ceiling in an approved manner.
- 10. 2nd Floor NEC 440.13 For cord-connected equipment such as room air conditioners, household refrigerators and freezers, drinking water coolers, and beverage dispensers, a separable connector or an attachment plug and receptable shall be permitted to serve as the disconnecting means. The appliance must plug directly into a permanent outlet.-A C on power strip.
- 11. Attic SPLC 34.09 (3), 34.32 (3) Repair and maintain the window in good condition.
- 12. Basement UMC 504.6 Provide, repair or replace the dryer exhaust duct. Exhaust ducts for domestic clothes dryers shall be constructed of metal and shall have a smooth interior finish. The exhaust duct shall be a minimum nominal size of four inches (102 mm) in diameter. This work may require a permit(s). Call DSI at (651) 266-8989.-PERMIT REQUIRED AND INSPECTION BY WARM AIR / VENT INSPECTOR CALL 266-9006
- 13. Basement SPLC 34.09 (3), 34.32 (3) Repair and maintain the door in good condition.-Door does not open.
- 14. Basement MSFC1026.1 Provide and maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI at (651)- 266-9090. Refer to the

Escape Windows for Residential Occupanices handout for more information.-Or remove beds. Or repair door so it opens.

- 15. Garage SPLC 34.08 (5), 34.31 (3) Repair, replace and maintain all exterior surfaces on fences, sheds, garages and other accessory structures free from holes and deterioration. Provide and maintain exterior unprotected surfaces painted or protected from the elements.-Repair and paint siding.
- 16. Rear storm door. SPLC 34.09 (3), 34.32 (3) Repair and maintain the door in good condition.
- 17. SPLC 34.11 (6), 34.34 (3) Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.
- 18. SPLC 39.02(c) Complete and sign the provided smoke detector affidavit and return it to this office.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8688) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: mike.cassidy@ci.stpaul.mn.us or call me at 651-266-8984 between 7:30 a.m. - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Mike Cassidy Fire Inspector

Reference Number 104166