



APPLICATION FOR APPEAL

Saint Paul City Council – Legislative Hearings

310 City Hall, 15 W. Kellogg Blvd.
Saint Paul, Minnesota 55102
Telephone: (651) 266-8585

RECEIVED

JUL 20 2017

CITY CLERK

We need the following to process your appeal:

- ☒ \$25 filing fee (non-refundable) (payable to the City of Saint Paul)
(if cash: receipt number _____)
- ☒ Copy of the City-issued orders/letter being appealed
- ☐ Attachments you may wish to include
- ☒ This appeal form completed
- ☒ Walk-In OR ☐ Mail-In
for abatement orders only: ☐ Email OR ☐ Fax

HEARING DATE & TIME

(provided by Legislative Hearing Office)

Tuesday, August 8, 2017

Time 1:30 p.m.

Location of Hearing:

Room 330 City Hall/Courthouse

Address Being Appealed:

Number & Street: 507 N. Lexington Pky City: St. Paul State: MN Zip: 55104

Appellant/Applicant: Irish Johnson Email: IRIMC@hotmail.com

Phone Numbers: Business _____ Residence _____ Cell 651-335-9157

Signature: Irish Johnson Date: 7-20-17

Name of Owner (if other than Appellant): _____

Mailing Address if Not Appellant's: 247 Johnson Ave Thompson Ave East 55118

Phone Numbers: Business _____ Residence _____ Cell see above

What Is Being Appealed and Why?

Attachments Are Acceptable

- ☐ Vacate Order/Condemnation/
- ☐ Revocation of Fire C of O
- ☐ Summary/Vehicle Abatement
- ☒ Fire C of O Deficiency List/Correction
- ☐ Code Enforcement Correction Notice
- ☐ Vacant Building Registration
- ☐ Other (Fence Variance, Code Compliance, etc.)

According to Attached a renewal of Fire
C of O is needed. I am appealing as
the home is occupied currently by myself
& or husband. We are in the process
of renovations on two homes & time is
split between both.



CITY OF SAINT PAUL
Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220
Saint Paul, Minnesota 55101-1806

Telephone: 651-266-8989
Facsimile: 651-266-8951
Web: www.stpaul.gov/dsi

July 10, 2017

IRISH CONLEY
247 THOMPSON AVE E
WEST ST PAUL MN 55118-3215

FIRE INSPECTION CORRECTION NOTICE

RE: 507 LEXINGTON PKWY N
Ref. #124158
Residential Class: B

Dear Property Representative:

Your building was inspected on July 7, 2017 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date.

A re-inspection will be made on August 11, 2017 at 10:00 AM.

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional re-inspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

DEFICIENCY LIST

1. Exterior - Check All - SPLC 34.09 (4), 34.33 (3) - Provide or repair and maintain the window screen.-
Exterior screens missing or damaged.
2. Exterior - Dwelling Siding and Trim - SPLC 34.09 (1)(2), 34.33 (1) - Provide and maintain all exterior walls free from holes and deterioration. All wood exterior unprotected surfaces must be painted or protected from the elements and maintained in a professional manner free from chipped or peeling paint.-
Paint is peeling and flaking from siding and trim.

3. Exterior - Front Entry Stair - SPLC 34.09 (3) 34.33 (2) - Provide an approved handrail. The top of the handrail must be between 34 and 38 inches above the treads and run the entire length of the stair.-
4. Exterior - Garage - SPLC 34.08(5), 34.32(3) - All accessory structures including, but not limited to, detached garages, sheds and fences shall be maintained structurally sound and in good repair. Provide and maintain exterior unprotected surfaces painted or protected from the elements.-
Siding and trim are peeling and flaking paint.
5. Interior - Basement - SPLC 34.10 (1) - Abate and maintain the basement reasonably free from dampness and free of mold and mildew.-
Corners of basement show water intrusion, yellowing of walls and darker areas toward the floor.
6. Interior - Basement Dryer Vent - MMC 504.6 - Provide, repair or replace the dryer exhaust duct. Exhaust ducts for domestic clothes dryers shall be constructed of metal and shall have a smooth interior finish. The exhaust duct shall be a minimum nominal size of four inches (102 mm) in diameter and installed in accordance with the mechanical code. This work requires a licensed contractor to obtain a permit(s). to install a code-compliant dryer vent. Call DSI at (651) 266-8989.-
Clothes dryer vent is not installed properly.
7. Interior - See Comments - SPLC 34.11 (4), 34.35 (1), MPC 708.1- Connect or cap the sewer piping in accordance with the plumbing code.
Kitchen sink waste line is not code-compliant with flex-style sewer line.
Basement laundry sink has electrical tape at base of sewer line.
8. SPLC 39.02(c) - Complete and sign the smoke detector affidavit and return it to this office.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: <http://www.stpaul.gov/cofo>

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8585) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: laura.huseby@ci.stpaul.mn.us or call me at 651-266-8998 between 7:30 a.m. - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

An Equal Opportunity Employer

Laura Huseby
Fire Inspector

Reference Number 124158