

610 ST Albans

1. The roof on west side porch replaced old wood put on new shingles. Sound tight water proof.

2. The roof on the garage will start over weak end weather permits

3. The exterior walls on house will start next weak end. The trim is 90% done. We had to take a tree down to paint. We have to get the brush picked up to finish painting.

4+5 The exterior walls and trim on Garage. Husband fixed the North side and painted a few months ago. Will paint again when finish house

6+7 Windows and storms are getting worked on. Have a new ~~door~~ screen door for the front. The storms and screens you put on and off spring and Fall

67" 1 - MOMES AVE

① The Eaves and soffits work would like to wait till spring.

② Exterior Walls only have a little spot that has paint missing, will fix that. We have been painting trim on first floor. There are ~~no~~ things on second floor. Would like to wait till spring

3 There are no doors or screens missing. There are storm windows that have to go back on. These are also the kind that you change spring and winter.