

The City Clerk needs the following to process your appeal:

\$25 filing fee payable to the City of Saint Paul

APPLICATION FOR APPEAL

RECEIVED

JUL 1 3 2012

CITY CLERK

Saint Paul City Clerk

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8560

(ii casii: receipt number)		TOUR HEARING Date and Time:
Copy of the City-issued orders or lette	er which	
are being appealed		Tuesday, 1-34-12
Attachments you may wish to include	e	Tuesday, 7-34-12 Time/-30 P-M.
This appeal form completed		Time_/ + 30 P-M.
□ Walk-In OR > Mail-In		Location of Hearing:
		Room 330 City Hall/Courthouse
Address Being Appealed:		
Number & Street: 402 Stolvey Street & City: St. Paul State: MN Zip: 55107		
Appellant/Applicant: Relay Property Management Email braderelaypm.com		
Phone Numbers: Business 952-384-6051 Residence Cell 952-210-0313		
Signature:		
Name of Owner (if other than Appellant): Tacob Brunette		
Address (if not Appellant's): W1928 Chill Road Neillsville, WI 54156-8806		
Phone Numbers: Business	Residence	Cell
What Is Being Appealed and Why? Attachments Are Acceptable		
Vacate Order/Condemnation/		į.
Revocation of Fire C of O Summary/Vehicle Abatement Revocation of Fire C of O Revocation of Fire C of O		
Summary/Vehicle Abatement referenced on the attached		
Fire C of O Deficiency List Fre Inspection Correction Notice, #13.		
Fire C of O: Only Egress Windows	THE INSPECTIO	AV CALLUTION HOTTO, TIS.
	And the second s	
□ Code Enforcement Correction Notice	West of the second seco	
□ Vacant Building Registration		
□ Other		



CITY OF SAINT PAUL Christopher B. Coleman, Mayor 375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806

 Telephone:
 651-266-8989

 Facsimile:
 651-266-8951

 Web:
 www.stpaul.gov/dsi

July 2, 2012

JACOB C BRUNETTE W7928 Chili Rd Neillsville WI 54456-8806

FIRE INSPECTION CORRECTION NOTICE

RE:

402 SIDNEY ST E

Ref. #117578

Residential Class: C

Dear Property Representative:

Your building was inspected on July 2, 2012 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date. A reinspection will be made on July 31, 2012 at 1:00 pm.

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

DEFICIENCY LIST

- 1. Basement CO Detector MN State Statute 299F.50 Immediately provide and maintain an approved Carbon Monoxide Alarm in a location within ten (10) feet of each sleeping area. Installation shall be in accordance with manufacturers instructions.-Missing CO detector in basement.
- 2. Basement Ceiling MN Stat. 299F.362 Immediately provide and maintain a smoke detector located outside each sleeping area.-Replace missing hard wired smoke detector on basement ceiling.
- 3. Basement Furnace Room MSFC 605.6 Provide electrical cover plates to all outlets, switches and junction boxes where missing.-Install missing light switch cover plate.

- 4. Basement Furnace Room UMC 1346.703 Provide 30 inches clearance around all mechanical equipment.-Tenants are to move material away from furnace.
- 5. Basement Southeast Bedroom MSFC 605.5 Discontinue use of extension cords used in lieu of permanent wiring.-Remove extension cord.
- 6. Exterior Tree SPLC 34.08 (5), 34.31 (3) Repair, replace and maintain all exterior surfaces on fences, sheds, garages and other accessory structures free from holes and deterioration. Provide and maintain exterior unprotected surfaces painted or protected from the elements.-Remove tree lying on front side of property. Fill in and level hole left my tree.
- 7. Garage Address Numbers SPLC 71.01 Provide address numbers on garage facing the alley.-The address number to be posted is:
- 8. House Address Numbers SPLC 71.01 The address posted is not visible from street.-Provide address numbers that contrast with the background. Provide reflective numbers or background or illuminate at night. House numbers sitting on front staircase.
- 9. House North Front Cement Staircase SPLC 34.09 (2), 34.32(2) Repair or replace the unsafe stairways, porch, decks or railings in an approved manner. This work may require a permit(s). Call DSI at (651) 266-9090.-Repair bottom step from main grade up to first step. Measured step height from ground up at above 12 inches.
- 10. Kitchen Cabinets SPLC 34.10 (7), 34.33 (6) Repair and maintain the cabinets in an approved manner.-Repair or replace damaged kitchen cabinet drawers.
- 11. Main Floor Bathroom Sink Piping SPLC 34.11, SBC 2902.1, SPLC 34.17, MPC 415.0220 Repair or replace and maintain the plumbing fixture to an operational condition.-Remove accordion piping and install solid PVC piping.
- 12. Main Floor Hallway Ceiling and Southeast Bedroom MSFC 605.1 Repair or replace damaged electrical fixtures. This work may require a permit(s). Call DSI at (651) 266-9090.-Repair or replace hallway ceiling fixture. Repair southeast bedroom ceiling fixture.
- 13. Main Floor Southeast Bedroom Sleeping Room Egress Windows MSFC1026.1 Provide and maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI at (651) 266-9090. Refer to the Escape Windows for Residential Occupanices handout for more information.-

Southeast Sleeping Room Egress Windows (2 ea Double Hung) 16.5 h x 32.25 w openable 32.75 h x 30.25 glazed

14. SPLC 34.11 (6), 34.34 (3) - Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.

15. SPLC 39.02(c) - Complete and sign the smoke detector affidavit and return it to this office.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8688) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: sean.westenhofer@ci.stpaul.mn.us or call me at 651-266-8982 between 7:30 a.m. - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Sean Westenhofer Fire Inspector Ref. # 117578