Attu: Mai Vang

DCI

Fire / Water Restoration • Mold Remediation • Asbestos Abatement Soda Blasting • Drug Lab Decontamination • HVAC System Cleaning

June 20, 2017

Mr. Gary Johnson Arizona

Re: Mold Remediation Status at 855 South Lexington Blvd, St Paul, MN

Please consider this letter to be a project status of the mold remediation at the above referenced address.

DCI has completed the bulk removal of the building materials with visual mold growth. The exposed building materials that remain have been disinfected. The disinfecting also includes the basement block foundation walls.

***Due to the severity of the rot on the upper level, backside walls, DCI halted the final remediation process per our discussion. The final process would have included HEPA vacuuming and another disinfecting of the walls, ceilings and floors, and coating the exposed walls cavities with a stain blocker/sealer.

If you have any questions, please call me at (763) 229-7204.

Respectfully Submitted,

Charles Wilcox

Charles Wilcox President

*** Clarification of this paragraph – The mold remediation of this area, as well as the rest of the house, is complete, except for the final HEPA vacuuming and coating. The rotted/moldy materials have been removed and the remaining materials have been disinfected. This paragraph was originally included as an explanation as to why the final HEPA vacuuming and coating was not performed.